



KEEL BEAM BOX
SEE SKETCH ON
NEXT PAGE

LOG # LF-14 Rev A ^{SDG} ^{RTS 10-1-96} ^{RHS}

TARGET # _____

COORD: LAT _____

LONG _____

DEBRIS FIELD SEE BELOW

Rev A added extra segments
depth of structure
now have Parts A, B, C & D
Added Pages 1a, 9-12
Revised Pages 1, 5, 6


PART	DEBRIS FIELD
PART A	RED TAG # 1001 A-2048
B	GREEN C 061
C	↓ → WHITE D2133 Kurtz 2/28/97
D	ASSOCIATED WITH GREEN TAG # C-109 <div style="border: 1px solid black; padding: 5px; display: inline-block;">C-2440</div>

REFER METALLURGY GROUP NOTES

TWA 10-1-96
R. ... JAM 10-24-96

Pg 1
R. Harwood E/11/96
Stephen F. Klappert for FAA 10-21-96

LF 14 Rev A
ROAD MAP



- THE LOWER HORIZONTAL WEB BETWEEN KEEL CHORDS AFT OF STA 1144 IS MISSING.

R. Navarone 8/1/96

Stephen F. Kluppelt SA FRM 10-21-46
Fig 1a 2


LF14A

SIDE VIEW OF BOX (LHS)

ATTACH ANGLE / TEE TO WING
HAS FLANGES TORN
OFF FOR 50% IN
RANDOM MANNER

TEAR
L & R HS

WRINKLE
OUTBD
L & R HS



R. H. ...

SEE Pg 7 FOR FLAGNOTES

LF14 PART A

file, 'winword, keelbeam ' on pc against far wall
in command post

Duct is crumpled, and rotated fwd roughly 60 degrees

General Notes;

The upper chord of the keel beam box is buckled in the following manner;

LHS

Starting at the front spar location and moving aft, midway between Keel Beam Stiffeners (KBS) 2 & 3, there is an inward buckle, horizontal flange of upper inb'd chord is fractured. Just behind KBS 3 there is an outward buckle. Between KBS 4 & 5, there is an inward buckle. At KBS 5 there is outward buckle. 2 ½ forward of KBS 10 there is an outward deformation and at KBS 10 a minor inward deformation.

RHS

In between the front spar and KBS 1 an inward buckle, just behind KBS 3 an outward buckle. 2 " KBS 4 the start of an inward buckle which turns outward between KBS 5 & 6, coming to an apex at KBS 7. There is an inward buckle at KBS 8 with a major outward buckle at KBS 9.

The KBB cross bracing at SWB 2 & 3 and the Mid Spar bulkhead remained intact

Bolts that connect the upper chord of box to the wing

@Stiffener #1, on each side one bolt broke at the thread root, the other bolt still has threads, so the nut failed. Note 2 bolts per side.

Soot on bottom of Section 42 skin just forward of keel beam box (KBB) did not come through the KBB- box is clean of soot

Outer surfaces of box are lightly sooted, except for the right side outer surface, centered at Sta 1129 approx, exhibited evidence of sooting in an upward/forward and aft direction. This sooting is moderate. There is light sooting on the most aft 8" of the RHS vertical web.



There is also light to moderate sooting between Keel Beam Stiffener (KBS) 11 and 10, halfway up from the bottom of the keel beam.

RHS ATTACHMENTS

- @ Stiff # 3, duct supports bent forward located in bottom half of stiffener
- @ Stiffener #4 & #5, standoffs at top of stiffeners bent aft.
- @ Stiffener #7, standoff 6" from the bottom is broken off.
- @ Stiffener # 9, standoff 6" from the bottom is bent forward
- @ Stiffener # 10, bracket near top bent forward
- @ Stiffener # 11, standoff near bottom bent forward
- @ Stiffener # 13, has 3 standoffs near bottom, top bent upwards, bottom one has bolt/nut gone, and middle one looks OK
- @ Stiffener # 14, Duct bracket bent forward
- @ Stiffener #15, standoffs(2) near bottom bent forward
- @ Stiffener # 16, standoff 6" above keel chord bent aft



FRAGURE PLANE (LOWER RIGHT)

11 FRACTURE OF CUSHION FROM MOMENT ABOUT MASS AXIS OF SECTION AS INDICATED



Stephen F. Kluprecht, 512
FAA 10-21-96

FRACTURE PLANE (UPPER RIGHT CHORD) ∇




Stephen F. Klappert
FAA 10-21-46

LF-14
FIG 2
KD 9-17-96
DEAN
 ∇ (LEFT UPPER CHORD)
SIMILAR

FIG 3
 KD 9.11.96
 DEAN

KEEL BEAM (LEFT SIDE)
 LOWER CHORD FRACTURE LF-14



BS 1152

LF14C

LF14A

LOWER CHORD AFT SIDE

LEFT LOWER CHORD FORWARD SIDE

LARGE RADIUS

VIEW LKG UP, AFT & MID


LOWER CHORD FRACTURED IN BENDING ABOUT PRINCIPAL SECTION

VIEWED FWD

STRAIGHT EDGE

FWD


Stephen P. Klappett Sr
 FAA 10-21-96



DS
1150

FLUID

BENDING ABOUT MASSAL AXIS



VIEWED FORWARD

FRACTURE PLANE LF-14A
LOWER CHORD (RIGHT SIDE)

▷ SAME AS FIG 1 EXCEPT FRACTURE VIEWED FROM

FIG 4.

KO 9/12/96
 DEAN


Stephen F. Klapach, S.E.
 FAA 10 21-76

9

FL 5
 KD 9.17.96
 DEAN

KEEL BEAM TO SPANWISE BEAM ATTACHMENT
EASIER CONDITION

LF-14A




SUPPORT FITTING
 (TYPICAL)

VIEW A


STN	ATTACHMENT POSITION		BOLT CONDITION	
	LI	RI	TYPE	ϕ°
SNB ①	L1	R1	A	-
	LEFT	RIGHT	B	0
SNB ②	L2	R2	A	60
	LEFT	RIGHT	B	8
SNB ③	L3	R3	C	30
	LEFT	RIGHT	B	10

▷ BOLT FITTING MISSING.


▷ TYPE C



▷ TYPE B




▷ TYPE A



Stephen F. Klepach on
 FAA 10-21-96

LF14A




VIEW OF FWD END OF KEEL BEAM BOX

REV (A) ALL FRACTURE SURFACES FREE OF SOOT


Stephen F. Klepachuk
FBA - 10-26-96

Rev (A) RA 8/11
LF-14
Phononua 8/9/96
P. 11

LF14A



VIEW OF
RHS



KEEP BEAM
WEB BENT
BACK INTO
BOX

FRACTURE FACE OF
KEEP BEAM CHORD
TYP BOTH SIDES
BOTH SURFACES FREE
OF SOOT


REV (A) →

Rev (A) R4 E11
LF-14
R11 E10

R12

LF14A

MID
SPAR



VIEW B-B

Stephen F. Klupacz
10-21-96

LF-14
P/B

R. K. Korman 8/8/96

13

LF14A


- 1 Pushed Fwd
- 2 LOOKS LIKE DUCT WAS PUSHED DOWN & FWD

FOR OTHER VIEWS

A-A₁ HAS ONLY 1 UPR BRACKET WITH 2 TURN BUCKLES, UPR TURN BUCKLE IS SEVERED, LWR TURN BUCKLE IS STILL ATTACHED TO PIPE CLAMP. BRACKET ATTACHED TO STIFF HAS BEEN PUSHED FWD. PIPE CLAMP IS SEVERED

A-A₂ 1 UPR BRACKET w/ 1 TURNBUCKLE ATTACHED TO SEVERED PIPE CLAMP BRACKET PUSHED AFT

A-A₃ SIMILAR DESIGN TO A-A
 LWR BRACKET PUSHED FWD
 UPR BRACKET TWISTED ABOUT 10° CLOCKWISE



VIEW A-A

VIEW LK4 FWD

RHS VERTICAL WEB
OF KEEL BEAM BOX
(FROM GREEN DEBRIS FIELD)

NET AREA FAILURE
@ RIVET LINE

WING CTR LWR SKIN
(REF CW-211, C2138)
STA 1151.95
SUB #1

FRACTURE SURFACE
OF KEEL CHORD IS
HEAVILY SOOTED

REAR
SPAR

VIEW LK9 INBD
UP ↓ FWD →

LF14B

WING REAR SPAR WEB
A-FRAME ATTACHED TO

HYDRAULIC
ARM

THIS STIFFENER &
PORTION OF WEB
PULLED OUT'D 5"
FROM WEB

WEB IS TORN
AWAY

10" DIA
CUTOUT

STA 1265

HYDRAULIC
ARM


WING GEAR
DOOR SUP'TS

STA 1338

RECEIVED THIS KEEL BEAM BOX IN 2 PIECES, RHS VERTICAL
WEB SHOWN ABOVE

Pg 15
Pg 9
RHarauer 8/11/96

15
Stephen F. Klappelt Jr
FAA-10-21-96



- OUTB'D SURFACE OF KEEL BEAM BOX VERTICAL WEB IS HEAVILY SOOTED FROM REAR SPAR FWD, SOOTING FROM STA 1265 - R/S IS MEDIUM. SOOTING FROM STA 1265 AFT TO END OF PART IS LIGHT

1. FRACTURE SURFACE OF WEB IS SOOTED
2. FRACTURE SURFACE OF VERTICAL LEG OF R/S CHORD IS SOOTED AT LBL 7. FRACTURE SURFACE OF R/S CHORD AT RBL 9 CENTER BOX LWR SKIN IS NOT SOOTED

- THE INBD SURFACE OF THE KEEL BEAM BOX VERTICAL WEB EXHIBITS THE SAME SOOTING TREND AS OUT'D SURFACE BUT TO A LESSER DEGREE. NOTE, THAT FROM STA 1265 TO AFT END OF PART THERE IS ONLY SLIGHT SOOTING - THE GREEN PRIMER IS PREDOMINATE
- THE KEEL BEAM BOX INNER CROSS BRACING STRUCTURE AT STA 1265 & 1330 SEPARATED FROM THE LHS KEEL STRUCTURE.

Pg 10
8/11/96 14

(GREEN DEBRIS FIELD)

LF14C

15"

LOW
WING
SKIN

A-A
STA
1151.95

SWB#1

PART C

STA
1255

KEEL CHORD IS
FRACTURED AT
STA 1252

THIS PORTION OF VERT
WEB BENT BACK OVER
ON ITSELF OUTWARD

KEEL CHORD FRACTURE
SURFACES - NO SOOT
IN FRACTURE

UP
FWD

VIEW LKG INBD
ON LHS

KEEL CHORD
FRACTURE
SOOTED

THE RECEIVED PORTION OF THE LHS VERTICAL WEB EXTENDS 8 BAYS FWD OF R/S (SAME AS PIECE FROM RHS) AND 2 BAYS AFT OF R/S. LAST-AFT BAY INCLUDES 10" DIA. CUTOUT


LHS

- INB'D SURFACE OF VERTICAL WEB IS SOOTED IN SIMILAR MANNER TO THE INBD SURFACE OF RHS VERTICAL WEB
- THE OUTB'D SURFACE OF VERTICAL WEB (LHS) HAS GREY COLOR - MEDIUM SOOTING
- THE FRACTURE SURFACE OF FWD END OF KEEL BEAM CHORD AT FWD END OF THIS SEGMENT IS SOOTED. THIS LHS KEEL CHORD IS FRACTURED AT R/S & JUST FWD OF STA 1265 - NEITHER OF THOSE 2 SURFACES EXHIBIT SOOTING

LF14D

ASSOCIATED WITH
GREEN TAG C-109
LAT 40° 39' 46.9"
LONG 72° 37' 27.9"

AFT WEB PULLED
OUT OF FASTNRS



VIEW LOOKING INBD
ON RHS KEEL BEAM BOX

LESS THAN 10% OF TOP & LWR
PANELS ARE STILL ATTACHED
Pg 12 RANAMUA 8/11/96

CHORD EXTENDS TO END OF OUTBD FLANGE WHERE IT THEN IS SEVERED IN A DOWN & INBD DIRECTION ACROSS A FRAME CHD & WEB. ATTACH ANGLE/TEE IS SEVERED AT BK & THE ATTACH ANGLE/TEE FRACTURE IS SOOT FREE.

Stephen F. Harp...
FNA-10-21-96
1913

