## BS 1480 Bulkhead Assembly Approximately LBL 8 to LBL 75

			•			
	Log Number Debris Field Target Number Coordinates: Latitude Longitude	LF92 Green C104	19-3 No	New Tog., BETAUSE THE PROM LG	No.15. GIVES. IS PIECE WAS	= C-2468 RG
	Body gear trunnion fittings 65B11782 and 65B10462 are attached to the body gear assembly, see LG3, and a portion of 65B10005 web as shown on attached illustration.					
	Inboard trunnion fitting lates The outboard rod end no that failed. The inboard	t connected to t	the trunnion fitting	contains a small portio	n of structure or linkage	
	Horizontal stiffeners located on the aft side of web have torn away at the radius and departed. A segment, the same width as each trunnion fitting, of horizontal web assembly 65B01865-6 is attached at each trunnion fitting.  To LG3 RH 324/97 7BC Starter Various types and lengths of wiring and conduits are attached twelve inches above \$45R and \$46R.					
	Various types and length	s of wiring and	l conduits are attach	TC LG3 KH ed t <del>welve inches abov</del>	324/97 1BC Sto 16 e S45R and S46R. 3	14 14/77
	Structure has minor surfa	ace abrasions at	t random locations t	hrough paint laver. Pri	imer remains No visibl	le l
	indication of soot.  Segment of 14	brizontal	i beam ar	lached on a	aH side 6	WEILG.
1>"	LF92" CRATED See attached roudmap	2-26-97 , ps.	, removed from	_"LG3", hung	on mackupat F.	'S 1480 Bulkhad
2	SEE LF 149					
	Denris Santa 3-24-97	ago IAM				
	Dru Todaya Bhandahudu	TWA 3/19/9	7			

Leid D. John ALPA 13 Mai 37 Rélavauer 3/24/97 Boeing

The Author of This is Dan Rephlo of TwA



