

1  
2  
3  
4  
5  
6 **NATIONAL TRANSPORTATION SAFETY BOARD**

7  
8  
9  
10 **Office of Railroad, Pipeline and Hazardous Materials Investigations**  
11 **Washington, DC**

12  
13  
14  
15 **TRACK & ENGINEERING GROUP CHAIRMAN**  
16 **FACTUAL REPORT**

17  
18  
19 **DCA-14-MR-004**

20  
21  
22  
23 **Collision and Derailment with Hazardous Materials Release**  
24 **Eastbound BNSF U FYNHAY4-05 (Petroleum Train) with Westbound BNSF**  
25 **Train G RYLRGT9-26 (Grain Train) at Casselton, North Dakota**

26  
27 **Casselton, North Dakota**  
28 **BNSF's KO Subdivision**  
29 **December 30, 2013**

30  
31  
32  
33  
34  
35  
36  
37  
38  
39 Preliminary Factual Report Prepared by:  
40 R. A. Hipskind,  
41 Track and Engineering Group Chairman  
42

Date: January 23, 2014

1           **Accident**

2  
3           NTSB Accident Number:     DCA-14-MR- 004  
4           Date of Accident:         December 30, 2013  
5           Time of Accident:         2:11 p.m. (CDT)  
6           Type of Train and No:     U FYNHAY4-05 (Petroleum Train) & G RYLRGT9-26  
7   (Grain Train)  
8           Transit Owner:            BNSF Railway (BNSF)  
9           Transit Operator:         BNSF  
10          Crew Members:            Petroleum train—engineer & conductor  
11                                        Grain train—engineer, student engineer & conductor  
12          Location of Accident:     Casselton, ND  
13  
14

15          **Synopsis**

16  
17           On Monday, December 30, 2013, at 2:11 pm CST, westbound BNSF Railway  
18           grain train G-RYLRGT9-26A consisting of two head end locomotives, one rear  
19           distributive locomotive power unit (DPU) and 112 cars derailed 13 loaded cars (the 43<sup>rd</sup>  
20           through 55<sup>th</sup>) at MP 28.5 of the KO Subdivision, Twin Cities Division in Casselton,  
21           North Dakota while traveling on main track 1. The derailment occurred in the middle of  
22           the train resulting in one of the grain cars, the 45<sup>th</sup> car in the line, fouling main track 2.  
23           Eastbound BNSF petroleum crude oil train U-FYNHAY4-05T consisting of two head  
24           end locomotives, one rear DPU and 106 cars, collided with BNSF grain car 486653 of the  
25           grain train and derailed the leading locomotives and cars 1 through 20 to the south on  
26           main track 2. After the collision an undetermined amount of petroleum crude oil was  
27           released from 18 loaded tank cars fueling a fire.  
28

29           Local emergency officials ordered a voluntary evacuation of the town of  
30           Casselton. Approximately 1400 civilians from the town of Casselton were reported to  
31           have evacuated. No civilian injuries were reported. The train crew from U-FYNHAY4-  
32           05T, consisting of an engineer and a conductor, escaped from the rear door of the lead  
33           locomotives uninjured. The crew from train G-RYLRGT9-26A was not injured.  
34

35           BNSF has estimated damages at \$6.1 million; this does not include lading or  
36           environmental remediation. The weather at the time of the accident was cloudy and -1°  
37           Fahrenheit, winds north at 7 mph.  
38

39           The parties to the investigation include the Federal Railroad Administration  
40           (FRA), the US Department of Transportation Pipeline and Hazardous Materials Safety  
41           Administration (PHMSA), the BNSF Railway, the Brotherhood of Locomotive Engineers  
42           and Trainmen (BLET), the International Association of Sheet Metal, Air, Rail and  
43           Transportation Workers (SMART)<sup>1</sup> and Trinity Rail Car.  
44

---

1 Formally the United Transportation Union (UTU)

1 **Circumstances Prior to the Accident:**

2  
3 On December 30, 2013, at 2:11 pm CST, westbound BNSF grain train G-  
4 RYLRGT9-26A consisting of two head end locomotives, one rear DPU<sup>[1]</sup> and 112 cars  
5 was operating on main track 1 near Casselton, ND. The train experienced an uninitiated  
6 emergency brake application. Immediately a crewmember radioed an emergency  
7 announcement on channel 70. At the same time, a signal maintainer was in a vehicle on  
8 an access road near the west switch of the crossover located at milepost 28.5. He had  
9 noticed that the switch heater covers were damaged and radioed on channel 70 to the  
10 grain train and asked if they were aware that their train might be dragging equipment.  
11 Simultaneously, the petroleum train was operating eastbound on main track 2 and had  
12 passed the head portion of the grain train. The crew of that train was in the process of  
13 clearing their authority to hold a track warrant from the subdivision that they had recently  
14 exited.  
15

16 Prior to the westbound grain train's derailment, it was traversing straight track  
17 (main track 2) from Dalrymple at milepost 25.5 on a slight ascending grade that varied  
18 from .00% to .27%. Prior to the eastbound petroleum train's collision with the fouled car  
19 and subsequent derailment, it was on straight track (main track 1) from milepost 30.0 to  
20 28.5 on a slight descending grade that varied from .04% to .13%.  
21



41 **Figure 1. Global view of derailment area.**

42  
43  

---

[1] DPU refers to distributive locomotive power, generally located as the rear end of a train..

1 **The Accident:**

2  
3 The grain train went into emergency due to a train separation that occurred in the  
4 middle portion of the train. The train separated when 13 loaded grain cars derailed with  
5 at least one of the cars fouling main track 2. It was later learned that the grain train  
6 derailed 13 loaded cars (the 44th through 56<sup>th</sup>) at MP 28.5. As eastbound BNSF  
7 petroleum oil train proceeded on main track 2, the crew observed the car fouling their  
8 route and the engineer made an emergency brake application prior to taking protective  
9 measures for their safety. The leading locomotive struck the grain car and the both  
10 locomotives and the head 21 cars derailed primarily to the south of main track 2.

11  
12 After the collision both crewmembers of the petroleum train exited the  
13 locomotive and cleared the immediate area. As they placed themselves in a safer position  
14 from the train an undetermined amount of petroleum crude oil was released fueling a fire  
15 allowing cars to explode.

16  
17 **Track Description:**

18  
19 The main tracks are constructed on 136 pound continuous welded rail affixed to wooden  
20 crossties with elastic fasteners. The derailment occurred in a No. 20 turnout.

21  
22 BNSF inspects and maintains the KO Subdivision according to BNSF policy which calls  
23 for four complete inspections per week. The track was last inspected on December 29, 2013, by  
24 a qualified BNSF track inspector. No defects were noted on that report in the area of the  
25 collision/derailment.

26  
27 The BNSF KO Subdivision is a multiple main track (main tracks 1 & 2) system. The  
28 tracks are signaled for train movement on either track in either direction. The predominant rail  
29 section is 132 pound continuous welded rail (CWR). The rail is fastened to conventional  
30 wooded crossties through double shouldered tie plates with one anchor and one rail spike on  
31 each side of the rail. BNSF operates an average of 17 trains within a twenty-four hour period,  
32 which amounts to about 66.2 million gross tons (mgt) annually for the line.



1  
2 **Figure 2.** View looking west (direction the train was travelling) from near the point of derailment.

3  
4 **Derailed Cars:**

5  
6 The petroleum train derailed the lead and second locomotives, a buffer car of sand and  
7 the head 20 loads of petroleum product. The grain train derailed 13 loads of grain, the 44<sup>th</sup>  
8 through the 56<sup>th</sup> cars of the train.

9  
10 **Damages Estimates:**

11  
12 BNSF engineering personnel estimated total track structural damages at \$486,000.  
13 This figure includes costs for the installation of replacement rail and cross-ties associated  
14 with damage from the accident. BNSF estimated the total damages for the accident at  
15 \$6.1 million.

16  
17 **Post-Accident Inspection/Testing of Track**

18  
19 Investigators measured the track geometry preceding marks found in the west switch of  
20 the crossover located at milepost 28.5 and noted the following:

1  
2 The track inspection field notes noted:  
3

- 4 • The maximum measurement allowed for gage in FRA Class 4 track, a maximum  
5 authorized speed of 60 mph (freight) is 57 1/2 inches. Track notes determined that  
6 the widest gage prior to the POD was 56 5/8 inches; or about 7/8 of an inch under  
7 the FRA maximum allowable limit.  
8
- 9 • The maximum allowed deviation for alignment measured with a 62' chord in  
10 FRA Class 4 track is 1 1/2 inches for tangent track. Track notes determined that  
11 the greatest alignment deviation prior to the disturbed track was 1/2 of an inch; or 1  
12 inch under the FRA maximum allowable limit.  
13
- 14 • The maximum allowable deviation from zero crosslevel at any point on tangent or  
15 reverse crosslevel elevation on curves may not be more than 1 1/4 inches for  
16 Class 4 track. Track notes determined that the maximum crosslevel prior to the  
17 disturbed track was 1/4 of an inch; or 1 inch under the FRA maximum allowable  
18 limit.  
19

20 This is the last segment of track the grain train traveled over prior to the  
21 December 30, 2013, derailment. Investigators post-accident inspection from mile post  
22 25.2 (east of the accident site) to the beginning of the disturbed track, found there were  
23 no visual exceptions.  
24

#### 25 **Point of Derailment<sup>2</sup>:** 26

27 Investigators observed marks at the frog area and on top of the closure rail extending  
28 from the switch point area to the frog. The rail exhibited several marks but there were no wheel  
29 flange marks departing the rail head.  
30

31 Investigators identified the point of derailment (POC) at a location where the outside  
32 edge (field side) of the south rail showed an indication of wheel flange trailing off to the field  
33 side and continuously marking the field side OTM in a westerly direction. The initial mark was  
34 located 60 feet 3 inches from the frog point and 96 feet 6 inches from the switch point. On the  
35 opposite rail, marks indicated a wheel flange trailing to the inside of the rail head and downward  
36 onto the track and OTM marking elastic clips and proceeding in a continuous manner to the heel  
37 block location. Investigators observed and documented a deep strike mark at the heel block.  
38 The switch crossties supporting the switch point area were damaged and the track west of the  
39 switch was destroyed.  
40  
41  
42  
43

---

2 Point of derailment (POD) GPS coordinates are N46.901067, W97.2278290

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45




Figure 3. View of derailment marks; blue arrow indicates direction of train travel.



Figure 4. View of south rail derailment marks; blue arrow indicates direction of train travel.

1  
2  
3



4  
5

**Figure 5. Strike mark located at left hand switch point heel block**

6  
7

### **Geometry Tests**

8  
9  
10  
11

BNSF operated their track measurement geometry vehicle (car 87) over the K O subdivision, main track 1 on November 13, 2013. The BNSF geometry data generated no exceptions for this area.

12  
13

### **Internal Rail Tests Data:**

14  
15

#### **Herzog Reports Review:**

16  
17  
18  
19

On December 10, 2013, an ultrasonic rail test was conducted on BNSF's K O subdivision. Herzog vehicle HRZ134 conducted this inspection. No defects were recorded in the vicinity of the derailment.

20  
21

#### **Track Inspection Records:**

22  
23  
24  
25  
26  
27

FRA regulations found in 49 CFR 213 require that a rail carrier's track inspection records be prepared and signed on the day of the inspection for frequency of compliance with the Federal Railroad Administration Track Safety Standards (FRA/TSS). FRA track inspection records are required to reflect actual field conditions and deviations from the FRA TSS. BNSF has elected to maintain to FRA Class 4 standards requiring BNSF



1 personnel to inspect the main track at least twice per calendar week. However, BNSF  
2 inspects this area of main line tracks a minimum of four times per week.

3  
4 Track inspection records for the BNSF K O subdivision were examined from  
5 October 22, 2013, through to December 31, 2013. The records show that the frequency  
6 of inspections is in compliance with federal regulations.

7  
8 The track in the area of the derailment was last inspected on December 29, 2013,  
9 by a FRA qualified BNSF track inspector (T/I). The T/I noted no defects in the affected  
10 area.

### 11 **Regulatory Track Inspection History**

12  
13  
14 On March 21, 2013, FRA conducted a walking inspection of six switches in the  
15 Casselton area. No defects were noted for the switch where the derailment occurred.  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45

Parties to the Investigation - Acknowledgment Signatures

The undersigned designated *Party to the Investigation* representatives attest that the information contained in this report is a factually accurate representation of the information collected during the investigation, to the extent of their best knowledge and contribution in this investigation.

\_\_\_\_\_

\_\_\_\_\_  
//s// Date 2-10-14  
Richard A. Hipskind, NTSB

\_\_\_\_\_  
//s// Date 2-10-14  
Douglas J. Jensen, BNSF

\_\_\_\_\_  
//s// Date 2-11-14  
Blain R. Luck, FRA

\_\_\_\_\_  
//s// Date 2-11-14  
Quinn Ligon, FRA