Report:	Reported Date:	Corrective Action:	Resolved Date:
right vac pump inop.	2014-01-23	rep. pump	2014-01-24

A	DISTRIBUTOR OF AIRCRAFT PARTS, PAINT, AND ACCESSORIES WITH OVER 100 FACTORY DIRECT LINES												
			WITH OVER 100 FACTO	DRY DIRECT L	INES		-					Invoice # Date Page	799942 08/06/2013
Bill To:	S# AIR	LINE TRA	NSPORT PROFESSIO		Ship To:	S# AIRLINE	TRA	NSPORT	PROFES	SIO	7	Doc #	486772
		VEDRA B	EACH, FL 32004		61	JACKSONVI	LLE	, FL 3222	5				
PON	101 Con 100	Shipped	Salesperson	Terms	Tax Cod	e Doc#	WD	Freight		Ship Via			
		08/06/13	DG DAVID GLAS	NET 30		486772	11	PRE/AD	D UPSG	ROUNDFRE	Æ		
1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 -	al and	item / Descri	iption.	Ordered	Shipped	Backordrd	UM	Cts	List Price	Disck	Net Price	Line Po	Extensi
RAD9-18-1 VACUUM INLET F	LTER	NE	No. 22	5.00	5.00	.00	EA	41		.00			
RA66-105 BRAKE LINING R	A066-1050	00 NE 06	6-05500.66-105	60.00	60.00	.00	EA	95R		.00	5.1	128 - St . 3.8	No. of Lot of Lo
DRY AIR PUMP O	OH	24/22		5.00	5.00	.00	EA	99P		40.00	-	-	
		LED OH Ser#	155118 155119 155223 155224 155225	•	1.00 1.00 1.00 1.00 1.00								
115CC-RAPCOM REPAIRED CORE		OH		5.00	5.00	.00	EA	99P		0.00		And some station	Contract of the
16CW-RAPCO-		The two	a Salara and	5.00	5.00	.00	EA	99P		00			
ORY AIR PUMP O	VERHAUL	ED OH Ser#	143128 155135 155159 155161		1.00 1.00 1.00	~				.00			ES BAN
			155162		1.00		61	131			20		
EPAIRED CORE	the state of the s	OH		5.90	5.00	.00	EA	99P		0.00	50	AL MARKEN	
PSGROUNDFR PS GROUND FR racking Number	EE	ALC: NOT		1.00	1.00	.00	EA	P		.00		Ulic Sectory	
En			If this increase in storp place user here care plate in UMA Choices is it is NOT any spectra insplate insplation of the store of the store of the insplate insplate insplace in the store of the effect of the store insplace insplace care will be store of the store of the store of the effect of the store of the store of the store will be store of the store of the store of the effect of the store of the store of the store of the store of the store of the store of the store of the store of the store of the store of the store of the store of the store of the store of the store of the effect on store for all store of the store of the store of the effect on store for all store of the store	(b) An Up, showing Estimate wherful analytical addptate at the AC days. XII secondary Trans. Any disputit in post-		Merchan	dise		Masc	Dissour	4 T.	ax Fraight	Total Du
									.00				

1

THANK YOU, WE APPRECIATE YOUR BUSINESS!

APPROVED AUG 1 6 2013

.

FAA/UNITED STATE 4. Organization Name and Ad Rapco, Inc., 6. Item: 1	Idress	WI 53029 (NE5R064 8. Part Number 216CW	IN)	00	. 51	WorkOrder/Contract/Invoice Number: 155135
Rapco, Inc.,	7. Description:	8. Part Number		00		Number:
6. Item: 1	And in the local division of the local divis	the second se				
1	Vасиция Ритр	216CW		10. Quantity	11. Seriel/Batch Numi	er: 12. Status/Work:
	1		N/A	1	155135	OVERHAULED
ru (4474) Re (Babyens au (B) Annovel dessen das Novementores dessen	differite		Certifi Block 14, Ce	es that unless othe	rwise specified in Block 1 in Block 13 was accompli- stations, part 43 and in re-	regulation specified in Block 13 13, the work identified in thed in accordance with Title spect to that work, the items
(s) (a)thorized Studiet on			20. 4:	thorized Signafu	21. Ap	proval/Certificate No.:
ระหมาย สร้างหัติ สะสุขารที่ได้				ne (Urped or Pri IENNIFER L.		e (m/d/y): June 18, 2013
and the second		Us	er/Installer Respon	sibilities		
It is important to understand that the exi- Where the user/installer performs work in Block 1, it is essential that the user/in- specified in Block 1. Statements in Blocks 14 and 19 do not of with the national regulations by the user FAA. Form 8130-3 (6-01)	in accordance with the m staller ensures the his/he constitute install align our	ational regulations of an airwor a sinworksiness authority accept tification. In all cases, aircraft r	thiness authority differen ts parts/components/asser	that the airworthiness ablies from the airwort	authority of the country specifi thiness authority of the country	



MEMORANDUM OF RECORD

Shawn Etcher Air Safety Investigator Eastern Region Aviation

March 26, 2014

Subject: Operator Verbally provided Information on the Vacuum Pump **Persons Present during the Conversation:** Mr. Robert Taylor (Airline Transport Professionals), Mr. Philip R. Cooper (Airline Transport Professionals), Mr. Jim Payne (FAA), and Shawn Etcher (Self)

During the on scene examination of the wreckage following the recovery from the swamp. The above operator's personnel reported the following:

- The day of the accident the operator received a message that the accident airplane's right vacuum pump was inoperative
- It was reported that the previous flight, in the accident airplane, noted a problem with the right vacuum pump.
- The previous crew was not the same pilots on the accident flight
- Maintenance personnel at the Craig Airport base were notified of the discrepancy
- The operator had the unit placarded as inoperative and the determination was made, by the operator, to have the airplane flown to Craig Airport so maintenance could be accomplished at the Craig Maintenance facility.
- The accident pilots, who flew into the accident flight's departure airport, on another airplane, were assigned to fly the airplane back to the Craig Airport.
- The pilots were verbally provided the opportunity, by the operator, to refuse the flight, if they felt it was appropriate, which there was no indication reported that the pilots felt it necessary for the refusal
- The operator's personnel showed the NTSB investigator the message sent to them showing the inoperative vacuum pump on the operator's personnel phone. Note: this investigator did not obtain a copy of the screen shot of the message.
- The operator's personnel further stated that the flight was still legally operated under Part 91 and that no minimum equipment list (MEL) existed for the PA-44 aircraft.
- The operator further reported that no paperwork showing the inoperative equipment had been located and could have been on board the airplane at the time of the accident and likely lost.

-END-

Note: as of September 30, 2015 no documentation was located or provided to the investigator in regards to the inoperative vacuum pump -END-