d ~

Date: 9 December 2012

Observations of Crash of Cessna 421 (N297DB) on 8 December 2012:

Sometime between 1:00PM and 2:00PM I watched the subject aircraft takeoff from Lantana Airport (LNA). I was standing on the transient ramp halfway between the aircraft administration building and hangar 805. The aircraft departed runway 3. The takeoff roll appeared normal with the aircraft breaking ground mid-way down the runway. The initial climb appeared normal. As the aircraft passed a bearing of north from my position, I noticed the aircraft yaw to the left. Shortly after the yaw, the aircraft started pitching nose up. I could not tell whether the landing gear was retracting because of the attitude of the aircraft. The aircraft continued to pitch nose up to an almost vertical attitude (nose pointed skyward). The aircraft then executed a hammerhead turn to the left and dove for the ground nose down. The aircraft was nose down in a steep dive as it passed out of sight behind the tree line. A fireball and black smoke then rose from beyond the tree line. I did not hear the sound of aircraft impact.

James F. Leach

## 9 December 2012

Recount of witnessing crash of Cessna N297DB, 421C, S/N: 421C0826, 8 December 2012.

Sometime after 1 pm on Saturday, 8 December 2012, I came out of Hangar 805/806 at KLNA, Palm Beach County Park(Lantana) airport to watch the aircraft take off. I stood with Mr. Tim Johnson, Sr. and my partner, Jim Leach on the tarmac between the Florida Airmotive Terminal Building and Hangar 805/806.

We watched as the aircraft accelerated down runway 03 for the intended flight to KTMB. The aircraft rotated at around half way down the runway and established a normal climb out trajectory. No abnormalities were seen or heard. I do not recall if the gear was retracted, but nothing seemed out of the ordinary, so I think I would have considered it unusual if the gear had not been retracted. I watched as the aircraft cleared the departure end of 03, still climbing in a normal line. I estimate the aircraft to have been at 2-300 ft AGL. The aircraft then seemed to follow a different line, as if trying to avoid something or beginning a left turn toward crosswind. The turn was premature for a standard pattern. My impression was the aircraft slightly slowed and began to pitch up at an abnormally higher angle of attack than the initial trajectory. The aircraft then rapidly turned to the left and headed for the ground nose down.

It was evident that a crash was about to happen and Mr. Johnson and I ran for my van near hangar 805/806 to go to the aircraft crash site to help. I did not see or hear the impact. By the time I got my van backed away from the hangar, we could see black smoke to the north. Mr. Johnson and I arrived at John Prince Park and proceeded to the crash site. The aircraft was in flames. Police were on the scene and informed us that no one got out of the aircraft. Fire rescue had not yet arrived, so we were asked to stand back from the aircraft. I did not look at my watch to verify the time, but I estimate we arrived within 3-4 minutes of the crash.

Marisa S. Leach

## - Cory + Bivins 12/8/12 Line Services

.8:10am Sumped 84 100th AVGaS Truck (NO Water, No Dist Clean and Blue)

12:40pm faction by front Desk to fuel N297DB.

i pilot was in Office, Request - top both mains.

and nacelle tank's total 171.1 Gallon's

-1:30pm Na97 DB took off Runny 3 North bound

After take off N297 DB crashed.
"I Walked into office and turned around and N297 DB was Spinning out of control in a nose dive. Huge explosion, black Smoke, fire ball."

Cory H Bivins,



Summary of accident of aircraft N297DB on 12/8/2012:

David Levine

Pilot certifications

Commerical ASEL, ASES, AMEL; Instrument rated; CFI/I

Approx: 2000 hrs

Synopsis:

I was in the office of the flight school I where I instruct. I looked out the window just as the accident aircraft was departing on runway 3 at Palm Beach County Park Airport. I saw the aircraft roll down the runway and lift off. It looked as if it was climbing out normally until it reached approximately 400 feet. The airplane then pitched up and rolled to the left. At first, it looked as if it was rolling very sharply on to the crosswind. About a second or so after the roll initiated, the nose of the plane dropped and the airplane rolled over. At this point I had started running out of the flight school in the direction of the accident scene, attempting to call 911. At this time, I lost sight of the airplane and saw a plume of smoke coming out of an area where the aircraft crashed.

Weather conditions at the time of the crash were VFR with calm to slight winds.

Witness Statement

DAVED LEVING 12/9/12

## Aircraft Accident Report

Signature



BO Information with the state of the land with the state of the state	Service and the appropriate to the service of the s
FBO Name FLORIDA AIRMOTIVE INC.	ALEPORT NAME GUMBEACH COUNTY PARK AIRPORT
Address	Airport ID KLNA
City LANTANA FL. ST FL.	zzp 33462_
Accident Reported By	Desirer Contact Information
Name JEFE SWATERS Phore	Маям
Company were ELCREDA Per motive, Inc	Phone
поравляния 12-8-12. Тими: 1:45	Patrice . I
Colden Petalle Bit Side Main a majerie at material to the state of the second	
Tail Number N297DB Alicraft Type CESSA	va 421
Departure	Accident
Date 12-8-12 Time: 1:15 am @ APPROX.	Date /2-8-/2 Time: /:/5
Location KLNA RUNNAY 03 DEPARTURE	Location 1/4 NM, N. OF KLNA
Injuries ? Names _Timethy _ Tohnsen _	
f Fatélitics 7 Names 2	
Property Damage [circle one] Yes / No Explain	
Accident Description: AIRCRAFT DEPARTED	RUNWAY 03, LEFT ENGINE FAILED.
STALLED THE SPUN FROM ACCROX, 400	
well Detailed the Sept District the second of the second o	
How was the alreraft fueled? [circle one] Refueler   Self Serve Dispenser   Full Serve Dispenser	
Type of Fuel? [circle one] Jet A / Jet A with FSII (Argas)	
If jet, does it contain SDA? [circle one] Yes / No / Unknown / NA	
Fuel Uplifted . 171,1 12-8-12 1:10	<b>கா</b> டு
Were samples retained? [dicte one] Yes / No	
How many aircraft fueled since the aircraft in ques	stion? O Total gallons? N/A
Other Fuel related problems reported? [crole one] Yes	No Explain
Has fueling trom involved equipment ceased?	
A fuel quality assurance review will be conducted based on the Phillips 68 Aviation Fuel Quality Assurance Requirements. See reverse side for information needed.	
Name (print) JEFFREY R. SWATERS	Title LINE SERVICE   OFFICE

Date 12-8-12-

AT AITHON I'UIM I SAN NZ97DB ON
TANLOFF ROLL, KLAWAY OB. IMMEDIATELY AFTER
LIFICIT, I NOTCLD A TIN TRAIL OF BLACK SMOKE
TRAILING TRUM LLIT LNCHE I LACOUP A SET OF
BINGCOLARS AUD WATCHED THE AIRCRAFT CONTINUE TO
CLIMB IN A NORMAL ATTITUTE TO APPROX. 300 FT.
AIRCRAFT SLOWING STANDED TO PILH UP AND ROLL
TO THE LEFT. LEFT FROP WAS WINDMILLING,
AND EVENDALLY CAME TO A COMPILTE STOP. AIRCRAFT
CONTINUED TO ROLL TO THE LEFT UNTIL INVERTED.
STALLED A ID STUN 1/2 TO 2 ROTATIONS BEFORE
IMPALT,

i.

Nicola Albano ert, con on Dec. 9 of approximately 100 I was a they so The F80 Floored fremster when I observed an arrest at the window deporting warray 3 there appeared to be brown smake " and Jeff the gentle wan at the dat shorted actash I ran to the window and saw the account appropriate toll over into aball of flame and block smote on the north earlost the park around the John price park C. Mirele Albano