

LJ-1775, N508GT

C90-GT, King Air

June 22, 2012

Morgantown, WV

NTSB Accident Number ERA12FA409

## **HBC - GPS Waypoint Index**

- 13. Roof of antenna tower building
- 14. Base of tower struck by airplane
- 15. Oil soaked fragment with ground strap
- 16. Fuel bladder fragment
- 17. Separated tower antenna
- 18. Side of antenna with black marks
- 19. Oil access door
- 20. Engine cowling fragment with fire detector
- 21. Same as 20
- 22. Fragment with 4 inch diameter impact mark
- 23. Fragment of right propeller spinner with thread mark
- 24. Nose landing gear door
- 25. Right wing tip Outboard of right aileron
- 26. Left horizontal stabilizer and left elevator
- 27. Oil access door
- 28. Right propeller blade S/N K36272 separated 32 inches from shank
- 29. Top of vertical stabilizer with strobe light
- 30. Fragment of engine fire detector

- 31. Right wing
- 32. Fragment of antenna access ladder with fragment of airframe attached
- 33. Top of right engine nacelle nacelle baggage compartment burned
- 34. Luggage and clothing
- 35. No component at this location
- 36. Right elevator balance weight
- 37. Engine mounting truss fragment
- 38. Electro mec actuator
- 39. Fragment of oil scavenge line
- 40. Right propeller hub and 3 propeller blades One blade broken at 17.5 inches from hub
- 41. Right main landing gear wheel, tire and brake with separated portion of strut
- 42. 12 foot 4 inch portion of antenna access ladder
- 43. Propeller counterweight
- 44. Left engine and propeller all four blades present
- 45. Propeller counterweight
- 46. No component at this location
- 47. Antenna ladder fragment 44 inches in length
- 48. Right propeller dome
- 49. Right engine compressor and turbine section
- 50. Right engine ground impact crater
- 51. Right engine accessory section and data plate
- 52. Fuselage, left wing, left aileron, left inboard and outboard flap, vertical stabilizer, rudder, right horizontal stabilizer and elevator