

VEHICLE FACTORS ATTACHMENT

2020 Volvo Post-Crash CVSA Inspection

Greenville, AL

HWY21MH009

(4 pages)

DRIVER/VEHICLE EXAMINATION REPORT Aspen 3.0.0.17 ALABAMA LAW ENFORCEMENT AGENCY Report Number: ALJLJG011363 MOTOR CARRIER SAFETY UNUT Inspection Date: 06/22/2021

ALABAMA LAW ENFORCEMENT AGENCY MOTOR CARRIER SAFETY UNIT										Report Number: ALJLJG011363 Inspection Date: 06/22/2021				
PO BOX 1511 MONTGOMERY, AL 36102-1511									•	:30 AM CT		: 3:00:00	РМ СТ	
									Inspection Level: - Full					
		-4395 Fa		277-32	85					•	ection Typ		•	
		NS AUTO	TRANS	PORT	INC				Driver:					
3552 GREEN AVENUE						License#:						Sta	ite: AL	
LOS ALAMITOS, CA 90720 USDOT#: 00568253 Phone#: (562)430-4100						100	Date of Birth:							
USDOT# : 00568253 Phone# : (562)43 MC/MX# : 277621 Fax# :				2)430-41	30-4100 CoDriver: License#:							Sta	to	
State#:					Date of Birth:							018	ite.	
Location	: WREC	KER YAR	D			MilePost: Shipper:								
Highway: US 31 County: BUTLER, AL					Origin: MOBILE, AL Bill of Lading: Destination:TARRANT, AL Cargo: EMPTY									
,						Destin	iation:		ANT, AL	Ca		T		
		FICATION	1											
• •		<u>/ear</u> <u>State</u>	Plate			oment ID			VIN	<u>GVWR</u>	<u>CVSA #</u> (CVSA Issu	ued # 003	<u>S Sticker</u>
			-	347			H7LN235052	- ,						
2 ST CTRE 2020 CA 4SM4153			13	347T	5E0	DAA16	649LG328501	47,000						
BRAKE A	DJUST	MENTS												
<u>Axle #</u>	<u>1</u>	<u>2</u>	<u>3</u>	<u>4</u>	<u>5</u>									
Right	N/M	1 1/2	1 3/4	1 1/4										
Left	N/M	1 5/8	1 7/8	1 1/4										
Chamber	C-24	L-24	L-24	C-24	C-24	ł								
VIOLATIO	ONS													
Vio Code		Section				ation #			Violations Dis				_	
393.9		393.9(a)		1	Ν		Ν	Y	Inoperable R ,head lights,				n on front o	or rear
393.95F		393.95(f)	1	1	Ν		Ν	Y	No / insufficie		•		•	
393.207A		393.207(a)	1	Y		U	Y	Axle position axle/spring I		s defective/	missing:	d/s broke	n
396.17C		396.17(c)	1	Ν		Ν	U	Operating a (located		out proof of a	a periodic	inspection	: none
393.205A		393.205(a)	1	Y		U	Y	Wheel/rim ci outer rim	acked or	broken: D/	S missinę	g a sectio	n of the
HazMat:	No HM 1	Fransported	1.								Placard: N	No C	argo Tan	k:
Special C	hecks:	Post Cras	h											

State Information:

Nearest City: GREENVILLE;

Report Prepared By:



Copy Received By:

Х

Page 1 of 2

X

00568253 AL ALJLJG011363

DRIVER/VEHICLE EXAMINATION REPORT

Aspen 3.0.0.17

ALABAMA LAW ENFORCEMENT AGENCY MOTOR CARRIER SAFETY UNIT PO BOX 1511 MONTGOMERY, AL 36102-1511	l S	Report Number: ALJLJ Inspection Date: 06/22/ Start: 09:30 AM CT Inspection Level: I - Fu				
Phone: (334)242-4395 Fax: (334)277-3285		HM Inspection Type: None				
HANSEN & ADKINS AUTO TRANSPORT INC 3552 GREEN AVENUE LOS ALAMITOS, CA 90720 USDOT#: 00568253 Phone#: (562)430-41	Driver: License#: Date of Birt 00 CoDriver:	h:	State: AL			
MC/MX#: 277621 Fax#: State#:	License#: Date of Birt	h:	State:			
Location: WRECKER YARD	MilePost: Ship					
Highway: US 31	Origin: MOBILE, AL	Bill of Lading:				
County: BUTLER, AL	Destination:TARRANT, AL	Cargo: EMPTY				
Pursuant to authority contained in Title 32, Chapter 9A, Code of Alabama of service" have been repaired. No person shall operate the vehicle or re						
Mechanic Certification: Please repair violations noted on this report, sign Retain a copy at the motor carrier's principal place of business or where the MAIL or e-mail at MCSUinfo@alea.gov or FAX to (334)-277-3285.						
Signature Of Repairer X:	Facility:	Facility:				

The undersigned certifies that all violations on this report have been corrected and action taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Material Regulations insofar as they are applicable to motor carriers and drivers. This certification MUST BE SIGNED by the Motor Carrier and RETURNED WITHIN FIFTEEN (15) days by MAIL or e-mail at MCSUinfo@alea.gov or FAX to (334)-277-3285.

Further information can be found at: http://www.alea.gov/MC

** Failure to return this report with the required certification can result in penalties up to \$1000 per day for each day the violation continues, up to a total of \$10,000. Signature Of Motor Carrier X: _____ Title:__ __ Date:_

Report Prepared By:



Copy Received By:

Page 2 of 2



DRIVER/VEHICLE EXAMINATION REPORT

ALABAMA LAW ENFORCEMENT AGENCY	Report Number: ALJLJG011363			
MOTOR CARRIER SAFETY UNIT	Inspection Date: 06/22/2021			
PO BOX 1511	Start Time: 9:30:00 AMEnd Time: 3:00:00 PM			
MONTGOMERY, AL 36102-1511	Inspection Level: I - Full			
Phone: (334)242-4395 Fax: (334)277-3285	HM Inspection Type: None			
HANSEN & ADKINS AUTO TRANSPORT INC	Driver: State: AL			
3552 GREEN AVENUE	License#: State: AL			
LOS ALAMITOS, CA 90720	Date of Birth:			
Phone#: (562)430-4100 Fax#: USDOT#: 00568253 MC/MX#: 277621 State#: Content Content Content	CoDriver: License#: State: Date of Birth:			

Inspection Notes

QC ran on Company

Driver thru CDLIS

An inspection was performed at Till's wrecker yard off of US 31. Assisting was Cpl. Jerry Allen and Trooper Steven Kelley. Also, present was NTSB Investigator Brain Bragonier.

The rear of Unit #2 was raised with a Loader and placed on CMV brake drums. The brakes for axles #2,3,4 and 5 were uncaged by personnel from the wrecker service. A supply line was attached from a large wrecker to the rear supply tank with pressures between 90-100 psi to get the reading for the pushrods on axles #4 and 5. I, removed the cat-walk cover to allow access to the Brake Chambers of axles 2 and 3. Cpl. Allen along with Trooper Kelley connected each of the chambers on axles 2 and 3 separately to get the push-rod measurements. Cpl. Allen was marking, engaging the air valve, and reading the measurements. The supply pressure was observed/maintained by a handheld system controlled by Cpl. Allen.

The cover to the rear trailer/stinger electrical and air supply lines was removed to gain access to the electrical system to check the lights. It was determined that the electrical system cable was not long enough to connect into a donor truck to verify the operation of the lights. A jumper box/system was purchased and wired by Trooper Kelley that allowed for the testing of the lights.

Due to the severe nature of the crash, NTSB personnel were enroute to assist and provide resources. The post-crash inspection was delayed until Tuesday.

Video of on-board camera system shows operation of windshield wiper system at time of crash.

Special Studies No Special Study Data Recorded