Inspecti	Inspection Activities						
Test No.	Task Description	Condition/Steps	Results	Notes	Unexpected Result Comments/Changes made to equipment during inspection		
	outine Inspections						
	The purpose of Section 1 is to determine the condition of the machine for the safety of the test team as well as to create a baseline understanding of the pre-inspection condition. Any unexpected conditions or deficiencies will be documented and reviewed before further inspections are conducted.						
Any unexpecte	d conditions or deficiencies will b	be documented and reviewed be	etore further insp	ections are conducted.			
Other Questio	ns:						
		oystick functions ergonomically for	or the "normal" o	peration. That is, travel forward then tamp a tie (cycle). This is forward, then be	ackward, on the joystick, maybe thousands of times per day.		
Is it consistent	with other manufacturers? - Still u	undetermined.					
	(0 1= 0)						
1.1 - Daily Iten	s (Operations Manual 7-6) Check Air Pressure with Engine		x - Expected				
1.1.1	Running	Should maintain 120 PSI	□-Unexpected				
			x - Expected				
1.1.2	Check Hydraulic Oil Level.	3/4 full	□-Unexpected				
	Inspect Hoses and Fittings for	No Leaks, hoses with outer	. Funcated				
1.1.3	Leaks.	cover worn through or damaged are defective	x - Expected -Unexpected				
1.1.0		dumaged are derective	опекрессев				
		*Limited to workhead areas.					
		*Is evidence consistent with			o Right front workhead hyd hose had ruptured due to workhead being lowered while the machine was in		
	Note the location of hoses	the condition being non- causative, and not detrimental	x - Expected		motion. It was a #12 hose approximately 5' long. o Left lower step had been removed to extract the injured employee. Step was returned to service.		
1.1.3.1	installed post-accident	to further inspection?		Results from UP Testing Feb. 2-3, 2021	o Middle lower window broken during incident. No window replacement on hand.		
		*Limited to rear hydraulic					
		motor area *Is evidence consistent with			Rear travel motor had a leaking output shaft seal on 1/30 that required replacement WO# 40624494. o Mechanic also opened a WO# 40624514 to check hyd pressures and fix hyd leak with reference to the motor.		
		the condition being non-			o Mechanic replaced rear motor with in stock motor.		
	Note the location of hoses	causative, and not detrimental	x - Expected		o Replacement hyd motor started leaking ¾ mile after replacement. Mechanic didn't have another replacement		
1.1.3.2	removed pre-accident	to further inspection?	□-Unexpected	Results from UP Testing Feb. 2-3, 2021	so the motor chain was removed and the lever for the rear motor was disengaged and removed from service.		
		Oil to top of sight gauge, clear,					
1.1.4	Check Hydraulic Oil Return Filter Indicator when running	not dark, and not milky colored	x - Expected -Unexpected				
1.1.4	Filter <u>indicator</u> when running	colored	□-onexpected		The IVO. 1 filter mulcator had two dark lights. Normany either clean or bypass should be lit.		
					The no. 2 filter indicator had the "bypass" light lit, indicating a blocked filter or faulty sensor/light.		
					The No. 2 pressure differential sensor was replaced, with no effect.		
					The No. 2 pressure differential sensor was replaced, with no effect.		
					The high pressure filters themselves were removed and inspected. There was no blockage, and very little		
					filtered material. This is consitent with a fairly recent maintenance overhaul with oil changed, prior to the		
					accident.		
					The working group determines there is either (1) a problem in the light bank itself or (2) because the filters used		
					by UP are twice as restrictive as Nordco's original filters (UP = 5 micron, Nordco = 10 micron). This could		
					possibly cause a sensor error.		
	Check Hydraulic Oil Pressure		☐ - Expected		The mechanical working group determines a hydraulic oil analysis by a lab is necessary to determine oil quality		
1.1.5	Filter Indicator when running	harness to controllers,	x-Unexpected		and contaminiation levels.		
		operator control boxes,					
		footswitches, and main control					
		cabinet must have proper					
	Inspect Electrical	connection otherwise	. Funcated		Electrical cohinests and horsesses are in availant condition with no dist dehale coveries or other unauscated		
1.1.6	Connections/Harnesses for Tightness	problems in starting or stopping may occur.	x - Expected -Unexpected		Electrical cabinents and harnesses are in excelent condition with no dirt, debris, corrosion, or other unexpected wear noted.		
					At some point, the air tank drain pull tab was replaced with a more robust valve piped to the side of the		
	Drain Air Tanks, checking for excessive water or oil.		□ - Expected		machine. This device is capable of blowing water from the bottom of the air tank. It is non-standard, but		
1.1.7	CACCOSTAC WATER OF OIL		x-Unexpected	*From Monthly List "If Water in Air tanks, Check Air Dryer desiccant. "	effective.		
					As noted in the prior inspections, the brakes were out of adjustment. The standard is for the brakes to release		
	Inspect wheels, wheel nuts,				no more than 1/8th inch from the wheel when released. The average of the top and bottom gaps are measured.		
	brake shoes, and check gap				The group noted that all wheels had at least some portion of the brake/wheel gap larger than 1/8th inch.		
1	between brake shoes and		x - Expected		However, because prior brake testing had already been completed and the vehicle was known to stop safely in		
1.1.8	wheels.		⊔-Unexpected	Results from UP Testing Feb. 2-3, 2021	an 'as-is' condition, the protocol was continued without further inspection or work to the brake system.		

Test No.	Inspection Activities				
	Task Description	Condition/Steps	Results	Notes	Unexpected Result Comments/Changes made to equipment during inspection
	Check all brake chamber for		x - Expected		
1.1.9	caging bolts.		□-Unexpected		
	Check machine for cracks or		x - Expected	*An unexpected result may limit further testing	
1.1.10	other structural damage.		□-Unexpected	*See also, Section 3 regarding work head damage inspection	
	Check that all lights (brake,		· ·	, , , , , , , , , , , , , , , , , , , ,	
	marker, work, travel, strobes)		x - Expected		
1.1.11	are functioning.		□-Unexpected	*Unexpected results may require repair before continuing for employee safety.	
212122	Clean (Inspect for) debris/trash		x - Expected	Chespected results may require repair before continuing for employee surety.	
1.1.12	from machine.			*Unexpected results may require repair before continuing for employee safety.	
1.1.12	ITOITI IIIacillile.	Should be 1/2 to 3/4 in sight	x - Expected	Offexpected results may require repair before continuing for employee safety.	
1.1.13	Charles II I and I and I and I and I				
1.1.13	Check oil level in vibrators	glass	□-Unexpected		
					<u> </u>
1.2 - Weekly Ite	ems (Operations Manual 7-11)				
	Adjust and oil (Inspect)				
	Propulsion Chains, Adjusting				
	screw and yoke threads (Front		x - Expected		As noted in the prior inspection, the front travel chain was out of adjustment and riding on the vehicle frame.
1.2.1	& Rear)		□-Unexpected		The rear chain was removed prior to the accident. Neither condition prevents further testing.
			x - Expected		
1.2.2	Check Oil Level in Pump Drive		☐-Unexpected		
	Visually Inspect Hydraulic Tank		x - Expected		
1.2.3	Air Breather for COLOR change		□-Unexpected		
1.2.3					
1	Check tamping tool tightness		x - Expected		
1.2.4	and wear		□-Unexpected		
		Condemning limit is a pad <	x - Expected		
1.2.5	Check brake shoes for wear	3/8" thick	□-Unexpected		
	Grease Inspect Brake Lever		x - Expected		
1.2.6	Pivot		□-Unexpected		
	Remove & Inspect BOTH		□ - Expected □		
1.2.7	Suction Strainer Elements		Unexpected	*Skip. Tests in 1.5 instead. See Ops Manual page 86.	Not conducted.
1.3 - Monthly It	tems (Operations Manual 7-15)	I			
2.0	Ensure engine mounts, fuel	I			
	tank mounts and hydraulic tank		x - Expected		
4.2.4					
1.3.1	mounts are secure		□-Unexpected		
	Check Fan, Alternator, and		x - Expected		
1.3.2	Generator Belts		□-Unexpected		
	Check hydraulic hoses on		x - Expected		
1.3.3	machine for wear and leaks		□-Unexpected		
	Check hydraulic cylinders for		x - Expected		
1.3.4	leaks and/or damage		□-Unexpected		
	Check hydraulic valves for leaks		x - Expected		
1.3.5	and/or damage		☐-Unexpected		
	Inspect Hydraulic Tank Top Off		x - Expected		
1.3.6	for Damage/Cleanliness		□-Unexpected		
1.5.0	Tot Damage/Cleaniness		□-onexpected		Hydraulic system checks:
					o System Pumps
					☑ P1 rear pump 2750 PSI
					☐ P1 rear pump 2750 PSI ☐ P2 front pump 2669 PSI
					☐ P1 rear pump 2750 PSI ☐ P2 front pump 2669 PSI ☐ Pump system pressures are to be set @ 2700 PSI
					☐ P1 rear pump 2750 PSI ☐ P2 front pump 2669 PSI
					☐ P1 rear pump 2750 PSI ☐ P2 front pump 2669 PSI ☐ Pump system pressures are to be set @ 2700 PSI
	Check both implement oumo	Oil Temp 100F	x - Expected		☐ P1 rear pump 2750 PSI ☐ P2 front pump 2669 PSI ☐ Pump system pressures are to be set @ 2700 PSI O Travel motor cross over reliefs
1.3.7	Check both implement pump pressures.			Results from UP Testing Feb. 2-3, 2021	☐ P1 rear pump 2750 PSI ☐ P2 front pump 2669 PSI ☐ Pump system pressures are to be set @ 2700 PSI O Travel motor cross over reliefs ☐ Front 2910 PSI ☐ Reverse 2950 PSI
1.3.7	Check both implement pump pressures.	Oil Temp 100F Should be 2700 psi		Results from UP Testing Feb. 2-3, 2021	☐ P1 rear pump 2750 PSI ☐ P2 Front pump 2669 PSI ☐ Pump system pressures are to be set @ 2700 PSI ☐ ravel motor cross over reliefs ☐ Front 2910 PSI
	pressures.			Results from UP Testing Feb. 2-3, 2021	☐ P1 rear pump 2750 PSI ☐ P2 front pump 2669 PSI ☐ Pump system pressures are to be set @ 2700 PSI O Travel motor cross over reliefs ☐ Front 2910 PSI ☐ Reverse 2950 PSI
1.3.7 1.4 - Quarterly	pressures.			Results from UP Testing Feb. 2-3, 2021	☐ P1 rear pump 2750 PSI ☐ P2 Front pump 2669 PSI ☐ Pump system pressures are to be set @ 2700 PSI O Travel motor cross over reliefs ☐ Front 2910 PSI ☐ Reverse 2950 PSI ☐ Motor crossover reliefs are to be set @ 2900
	pressures.			Results from UP Testing Feb. 2-3, 2021	■ P1 rear pump 2750 PSI ■ P2 front pump 2669 PSI ■ Pump system pressures are to be set @ 2700 PSI o Travel motor cross over reliefs ■ Front 2910 PSI ■ Reverse 2950 PSI ■ Motor crossover reliefs are to be set @ 2900 As noted elsewhere, the high-pressure and return filters (4 total) were removed and inspected. The filters were
	pressures.	Should be 2700 psi	□-Unexpected	Results from UP Testing Feb. 2-3, 2021	□ P1 rear pump 2750 PSI □ P2 front pump 2669 PSI □ Pump system pressures are to be set @ 2700 PSI □ Pump system pressures are to be set @ 2700 PSI □ Travel motor cross over reliefs □ Front 2910 PSI □ Reverse 2950 PSI □ Motor crossover reliefs are to be set @ 2900 □ As noted elsewhere, the high-pressure and return filters (4 total) were removed and inspected. The filters were very clean, with very little debris noted. One return filter had a failed O-ring which was captured in the
	pressures.			Results from UP Testing Feb. 2-3, 2021	■ P1 rear pump 2750 PSI ■ P2 front pump 2669 PSI ■ Pump system pressures are to be set @ 2700 PSI o Travel motor cross over reliefs Front 2910 PSI ■ Reverse 2950 PSI ■ Motor crossover reliefs are to be set @ 2900 As noted elsewhere, the high-pressure and return filters (4 total) were removed and inspected. The filters were

Inspection Activities					
Test No.	Task Description	Condition/Steps	Results	Notes	Unexpected Result Comments/Changes made to equipment during inspection
1.4.2	Inspect hydraulic tank breathers and filler screens Check all wiring for wear and/or damage		x - Expected Unexpected x - Expected Unexpected	*Especially [Work/Travel], [Auto/Manual], Joystick and Foot switch wiring	The breather was inspected and found to be in like-new condition. This is consistent with a recent maintenance cycle being completed prior to the accident. All wiring (including the foot pedal) was in good operating condition with no wear or corosion.
1.4.5	Check switches and contacts for		x - Expected	respecially (work/fravel), (Auto/Manual), Joystick and Foot switch wiring	All wiring (including the root pedar) was in good operating condition with no wear or corosion.
1.4.4	tightness.			*Same as above	
	Check terminal strips for		x - Expected		
1.4.5	tightness		□-Unexpected		
1.5 - 6/12 Mth	Items				
1.5.1 1.5.2	Drain and inspect hydraulic- tank Inspect both suction strainer- elements	Including Magnetic separator	Unexpected Unexpected Unexpected Unexpected Unexpected	*AFTER Dynamic testing, filter the oil that is removed.	These tests were determined to be unnecessary by the group. First, the hydraulic oil filters were inspected for contamination or evidence of debris. None was found. Second, the oil itself was sampled at three different tank locations and sent to a lab for analysis. (Results pending) and Finally, a hydraulic schematic review was conducted. During this review it was determined that a "runaway" due to hydraulic causes could only occur if debris was lodged in three seperate valves simultaneously. The oil condition is not consistent with a failure like that. Finally, if the hydraulic system were to experience runaway propultion, the brake system would also have to fail to enduce movement. It was demonstrated in subsequent testing that the brake system is in working order and capable of holding the machine in place against tractive effort.
	ormal Operation				
				ns known, or assumed, to have existed at the time of the accident.	
Any unexpecte	d conditions or deficiencies will b	e documented and reviewed b	erore turtner insp	pections are conducted.	
	To be completed as described				
2.1 Start up/	in Ops. Manual Section 6 (pages		x - Expected		
Warm up	6-1 to 6-3)		□-Unexpected		The battery condition required a portable jump-start device
	Done on 0.73% uphill grade,		x - Expected		
2.2 Stop Tests	with rear motor cut out	Tour Connections 1	□-Unexpected	Results from UP Testing Feb. 2-3, 2021	
	Mark Made Ten Speed	Top Speed: 9mph	- Funcated		
2.2.3	Work Mode - Top Speed,	Emergency Stop Button: Stopped at 23'	x - Expected	Results from UP Testing Feb. 2-3, 2021	
2.2.3	emergency	Top Speed: 9mph	⊔-unexpected	Results from OP resting Feb. 2-3, 2021	
	Work Mode - Top Speed,	Release joystick: Stopped at	x - Expected		
2.2.4	Release Joystick to Stop			Results from UP Testing Feb. 2-3, 2021	
	, ,	1		1	

Inspection Activities						
Test No.	Task Description	Condition/Steps	Results	Notes	Unexpected Result Comments/Changes made to equipment during inspection	
	i i	· ·			Machine travel speeds w/ stop	
					☑ Low travel 14mph - 55'	
2.2.5 - Travel			x - Expected		The machine reached top speed in 1/8th mile, traveled additional 1/8th mile before brake application	
Top Speeds	Low Travel - 14mph	Over what distance?	□-Unexpected	Results from UP Testing Feb. 2-3, 2021		
					Machine travel speeds w/ stop	
2.2.6 - Travel			x - Expected		☐ High travel 17mph - 17′- 59′	
Top Speeds	High Travel - 17mph	Over what distance?	□-Unexpected	Results from UP Testing Feb. 2-3, 2021	The machine reached top speed in 1/8th mile, traveled additional 1/8th mile before brake application	
					Time/Distance traveled	
					☐ Tie 1 – Tie 5 - 3:53 seconds	
2.2.7 - Feb. 2			x - Expected		☐ Tie 5 – Impact (start at tie 1) - 9:33 seconds	
"Reenactment"			□-Unexpected	Results from UP Testing Feb. 2-3, 2021	☑ Tie 1 – Tie 5 applying E-stop - 11'	
	a. Machine is stopped at a tie to					
	be worked					
	b. Operator tamps the tie while					
	in [Work] and [Manual] mode	a. What maximum speed does				
	using the joystick	the machine reach?				
	c. Operator uses the joystick to					
	"skip" 5 ties (about 10-feet)	traveled between 'Joystick				
	d. Operator attempts to stop by					
	releasing the joystick and	c. Do all brakes function as			a. The speed was not recorded	
	"sliding" into the sixth tie.	expected?			b. Approximatley 2.5 ties (~5')	
2.3 - Mar. 24		d. Is the stopping distance	x - Expected		c. Yes	
"Reenactment"	e. Reverse and repeat 5 times	consistent?	□-Unexpected		d. Yes	
	a. Machine is stopped as if					
	tamping a tie had been					
	completed					
	b. Travel forward until the					
	maximium speed from 2.2 is					
	reached					
	c. Press the Emergency Stop					
2.4 - Emergency						
Stop Button	d. record the stop distance			Discussion to accept UP stop testing (2.2.7) in place of this test		
	vestigative Scenarios					
				ditions may have contributed to an unintended acceleration, or failure to dece	elerate?	
Any unexpected	d conditions or deficiencies will b	e documented and reviewed b	efore further ins	pections are conducted.		
	I	I		1		
	a. While stopped operator					
	should demonstrate the					
	operation of the horn					
	b. Record observations about					
	mechanical/tactile operaton					
	from the operator (Is the cord					
	obstructed, hard to reach,					
	etc.?)					
	c. Record qualitative		Forestand		The beautiful to the control of the	
	observations about horn sound		x - Expected		The horn operates normally and at an expected volume. The cable is not difficult to reach from the operator's	
3.1 - Horn Test	(no decible requirement exists)		□-Unexpected		normal position.	
	tamping a tie had been					
	completed					
	b. Travel forward until the					
	maximium speed from Test No.					
	· '					
	2.2 is reached					
	c. Press the Emergency Stop					
2.2	mushroom switch.					
	d. record the stop distance and			Discussion to account UD atom to the 2.2.2.7) in allow of this to		
Stop Button	time to full stop	l .		Discussion to accept UP stop testing (2.2.7) in place of this test		

Inspection	Inspection Activities					
Test No.	Task Description	Condition/Steps	Results	Notes	Unexpected Result Comments/Changes made to equipment during inspection	
	(*) Review previously					
3.3 - Baseline	conducted UP tests, otherwise,					
	construct test plan for stop-					
recorded speed	distance testing at 3, 5, 10 mph			Discussion to accept UP stop testing (2.2.7) in place of this test		
	a. Situate cab in normal	Operators have stated that the				
	operating condition, including	[work/travel] switch may be				
	[Work] Mode and [Manual]	inadvertantly toggled when				
	Mode.	reaching over-shoulder for				
	b. Travel forward at ~3mph with joystick	another switch or item. They describe the change in				
	c. Depress foot switch and hold					
	it down (to simulate debris or	especially engine speed noise				
	an electrical fault)	and a slowing of the machine.				
	c1. Release Joystick. Observe	This test is intended to give				
3.4 - Dynamic Test	vehicle behavior and then stop safely	investigators insight with this machine.	x - Expected -Unexpected		With the machine set to [Work] and [Manual], the foot pedal is disabled by design as explained elsewhere.	
rest		machine.	<u> </u>		with the machine set to [work] and [wandar], the root pedans disabled by design as explained eisewhere.	
	a. Situate cab in normal					
	operating condition, including [Work] Mode and [Manual]					
	Mode.					
	b. Travel forward at ~3mph				There are no noticable changes in 'jerk', or engine speed, when this is done. The vehicle continues to travel	
	with joystick				normally.	
	c. Toggle from [Work] to				The Charles of the The Lade of the Charles of the C	
3 4 2 - Dynamic	[Travel] d. Record speed changes,		x - Expected		The vibrators do stop. The hydraulic pressure holding the work heads up is reduced. The work heads were observed to not drop a noticable ammount in 1-minute but after several minutes they do begin to reach tie	
Test 2	engine noise changes, and 'jerk'		□-Unexpected		height and need to be reset.	
	It has been stated that the foot		i i			
	switch does not operate as intended on this machine. Can					
	the anomoly be gantified and					
	can a determination be made as				[UP 2/2/21] Foot pedal for workhead cycle was inoperative – bad switch in the pedal	
3.5 - Foot	to why the foot switch does not		x - Expected			
switch	work?		□-Unexpected		The foot pedal works as designed as described above	
	Two drive motors on the rear					
	axle failed in rapid succession.					
	Can the investigative team					
	determine any reason, other than low quality					
	remanufactured motors, for				The group discussed the possibilities. It was agreed that the motors require frequent maintenance, are not as	
3.6 - Motor	these failures. Could these				reliable as Nordco would like, and fail with some regularity due to no fault of the rest of the machine. No	
failure	reasons be causative? a. Travel 5 Tie lengths and use				causitive link to the accident could be established for further investigation.	
	the service brake.					
	B. Travel 5 tie lengths and use					
Other	the parking brake				a. The machine comes to a complete stop within 5'	
observational	c. Travel 5 tie lengths and use		x - Expected		b. The machine comes to a complete stop within 5'	
tests	the emergency brake Starting in work mode, push		□-Unexpected		c. The machine comes to a complete stop, and the engine shuts down, within 2.5'	
observational	foot pedal and hold it, then		x - Expected			
tests	switch to travel mode.		□-Unexpected		The machine doesn't do anything in work mode, but travels as soon as travel is selected	
Other	Attempt to travel with		. Funanted		a Ne mayamank	
observational tests	(a) Service brake applied (b) Parking brake applied		x - Expected -Unexpected		a. No movement b. No movement	
Other	With machine in work mode		onexpected		o. no movement	
observational	and auto mode, press foot					
tests	pedal		"As designed"		Machine completes one tamping cylce and travels forward so long as the pedal is held down.	

Inspection Activities							
Test No.	Task Description	Condition/Steps	Results	Notes	Unexpected Result Comments/Changes made to equipment during inspection		
	With machine in work mode						
	and auto mode, press foot						
Other	pedal and joystick						
observational	simultaneously, release joystick						
tests	but not foot pedal		"As designed"		Machine completes one tamping cylce and travels forward so long as foot pedal is held down.		
Section 4 - C	Section 4 - Component Removal						
The purpose of this section is to remove, inspect, and retain and components needed for further study.							
Any unexpected conditions or deficiencies will be documented and reviewed before further inspections are conducted.							
*Ensure all sta	tic/dynamic tests are complete						
	Remove and inspect hydraulic	Signs of wear, damage, debris,					
4.1	propel valve (front motor)	etc.?					
	Remove and inspect joystick	Signs of wear, damage, debris,					
4.2	control	etc.?					
		Signs of wear, damage, debris,					
4.3	Remove and inspect foot pedal	etc.?					
	Remove and inspect switches	What diagnostics might be			The mechanical working group determines that external observations and oil analysis are sufficient to elminate		
4.4	[Work/Travel], [Auto/Manual]	needed?			these tests from the protocol.		
					PLC controller was observed and noted to be in normal working order. The delay between joystick release and		
	Microprocessor controls to be		x - Expected		brake application was 0.2 seconds, as set from the factory. The service brake application valve was noted to be		
4.5	reviewed by Nordco, team		□-Unexpected		in working order.		

Section 5 - Wrap Up