


# PennDOT Email to NTSB April 14, 2023

Pittsburgh, PA

**HWY22MH003** 

(4 pages)



[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Good morning Steve,

The 2007 edition of Publication 100A only had the three examples shown below for a PO:

## Priority Code Rating of 0:

- Severe scour or undermined substructure foundation
- Fractured primary member due to fatigue or vehicle damage
- Missing load posting or vertical clearance signs (includes advance signs)

In 2009, we introduced the FCM maintenance item (see below). In general, the 2007 edition had very basic examples overall and the 2009 Edition is when we went to the current format with very detailed examples.

PENNDOT Pub #100A July 2009

TIMBER: 62-A744601 - Stringer (Rep / Repl)
STEEL: 25-A744602 - Stringer (Rep / Repl)
50-B744602 - Floorbeam (Pen / Pen)

50-B744602 - Floorbeam (Rep/Repl) 49-C744602 - Girder (Repair)

REINF.CONC. /

PRESTRESSED CONC.: 42-A744603 - Stringer (Rep/Repl)

TRUSS: 36-A744701 - Members (Strengthen/Rep/Repl)

82-B744701 - Portal (Modify)

#### Fracture Critical Members (FCM):

a. Impact Damage: Impact damage that results in gouging or tearing of FCM components in tension. Since gouging/tearing are considered locations of stress risers and crack initiation points in a tension member, unexpected fracture could result.

- b. Direct Stress Cracks: Direct stress cracks are those in the base metal or weld materials that are perpendicular to the tensile stress carried by the member. <u>Use Priority code 1 if</u> <u>supported by a structural evaluation</u>. FCM examples include, but are not limited to:
  - Truss members in direct tension or reversible tension/compression including welded or riveted members, eyebars and loop rods
  - Tension zones of gusset plates connecting FCMs
  - Tension component or tension zone of a girder, cross girder, steel pier cap or floorbeam
- Severe Corrosion: Holes due to corrosion in FCM girder flanges, webs or in truss members.
- d. Cracks Parallel to Stress in FCMs: Initial cracking found in the tension zone of FCMs that is oriented <u>parallel</u> to the primary stress carried by the member. This type of cracking may be the result of out-of-plane distortion, bi-axial restraint or poor weld details, and could suddenly change direction under service conditions without mitigation, and become more serious.

If you have any other questions, please let me know.

Thanks, Rich

### Richard W. Runyen, P.E. | Director

PA Department of Transportation | Bureau of Bridge 400 North Street, 7<sup>th</sup> Floor | Harrisburg, PA 17120 Office: | Cell:

Office: www.penndot.gov

From: Prouty Steven

**Sent:** Thursday, April 13, 2023 7:34 AM **To:** Runyen, Richard W

Cc: Collins Dennis Buck, Jonathan (FHWA)

Subject: [External] Question related to PennDOT Publication 100A

**ATTENTION:** This email message is from an external sender. Do not open links or attachments from unknown senders. To report suspicious email, use the <u>Report Phishing button in Outlook</u>.

Hi Rich -

I hope you are doing well.

I have a couple of questions about PennDOT's Publication 100A that I am hoping you can help me with. In the 2019 version of Pub. 100A, a priority code - 0 example for FCMs is provided on page 3-333 (item 9 c - Severe Corrosion in Fracture Critical Members) indicating that: "Holes due to corrosion in FCM girder flanges, webs or in truss members" would be an example of a finding that should be a priority code - 0.

## My questions are:

- Which previous versions, if any, of Publication 100A included 'holes due to corrosion in FCM girder flanges webs, or in truss members' as an example of a priority code - 0?
- What was the date on which the earliest version of Publication 100A that contained 'holes due to corrosion in FCM girder flanges, webs or in truss members' as an example of a priority code - 0, went into effect? If the effective date is not available, knowing at least the year should be sufficient.

Thanks, Steve



Steve Prouty, PE Senior Investigator **Highway & Structural Engineering** 

**National Transportation Safety Board** Office of Highway Safety 490 L'Enfant Plaza SW Washington, D.C. 20594



www.ntsb.gov





CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.