


The Standard ENGINE LOG

06/28/2022 14:18

Engine Record General Information

Manufacturer BRAMO (SIEMEN.	S) Model SH14A4	
Manufacturer 2,8258	Type Certificate	/
Manufacturer 28258 Serial 28258 This engine is currently installed in air	craft: Bucker 133C, S	N: 3+
1/1940 H		
Ostono Fuel 100 LL	Oil Grade Summer Mineral 100	Firing Order 1357246
Magneto Time 300 before 1 DC	Point Setting	Firmy Order 2.
Spark Plug Gap 0, 3 mm	ul at 600 hours	
Manufacturer's Recommended Overhau	ul at nours	



YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entres 29 N.
engine oil tested spa Inspected	d valvetrain nce manual and service rk plugs. Dr	ed with 5 rained flo	quarts aer pat bowls. maintena	and jewel amber oil. Reset all valve clearances to spec pecular coshell 100. No foreign particulates found. Cleaned gaped Engine test run no leaks noted. Reinstalled cowelings.
David Woo	sley	AF		
				5
1-16y 2	0.2			ENGINE LUBED VALVE CLEAR ANCE CHECKED . DOS AMBEY, DIL ANDAS DO WITH 578
				CLEUT ance CHECKED, DOS
				AMBER, DIL andAS 100 WITH 578
2374 2	3.0 esT			ENGINE EUpedwITH AMBER DILANG
				areognous 100 valve cherrance
				c 40c x 0d .008

14:22

Compression check 1. 70 2. 70 3. 65 4. 64 5. 70 6. 73 7. 71/80. Cleaned engine removed valve springs and cleaned old oil from stems ,rockers , pushrods and valve tapets. Reinstalled valve train. Valve clearance checks and lubrication required before use. serviced engine with 5 Qts aeroshell 100W+. checked magneto timing. Drained float bowls. Removed 7 spark plugs and

aeroshell 100W+. checked magneto timing. Drained float bowls. Removed 7 spark plags are installed discant plugs. I certify I have inspected this engine in accordance with the maintenance manual and scope and detail of AC 43 appendix "d" and was determined to be incompared to be

David Woosley

-		
5-24-21	25.2	GET VALVE CLEONAMICS DUE-24
		LUBED VALUE Train, SET VALUE
		110-11 Nes Removed discari 16069
		Reministrated Donoved all Konaving Plucy
		1100 ved balled and legita 1200
		ReingTalled & Park PLUGG. ENGINE
		OKFOV OPERATION.
		AI

VEAR INCOME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries) to
12-1521 27.2 055			Removed 7 SPATK PLUGS, INSTAlled LA discant PLUGS. Theaned valve Train, was Hed 2 Noive with son Chequed Aircraft.

N1940H

5-25-2022

ACTT 1475.8

SMOH 27.2

Compression checked 1. 71 2. 71 3. 72 4. 66 5. 74 6. 68 7. 70/80. Valve clearance checks and lubrication required before use. serviced engine with 5 Qts aeroshell 100W+. checked magneto timing. Drained float bowls. Checked throttle throw full to idle ops check ok. Cleaned engine. I certify I have inspected this engine in accordance with the maintenance manual and scope and detail of AC 43 appendix "d" and was determined to be in a safe condition for operation.

David Woostey

6-29-21 27,2

LUPO & Value Train, set value

Cheavarces, Chear 06/28/2022 et 4:23 che

Reingralled Plubs, ENGIAL Ready Following

TEAR 0ATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
coxi				OPEIATION.
				06/28/2022