DATE RE TAI	CH FLIC	DAYS TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
12/20			Tustaled New Battery Concorde RGQ4-16

Airframe Log Entry


N143JB

Cessna 337 S/N 337-0102

January 20th, 2021

TTAF 3896.4 HOBBS 3791.1

- Installed on both engines, customer supplied E-Z Heat, Inc aircraft engine heater model 440 IAW manufacturer's installation instructions. Cleaned area, removed paint and adhered heating pads to oil sump. Routed power cables and secured with MS21919-WH high temperature clamps. OPS check normal.
- Defueled left auxiliary fuel tank, removed and replaced fuel drain valve with FAA-PMA valve p/n F391-72. Enlarged cover opening for easier access to both aux tanks. Re-fueled aux tanks, OPS check normal, no leaks detected.
- Serviced nose strut with dry nitrogen to 35 PSI, after service and compression and release of nose, strut extension now at over 4 inches.
- Troubleshot inop CHT gage for rear engine. Removed gauges to inspect. Found bad probe and open connection on wires. Upon reassembly we found a second pair of wires and another gasket washer type CHT thermocouple sensor. Tested sensor to be bad. Replaced with JPI CHT bayonet kit p/n 1260. Checked operation and found normal.
- Above work performed IAW Cessna 337 service manual and manufacturer's installation instructions.



Alterations Description of Inspections, Tests, Repairs and Alterations TODAYS TOTAL RECORDING DATE Entries must be endorsed with Name, Rating and Certificate Number of Number of FLIGHT TIME IN TACH cific entries.) Technician or Repair Facility. (See back pages for other specific entries.) SERVICE TIME Airframe Log Entry N143JB Cessna 337 S/N 337-0102 March 18^{th,} 2021 HOBBS 3796.3 TTAF 3901.6 Removed forward engine's gasket style CHT probe on #1 cylinder and installed JPI bayonet style probe p/n 1260. Serviced hydraulic reservoir with 5606 hydraulic fluid. Above work performed IAW Cessna 337 service manual.

DATE	Airframe Log Entry	N143JB
19		il 16 ^{th,} 2021
	 Hydraulic fluid leaking near nose gear. Brought aircraft to hangar, removed cowls, seats and carpet. Clear system of leaking hydraulic fluid to troubleshoot. Found leak at hydraulic power pack installation at fire filter assembly. Removed connection, cleaned and inspected, replaced (1) o-ring p/n MS28778-4. Placed jacks and performed normal gear swing operations using external hydraulic testing unit. Found minor leaks at unit actuator assy, at forward of barrel. Cleaned area, no significant leak at this time. Aircraft landing gear declosed without defects. Serviced hydraulic reservoir with 5606 fluid. Reinstalled all removed items. During inspection, found excessive movement on left wheel assembly. Removed wheel assembly, clean inspected, found wear on cone bearing and cracks on outer wheel half. Replaced with (customer supplied approved Timken bearing p/n 13889-20629 and (customer supplied) serviceable outer wheel half p/n 10 Installed with new ring-grease seal p/n 153-00300 and molded grease seal p/n 154-12400. Reinstalled with serviced tire to specs, no defects noted. Above work performed IAW Cessna 337 Skymaster series service manual. 	wall's pressure d aircraft on ak at nose gear oors opened and ed) new FAA 62-02724
	GERDES AVIATION SERVICES FAA Approved Repair Station G3RR399J IFR CERT. TESTS - The Altimeter / Static and Transponder Systems have been tested and inspected per 14 CFR 91.411 & 91.413. The systems were found to comply with 14 CFR 43, Appendix E & F to an altitude of 25,000 feet. N Number 14318 Tach/Fobbs 3818.8 ACTT — Date 11-15-2021 Authorized Signature: P.O. Box 2872 Fullerton CA 92833 Office (714) 525-7545	

43JB 5^{th,} 2021

aircraft and s pressure craft on t nose gear opened and

ew FAA 2724. lassy,


DATE 19	RECORDING TACH TIME	FLIGHT		Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
MINICH MAN	MINION ON	Willy Com	THE STATE OF THE S	PON L
WAS TO THE STATE OF THE STATE O	2010		1770 1770 1777	DATE C/2/2/ TACES 27022
CHANGE OF THE STATE OF THE STAT	11/11/2016 11/11/2016 11/11/2016 11/11/2016	6 (17) 6 (17) 6 (17)	1/2/N/G	THIS MACCORDANCE WITH A HUMANIA INSPECTED IN ACCORDANCE WITH A HUMANIA INSPECTION AND FOLDER TO DESCRIPTION OF THE PROPERTY OF
	SCA ZA			AIRWORTHY CONDITION W.O. LATERAL SIGNED A/R IA
10000000000000000000000000000000000000	1200 A			80 RC 20201
10 / C/2	04/	(XX/	2 0X4x20A	JUNCE CAMP DE POLY STEREN


N143JB Airframe Log Entry ations January 22^{nd,} 2022 Cessna 337 S/N 337-0102 TTAF 3930.6 HOBBS 3825.3 Serviced both brakes with 5606 hydraulic fluid to specifications, no defects noted. Replaced ELT battery p/n BP-1010, I certify that the ELT has been inspected IAW the requirements of FAR 91.207 (d) and found to be in satisfactory condition. Battery replacement due October 2023. Above work performed IAW Cessna 337 Skymaster series service manual. Fred Sholy A&P Manual Committee of the Parish The same of the sa


© 1992 ASA

19_

Rear Engine Log Entry DATE N143JB Continental IO-360-D S/N R55107-5-D 19___ TSMOH 1060.5 TSN 2086.0 HOBBS 3801.1 June 15th, 2021 Performed compression test: #1: 74/80 #2: 72/80 #3: 75/80 #4: 60/80 #5: 74/80 #6: 73/80 Drained oil and removed oil screen, cleaned and inspected. Reinstalled and serviced with (7) qts of Aeroshell W100 engine oil, replaced oil screen crush washers. Ran engine and leak checked, no defects noted. Above work performed IAW Cessna 337 service manual and Continental standard practice maintenance manual Michael Fuller A&P







Rear Propeller Log Entry McCauley D2AF34C6-N0 S/N 753582 HOBBS 3801.1

N143JB

June 25th, 2021

- Cleaned blades for inspection, filed leading edge, sanded back of blades and painting with black propeller paint.
- Above work performed IAW McCauley propeller systems owner operator information manual MPC26-05.

Michael Fuller A&P

Airframe Log Entry

N143JB

Cessna 337 S/N 337-0102 TTAF 3930.7 HOBBS 3825.4 February 2^{nd,} 2022

 Placed forward section on jacks in order to remove nose gear assy. Removed nose gear strut assy, cleaned and inspected. Resealed strut with McFarlane Aviation Product's FAA-PMA Cessna nose strut seal kit p/n MCSK172-1F. Reinstalled nose strut assy, serviced with 5606 hydraulic fluid and dry nitrogen IAW with service manual section 2 servicing instructions

2. Above work performed IAW Cessna 337 Skymaster series service manual.

Michael Fuller A&P

Airframe Log Entry

N143JB

Cessna 337 S/N 337-0102 TTAF 3930.6 HOBBS 3825.3 January 22^{nd,} 2022

- Serviced both brakes with 5506 hydraulic fluid to specifications, no defects noted.

 Replaced ELT battery p/n BP-1010, I certify that the ELT has been inspected IAW the requirements of FAR 91.207 (d) and found to be in satisfactory condition. Battery replacement due October 2023.
- 3. Above work performed IAW Cessna 337 Skymaster series service manual.

Fred Sholy A&P

Front Engine Log Entry

N143JB

Continental IO-360-C S/N 501005-5-C TSMOH 1125.1 TSN 2150.6 HOBBS 3801.1

June 25th, 2021

- 1. Performed compression test: #1: 74/80 #2: 75/80 #3: 72/80 #4: 76/80 #5: 73/80 #6: 75/80
- Drained oil and removed oil screen, cleaned and inspected. Reinstalled and serviced with (7) qts of Aeroshell W100
 engine oil, replaced oil screen crush washers. Ran engine and leak checked, no defects noted.
- Above work performed IAW Cessna 337 service manual and Continental standard practice maintenance manual publication M-0.

Michael Fuller A&P

Rear Engine Log Entry

N143JB

Continental IO-360-D S/N R55107-5-D TSMOH 1060.5 TSN 2086.0 HOBBS 3801.1

June 15th, 2021

- 1. Performed compression test: #1: 74/80 #2: 72/80 #3: 75/80 #4: 60/80 #5: 74/80 #6: 73/80
- Drained oil and removed oil screen, cleaned and inspected. Reinstalled and serviced with (7) qts of Aeroshell W100
 engine oil, replaced oil screen crush washers. Ran engine and leak checked, no defects noted.
- Above work performed IAW Cessna 337 service manual and Continental standard practice maintenance manual publication M-0.

Michael Fuller A&P

Front Propeller Log Entry

N143JB

McCauley D2AF34C306 S/N 805445 HOBBS 3801.1

June 25th, 2021

- 1. Cleaned blades for inspection, filed leading edge, sanded back of blades and painting with black propeller paint.
- 2. Above work performed IAW McCauley propeller systems owner operator information manual MPC26-05.

Michael Fuller A&P