





# ENGINE EXAMINATION REPORT

<b>ENGINE MODEL</b>	O-300-D (6B)
<b>ENGINE SERIAL NUMBER</b>	27160-D-2-D
<b>AIRCRAFT MAKE &amp; MODEL</b>	1958 Cessna 172
<b>AIRCRAFT SERIAL NUMBER</b>	36320
<b>AIRCRAFT REGISTRATION</b>	N8620B
<b>FILE NUMBER</b>	18-370

<b>NAME</b>	<b>SIGNATURE</b>	<b>DATE</b>
Phillip Grice		03-02-2020
Mike Council		2-18-2020

**ENGINE EXAMINATION REPORT**

<b>FILE NUMBER:</b>	18-370	<b>ENGINE S/N:</b>	27160-D-2-D	<b>PAGE 2 of 39</b>
---------------------	--------	--------------------	-------------	---------------------

**GENERAL INFORMATION**


EXAMINATION		ACCIDENT DATA	
<b>DATE</b>	6-17-2019	<b>NTSB ACCIDENT #</b>	CEN19FA099
<b>FACILITY</b>	Continental Aerospace Technologies-Analytical	<b>NTSB INVESTIGATOR</b>	Michael Hodges, IIC Central Region
<b>ADDRESS</b>	2039 South Broad Street Mobile, Alabama	<b>FAA INVESTIGATOR</b>	NA
		<b>ACCIDENT DATE</b>	3-14-2019
		<b>ACCIDENT LOCATION</b>	Lakeway, TX

**ENGINE INFORMATION**

<b>ENGINE POSITION</b>	Single
<b>TOTAL TIME</b>	4630.5 calculated
<b>TIME SOH</b>	153.3 hours calculated
<b>TYPE &amp; TIME SLI</b>	99.3 hours calculated since last 100-hour inspection dated 11-7-2018
<b>BUILD DATE</b>	3-26-1962 (shipped to Cessna Aircraft) according to CMI Serial Data
<b>IN SERVICE DATE</b>	Original undetermined

**Significant logbook information:**

According to the engine logbooks, the accident engine was overhauled to factory new limits in the field 4-21-2016 using new Superior Air Parts cylinders. See copy of logbook excerpt below:



**Report Summary:**

Search Code(s): 15-12-68

The engine was disassembled and inspected under the supervision of the NTSB IIC. This inspection did not reveal any pre-impact anomalies that would have prevented its ability to produce rated horsepower.

**Disposition of engine following exam:** The engine was released by the NTSB IIC and returned to Air Salvage of Dallas. See shipper # AD01162 dated 6-19-2019.

**ENGINE EXAMINATION REPORT****FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 3 of 39****INSPECTION WITNESSES**

<b>NAME</b>	Phillip Grice	<b>NAME</b>	Lisa Jersild
<b>ADDRESS</b>	Mobile, Alabama	<b>ADDRESS</b>	Mobile, Alabama
<b>ORGANIZATION</b>	Continental Aerospace Technologies	<b>ORGANIZATION</b>	Continental Aerospace Technologies
<b>PHONE</b>	██████████	<b>PHONE</b>	██████████
<b>NAME</b>	Randy Bryant	<b>NAME</b>	Michael Hodges, IIC
<b>ADDRESS</b>	Mobile, Alabama	<b>ADDRESS</b>	Central Region
<b>ORGANIZATION</b>	Continental Aerospace Technologies	<b>ORGANIZATION</b>	NTSB
<b>PHONE</b>	██████████	<b>PHONE</b>	██████████
<b>NAME</b>	Peter Basile	<b>NAME</b>	NA
<b>ADDRESS</b>	Wichita, KS	<b>ADDRESS</b>	
<b>ORGANIZATION</b>	Textron Aviation	<b>ORGANIZATION</b>	
<b>PHONE</b>	██████████	<b>PHONE</b>	

ASI-Mike Council did not attend the engine tear down examination.

## ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 4 of 39

### EXTERNAL INSPECTION OF ENGINE

The accident engine was received in a Continental Aerospace Technologies engine crate. The engine crate was opened in the presence of the NTSB IIC and the engine was removed and placed on an examination stand. A data plate attached to the crankcase identified the engine as a Continental Motors model O-300-D (6B) engine, serial number 27160-D-2-D.

Engine mounts were broken. The oil sump was impact damaged and the left forward/side separated. Cylinder # 2 intake and exhaust push rods and push rod tubes were impact damaged.

Exhaust mufflers, tailpipes and risers were impact damaged.

Left induction manifold was impact damaged.

Ignition harness leads were cut and pinched.

Carburetor was impact damaged and shipped loose.

This engine has been visually inspected previously at the accident site. The following parts had been removed at the previous examination and not reinstalled:

Cylinder rocker arm covers

Left and right magnetos

Spin-on engine oil filter

Engine driven generator

# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 5 of 39



**ENGINE EXAMINATION REPORT**


**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 6 of 39**



## ENGINE EXAMINATION REPORT

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 7 of 39**

### AIRFRAME COMPONENTS RETURNED WITH ENGINE

Cooling baffles

Engine driven generator

Right muffler assembly (Left muffler not received)

Instrument air pump

Aftermarket oil filter adapters and hoses

Oil Cooler – NOTE:

The current Continental Aerospace Technologies Illustrated Parts Catalog for this engine does not indicate that an oil cooler was included during the manufacturing of engine model O-300-D (6B) engines.

# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 8 of 39

## ENGINE TEARDOWN AND COMPONENT EXAMINATION

### EXHAUST SYSTEM

Condition:

The exhaust system components were impact damaged. The muffler/heat exchanger was impact damaged. Left muffler assembly not shipped with engine.



### INDUCTION SYSTEM

Condition:

The left induction manifold was impact separated and not returned with the engine. The right induction manifold was intact except damage to the mounting flange.





## ENGINE EXAMINATION REPORT


<b>FILE NUMBER:</b>	18-370	<b>ENGINE S/N:</b>	27160-D-2-D	<b>PAGE 9 of 39</b>
---------------------	--------	--------------------	-------------	---------------------

### IGNITION SYSTEM

<b>MAGNETO-TO-ENGINE TIMING</b>	Specification: Rt. 26° BTDC Lt. 28°	L/H Magneto: NA	R/H Magneto: NA
Ignition timing could not be determined. The magnetos had been removed during the recovery examination.			
<b>IGNITION HARNESS</b>	Manufacturer: Slick-Unison	P/N: M-2930 (L) M-2931 (R)	S/N: Undetermined
Condition:	The ignition harness was impact damaged		



<b>SPARK PLUGS</b>	Manufacturer: Tempest	P/N: UREM40E
Condition:	When compared to a Champion Spark Plug "Check-A-Plug" chart, the sparkplugs appear to be in <i>worn out normal</i> condition.	



## ENGINE EXAMINATION REPORT

<b>FILE NUMBER:</b>	18-370	<b>ENGINE S/N:</b>	27160-D-2-D	<b>PAGE 10 of 39</b>
---------------------	--------	--------------------	-------------	----------------------

<b>LEFT MAGNETO</b>	Manufacturer: Slick-Unison Industries	M/N: 6364	S/N: 07090201
Condition:	The magneto had been removed during the initial recovery examination. The magneto and tested by manually rotating the drive and noting spark at all six ignition leads. The magneto was shipped loose in the shipping container. The magneto was bench tested and functioned normally.		



<b>RIGHT MAGNETO</b>	Manufacturer: Slick-Unison Industries	M/N: 6364	S/N: 07090204
Condition:	The magneto had been removed during the initial recovery examination. The magneto and tested by manually rotating the drive and noting spark at four of the six ignition leads. The magneto was shipped loose in the shipping container. The magneto was bench tested and functioned normally.		



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 11 of 39

## FUEL SYSTEM

### FUEL PUMP

Manufacturer: NA

P/N: NA

S/N: NA

Condition:

The engine was not equipped with an engine driven fuel pump in this application.

### CARBURETOR

Manufacturer: Precision

P/N: 10-4439-1

S/N: FV2192

Condition:

The airframe airbox and carburetor were impact separated at impact. The carburetor was destroyed by impact forces. Metal floats exhibited "hydraulic" damage consistent with fuel in the carburetor bowl at impact.



ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 12 of 39



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 13 of 39

## LUBRICATION SYSTEM

### OIL SUMP

Condition:

The oil sump was impact damaged. The left-forward section impact separated.



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 14 of 39**

**OIL PICK-UP  
SCREEN**

**Condition:** The oil pick-up screen was uncontaminated.



**OIL PUMP**

**Condition:** The oil pump rotated normally with no binding or internal damage due to hard particle passage.



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 15 of 39

## OIL FILTER

Manufacturer: Tempest

P/N: AA48108-2

Condition:

The spin-on oil filter had been previously removed at the recovery inspection and cut open for inspection. There was no metal contamination noted. Four photos below were taken at the recovery examination.



## ENGINE EXAMINATION REPORT

<b>FILE NUMBER:</b>	18-370	<b>ENGINE S/N:</b>	27160-D-2-D	<b>PAGE 16 of 39</b>
---------------------	--------	--------------------	-------------	----------------------

<b>OIL COOLER</b>	Manufacturer: Niagara Thermal Products, Inc	P/N: 20002A	S/N: E15-12882-19
Condition:	The oil cooler exhibited impact damage		



The current Continental Aerospace Technologies Illustrated Parts Catalog for this engine does not indicate that an oil cooler was included during the manufacturing of model O-300-D (6B) engines.

### AFTERMARKET OIL FILTER ADAPTER

<b>FILTER ADAPTER</b>	M/N: F&M 370-1	S/N: 10190
<b>OIL COOLER ADAPTER</b>	STEVE'S AIRCRAFT	S/N: 252





## ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 17 of 39



NOTE: The accident engine was equipped with an F&M aftermarket spin-on oil filter adapter model CO-300-1, serial number 10190. In addition, another aftermarket device was attached where the spin-on oil filter normally would be attached to the F&M adapter. This device had a placard indicating that it was manufactured by "Steve's Aircraft", serial number 252. This adapter included two flexible oil hoses attached which bypassed to the oil cooler. It was not determined if the two unrelated STC'd appliances were joined within the scope of either STC or with permission of either STC holder.

**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 18 of 39**


**CYLINDERS**

**ALL CYLINDERS WERE MANUFACTURED BY SUPERIOR AIR PARTS AS FAA-PMA APPROVED CYLINDERS**

<b>CYLINDER #1</b>	P/N: SA 10200-A1	S/N:20-C15-41895	Head Date: Undetermined
Work Orders:	B-03309		
Condition:	No damage was noted.		



<b>CYLINDER #3</b>	P/N: SA 10200-A1	S/N:20-C15-41893	Head Date: Undetermined
Work Orders:	B-03291		
Condition:	Intake and exhaust push rods and push rod tubes were impact damaged.		



# ENGINE EXAMINATION REPORT

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 19 of 39**

**CYLINDER #5**

P/N: SA 10200-A1

S/N: Undetermined

Head Date: Undetermined

Work Orders:

B03929

Condition:

No damage was noted



**CYLINDER #2**

P/N: SA 10200-A1

S/N: 20-C15-41889

Head Date: Undetermined

Work Orders:

B-03365

Condition:

No damage was noted except impact damage to pushrod tubes and pushrods



### ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 20 of 39

**CYLINDER #4**

P/N: SA 10200-A1

S/N:20-G15-42231

Head Date: Undetermined

Work Orders:

B-03970

Condition:

No damage was noted



**CYLINDER #6**

P/N: SA 10200-A1

S/N:20-C15-41886

Head Date: Undetermined

Work Orders:

B-03478

Condition:

No damage was noted



## ENGINE EXAMINATION REPORT

**FILE NUMBER:**

18-370

**ENGINE S/N:**


27160-D-2-D

**PAGE 21 of 39**


### Cylinder Through-Bolt and Deck Stud Break-Away (Tightening/Loosening) Torque Measurements (in-lbs.)

(NOTE: Position numbers 1 and 5 are through bolts)

	Bolt 1	Stud 2	Stud 3	Stud 4	Bolt 5	Stud 6	Stud 7	Stud 8	Stud 9
	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose
Cylinder #2	563 / 430	570 / 390	626 / 473	N/A	598 / 450	565 / 450	746 / 589	N/A	N/A
Cylinder #4	550 / 449	586 / 428	673 / 483	N/A	487 / 467	593 / 466	694 / 516	N/A	N/A
Cylinder #6	668 / 523	660 / 606	748 / 617	N/A	670 / 576	654 / 572	851 / 730	N/A	N/A



	Bolt 1	Stud 2	Stud 3	Stud 4	Bolt 5	Stud 6	Stud 7	Stud 8	Stud 9
	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose	Tight / Loose
Cylinder # 1	517 / 584	631 / 557	748 / 647	N/A	653 / 598	530 / 454	752 / 659	N/A	N/A
Cylinder # 3	Loose	527 / 430	682 / 540	N/A	Loose	465 / 434	706 / 605	N/A	N/A
Cylinder # 5	405 / 373	615 / 608	761 / 664	N/A	626 / 542	565 / 517	653 / 565	N/A	N/A



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 22 of 39**

**VALVES AND GUIDES**

**Condition:**

All intake and exhaust valves were intact and exhibited normal combustion signatures.



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 23 of 39

## ROCKER ARMS AND SHAFTS

Condition: All rocker arms and shafts were intact and moved normally when the engine was rotated manually except cylinder 2 which sustained impact damage to the intake and exhaust pushrods.



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 24 of 39**

**#1 PISTON,  
RINGS AND PIN**

Piston P/N: 654853B

**Condition:**

Normal combustion signatures and wear patterns



**#3 PISTON,  
RINGS AND PIN**

Piston P/N: 654853B

**Condition:**

Normal combustion signatures and wear patterns





**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 25 of 39**

**#5 PISTON,  
RINGS AND PIN**

Piston P/N: 654853B

**Condition:**

Normal combustion signatures and wear patterns



**#2 PISTON,  
RINGS AND PIN**

Piston P/N: 654853B

**Condition:**

Normal combustion signatures and wear patterns



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 26 of 39**

**#4 PISTON,  
RINGS AND PIN**

Piston P/N: 654853B

**Condition:**

Normal combustion signatures and wear patterns



**#6 PISTON,  
RINGS AND PIN**

Piston P/N: 654853B

**Condition:**

Normal combustion signatures and wear patterns



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D


**PAGE 27 of 39**

**CRANKCASE ASSEMBLY**

<b>CRANKCASE</b>	Casting Number:	1-3-5: 530836	2-4-6: 530837	S/N: 51157-103
Condition:	Exhibited normal operating signatures			



<b>#1 MAIN BEARINGS</b>	P/N: 626230-M010	Date Code: 06/13
Condition:	Exhibited normal operating signatures	



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D



**PAGE 28 of 39**

**#2 MAIN BEARINGS**

P/N: 626230-M010

Date Code: 06/13

Condition: Exhibited normal operating signatures




**#3 MAIN BEARINGS**

P/N: 626230-M010

Date Code: 06/13

Condition: Exhibited normal operating signatures



ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 29 of 39


#4 MAIN BEARINGS

P/N: 652152-M010

Date Code: 03-14

Condition:

Exhibited normal operating signatures



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 30 of 39

## CRANKSHAFT ASSEMBLY

CRANKSHAFT

Forging Number: 27883

S/N: 385

Heat code: F6

Condition:


Exhibited normal operating signatures



COUNTERWEIGHTS

Condition:

Dampers were free to move on pins. All plates and snap-rings were intact.



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 31 of 39**

**INTERNAL  
TIMING**

**Condition:**

Correct internal timing was confirmed. Red arrow points to timing mark on camshaft gear.



**ENGINE EXAMINATION REPORT****FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 32 of 39****#1 CONNECTING  
ROD**

P/N: 654795A1

Forging Number: 530186

Condition: Exhibited normal operating signatures

**#1 CONNECTING  
ROD BEARING**

P/N: SA639640-M010

Condition: Exhibited normal operating signatures

**#3 CONNECTING  
ROD**

P/N: 654795A1

Forging Number: 530186

Condition: Exhibited normal operating signatures

**#3 CONNECTING  
ROD BEARING**

P/N: SA639640-M010

Condition: Exhibited normal operating signatures

**#5 CONNECTING  
ROD**

P/N: 654795A1

Forging Number: 530186

Condition: Exhibited normal operating signatures

**#5 CONNECTING  
ROD BEARING**

P/N: SA639640-M010

Condition: Exhibited normal operating signatures

**#2 CONNECTING  
ROD**

P/N: 654795A1

Forging Number: 530186

Condition: Exhibited normal operating signatures

**#2 CONNECTING  
ROD BEARING**

P/N: SA639640-M010

Condition: Exhibited normal operating signatures

**#4 CONNECTING  
ROD**

P/N: 654795A1

Forging Number: 530186

Condition: Exhibited normal operating signatures

**#4 CONNECTING  
ROD BEARING**

P/N: SA639640-M010

Condition: Exhibited normal operating signatures



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 33 of 39

## #6 CONNECTING ROD

P/N: 654795A1

Forging Number: 530186

Condition: Exhibited normal operating signatures

## #6 CONNECTING ROD BEARING

P/N: SA639640-M010

Condition: Exhibited normal operating signatures



ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 34 of 39



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 35 of 39**

**CAMSHAFT**


**CAMSHAFT**

P/N: 643068

S/N: 211706

**Condition:**

Exhibited normal operating signatures



LIFTERS	#1	#3	#5	#2	#4	#6
INTAKE	530851	530851	530851	530851	530851	530851
EXHAUST	530851	530851	530851	530851	530851	530851

**Condition:**

All lifter surfaces exhibited normal operating signatures



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:


27160-D-2-D

PAGE 36 of 39

## ACCESSORY GEARS

Condition:

The accessory gears were intact with no damage noted. Red arrow indicates cotter pin missing but it had been removed at the recovery examination.



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 37 of 39**

**ACCESSORIES**

<b>STARTER</b>	Manufacturer: Delco Remy overhauled by Cline's Electric Service	P/N: 1109514	S/N: 3755
----------------	---	--------------	-----------

Condition:	The starter motor mounting collar was impact damaged.
------------	---



<b>STARTER ADAPTER</b>	Manufacturer: Continental	P/N: Undetermined	S/N: Undetermined
------------------------	---------------------------	-------------------	-------------------

Condition:	The starter adapter was undamaged and rotated normally.
------------	---



### ENGINE EXAMINATION REPORT

**FILE NUMBER:**

18-370

**ENGINE S/N:**

27160-D-2-D

**PAGE 38 of 39**

**GENERATOR**

Manufacturer: Delco-Overhauled by Aerotech

P/N: 1101898

S/N: A798030

Condition:

The generator had been previously removed during the recovery examination. Impact damage was noted on the mounting ring and the electrical posts were damaged.



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-370

ENGINE S/N:

27160-D-2-D

PAGE 39 of 39

## VACUUM PUMP

Manufacturer: Airborne

P/N: 215CC

S/N: 161426

Condition:

The instrument air pump was rotated by hand. The pump rotated smoothly thumb suction was achieved. The plastic drive coupling was intact.

