

Non-destructive testing of a Garmin memory module, case CEN21FA150


Anju Sharma

Summary and Conclusions

- One Garmin memory module, CEN21FA150, was received for non-destructive testing to evaluate any external and internal damage.
- The module was examined with the optical, x-ray and acoustic microscopy.
- Optical inspection results:
 - Physical damage and signs of thermal damage are seen in bottom 1/3 area of the module. There is damage to the mold compound as well as discoloration of the substrate material in this area. The module is slightly bent. Mold material is broken-off in the bottom right corner of the package exposing internal features such as Cu planes, gold wire with its wedge bond and a bent Cu line.
- X-ray imaging results
 - X-ray imaging was done with medium size x-ray spot (mode 1), minimal exposure time and Cu filter to prevent any data corruption from x-ray exposure.
 - Memory module contains a single die with wire-bonds on two sides of the die. All wire bonds were examined at high magnification and from various oblique angles. No wire and/or wire bond damage was seen except for the one in the chipped corner of the module.
 - Side view of the module reveals separation between the mold compound and the die in the damaged area. This separation extends all the way to wire-bonds likely resulting in their lift-off and electrical discontinuities, Mold compound shows internal damage. Substrate is bent in this area.
- Acoustic Microscopy (C-SAM) results
 - Acoustic imaging was performed in the pulse-echo mode using 100 MHz transducer.
 - C-SAM results show severe degradation and damage to the mold compound and substrate material in the bottom 1/3 area of the package. C-SAM imaging confirms separation at the mold/die interface and reveals delamination of the mold/substrate.
- Conclusions:
 - This module is damaged at multiple fronts, namely (i) possible wire-bond separation from the die, (ii) damage to Cu planes and material of the substrate (iii) mold compound damage. It will not be possible to repair this module.

OPTICAL MICROSCOPY RESULTS

Front side



1000 μm

Separated piece from the damaged corner with a broken Cu line

Interior parts of the package are exposed

Mold is damaged

Front side




Exposed Cu plane of the substrate

Damaged area of the mold

Exposed wire bond

Damaged corner




Exposed Cu
plane of the
substrate

Exposed wire bond

Damaged corner

Exposed Cu plane of the substrate




crack

Spherical Silica fillers in the mold

Exposed wire bond on the substrate

Exposed wirebond

Exposed gold wire with wedge bond on the substrate




Gold wire

Wedge bond

Damaged Cu line

Damage to the mold




Back side


1000 μm

Solder ball grid array

Discoloration of the substrate material suggests possible thermal damage



Backside: Damaged area



Discoloration of the substrate material.


2000 μm

Damaged corner¹¹

Backside: Damaged corner and edges of the package




Damaged edge of the package




Damaged corner with exposed Cu plane

Side view of the package: side 1



Package is bent.



Exposed Cu planes

Cracks/separation of Cu lines in the substrate

Side view of the package: side 1


200 μm

Cu line of the exposed wire bond, is lifted off





Cracks/separation of Cu lines in the substrate possibly due to bending of the package



200 μm



Side view of the package: side 2



Side view of the package: side 3



Undamaged side of the package

X-RAY MICROSCOPY RESULTS


X-ray image of the entire package

The memory module has a single die with wire-bonds on two sides

Row of wire-bonds


Row of wire-bonds

Damaged corner



X-ray image of the die with wirebonds

Row of wirebonds



The memory package has a single die with wirebonds on two sides


Solder ball grid array

Row of wirebonds


1000 μm

120 kV 60 uA ZrO

X-ray image of the damaged corner




Exposed wirebond with damaged Cu line






X-ray image of the wire-bonds

Damaged wire-bond
at the corner




X-ray image of the wire-bonds: Oblique view




Die edge

No broken wires seen except for the damaged wedge bond at the corner.

X-ray images of the wire-bonds: Oblique view




No broken wires seen




X-ray image of the wire-bonds: Oblique view

No broken wires seen





X-ray image of the wire-bonds: Oblique view


No broken wires seen



X-ray image of the side of the package




There is separation between the mold and the die which extends to the edge where wire-bonds are located. Wire-bonds are likely lifted off the bond pads.



X-ray image of the damaged side of the package

There is separation between the mold and the die which extends to the edge where wire-bonds are located. Wire-bonds are likely lifted-off the bond pads possibly resulting in discontinuities.



ACOUSTIC MICROSCOPY RESULTS

Acoustic images of the memory module: Front side

Surface image









Image from within the mold compound




Acoustic imaging shows that there is a lot of sound attenuation/ scattering/ reflection from the mold compound in bottom 1/3 area of the package. This area exhibited voiding/cracks/ degradation in the mold material.



Acoustic images of the memory package



- Acoustic imaging confirms separation of the mold from the die (brightest areas due to high sound reflection)
- Because of the damaged mold in the bottom area of the package, sound is scattered/ reflected/attenuated and can not travel beyond the mold thickness.




Acoustic images of the memory package


Image from substrate




Composite image




- Because of the damaged mold in the bottom area of the package, sound is severely attenuated and can not travel beyond the mold thickness.



Acoustic images of the memory package




Red areas indicate possible delamination between the die and mold compound




Red areas indicate possible delamination between the substrate and the mold compound

Acoustic images of the memory module from the backside




Substrate Surface




Within the substrate

Acoustic imaging from the backside of the module shows internal damage within the substrate in the bottom area of the package

Acoustic images of the memory module from the backside



Deeper layers



Deeper layers

Acoustic imaging from the backside of the module shows internal damage within the substrate.