



CEN21LA367 - Examination Notes (Photos to be sent via Kiteworks) Wednesday, October 13, 2021 2:14:01 PM

Hello Craig,

Field Notes on today's examination of N997EM; Pulsar Sport 150; S/N: 603

Visual Examination:

- 1. Photos of airframe and engine (Continental O-200-A) left and right wings removed/separated
- 2. 1 control lead of the electric magneto was pulled/separated from the control plug see photo
- 3. Carburetor broken/separated above throttle valve (impact damaged), remained attached via engine control cables and fuel line
- 4. Fuel selector in RIGHT tank position
- 5. #4 cylinder intake tube did not contain a gasket (no leakage noted)
- 6. Both wooded propeller blades fractured about mid-span no leading edge damage noted
- 7. HOBBS: 306.2
- 8. Battery remained connected fuel pump activated when switched ON

Examination/Disassembly:

- 1. Cylinder rocker covers removed residual oil noted at bottom of valves
- 2. Spark plugs removed and photographed normal deposits noted lower plugs contained residual oil
- 3. Propeller assembly rotated by hand
- 4. Mechanical continuity noted throughout the engine forward to accessories
- 5. Spark, impulse magneto, noted on the four top ignition leads
- 6. No spark noted from E-Mag
- 7. E-Mag removed for further examination
- 8. Carburetor removed and disassembled. No issued noted and no residual fuel in bowl.
- 9. Compression check on cylinders: #1 60; #2 70; #3 74; #4 51
- 10. Air applied to wing fuel line fittings continuity and no obstructions noted in fuel lines to fuel selector to carburetor both left and right fuel lines contained an undocumented amount of residual fuel, consistent with 100LL.

Examination photographs sent via Kiteworks	
END	

Best,

Aaron