

# National Transportation Safety Board

Office of Research and Engineering

Washington, DC 20594



DCA22FA082

## **MATERIALS LABORATORY**

Factual Report 23-056

**January 09, 2024**

(This page intentionally left blank)

## **A. ACCIDENT INFORMATION**

Location: Jolon, California  
Date: 02/16/2022  
Vehicle: JOBY AERO inc. JAS4-2 (N542AJ)  
Investigator: Michael Hauf

## **B. COMPONENTS EXAMINED**

The following parts were received at the NTSB Materials Laboratory on July 6, 2023.

1. Station 2 tilt actuator
2. Station 2 tilt slide anti sag roller bearing and mount
3. Station 3 tilt actuator
4. Station 3 portion of tilt slide anti sag roller bearing mount

## **C. EXAMINATION PARTICIPANTS**

Specialist Michael Budinski  
NTSB  
Washington, DC

SEM Microscopy Edward Komarnicki  
NTSB  
Washington, DC

## **D. DETAILS OF THE EXAMINATION**

The submitted items are shown in Figures 1, 2, and 6. No laboratory exam was conducted on the Station 2 and 3 tilt actuators shown in Figure 1.

Figure 2 shows multiple views of the Station 2 tilt slide anti sag roller bearing and mount. The tapered ring pressed onto the outer bearing race exhibited a dent as revealed in Figure 2b. The bearing assembly was removed from the mount using a plate-type bearing puller and an arbor press. A high force was required to remove the bearing indicating that the inner bearing race was assembled on the mount shaft with a tight interference fit. The Station 2 mount with the bearing assembly removed is shown in Figure 3.


Close digital microscope images of the transition from the bearing shaft to the mount body on the Station 2 mount are shown in Figures 4 and 5. The transition area was visually inspected with a 5x to 50x stereozoom microscope for the presence of any cracks. As indicated in the figures, skived and raised material is present near the

shaft base consistent with deformation associated with press-fitting the bearing onto the shaft. No preexisting cracks were observed.


Images of the Station 3 mount are shown in Figure 6. The bearing shaft has been fractured from the mount (bearing and shaft portion were not recovered from the accident scene). Figures 7 and 8 show the overall fracture surface at the base of the bearing shaft using digital and scanning electron (SEM) microscopy, respectively. Approximately 90% of the fracture surface is mechanically damaged and precluded fractographic examination. The undamaged areas of the fracture surface exhibited fracture features consistent with monotonic overload (detail images are shown in Figures 9 and 10).

Submitted by:



Michael K. Budinski  
Chief, Materials Laboratory




**Figure 1.** Images of the Station 2 (views a, b, and c) and Station 3 (views d, e, and f) tilt actuators, as-received.



**Figure 2.** Digital microscope images of the Station 2 tilt slide anti sag roller bearing and mount, as-received.




**Figure 3.** Digital microscope images of the Station 2 tilt slide anti sag roller bearing mount, with the bearing removed.




**Figure 4.** Close view digital microscope image of the base of the bearing shaft where it meets the mount body for the Station 2 tilt slide anti sag roller bearing mount. Note the raised material and skived filament associated with the pressing of the bearing onto the shaft.






**Figure 5.** Higher magnification digital microscope images of the base of the bearing shaft where it meets the mount body for the Station 2 tilt slide anti sag roller bearing mount. Note the raised material and skived filament associated with the pressing of the bearing onto the shaft. Views a and b are 180° apart. No preexisting cracks were observed.





**Figure 6.** Digital microscope images of the Station 3 portion of tilt slide anti sag roller bearing mount, the separated shaft and bearing were not submitted.





**Figure 7.** Digital microscope image of the bearing shaft fracture surface from the Station 3 portion of tilt slide anti sag roller bearing mount.



**Figure 8.** Scanning electron microscope image of the bearing shaft fracture surface from the Station 3 portion of tilt slide anti sag roller bearing mount.



**Figure 9.** Close scanning electron microscope images of the bearing shaft fracture surface from the Station 3 portion of tilt slide anti sag roller bearing mount (see figure 9 for the specific location). The fracture features are consistent with monotonic overload.



**Figure 10.** Close scanning electron microscope images of the bearing shaft fracture surface from the Station 3 portion of tilt slide anti sag roller bearing mount (see figure 9 for the specific location). The fracture features are consistent with monotonic overload.