

Step Number	Task Description	Results	Notes	Unexpected Result Comments; or Changes made to equipment during inspection
-------------	------------------	---------	-------	--

Test the multimeter for proper function before beginning. Also, after finishing. Conduct "6-point test" before beginning work. Machine performs the same as previous inspections?

**Switch Position: Pedal Pushed - Alarm Sound**  
 Forward: Forward - \_\_\_\_\_  
 Forward: Reverse - \_\_\_\_\_  
 Center: Forward - \_\_\_\_\_  
 Center: Reverse - \_\_\_\_\_  
 Reverse: Forward - \_\_\_\_\_

**Phase 1 - Determine if wires are mislabeled, or if wires are in the wrong place.**

1	Open Master Control Cabinet (MCC)			
2	Locate Travel light directional Switch labeled RKS 1002 inside the panel			NS Contractor On-site to record video of process.
3	Verify RKS 1002 has the following wires in the corresponding spots on the back of the switch			
3.1 a.	Wire #1002 (red) Spot 2b	Verified; or Not Verified		
3.2 b.	Wire #1726 (red) spot 5b	Verified; or Not Verified		
3.3 c.	Wire #1002A (black) spot 3	Verified; or Not Verified		
3.4 d.	Wire #1013 (black) spot 1	Verified; or Not Verified		
3.5 e.	Wire #2422 (black) spot 6	Verified; or Not Verified		
3.6 f.	Wire #2425 (black) spot 4	Verified; or Not Verified		
4	Locate Terminal block #12 spot 2422 verify wire #2422 (Black) is in this spot	Verified; or Not Verified		
4.1 a.	Remove wire #2422 form terminal block #12 spot 2422.			
4.2 b.	Using a multimeter set to make a tone when probes are touched together. Place one probe on wire #2422 that was removed from terminal block, and the other probe on wire #2422 at rocker switch (RKS1002) spot 6 listen for tone on Multimeter.	Tone; or No Tone		
4.3 c.	If tone is heard wire are labeled correctly. If no tone is heard move to next step.	Expected; or Unexpected		What do we do if the tone is heard? Move to step 7
5	Move probe from Wire #2422 spot 6 to wire #2425 at spot 4 of rocker switch (RKS1002).	Tone; or No Tone		This step is only done if no tone is heard in step 4.3
6	Reinstall Wire #2422 in Terminal block #12 spot 2422			If tone is heard, wires are mislabeled
7	Locate terminal block #12 spot 2425			
7.1 a.	Verify wire #2425 (black) is in this spot and remove from terminal block.	Verified; or Not Verified		
7.2 b.	Using multimeter set to make a tone when probes are touched together place one probe on wire #2425 that was just removed, and one probe on wire #2425 at rocker switch (RKS1002) spot 4.	Tone; or No Tone		
7.3 c.	If tone is heard from the Multimeter wires are labeled correctly. If no tone is heard move on to the next step.	Expected; or Unexpected		What do we do if the tone is heard? Move to step 9
8	Move probe from wire #2425 spot 4 to Wire #2422 spot 6	Tone; or No Tone		This step is only done if no tone is heard in step 7.3
8.1	If tone is heard, wires are mislabeled	Expected; or Unexpected		
8.2	Reinstall wire #2425 in Terminal Block #12 spot 2425			
9	Locate the plug at the computer and unplug the computer			
9.1 a.	Locate Wire #2422 (yellow) at terminal block 12 spot 2422.			
9.2 b.	Remove wire #2422 (yellow) from the terminal block.			
9.3 c.	With the multimeter set to tone place one probe on pin #74 of the computer plug.			
9.4 d.	Place the other probe on wire #2422 (yellow) that was removed from terminal block #12 spot 2422.	Tone; or No Tone		
9.5 e.	If you hear a tone from the multimeter wire is label correctly. If no tone is heard move to next step.	Expected; or Unexpected		What do we do if the tone is heard? Move to step 10.1 a
10	Move probe from wire #2422 at terminal block to wire #2425, if tone is heard, wire is mislabeled	Tone; or No Tone		This step is only done if no tone is heard in step 9.5
10.1 a.	Reinstall wire 2422 in terminal block #12 spot 2422.			
10.2 b.	Locate wire #2425 at terminal block #12 spot 2425, and remove.			
10.3 c.	Place one probe on wire #2425 that was just removed from terminal block, and place the other probe on pin #16 of the computer plug. If tone is heard wires are labeled correctly. If no tone is heard move to next step.	Tone; or No Tone		What do we do if the tone is heard? Move to step 11.2.b
11	Move probe from wire #2425 (yellow) at terminal block #12 to wire #2422 at terminal block #12	Tone; or No Tone		This step is only done if not tone is heard in step 10.3
11.1 a.	If tone is heard wires are mislabeled.	Expected; or Unexpected		
11.2 b.	Reinstall wire #2425 in the terminal block #12 spot 2425.			

Step Number	Task Description	Results	Notes	Unexpected Result Comments; or Changes made to equipment during inspection
12	Find control Relay 2826 and verify the wire are as follows			
12.1 a.	Wire #2826 is on spot A1.	Verified; or Not Verified		
12.2 b.	Wire #2 is on spot A2.	Verified; or Not Verified		
12.3 c.	Wire #944a is on spot 14	Verified; or Not Verified		
12.4 d.	Wire #944 is on spot 11	Verified; or Not Verified		
13	Find control relay #2829 and verify the wire are as follows.			
13.1 a.	Wire #2829 on spot A1.	Verified; or Not Verified		
13.2 b.	Wire #2 on spot A2.	Verified; or Not Verified		
13.3 c.	Wire #947 on spot 14.	Verified; or Not Verified		
13.4 d.	Wire #944 on spot 11	Verified; or Not Verified		
14	With Multimeter set to tone, place one probe on pin #13 of the computer plug, and the other probe on wire 2826 spot A1. Listen for tone on multimeter. If no tone, move to next step	Tone; or No Tone		What do we do if there is a tone? Move to step 16
15	Move probe from wire #2826 of the control relay 2826 to wire #2829 on control relay 2829. If there is a tone, wires are mislabeled	Tone; or No Tone		This step is only done if there is no tone on step 14.
16	Move probe to pin #14 on the computer plug and place the other probe on wire #2829 of the control relay. Listen for tone. If no tone is heard, move to the next step	Tone; or No Tone		What do we do if there is a tone? Move to step 18.
17	Move probe from wire #2829 of the control relay to wire #2826. If tone is heard, wires are mislabeled.	Tone; or No Tone		This step is only done if there is no tone on step 16
18	locate Plug 904 on the side of the MCC and unplug			
18.1 a.	Place one probe on wire #944a At control relay 2826 pin 14 and the other probe on on pin H of plug 904 on side of MCC. Listen for tone if no tone is heard move to step	Tone; or No Tone		if tone is heard move to step 20
19	move probe from plug 904 pin H to pin J. if tone is heard wires are in wrong location in plug	Tone; or No Tone		This step is only done if there is no tone on step 18
20	Place probe on wire #947 spot 14 of control relay 2829 and the other probe on pin J of plug 904 on the Side of the MCC. If no tone move to the next step.	Tone; or No Tone		if tone is heard move to step 22
21	move probe from pin J of plug 904 on the side of MCC to pin H if tone is heard wire are in the wrong spot of pug 904.	Tone; or No Tone		
22	locate Plug for the front change of direction alarm on the front roof			
22.1 a	locate pin 1 of the front change of diretion alarm and place probe on pin. Place the other probe on pin H of plug 904 inside the cab. If no tone is heard move on to the next step	Tone; or No Tone		if tone is heard move on to step 23
22	move probe from pin H on plug 904 inside the cab to pin J. if tone is heard the wire is in the wrong location in plug 904	Tone; or No Tone		
23	locate plug for rear change of direcion alarm on the rear roof and unplug			
23.1 a	place one probe on pin 1 of the rear change of direction alarm and the other probe on pin J of plug 904 inside the cab. If no tone is heard move to the next step.	Tone; or No Tone		
24	move prove from pin J of plug 904 inside the cab to pin H if tone is heard wire is in the wrong location in plug 904.	Tone; or No Tone		

#### steps to test the roof mounted horns

1	verify the following wire are on control relay 923			
1.1 a.	Wire #951 Spot 11	Verified; or Not Verified		
1.2 b.	Wire #951 Spot 41	Verified; or Not Verified		
1.3 c.	Wire #951a spot 14	Verified; or Not Verified		
1.4 d.	Wire #951a spot 44	Verified; or Not Verified		
2	with multimeter set to read DC Volts place black probe on Ground stud in side the MCC and the red probe on #951 spot 11 of control relay 923. push horn button meter should read 24V			
3	move red probe to wire #951 spot 41 on control relay 923. push horn button should read 24V.			

Step Number	Task Description	Results	Notes	Unexpected Result Comments; or Changes made to equipment during inspection
4	move red probe to Wire #951a spot 14 of control relay 923. push the horn button on the MCC. Should read 24V if not relay is bad			
5	Move red probe to Wire #951a spot 41 of control relay 923. push the horn button on MCC. Should read 24V. If not the relay is bad.			
6	locate the plug for the front and rear facing horns on the roof and unplug both.			
6.1 a	set multi meter to read DC volts			
6.2 b	Place red probe on pin 1 and the black probe on pin 2 of front facing horn plug. and push the horn button located on the MCC in the cab should read 24V or higher.		If the meter reads 24V move to step 7 if no reading move to step 8	
6.3 c	place red probe on pin 1 and the black probe on pin 2 of the rear facing horn plug. Should read 24V or higher.		If the meter reads 24V move to step 7 if no reading move to step 9	
7	plug in new horn and test function.			
8	with meter set to make a tone when probes are touched together place one probe on pin1 of the front facing horn and the other probe on pin L of plug 904 inside to cab. If no tone wire is broke between the horn plug and plug 904 inside the cab.	Tone; or No Tone		if tone is heard move to step 10
9	with meter set to make a tone when probes are touched together place on probe on pin1 of the rear facing horn plug and the other probe on pin L of plug 904 inside to cab. If no tone wire is broke between the horn plug and plug 904 inside the cab.	Tone; or No Tone		if tone is heard move to step 10
10	Place one probe on pin L on plug 904 on the side of the MCC and the other probe on wire #951a on pin 14 of control relay 923 if no tone is heard there is a break in the wire from plug 904 pin L to control relay 923			

**Phase 2: Move Wires to "Correct" Location**

18	Based on Phase 1 results, document any changes made to the equipment to put it in "proper" or "correct" working condition		(photograph and video)	
19	Conduct "6-point test"			
19.1	<b>Switch Position: Pedal Pushed - Alarm Sound</b> Forward: Forward - No Alarm Forward: Reverse - Rear Speaker Center: Forward - Both Speakers Center: Reverse - Both Speakers Reverse: Forward - Front Speaker Reverse: Reverse - No Alarm	<b>Switch Position: Pedal Pushed - Alarm Sound</b> Forward: Forward - _____ Forward: Reverse - _____ Center: Forward - _____ Center: Reverse - _____ Reverse: Forward - _____ Reverse: Reverse - _____		
19.2	Once the machine is set up for "correct" operation. Conduct a final inspection for signs of failure or maintenance that may have led to the improper functions.			

**Phase 3: How to leave the machine?**

20	<ol style="list-style-type: none"> <li>Do we reinstall all wiring back to the way it was found until the machine is released back to Norfolk Southern?</li> <li>Do we leave it in the way that makes the alarms work properly, and re-label any wires that are mislabeled?</li> </ol>			
20.1	<b>NTSB Legal Advice</b> . My main concern is that if we try to "fix" it, then we could arguably assume responsibility for making sure it is correct. At the same time, if we fix it, I don't want to break it again. I am going to assume the company has maintenance people on staff. I suggest involving them in the testing process, or at least give them a very thorough, and documented, briefing when we are done outlining exactly what you changed. Make sure to stress to them that they should follow their own procedures to verify the work and ensure the system is configured according to their own standards and procedures. Be sure to document all of that in writing to them, with a copy in the OOU docket.			

218 D. E. 2000  
10/20/00

Page \_\_\_\_ of \_\_\_\_  
Meeting \_\_\_\_\_  
Date: \_\_\_\_ Start: \_\_\_\_ End: \_\_\_\_

Attendance Record



Full Name	Organization	Title	Phone	e-mail	Group/Role
John Manutes	NTSB				Mech WG Chair
Dave Graubard	FRA				MPE Inspector
Kenneth Pugh	FRA				
Todd Krahoilk	FRA				Track Inspector
Jason Gurzynski	FRA				MPE Inspector
Roy Morrison	BMWED				
Joe Young	NS				NS
Dwayne Gibson	NS				
Jon Mick	Nat. Salvage				NATIONAL
Ian Barlick	Nat Salvage				
John Gobert	Nordco				
	Nordco				

Attendance Record



Page \_\_\_\_ of \_\_\_\_  
 Meeting \_\_\_\_\_ Start: \_\_\_\_\_ End: \_\_\_\_\_  
 Date: \_\_\_\_\_

Full Name	Organization	Title	Phone	e-mail	Group/Role
Forrest Kooner -Fox	National Salvage	Project manager			
Todd Yates	N/S	Representative			Company
Danny Thomas	Nordco	General Manager			
Michael Polite	N/S	Manager work log			

Step Number	Task Description	Results	Notes	Unexpected Result Comments; or Changes made to equipment during inspection
-------------	------------------	---------	-------	--

Test the multimeter for proper function before beginning. Also, after finishing. Conduct "6-point test" before beginning work.

Machine performs the same as previous inspections?

Switch Position: Pedal Pushed - Alarm Sound	
Forward: Forward	no
Forward: Reverse	no
Center: Forward	2
Center: Reverse	2
Reverse: Forward	no
Reverse: Reverse	no

FR : R - front

**Phase 1 - Determine if wires are mislabeled, or if wires are in the wrong place.**

- 1 Open Master Control Cabinet (MCC)
- 2 Locate Travel light directional Switch labeled RKS 1002 inside the panel
- 3 Verify RKS 1002 has the following wires in the corresponding spots on the back of the switch
  - 3.1 a. Wire #1002 (red) Spot 2b  Verified; or Not Verified
  - 3.2 b. Wire #1726 (red) spot 5b  Verified; or Not Verified
  - 3.3 c. Wire #1002A (black) spot 3  Verified; or Not Verified
  - 3.4 d. Wire #1013 (black) spot 1  Verified; or Not Verified
  - 3.5 e. Wire #2422 (black) spot 6  Verified; or Not Verified
  - 3.6 f. Wire #2425 (black) spot 4  Verified; or Not Verified
- 4 Locate Terminal block #12 spot 2422 verify wire #2422 (Black) is in this spot  Verified; or Not Verified

NS Contractor On-site to record video of process.

- 4.1 a. Remove wire #2422 form terminal block #12 spot 2422.
- 4.2 b. Using a multimeter set to make a tone when probes are touched together. Place one probe on wire #2422 that was removed from terminal block, and the other probe on wire #2422 at rocker switch (RKS1002) spot 6 listen for tone on Multimeter.  Tone or No Tone

- 4.3 c. If tone is heard wire are labeled correctly. If no tone is heard move to next step.  Expected; or  Unexpected

What do we do if the tone is heard? Move to step 6

- 5 Move probe from Wire #2422 spot 6 to wire #2425 at spot 4 of rocker switch (RKS1002).  Tone; or  No Tone

This step is only done if no tone is heard in step 4.3

- 6 Reinstall Wire #2422 in Terminal block #12 spot 2422
- 7 Locate terminal block #12 spot 2425
- 7.1 a. Verify wire #2425 (black) is in this spot and remove from terminal block.  Verified; or  Not Verified

If tone is heard, wires are mislabeled

- 7.2 b. Using multimeter set to make a tone when probes are touched together place one probe on wire #2425 that was just removed, and one probe on wire #2425 at rocker switch (RKS1002) spot 4.  Tone; or  No Tone

- 7.3 c. If tone is heard from the Multimeter wires are labeled correctly. If no tone is heard move on to the next step.  Expected; or  Unexpected

What do we do if the tone is heard? Move to step 8.2

- 8 Move probe from wire #2425 spot 4 to Wire #2422 spot 6  Tone; or  No Tone

This step is only done if no tone is heard in step 7.3

- 8.1 If tone is heard, wires are mislabeled  Expected; or  Unexpected

- 8.2 Reinstall wire #2425 in terminal block #12 spot 2425
- 9 Locate the plug at the computer and unplug the computer

- 9.1 a. Locate Wire #2422 (yellow) at terminal block 12 spot 2422.

- 9.2 b. Remove wire #2422 (yellow) from the terminal block.

- 9.3 c. With the multimeter set to tone place one probe on pin #74 of the computer plug.

- 9.4 d. Place the other probe on wire #2422 (yellow) that was removed from terminal block #12 spot 2422.  Tone; or  No Tone

- 9.5 e. If you hear a tone from the multimeter wire is label correctly. If no tone is heard move to next step.  Expected; or  Unexpected

What do we do if the tone is heard? Move to step 10.1 a

- 10 Move probe from wire #2422 at terminal block to wire #2425, if tone is heard, wire is mislabeled  Tone; or  No Tone

This step is only done if no tone is heard in step 9.5

- 10.1 a. Reinstall wire 2422 in terminal block #12 spot 2422.

- 10.2 b. Locate wire #2425 at terminal block #12 spot 2425, and remove.

- 10.3 c. Place one probe on wire #2425 that was just removed from terminal block, and place the other probe on pin #16 of the computer plug. If tone is heard wires are labeled correctly. If no tone is heard move to next step.  Tone; or  No Tone

What do we do if the tone is heard? Move to step 11.2.b

- 11 Move probe from wire #2425 (yellow) at terminal block #12 to wire #2422 at terminal block #12  Tone; or  No Tone

This step is only done if not tone is heard in step 10.3

- 11.1 a. If tone is heard wires are mislabeled.  Expected; or  Unexpected

- 11.2 b. Reinstall wire #2425 in the terminal block #12 spot 2425.

1 of plan:  
 ① 2422 w/ 2425  
 ② 6p + clk

F:F	no
F:R	front
C:F	2
C:R	2
R:F	rear
R:R	no

Step Number	Task Description	Results	Notes	Unexpected Result Comments; or Changes made to equipment during inspection
-------------	------------------	---------	-------	--

12	Find control Relay 2826 and verify the wire are as follows			video narrative starting here
12.1 a.	Wire #2826 is on spot A1.	Verified; or Not Verified		
12.2 b.	Wire #2 is on spot A2.	Verified; or Not Verified		
12.3 c.	Wire #944a is on spot 14	Verified; or Not Verified		
12.4 d.	Wire #944 is on spot 11	Verified; or Not Verified		
13	Find control relay #2829 and verify the wire are as follows.			Computer Swap
13.1 a.	Wire #2829 on spot A1.	Verified; or Not Verified		
13.2 b.	Wire #2 on spot A2.	Verified; or Not Verified		
13.3 c.	Wire #947 on spot 14.	Verified; or Not Verified		
13.4 d.	Wire #944 on spot 11	Verified; or Not Verified		
14	With Multimeter set to tone, place one probe on pin #13 of the computer plug, and the other probe on wire 2826 spot A1. Listen for tone on multimeter. If no tone, move to next step	Tone; or No Tone		What do we do if there is a tone? Move to step 16
15	Move probe from wire #2826 of the control relay 2826 to wire #2829 on control relay 2829. If there is a tone, wires are mislabeled	Tone; or No Tone		This step is only done if there is no tone on step 14.
16	Move probe to pin #14 on the computer plug and place the other probe on wire #2829 of the control relay. Listen for tone. If no tone is heard, move to the next step	Tone; or No Tone		What do we do if there is a tone? Move to step 18.
17	Move probe from wire #2829 of the control relay to wire #2826. If tone is heard, wires are mislabeled.	Tone; or No Tone		This step is only done if there is no tone on step 16
18	locate Plug 904 on the side of the MCC and unplug			
18.1 a.	Place one probe on wire #944a At control relay 2826 pin 14 and the other probe on on pin H of plug 904 on side of MCC. Listen for tone if no tone is heard move to step	Tone; or No Tone		if tone is heard move to step 20
19	move probe from plug 904 pin H to pin J. if tone is heard wires are in wrong location in plug	Tone; or No Tone		This step is only done if there is no tone on step 18
20	Place probe on wire #947 spot 14 of control relay 2829 and the other probe on pin J of plug 904 on the Side of the MCC. If no tone move to the next step.	Tone; or No Tone		if tone is heard move to step 22
21	move probe from pin J of plug 904 on the side of MCC to pin H if tone is heard wire are in the wrong spot of pug 904.	Tone; or No Tone		
22	locate Plug for the front change of direction alarm on the front roof			
22.1 a	locate pin 1 of the front change of direction alarm and place probe on pin. Place the other probe on pin H of plug 904 inside the cab. If no tone is heard move on to the next step	Tone; or No Tone		if tone is heard move on to step 23
22	move probe from pin H on plug 904 inside the cab to pin J if tone is heard the wire is in the wrong location in plug 904	Tone; or No Tone		
23	locate plug for rear change of direction alarm on the rear roof and unplug			
23.1 a	place one probe on pin 1 of the rear change of direction alarm and the other probe on pin J of plug 904 inside the cab. If no tone is heard move to the next step.	Tone; or No Tone		
24	move prove from pin J of plug 904 inside the cab to pin H if tone is heard wire is in the wrong location in plug 904.	Tone; or No Tone		

AP	rear
FT	no
CB	2.
CT	2
TP	2
FF	front

Step	Task Description	Results	Notes	Unexpected Result Comments; or Changes made to equipment during inspection
1	verify the following wire are on control relay 923			
1.1 a.	Wire #951 Spot 11	Verified; or Not Verified		
1.2 b.	Wire #951 Spot 41	Verified; or Not Verified		
1.3 c.	Wire #951a spot 14	Verified; or Not Verified		
1.4 d.	Wire #951a spot 44	Verified; or Not Verified		
2	with multimeter set to read DC Volts place black probe on Ground stud in side the MCC and the red probe on #951 spot 11 of control relay 923. push horn button meter should read 24V			
3	move red probe to wire #951 spot 41 on control relay 923. push horn button should read 24V.			

Step Number	Task Description	Results	Notes	Unexpected Result Comments; or Changes made to equipment during inspection
4	move red probe to Wire #951a spot 14 of control relay 923. push the horn button on the MCC. Should read 24V if not relay is bad			
5	Move red probe to Wire #951a spot 41 of control relay 923. push the horn button on MCC. Should read 24V. If not the relay is bad.			
6	locate the plug for the front and rear facing horns on the roof and unplug both.			
6.1 a	set multi meter to read DC volts			
6.2 b	Place red probe on pin 1 and the black probe on pin 2 of front facing horn plug. and push the horn button located on the MCC in the cab should read 24V or higher.			If the meter reads 24V move to step 7 if no reading move to step 8
6.3 c	place red probe on pin 1 and the black probe on pin 2 of the rear facing horn plug. Should read 24V or higher.			If the meter reads 24V move to step 7 if no reading move to step 9
7	plug in new horn and test function.			
8	with meter set to make a tone when probes are touched together place one probe on pin 1 of the front facing horn plug and the other probe on pin L of plug 904 inside to cab. if no tone wire is broke between the horn plug and plug 904 inside the cab.	Tone; or No Tone		if tone is heard move to step 10
9	with meter set to make a tone when probes are touched together place one probe on pin 1 of the rear facing horn plug and the other probe on pin L of plug 904 inside to cab. if no tone wire is broke between the horn plug and plug 904 inside the cab.	Tone; or No Tone		if tone is heard move to step 10
10	Place one probe on pin L on plug 904 on the side of the MCC and the other probe on wire #951a on pin 14 of control relay 923 if no tone is heard there is a break in the wire from plug 904 pin L to control relay 923			

**Phase 2: Move Wires to "Correct" Location**

18 Based on Phase 1 results, document any changes made to the equipment to put it in "proper" or "correct" working condition (photograph and video)

19 Conduct "6-point test"

19.1 Switch Position: Pedal Pushed - Alarm Sound

Forward: Forward - No Alarm  
 Forward: Reverse - Rear Speaker  
 Center: Forward - Both Speakers  
 Center: Reverse - Both Speakers  
 Reverse: Forward - Front Speaker  
 Reverse: Reverse - No Alarm

Switch Position: Pedal Pushed - Alarm Sound

Forward: Forward - \_\_\_\_\_  
 Forward: Reverse - \_\_\_\_\_  
 Center: Forward - \_\_\_\_\_  
 Center: Reverse - \_\_\_\_\_  
 Reverse: Forward - \_\_\_\_\_  
 Reverse: Reverse - \_\_\_\_\_

19.2 Once the machine is set up for "correct" operation. Conduct a final inspection for signs of failure or maintenance that may have led to the improper functions.

**Phase 3: How to leave the machine?**

20 1. Do we reinstall all wiring back to the way it was found until the machine is released back to Norfolk Southern?

2. Do we leave it in the way that makes the alarms work properly, and re-label any wires that are mislabeled?

20.1 NTSB Legal Advice

My main concern is that if we try to "fix" it, then we could arguably assume responsibility for making sure it is correct. At the same time, if we fix it, I don't want to break it again. I am going to assume the company has maintenance people on staff. I suggest involving them in the testing process, or at least give them a very thorough, and documented, briefing when we are done outlining exactly what you changed. Make sure to stress to them that they should follow their own procedures to verify the work and ensure the system is configured according to their own standards and procedures. Be sure to document all of that in writing to them, with a copy in the OOU docket.



# Swapped wire test

	<u>exp</u>	<u>Act</u>
f:f	no	<del>no</del> no
f:r	R	R
C:f	2	2
C:r	2	2
r:f	F	F
R:R	NO	NO

Travel ok

## Manutes John

---

**From:** Manutes John  
**Sent:** Tuesday, January 25, 2022 9:06 PM  
**To:** Young, Joseph; Gobert, John; Jon Mick [REDACTED] Roy Morrison; Graubard, David (FRA); Pugh, Kenneth (FRA)  
**Cc:** Gurzynski, Jason (FRA); [REDACTED]; Harley Sheryl; Lloyd Troy; Hoepf Michael  
**Subject:** Request: NTSB Investigative Hold Release  
**Attachments:** Attendance.pdf

(Please note: I buried a request for a reply below. Please read the whole message, distribute in your organizations as necessary, and have a representative reply before Jan 31.)

Mechanical Working Group,

Thank you for the great work today. I will compose a set of supplement field notes and distribute them for your approval/review in the next week.

In the meantime, we need to formalize the condition we left the Spiker and discuss the release of the investigative hold on the Spiker.

### **Condition of the Spiker**

Prior to the end of the day the Mechanical Working Group agreed to make every attempt to leave the Spiker in the condition we found it at the beginning of the day. We believe we met that goal. NS had a videographer on site to record every change we made to the machine, and every time we changed something back. Highlights and key components include:

- The rear speaker is plugged in. It was found on-site unplugged, however during the course of the initial on scene inspection it was plugged back in and was that way when we got there this morning. The team did unplug it to check continuity of the wires, but plugged it back in immediately following the test.
- All six pedals (three positions, Forward and reverse at each) were found to be miss-wired as compared to the Spiker's design. The left side forward and reverse plugs were swapped for testing and returned to the position where they were found (miss-wired) A yellow label was very nearly falling off the left side wiring bundle. The team zip-tied that wire in place where it was found.
- The plugs connected to the hydrostatic pump were found to be miss-wired at locations C1 and C2. These were swapped for testing. They were returned after testing.
- Wires in the MCC were removed for continuity testing and replaced to their original locations.
- The computer in the MCC was unplugged.
  - A new computer was plugged in, without actually removing the old computer physically from its brackets.
  - The original computer was plugged back in. The old computer was removed and returned to Nordco.
- A horn trumpet (No. 1 in our notes) was disassembled. It was reassembled.
- Both horn assemblies were unplugged to allow for a new horn to be tested on the existing wiring. The horn assemblies were plugged back in.

The mechanical working group, including Nordco and Norfolk Southern, understand that the machine is *not* in mechanically sound condition for operation. Prior to any return to service; testing, inspection, and repairs for compliance and safety would need to be addressed.

### **Investigative Hold**

The mechanical working group has released the NS Spiker GS 15022 to the Norfolk Southern for the purposes of additional inspection by claims agents and attorneys for the railroad and/or the family of the deceased. The mechanical working group has asked that any parts removed from the machine be held for NTSB inspection prior to any additional testing (on or off-site) or disposal. If any party member, including the NS, wishes to seek additional testing or inspection, the NTSB must be notified in advance.

Finally, the NTSB anticipates a full release of the Spiker GS 15022 to the Norfolk Southern by January 31<sup>st</sup>. This additional time is meant to give parties the opportunity to discuss this full release within their organizations. Please have a representative from your organizations reply to this message confirming your concurrence with the full release, or with any concerns. We can set up a Teams meeting to discuss any concerns.

I am grateful to have had the opportunity to spend the day with this team. Great things were accomplished, in short time, with a lot of creativity and drive. Thank you for your time, efforts, travels, expertise, and hospitality. I will be back in touch early next week.


Thank you,

John



**John Manutes**  
Railroad Accident Investigator  
Denver, Colorado

**Web:** [www.nts.gov](http://www.nts.gov)




REV	DESCRIPTION	BY	DATE	CHECKED BY:	DATE	APPROVED BY:	DATE	EQ#

THIS DRAWING AND DESIGN IS THE PROPERTY OF NORDCO INC. AND IS NOT TO BE REPRODUCED IN WHOLE OR PART, NOR EMPLOYED FOR ANY PURPOSE OTHER THAN SPECIFICALLY PERMITTED IN WRITING BY NORDCO INC. THIS DRAWING LOANED AND SUBJECT TO RETURN ON DEMAND

<b>D</b>	ALL DIMENSIONS IN INCHES
SIZE	IMPLIED TOLERANCES
FRACTION	± 1/8
X	± .06
XX	± .03
XXX	± 0.10

TITLE: CAB/OPERATOR SEAT CABLING	
PRODUCT: SE SPIKER	CAD FILE: 97551011DWG
SHEET: 22 OF 24	SCALE: NTS
LOCATION:	REV: A



OAK CREEK WISCONSIN


REV	DESCRIPTION	BY	DATE	CHECKED BY:	DATE	ECO #

THIS DRAWING AND DESIGN IS THE PROPERTY OF NORDCO INC. AND IS NOT TO BE REPRODUCED IN WHOLE OR PART, NOR EMPLOYED FOR ANY PURPOSE OTHER THAN SPECIFICALLY PERMITTED IN WRITING BY NORDCO INC. THIS DRAWING LOANED AND SUBJECT TO RETURN ON DEMAND

D	ALL DIMENSIONS IN INCHES
FRACTION	±.08
X	±.06
XX	±.03
XXX	±0.10

TITLE: MCC ENCLOSURE CONNECTIONS			
PRODUCT: SE SPIKER	SHEET: 7 OF 24	SCALE: NTS	REV: A
CAD FILE: 97551011DWG	LOCATION:		

# Observed Function / config



OAK CREEK WISCONSIN


REV	DESCRIPTION	BY	DATE	CHECKED BY:	DATE	ECO #

THIS DRAWING AND DESIGN IS THE PROPERTY OF NORDECO INC. AND IS NOT TO BE REPRODUCED IN WHOLE OR PART, NOR EMPLOYED FOR ANY PURPOSE OTHER THAN SPECIFICALLY PERMITTED IN WRITING BY NORDECO INC. THIS DRAWING LOANED AND SUBJECT TO RETURN ON DEMAND


D	SIZE	ALL DIMENSIONS IN INCHES
	IMPLIED TOLERANCES	
FRACTION	XX	±.18 ±.08 ±.03 ±0.10
XXX		

TITLE: MAIN BOARD INPUTS CONTINUED FOOT PEDALS, FRONT PROPEL MOTOR AND PULSE AMP	
PRODUCT: SE SPIKER	
CAD FILE:	97551003
SHEET:	22 OF 81
SCALE: NTS	LOCATION: MCC
REV	A

# Intended Function / config




								ALL DIMENSIONS IN INCHES IMPLIED TOLERANCES: FRACTION X XX .XXX 1/8 ±.08 .03 ±.010	TITLE: MAIN BOARD INPUTS CONTINUED FOOT PEDALS, FRONT PROPEL MOTOR AND PULSE AMP PRODUCT: SE SPIKER			CAD FILE: 97551003	SHEET: 22 OF 61	SCALE: NTS LOCATION: MCC	REV
	OAK CREEK WISCONSIN	REV	DESCRIPTION	BY	DATE	CHECKED BY:	DATE		ECO #	A					




	SEE LAST SHEET FOR REVISION HISTORY					THIS DRAWING AND DESIGN, IS THE PROPERTY OF NORDCO INC. AND IS NOT TO BE REPRODUCED IN WHOLE OR PART, NOR EMPLOYED FOR ANY PURPOSE OTHER THAN SPECIFICALLY PERMITTED IN WRITING BY NORDCO INC. THIS DRAWING LOANED AND SUBJECT TO RETURN ON DEMAND	<b>D</b> SIZE ALL DIMENSIONS IN INCHES IMPLIED TOLERANCES FRACTION ± 1/8 .X ± .06 .XX ± .03 .XXX ± 0.10	TITLE: MCC ENCLOSURE CONNECTIONS				
	REV	DESCRIPTION	BY	DATE	CHECKED BY: APPROVED BY:			DATE	ECO #	PRODUCT: SE SPIKER		
										CAD FILE: 97551011DWG	SHEET: 6 OF 24	SCALE: NTS LOCATION:






	SEE LAST SHEET FOR REVISION HISTORY					THIS DRAWING AND DESIGN, IS THE PROPERTY OF NORDCO INC. AND IS NOT TO BE REPRODUCED IN WHOLE OR PART, NOR EMPLOYED FOR ANY PURPOSE OTHER THAN SPECIFICALLY PERMITTED IN WRITING BY NORDCO INC. THIS DRAWING LOANED AND SUBJECT TO RETURN ON DEMAND	<b>D</b> SIZE ALL DIMENSIONS IN INCHES IMPLIED TOLERANCES FRACTION ± 1/8 .X ± .06 .XX ± .03 .XXX ± 0.10	TITLE: MCC ENCLOSURE CONNECTIONS				
	REV	DESCRIPTION	BY	DATE	CHECKED BY: APPROVED BY:			DATE DATE	ECO #	PRODUCT: SE SPIKER		
										CAD FILE: 97551011DWG	SHEET: 6 OF 24	SCALE: NTS LOCATION:

# Intended Function/config



	THIS DRAWING AND DESIGN IS THE PROPERTY OF NORDCO INC. AND IS NOT TO BE REPRODUCED IN WHOLE OR PART, NOR EMPLOYED FOR ANY PURPOSE OTHER THAN SPECIFICALLY PERMITTED IN WRITING BY NORDCO INC. THIS DRAWING LOANED AND SUBJECT TO RETURN ON DEMAND					<b>D</b> ALL DIMENSIONS IN INCHES IMPROVED TOLERANCES		TITLE: MOBILE CONTROLLER OUTPUTS - MAIN BOARD			
	FRACTION X XX XXX	± 1/8 ± .05 ± .03 ± 0.10	PRODUCT: SE SPIKER CAD FILE: 97551003	SHEET: 28 OF 61	SCALE: NTS LOCATION: MCC	REV A					
REV	DESCRIPTION	BY	DATE	CHECKED BY: APPROVED BY:	DATE	ECC #					


# Observed Function/cont'd



	OAK CREEK WISCONSIN	REV	DESCRIPTION	BY	DATE	CHECKED BY:	DATE	ECO #	THIS DRAWING AND DESIGN IS THE PROPERTY OF NORDCO INC. AND IS NOT TO BE REPRODUCED IN VEHICLE OR PART, NOR EMPLOYED FOR ANY PURPOSE OTHER THAN SPECIFICALLY PERMITTED IN WRITING BY NORDCO INC. THIS DRAWING LOANED AND SUBJECT TO RETURN ON DEMAND.	<b>D</b> ALL DIMENSIONS IN INCHES IMPLIED TOLERANCES	TITLE: MOBILE CONTROLLER OUTPUTS - MAIN BOARD		
										FRACTION X XX XXX	± 1/8 ± .005 ± .03 ± 0.10	PRODUCT: SE SPIKER CAD FILE: 97551003	SHEET: 28 OF 61

2000  
2001  
2002  
2003  
2004  
2005  
2006  
2007  
2008  
2009  
2010  
2011  
2012  
2013  
2014  
2015  
2016  
2017  
2018  
2019  
2020  
2021  
2022  
2023  
2024  
2025  
2026  
2027  
2028  
2029  
2030  
2031  
2032  
2033  
2034  
2035  
2036  
2037

CNTRL2001



PIN NO.	FUNCTION	PIN NO.	FUNCTION	PIN NO.	FUNCTION
1		33	HYDROSTAT REVERSE	65	CANBUS 4 LOW
2	GROUND	34	GAUGER BUGGY UP	66	SENSOR SUPPLY 1
3	POWER SUPPLY SLOT A	35	FRONT PROPEL SPEED PULSE 1	67	MIDDLE REVERSE PEDAL
4	GROUND SLOT B	36	SPIKE RAM EXTEND SWITCH	68	RIGHT FORWARD PEDAL
5	OUTPUT POWER SUPPLY	37	SPARE INPUT	69	ELECTRIC INTERLOCK READY
6	POWER SUPPLY	38	SPARE OUTPUT	70	E-STOPS READY
7	CANBUS 1 HIGH	39	SPARE OUTPUT	71	ALARM BUZZER
8	CANBUS 3 HIGH	40	POWER SUPPLY SLOT B	72	HYDROSTATIC BRAKING ACTIVE
9	MIDDLE BRAKE PEDAL	41		73	REAR PROPEL SPEED PULSE 1
10	RIGHT REVERSE PEDAL	42		74	FORWARD TRAVEL SWITCH
11	LEFT FORWARD PEDAL	43		75	DUST COLLECTION ON SWITCH
12	MCC FRONT E-STOP PRESSED	44	RS232 TX	76	SPARE INPUT
13	FORWARD MOTION ALARM	45	CANBUS 2 HIGH	77	SPARE OUTPUT
14	REVERSE MOTION ALARM	46	CANBUS 4 HIGH	78	AIR COMPRESSOR BYPASS VALVE
15	REAR PROPEL SPEED PULSE 2	47	ANALOG GROUND	79	
16	REVERSE TRAVEL SWITCH	48	MIDDLE FORWARD PEDAL	80	
17	SPIKE BUSTER SWITCH	49	LEFT BRAKE PEDAL	81	
18	SPARE INPUT	50	MCC RIGHT E-STOP PRESSED		
19	SPARE OUTPUT	51	FRONT PROPEL MOTOR ENGAGE		
20	SPARE OUTPUT	52	REAR PROPEL MOTOR ENGAGE		
21		53	GAUGER BUGGY DOWN		
22		54	FRONT PROPEL SPEED PULSE 2		
23		55	SPIKE RAM RETRACT SWITCH		
24		56	BRAKE RELEASE		
25	IGNITION	57	SPARE INPUT		
26	CANBUS 1 LOW	58	SPARE OUTPUT		
27	CANBUS 3 LOW	59	AT GAUGE LIGHTS		
28	GAUGER BUGGY RETRACT	60			
29	RIGHT BRAKE PEDAL	61			
30	LEFT REVERSE PEDAL	62			
31	MCC LEFT E-STOP PRESSED	63	RS232 RX		
32	HYDROSTAT FORWARD	64	CANBUS 2 LOW		



REV	DESCRIPTION	BY	DATE	CHECKED BY:	DATE	ECO #

THIS DRAWING AND DESIGN IS THE PROPERTY OF NORDCO INC. AND IS NOT TO BE REPRODUCED IN WHOLE OR PART, NOR EMPLOYED FOR ANY PURPOSE OTHER THAN SPECIFICALLY PERMITTED IN WRITING BY NORDCO INC. THIS DRAWING LOANED AND SUBJECT TO RETURN ON DEMAND.		<b>D</b> <small>SIZE</small> ALL DIMENSIONS IN INCHES	TITLE: MOBILE CONTROLLER LAYOUT PRODUCT: SE SPIKER
<small>IMPLIED TOLERANCES</small> FRACTION .X .XX .XXX	± 1/8 ± .06 ± .03 ± 0.10	CAD FILE: 97551003	SHEET: 20 OF 61 SCALE: NTS LOCATION: MCC
			REV A