

601AF 5-9-19

~~ND44AT~~ Crusing FL350 -25°C 1hr 20 min w/o flight  
Up to this point there were no problems w/ the flight. All  
indications were normal.

I was fine tuning the Ⓛ engine in an attempt to settle N,  
fan speed at or near 103%. I added thrust, N<sub>i</sub> went up as  
expected, but then moments later would creep down. After  
this happened a few times, all gauges still read regular. About  
one minute later Ⓛ engine began to spool down very slowly. It  
didn't shut down all at once. After about another minute, engine  
began descent with Ⓛ engine at idle power setting. I noticed  
no oil pressure on Ⓛ engine and shut it down entirely.

Several minutes pass and we are descending into KSAV  
without incident. I'm descending with the Ⓜ engine at roughly  
65% fan speed in order to maintain pressurization. We're  
getting ready for ~~solo~~ a single engine approach and all is going  
smoothly. At somewhere around 8,000', feet the right engine  
became unresponsive and began spooling down as well.  
I declared an emergency and we were RV to say 19 KSAV.  
ATC lost our altitude as well as our Altimeters quit  
displaying altitude. We still had radios. I recycled  
the battery switch, at which time, the altimeters returned

to normal and ATC could again read our altitude.

Some time between 6k' & 8k', we did attempt to restart  
B engine. It had no response, so was secured and  
attention went to gliding into airport after locating airport.

By [REDACTED]

[REDACTED]  
Assigned Captain

N744AT IFR KAPP-KIAG

2:30 PM 5-4-17 @ SAV

ABOUT 1+20 INTO THE FLIGHT @ 35,000 FEET LEFT ENGINE WILL NOT HOLD SET % VARYING 2-3% THEN A GRADUAL ROLL BACK OVER 2MIN TO 27-29%. AFTER CONFIRMING WITH ATC WE STARTED DESCENT TO 15,000 FT. LEFT ENGINE 28% RT 45% FOR DESCENT. CABIN PRESSURE WOULD NOT HOLD AND WE NEED MORE POWER ON RIGHT ENGINE. WHILE INCREASING POWER ON RIGHT ENGINE IT STARTED TO BE ERATIC ON % DISPLAY. THE LEFT FILTER BYPASS DID NOT EVER COME ON. THE RIGHT FILTER BYPASS DID COME ON. AT 8,500 FEET, 13 MILES FROM AIRPORT BOTH ENGINES WERE OFF. FIRST THE LEFT WAS SHUT OFF DUE TO LOW OIL PRESSURE THEN THE RIGHT ENGINE. ALL THREE ALTIMETERS WENT OFFLINE AT ABOUT 6,000 FEET AND RE-SETTING THE MASTER ALTIMETERS BROUGHT THEM BACK AT 5400 FT. A STRAIGHT IN APPROACH WAS MADE TO SAV RWY 19. LANDING WAS VERY GOOD. TOTAL FLIGHT TIME 1:34. AN AIRSTART WAS TRIED ON THE RIGHT ENGINE WITH NO SUCCESS AT ABOUT 10,000 FEET. NO Joy

[REDACTED]

By Gerald Downs