

## Report of Findings

**Date of accident:** May 6 2019  
**Location of accident:** Chelan Lake Airport  
**Aircraft registration:** N825PW  
**Aircraft type:** Just JA30  
**Engine type and S/N:** Rotax 914 UL S/N 7683354  
**NTSB or TSB file number:** WPR19FA133  
**Date of Report:** May 7 2019  
**File number:** 2019-026

### Original Accident Location:

Chelan Lake Airport

### Preliminary engine inspection

Inspection carried out at: Lake Aero

Date of inspection: May 7 2019

### Persons in attendance

#### Oversight by NTSB/FAA personnel:

Mrs. Maja Smith out of the Western Regional NTSB Office.  
Mr. Christopher A. Lang Spokane Flight Standards District Office [REDACTED]

Additional attendees:

William D. Mutter Owner of Lake Aero [REDACTED]

## **ENGINE**

Rotax Engine Model Number; Rotax 914UL

Rotax engine serial number; 7683354

## **OVERVIEW**

- See NTSB preliminary report
- Crashed shortly after take-off (See airport video footage of accident)

### **Initial condition of Engine as presented prior to detailed inspection**

- Engine, engine mount and firewall all separated from wreckage
- Substantial damage from Post impact fire
- Both carbs displaced from intake manifolds
- Ignition system partially consumed by post impact fire
- Coolant and oil hoses consumed by post impact fire
- exhaust system complete and remained attached
- Oil tank still mounted to fire wall

## ***Detailed Engine Inspection***

### **Spark Plugs & Spark plug Caps**

- Plug wires and caps consumed by fire
- Plugs examined after cylinder heads were removed.
- NGK DPR9EA 9
- All plugs appeared normal with no anomalies noted

### **Ignition System**

- Modules were consumed by post impact fire.
- Coils were partially consumed by post impact fire
- Ignition wires consumed by post impact fire

### **Fuel System including carb inspection and fuel lines**

- Both carbs were found displaced from intake manifolds and substantially damaged from post impact fire
- 1/3 Carb main jet was clear of obstruction and size 156
- 2/4 Carb main jet was not present for inspection and the mixing tube was substantially damaged from fire.
- Fuel pressure regulator was found sitting on top of engine. Only the stainless steel fuel line was found still attached.

**Fuel supply including fuel pump**

- Electric fuel pumps were not present during examination and could not be examine

**Lubrication system**

- All rubber oil lines were consumed by post impact fire
- Oil pump appeared to be in normal operational condition with no anomalies seen
- Stainless steel oil lines still intact and connected to oil pump and turbo

**Cylinder and cylinder head**

- #1 Cylinder head – Removed and inspected. No anomalies seen
- #2 Cylinder head – Removed and inspected. No anomalies seen
- #3 Cylinder head – Removed and inspected. No anomalies seen
- #4 Cylinder Head – Removed and inspected. No anomalies seen

Removed all cylinders and inspected. No anomalies seen with cylinders and cylinder bores.

Examined all pistons. No anomalies seen with any of the pistons.

**Rotary Valve train**

Valve train inspected and no anomalies seen

Removed most of the hydraulic lifters (the ones that were free of melted o-ring) and inspected with no anomalies seen

**Cooling system**

Coolant lines consumed by the post impact fire

Coolant pump appeared to be normal condition

**Air Filter system**

- Consumed by post impact fire

**Exhaust system**

Removed exhaust pipe from Cylinder heads. No anomalies seen with exhaust system and it appeared to be in good condition.

**Gearbox**

Removed gearbox from engine. Inspected the internal components. No anomalies seen with gearbox and evidence of oil lubrication was seen. The gearbox would not rotate normally due to the damage from the post impact fire.

**Crankcase and crankshaft**

The crankcase appeared to be in normal condition and undamaged. Crankshaft was inspected through the piston bore holes. No anomalies seen with the crankshaft

**Engine Maintenance and Journey Log (review all logs and note all maintenance entries, engine times, service history and bulletin compliance and retain copy for records or note lack of);**

Copy of log books provided

**Summary**

No mechanical anomalies were found with the engine components that were examined