



1
2 **ERA23FA001**

3 **October 1, 2022**

4 **11:17 pm local CDT**

5 **Cessna 172**

6 **NTSB EXAM NOTES**

7
8 **NTSB IIC: McCarter, Aaron**

9 **Textron/Cessna: Gibson, Kurt**

10 **Lycoming: Harsanyi, David**

11 **History**

12 On October 1, 2022, at 2317 central daylight time, a Cessna 172S, N262TA, was substantially
13 damaged when it was involved in an accident near Hermantown, Minnesota. The commercial
14 pilot and two passengers sustained fatal injuries and a married couple occupying a house
15 sustained minor injuries. The airplane was operated as a Title 14 Code of Federal Regulations
16 Part 91 personal flight.

17 The pilot (commercial instructor) and two passengers were all friends, and they were attending a
18 wedding in Duluth. The flight departed 1015 am local time and landed about 11:30 am local.
19 They departed South St Paul Municipal Airport-Richard E Fleming Field (SGS), South St Paul,
20 Minnesota, about 1015 and flew about 130 nautical miles to Duluth International Airport (DLH),
21 Duluth, Minnesota.

22 When the wedding/reception was over or when they choose to leave, they arrived back at the
23 airplane and departed back to their home airport SGS, about a 1 hour and 15 minute flight.

24 Weather at the time was Mist, low ceiling, clouds and reduced visibility (LIFR) and nighttime
25 conditions. Pilot had his instrument rating and was current.

26 Automatic Dependent Surveillance–Broadcast (ADS–B) data indicated the flight departed DLH
27 runway 09 at 2312, then turned on a southerly track while climbing to about 1,750 ft mean sea
28 level (msl) about 1 mile south of the departure runway. The airplane entered a tight teardrop turn
29 to the left while climbing through 2,000 ft msl, then continued the turn 360° until it was on a
30 track of about 270° at 2,800 ft msl, then began a descent that continued until powerline and
31 house impact. ATC was communicating with the pilot throughout taxi, clearance and takeoff.
32 The pilot was on an IFR flight plan. (Confirmed)

33 Personnel Information

34 Pilot: Tyler J. Fretland

35 Left front seat occupied; Comm/Flight Instructor/Instrument Airplane; ASEL) Per SPAS 0 hours
36 since last medical (First Class) on April 2, 2019 but as of the accident he had about > 300 hours
37 based on his hard cover logbook discovered at the accident site; the last entry was 3/1/2022 with
38 a total of 296.3 total hours and a note “moved to electronic logbook” Unknown currently how
39 much actual instrument time he has. Requesting his Foreflight logbook.

40 Airplane Info

41 According to FAA records, the airplane was manufactured in 2002, and was registered to
42 SVETFUR AVIATION LLC. In addition, it was equipped with a Lycoming IO-360-L2A. It was
43 a fuel injected 180 hp engine with a fixed pitch propeller.




Figure 1 Airframe and Engine Records.

45
46 Maintenance records discovered at the operator in Duluth, MN. Brought up to accident site by FAA
47 Inspectors. Last mx records. Note the day of last maintenance. It was the day before the accident. Check
48 this out in a little more detail. Note to Lycoming and Textron.

49 Weather

50 Location.....: KDLH Day of month.....: 02 Time.....: 03:55 UTC Wind.....: true direction
51 = 080 degrees; speed = 10 knots with gusts of 19 knots Visibility.....: 5 Statute Miles
52 Weather.....: mist Cloud coverage.....: overcast (8 oktas) at 200 feet above aerodrome level
53 Temperature.....: 09 degrees Celsius Dewpoint.....: 08 degrees Celsius QNH.....: 30.38
54 inHg Remarks site is automated and has a precipitation sensor Sea Level Pressure...: 1029.6 Mb
55 Temperature.....: 9.4 degrees Celsius Dew Point.....: 8.3 degrees Celsius
56 Weather study requested from AS-30 (WX)

57 **Wreckage and Impact**

58 The aircraft's initial impact point was electrical power wires. There was a small electrical arc fire
59 on the roof of the house that was extinguished by the time of arrival.

60 The airplane impacted the front facing roof of a two-story house at an elevation of about 1,300 ft,
61 and on a heading of about 208°. The airplane was in a 35° left bank as it impacted the structure
62 based on the wing and left landing gear imprint on the house as it passed through. It passed
63 through two upstairs bedrooms as the occupants of the house, a husband and wife slept, and then
64 struck terrain before coming to rest inverted between a vehicle and a detached garage. There was
65 no post-crash fire. The wreckage path was oriented on a magnetic heading of 205° and was about
66 200 ft in length. All major components of the airplane were located within the wreckage site. The
67 left wing was found in the front of the house. The wife reported that she pulled red glass out of
68 her hair. (Nav/Position Light) The occupants suffered minor injuries.




Figure 2 Front of house damage

69
70



71
72
73

Figure 3 Back yard of house damage with airplane model and approx. angle for reference.

74 The main wreckage including the fuselage and cockpit came to rest between a bard and a pickup
75 truck. There was no occupiable living space in the cockpit. The entire wreckage was covered in a
76 brown/tan paper like debris consisting of old blown insulation.

77 Safety brief to Cessna and Lycoming. There are hundreds of pieces of broken timber and wood
78 with nails pointed up plus insulation debris (respirators)

79

80 **Propeller**

81

82 The two blade, fixed pitch propeller remained attached to the propeller flange; however, the
83 propeller flange had broken free from the rest of the crankshaft. Both propeller blades were bent
84 aft and had chordwise scratches, gouges, and some leading-edge gouging. Minor S-bend.

85

86 **Engine**

87

88 The engine separated during impact and was found lying next to the main wreckage in front of
89 the truck. Engine impact damaged- No. 2 cyl. No holes in the case. Damaged rocker-box covers.
90 Several 720 ° of rotation were conducted through the accessory drive and crankshaft control
91 continuity was established. All rockers, valves and most pushrods appeared normal and were well
92 lubricated. Each of the cylinder was tested for compression and suction. Several pushrods damaged.
93 Champion Spark Plug Chart: All spark plugs normal wear.

94
95



Figure 4 Engine prior to internal examination



Figure 5 Spark Plugs

96
97



Figure 6 Engine with valve covers off.

99
100



101

102

Figure 7 Borescope of No. 4 Typical of all 4 pistons, valves, and cylinders.

103

104 Both wings had separated from the fuselage. The left landing gear strut had broken free from its
105 attach point and was found with the main wreckage. The nose gear strut had impact separated
106 from the aircraft and was located inside the impacted house.

107

108 Flight control continuity was established for all the flight controls through breaks that were
109 consistent with tension overload.

110

111 The empennage separated from the fuselage and was found in front of the barn. It was in
112 remarkably good condition. All the flight control surfaces remained attached and functioned
113 normally when manually operated.

114



115

116

Figure 8 Tail/Empennage

117 The elevator cables were fracture separated with breaks consistent with tensile overload.

118

119 The rudder cables remained attached to the rudder bell crank and to the rudder pedal attach
120 points. The elevator trim actuator had a measurement of approximately 1.28” which corresponds
121 with a neutral trim setting.

122

123 The flap actuator had a measurement of about .375” which corresponds with the flaps being in
124 the retracted position.

125

126 **Fuel**

127

128 The left and right fuel tanks were breached.

129 No fuel was recovered during examination and recovery. There was a faint smell of fuel
130 consistent with aviation fuel.

131 Both fuel tank caps had broken free from their respective tanks and were not located.
132 examination.

133 Four of the fuel tank pickup screens had some debris consistent with the residential insulation
134 that covered the entire scene.

135

136 The fuel selector was in the right position and air was blown through the selector and the valve
137 was unrestricted.

138

139 **ELT**

140

141 The ELT was found and remained attached to the frame and antennae. It was in the auto position
142 and was illuminated and sending out the “ping” Turned off unit.

143

144

145 **Cockpit documentation Instrument panel severely damaged**

146

147 Airspeed indicator was pointed to 130 in the yellow.

148 Altimeter indicated 1,500 ft msl and 30.3 hg.

149 Vertical Speed indicated negative about 2,000 fpm.

150 RPM was fractured and the needle was pointing to 900 RPM and showed 0612.1 hours.

151 Master switch was indicating on.

152 Avionics master was indicating off.

153 Magnetos: the key was fractured, and it was indicating right mag.

154 Alternate air was off.

155 Throttle was at about 70% in, but the control wires were pulled out of the engine and breather.

156 Mixture full rich

157 Trim was indicating neutral.

158 EGT and Fuel flow off scale

159 Nav 1 and Nav 2 off scale broken needles. OBS was set to 050 degrees on #1 and 350 degrees on
160 # 2

161 Heading indicator 016 degrees

162 COM and Radios off scale, broken and unknown.

163 Rotating beacon: Off
164 Landing Light: On
165 Taxi: On

166
167

168 **Gyros and primary flight instruments**


169

170 The attitude indicator, directional gyro, and turn coordinator: The gyros were capable of smooth
171 rotation and rotational scoring was noted on the electrically powered turn coordinator gyro, there
172 was no rotational scoring noted on the air powered attitude indicator gyro or directional gyro.
173 The vacuum manifold was examined, and the diaphragms displayed normal operating signatures.
174 All manifold and hose lines were free of breaks and leaks not impact related. Continuity was
175 established and air flowed freely and operated the gyros.

176
177



178



179



180



182



Figure 9 Vacuum pump and gyros. First photo at top prior to disassembly

184 **Seat Belts**
185

186 Each of the seats had a three (3) point safety belt system installed and each of them were cut by
187 first responders for body extraction however, only the pilot's seatbelt was confirmed to being
188 worn and buckled. The remaining seats, the buckles were found in the buckled position or had
189 been damaged.

190

191 **Muffler/Heat Exchanger/Shroud**

192

193 Checked to ensure muffler was not pre impact compromised (CO) No pin holes or cracks or
194 exposed seams observed. Muffler Assembly appears relatively new.

195

196



197
198

Figure 10 Muffler and heat shroud

199

200 Overall, View of Accident Site



201

202 *Figure 11 View of accident site take from exit hole of second story of house.*