# Operations Group Chairman Factual Report Attachment 4 - Emergency Procedures - Fuel System

**WPR09MA159** 

### 3.17 FUEL SYSTEM

### 3.17.1 LOW FUEL PRESSURE

Indication: FUEL PRESS CAWS CAUTION

1. Power Reduce to minimum to sustain flight

2. Fuel pumps ON

NOTE

Monitor the fuel state if the LH and RH FUEL PUMPS are set continuously on. If necessary, set the FUEL PUMPS on the emptier side to AUTO.

If FUEL PRESS caption remains ON:

3. Aircraft Land as soon as possible

Retain glide capability to landing area if possible.

NOTE

Fuel low pressure will normally cause the fuel pumps to come on automatically.

In this case the Indication are both FUEL PUMPS running continuously, cycling OFF/ON every 10-15 secs.

PUMP

4. Fuel Pumps

ON

5. Aircraft

Descent to warmer air:

(A possible cause is the fuel filter

blocked with ice crystals).

### 3.17.2 FUEL PUMP FAILURE

Indication: No FUEL PUMP advisory when fuel pump(s) ON.

1. Fuel pump(s) AUTO

\_\_\_\_\_

2. FUEL PUMP LH circuit breaker (Battery busbar)

Reset

 FUEL PUMP RH circuit breaker (Generator 1 bushar) Reset

(Generator 1 busbar)

ON

4. Fuel pump(s)

ON

5. L and R FUEL PUMP advisory

Check

Issued: March 30, 2001 Revision 2: February 28, 2005 Report No: 02211

3-47

## SECTION 3 EMERGENCY PROCEDURES



6. Fuel pump(s)

AUTO

If not successful monitor fuel state. For fuel imbalance refer to 3.17.3.

#### 3.17.3 AUTO FUEL BALANCING FAILURE

Indication:

EIS analogue fuel gauges indicate 3 segments or more difference between left and right without automatic activation. Possibly aileron deflection required for wings

level flight, especially at low speed.

1. Fuel Pump (fuller side)

ON

2. Fuel state

Monitor. If difference cannot be balanced, land as soon as practical

3. When fuel balanced

Fuel Pump AUTO

### 3.17.4 SUSPECTED FUEL LEAK

1. Fuel pump (on leaking side)

ON

2. FUEL PUMP CB (on good side) (Battery or Generator 1 busbar)

Pull

3. Fuel state

Monitor

Land as soon as practical.

### 3.17.5 LOSS OF FUEL QUANTITY INDICATION

Indication:

EIS display goes blank.

The automatic fuel balancing system will be inoperative.

Land as soon as practical.

Report No: 02211

3-48

Issued: March 30, 2001 Revision 2: February 28, 2005