



COLGATE-PALMOLIVE COMPANY

333 Industrial Avenue  
Teterboro, NJ 07608  
Telephone [REDACTED]  
Fax 201-2 [REDACTED]

light perations

January 8, 1999

BY PRIORITY MAIL

Hon. James E. Hall  
Chairman  
National Transportation Safety Board  
490 L'Enfant Plaza East, SW  
Washington, DC 20594

**RE: BK-117 Accident of April 15, 1997**  
**Reg. No. N909CP NTSB ID NYC97FA076**

Dear Chairman Hall:

I recently advised Investigator-In-Charge Robert Hancock that I had additional information that might be useful to the Board and responsive to the inquiries raised in the recent hearing. Mr. Hancock suggested that I send any such information to the attention of the full Board. I believe the following documents and comments will be helpful to your investigation:

#### RK-117 INSPECTION INTERVALS

As you are aware, aircraft inspection and TBO intervals are regularly increased or decreased based upon aircraft fleet experience. I was recently transferring files between my old laptop into my new one. During that process, I discovered a letter I had sent to American Eurocopter Corporation (AEC) in November of 1990 on the subject of tailboom cracks. Hopefully the attached copy will be useful in your search for data supporting the 1,200-2,400-3,600 hour intervals on the BK-117.

Informal information obtained within the community of BK-117 operators indicates that repair procedures were approved by MBB Helicopter Corporation, West Chester, PA for one or more unidentified aircraft several years ago. It is also our understanding that repair procedures were approved by AEC for two Arch (St. Louis) BK-117s some months before our accident. As far as we know, this information was not officially disseminated by the manufacturer. The detailed technical information on those approvals is not available to us, but may prove useful in evaluating that component's fleet history.

#### VERTICAL FIN SPAR CRACKS

We are in agreement with the Board's request for detailed information concerning the spar cracks on all other BK-117s. We believe the spar crack to have been the primary cause of the catastrophic failure of the vertical fin. Since we had performed a detailed inspection of that area during the aircraft's previous 3,600-hour inspection (590.9 flight hours prior to the accident), it seems obvious that our spar crack developed in less than 100 hours. As we stated in an earlier

submittal, we believe that it is critically important that the flight hour and cycle histories of those other BK-117s be reviewed in detail. The FAA/Eurocopter mandated repair scheme (ASB-MBB-BK117-30-106) must be confirmed adequate for the long-term safe operation of the active BK-117 fleet.

Review of those histories, in conjunction with the structural data supporting the repair scheme, should also clearly illustrate that the repair scheme is unrelated to a rivet problem. It is specifically targeted at a spar structural deficiency. This deficiency is a result of the long history of that tailboom design. Several aircraft gross weight increases and the repeated modifications installed to address other cracking problems over the course of the last fifteen years have apparently caused vibrations and structural stress to focus in the area that failed in N909CP. The blind rivets played no primary role in the failure. It is inconceivable that the vertical fin would have suffered a catastrophic failure without first experiencing the failure of the spar, its primary structural component.

#### USE OF BLIND RIVETS - COMMON INDUSTRY INFORMATION

We were concerned that during Mr. Hancock's presentation to the Board, he described our use of blind rivets in the replacement of the yaw SAS mount support as "improper". As outlined below, there is a significant body of literature, including FAA regulations, that supported the use of blind rivets in the repair. Mr. Hancock's Factual Report (*italicized*) included the following comments:

1. AC 43.13-1A, Sec 3, Par 99, RIVETING c. "...unless the lower strength is adequately supported by the structure. Five paragraphs earlier, the report noted: *The rivets /32 diameter rivets that were oversized by 1/64 of an inch.*"

I suggest the use of oversized rivets meets this recommendation, especially in light of the following:

2. AC 43.13-1A, Ch 5, Sec 1, Par 2, j. "*Blind rivets on the MS-20600 through MS-20603 structure may be replaced by 3/32 inch diameter rivets. NA 1398, 1399, 1403 and 1739 rivets may be replaced by blind rivets or aircraft manufacturer's rivets.*"

3. The report also notes: "*At the Textron Aircraft Fasteners and Hardware AA failed to properly mention the rivet substitution.*" They apparently failed to recall or mention:

Cherry Aerospace Products advertising contained in World Aviation Directory (Summer 1995) states: "The Bulbed CHERRYLOCK is a high strength blind rivet system particularly suitable for high vibration areas.. ...Conforms to NAS 1740 specification and NAS1738..."

Another Cherry TEXTRON chart titled "Interchangeability As Adopted By Industry" lists P/N CR3243 as interchangeable with NAS1738B.

A Skybolt Aeromotive Corporation 1997 catalog, page 10, contains a section on **Cherry Structural Blind Rivets** and states: "The CherryLock rivet was developed to gain strength ratings equivalent to solid AD rivets.. ... The CherryMax rivet was developed to replace

the CherryLock.. The Oversize CherryMax has strength ratings that meet or exceed solid AD rivets." It continues: "CherryMax are structural rivets". "CherryMax can be substituted for.. CherryLock" and "Cherry Max is an approved substitute for Solid Rivets in a structural application."

Those documents are references commonly circulated in the industry and were available at the time of our repair. They remain legitimate references today. They make it abundantly clear that our maintenance personnel were correct in their choice of the CherryMax, had no cause to consider the use of these rivets "improper", and needed no further approvals prior to their use.

4. The Factual Report also notes *That the majority of the rivets used with heavy SAS mounting support are easily accessible with a bucking bar.* That statement greatly underestimates the degree of technical difficulty and physical dexterity required for this procedure.

#### CONCLUSION

If the information you have received from Eurocopter and Cherry Textron (indicating that blind rivets are inferior to solid rivets in certain applications) is accurate, then we fully agree that the rivet information currently available in the aviation system is incomplete, outdated, and incorrect. The ultimate correction of this possible discrepancy could have a major beneficial effect on aviation safety on a global scale.

It is critically important, however, that this discovery not overshadow the specific cause of this accident: The fatigue failure of the vertical fin's primary structural component.. The vertical fins are.

I welcome your review of these items and the copies of the supporting documents. I remain available for further contact and discussion at your convenience. Thank you for the care and attention the Board is giving to this accident and investigation.

Sincerely,



George M. Jones  
Manager Corporate Aviation Services

cc: Hon. Robert Francis, Vice Chairman  
Hon. John Hammerschmidt, Member  
Hon. John Goglia, Member  
Hon. George W. Black, Member  
Mr. Gene Sundeen, Deputy Director, Regional/Technical Investigations  
Mr. Robert Hancock, Investigator

(All by Priority Mail)

November 29, 1990

Mr. Donald Lambert  
MBB Helicopter Corporation  
P.O. Box 2349  
West Chester, PA 19380

Dear Don:

The discovery of cracks in the tailboom and tailcone of our BK-117 B-1 and the extent of the damage, including the report of a twist in the tailboom concerns us greatly. Having experienced somewhat similar tailboom cracks in our BK-117 A-3 at the 3,000-hour point, and in spite of the greater take-off power available in the B-1, we are unable to understand how such greater damage could occur to our B-1 with only 467 flight hours.

I request that you investigate the following areas:

1. Do you have any indication that other B-1s (or A-4s) in the commercial fleet are experiencing tailboom/tailcone cracks at a similarly accelerated rate as compared to A-3s?
2. Have you had any previous reports of tailboom twists If so, in what aircraft
3. If you have not had such reports, is it possible to examine a tailboom for such a twist while installed on an aircraft
4. Should that be possible, I would request that our A-3 be inspected in order to help determine whether a twist could be caused simply by the higher take-off power limits of the B-1, or alternatively, by long-term use of the lower A-3 take-off limits. I suspect that similar inspections on other B-1s in the fleet would assist in that determination.

Being familiar with our operation, I am sure you realize that although our operating profile is demanding, our procedures are consistently conservative and conscientious. It is therefore imperative that this situation be promptly investigated in order to allow for a rapid correction of the origin of the defect, be it design or procedure. Our long-term confidence in the quality of the MBB product line is a critical part of our operation.

Best regards,

George M. Jones  
Chief Pilot

---

1997


PRICE \$4.

# Skybolt

FAN-MS-NAS

FASTENERS

551 North Park Avenue • Apopka, Florida 32711 • (407) 889-6133



Sales 800-223-9633  
FAX (407) 889-8333  
Minimum Purchase Requirements

## CHERRY Structural Blind Rivets



Traditional "Cherry Rivets" were originally designed with a knob stem, the most commonly used was the CR162/CR163 MS Series. These rivets require special tooling to install, and leave a protruding break stem that must be trimmed. Cherry developed the CR9162/CR9163 MS Series rivet to replace the knob stem, thus simple pulling tools could be used. The CherryLock rivet was developed to gain strength ratings equivalent to solid AD rivets. The CherryLock rivet required double action pulling tools to install. CherryLock rivets are all oversize diameters. The CherryMax rivet was developed to replace the CherryLock, required simple pulling tools to install, and is available in Nominal and oversize Shank. The Oversize CherryMax has strength ratings that meet or exceed solid AD rivets. The drawback to the CherryMax is removal. The break stem is constructed of 8740 Alloy Steel and is very difficult to drill out. The NEW Cherry INTERMAX rivet is manufactured to NAS1710 and NAS1721 specs, has strength ratings similar to the Nominal CherryMax, but uses a 7075 aluminum break stem, thus it can be drilled out for removal. The InterMax also has greater grip ranges than previous rivets.

Considerations for using Cherry Blind Rivets:


- 1) CherryMax and InterMax are structural rivets, Cherry Q or P Rivets are not
- 2) Panels must be clamped before installing CherryMax or InterMax. These rivets are not designed for excessive panel "Takeup"
- 3) CherryMax can be substituted for specifications calling for CR162/CR162 or CherryLock
- 4) CherryMax is an approved substitute for Solid AD Rivets in a structural application
- 5) InterMax should be considered for all Non Structural or Semi Structural applications such as windshield frames or loose out panels

SKYBOLT only supplies factory New Cherry products with full traceability, no surplus, no sweepings, no aftermarket parts

art#	Size	Grip Limit	Shear Lb	Tensile Lb	25 Bag Each	100
CR3212-4-2	1/8	.063-.125	411	285	\$0.9	\$49.00
CR3212-4-3	1/8	.126-.187	511	285	\$0.69	\$49.00
CR3212-4-4	1/8	.188-.250	511	285	\$0.9	\$49.00
CR3212-4-5	1/8	.251-.312	411	285	\$0.70	\$51.17
CR 212-5-2	5/2	.065-.125		445	\$0.70	\$54.00
CR 212-5-	5/2	.126-.187	714	445	\$0.70	\$54.00
CR 212-5-4	5/2	.188-.250	824	445	\$0.72	\$55.20
CR 212-5-5	5/2	.251-.312	1012	445	\$0.7	\$58.10
CR3212-5-6	5/2	.313-.375	1010	445	\$0.7	\$ 0.90



# RIVETS




Cherry G-704-40SR Split Riveter utilized In the Sikorsky robot

Sikorsky installing CherryMAX rivets with a robot in production of the SH-60B Seahawk. CherryMAX is the ideal fastener for robotic/automatic blind riveting — the pulling head installs six diameters and five different head styles with no tooling changes or adjustments!

C LUMN	COLUMN 2	C LUMN	C LUMN 1	C LUMN 2	C LUMN
NAS PART NUMBER	M7885 PART NUMBER	CHERRYMAX PART NUMBER	NAS PART NUMBER	M7885 ART NUMBER	CHERRYMAX PART NUMBER
NAS1398B & D	M7885/2	CR3713 or CR3223	NAS1739E	—	CR3253
NAS1399B & D	M7885/3	CR3212 or CR3222	NAS1738M	M7885/8	CR3553
NAS1398M	M7885/4	CR3523	NAS1738MW	—	CR3553P
NAS1398MW	—	CR3523P	NAS 739M	M7885/Q	CR3552
NAS1399M	M7885/5	CR3522	NAS1739MW	—	CR3552P
NAS1399MW	—	CR3522P	NAS1768D	M7885/6	CR3243 or CR3253
NAS1919B	M7885/2	CR3213 or CR3223	NAS1769D	M7885/7	CR3242 or CR3252
NAS 92 B	M7885/3	R31 or CR3222	NAS1768M	M7885/8	CR3553
NAS1738B	M7885/6	CR3243	NAS1768MW	—	CR3553P
NAS1738E	—	CR3253	NAS176QM	M7885/9	CR3552
NAS1739B	M7885/7	CR3242	NAS1769MW	—	CR3552P

Hope

**BULBED CHERRYMAX® RIVETS**



Bulbed CHERRYMAX® is a high stem retention locked spindle blind rivet with a visibly inspectable mechanical locking device. CHERRYMAX® blind rivet system retains the large blind head of the bulbed CHERRYLOCK® rivet. Each rivet is supplied with its own installation anvil which eliminates the problems resulting from worn anvils. CHERRYMAX® tooling provides the simplest, most trouble-free installation tooling system. CHERRYMAX® fasteners are currently available in 1/8" through 1/4" diameters in both nominal (NAS1400 sizes) and 1/64" oversize diameters (NAS1740 sizes). The tools utilize one pulling head to install many diameters and head configurations and material combinations. Use with G704 CHERRYMAX® installation tools.

**WIREDRAW CHERRYMAX® 'A' RIVETS**



CHERRYMAX® "A" rivets are shank expansion, locked-spindle, flush fastening rivets meeting the requirements of NAS 1400 specifications and conforming to NAS1398A/1399A code standard pages, but offering non shift tooling installation without hanging pulling head. Use with CHERRYMAX® tooling.

**CHERRY® MAXIBOLT BLIND BOLTS**



The CHERRY MAXIBOLT blind bolt alloy steel and A-286 CRES conforms to MS90353/90354, and MS21140/MS21141, and meets the requirements of MIL-F-81177 and MIL-F-8975 and is listed in QPL851177 and QPL8985. Use with Cherry tools.

**BULBED CHERRYLOCK® RIVETS**



The Bulbed CHERRYLOCK® is a high strength blind rivet system particularly suitable for high vibration areas and dimpled applications, with the strength of a solid rivet. Available in 1/8" through 3/16" diameters. Several head styles and various material strengths and combinations. Conforms to NAS 1740 specification and NAS1738/1739 standards pages. Use with G 700 and G 784 CHERRYLOCK® hydroshift tools.

**WIREDRAW CHERRYLOCK® RIVETS**




Wiredraw holefilling CHERRYLOCK® rivets offer the widest range of sizes (3/32" through 1/4" diameters), materials and strength levels of any blind fastening system. Conforms to NAS1400 specification and NAS1398/1399 standards pages. Use with G 700 and G 784 hydroshift tools.

**CHERRY® MS RIVETS**



Cherry MS self plugging and pull-through rivets and tooling systems have been a reliable standard of the industry since their introduction. Although superseded by the new locked-spindle specifications NAS1400 and NAS1740, Cherry MS rivets are still widely used under MS20600/01/04/05 part numbers. Use G 715 and G 740 installation tools.

**CRES® NUT-PLATE RIVETS**



Cherry® Nut-plate blind rivets are manufactured in 3/32" and 1/8" diameters, steel or CRES, for quickly and economically installing nut-plates to MIL-N-25027 requirements, with one operator. There are no blind side or limited accessibility problems, no damage or distortion to the surrounding material or nut baskets. They are available in pull-through or self plugging styles and may be installed with hand or pneumatic tools. Use G 70 power or G 79 hand tools or hydroshift tools.

