

**TESTING OF PRESSURE RELIEF
VALVE "RV1919"**

Prepared For

**OFFICE OF PIPELINE &
HAZARDOUS MATERIALS SAFETY
NATIONAL TRANSPORTATION
SAFETY BOARD
Washington, DC**

DECEMBER, 2000



STRESS ENGINEERING SERVICES, INC.
Houston, Texas



**National Transportation
Safety Board**

Memorandum

Date February 13, 2001

To: Docket File - DCA-99-MEW08

From: Allan C. Beshore, Investigator-in-Charge

Subject: Report Entitled "Testing of Relief Valve 1919"

The graphical representations contained in the Appendices to this report are in a multi-color format. Information may be lost when these graphs are reproduced in black and white.

Excel data files that can be utilized to reproduce the attached *graphs* in the original multi-color format are available upon request.

TESTING OF PRESSURE RELIEF VALVE "RV1919"

PN1006947CRA

Prepared for

**OFFICE OF PIPELINE & HAZARDOUS MATERIALS SAFETY
NATIONAL TRANSPORTATION SAFETY BOARD**


Washington, DC

Prepared By:



**George R. Ross, Ph.D.
Associate**

Reviewed By:



**S. Allen Fox, P.E.
Principal**



**Stress Engineering Services, Inc.
13800 Westfair East Drive
Houston, Texas 77041-1101**

IBEI 2000

EXECUTIVE SUMMARY

This report describes the tests that were conducted at Stress Engineering Services (**SES**) on September 18 through 22, 2000. The test subject was an 8 inch **ANSI 300#** relief valve. The valve **was** subjected to nondestructive tests which included radiography and the use of an optical probe. The valve was also subjected to a series of pressure tests. The pressure tests were conducted on the valve in the as-received condition, with the pilot valve replaced with a new high pressure (HP) exemplar pilot valve, and with the pilot valve replaced with a new low pressure (LP) exemplar pilot valve. Before installation onto the relief valve, the set point of the HP exemplar pilot valve **was** *checked with a dead weight tester. The original (accident) pilot valve **was** also checked with the dead weight tester. The set-point of the LP exemplar was checked with the dead weight tester and was changed to match the set point of the accident valve prior to installation on the relief valve.

When the accident pilot valve was on the relief valve, pressures in excess of the maximum allowable working pressure of the relief valve could be held on the inlet side. **This** was also the **case** when the LP exemplar pilot valve, with the set point adjusted to match the accident pilot valve, was installed on the relief valve. When the HP exemplar pilot valve was installed on the relief valve, the pressure and AE **data** and the volumes of hydraulic oil exiting the valve indicated that the pilot and relief valves **were** opening. Table 1 contains of **summary of** the pressure **tests** performed.

Once the tests were complete, the pilot valves and the relief valve were disassembled. Neither the nondestructive **examination** nor the disassembly revealed any broken parts. The components in the accident pilot valve were visually the same **as** those in the LP exemplar valve. After inspection, the valves were reassembled.

This report provides a factual account of the test activities and conclusions which **can** be drawn **from** the test **data**. The testing activities are presented in chronological order. Conclusions/observations which **can be** drawn **from** the **test** program include;

1. The components in the relief valve and accident pilot valve were in good condition. There was no damage to any of the components that would prevent the valve from functioning.
2. There were no debris or blockages in the pilot valve, relief valve, pilot sensing lines, or **small** valves in the pilot sensing lines which would prevent the valve from **operating**.
3. When **fitted** with **an** exemplar **HP** pilot valve, the relief valve operated properly. In every case where the inlet pressure exceeded the set-point of the **HP** pilot valve, the pressure **was** relieved.
4. The accident pilot valve **was** configured **as** a low pressure (LP) pilot valve, but **an** attempt had been made to increase the set point **to** that of a high pressure (HP) pilot valve.
5. Increasing the set point of a LP pilot valve to that of a HP pilot valve requires the main spring in the pilot valve to be too compressed to provide reliable operation.
6. It is possible that the accident pilot valve could have failed to operate in service due to the attempt to increase a LP pilot valve set point to that of a HP pilot valve. In order for the relief valve **to open**, the pilot valve must operate. Given the condition of the accident pilot valve, when it was examined at SES, it is conceivable that the accident pilot valve would operate sometimes and not operate at other times. **This means** that the relief valve could operate in **an** unpredictable manner.

Table 1. **Summary** of Pressure Tests on Relief Valve

Description	Pilot Valve Set point (psig)	Results
Relief Valve with Accident Pilot	440 expected (opened 550-600 psig in first dead weight test)	Pressures in excess of 697 psig held on valve inlet side. The valve did not open.
Relief Valve with HP Pilot	617 (650 fully open)	Maximum inlet pressures consistently in 624-668 psig range. AE data indicates opening of pilot and relief valve. Hydraulic fluid measured from relief valve and pilot valve outlets.
Relief Valve with Adjusted LP Pilot Valve	500 (600-650 fully open)	Pressures in excess of set point held on valve inlet side The valve did not open.

TABLE OF CONTENTS

	<u>Page No.</u>
Executive Summary	i
1.0 Introduction	1
2.0 Day 1: Nondestructive Examination	2
2.1 Uncrating the Valve	3
2.2 Discussion of Test Set-up	11
2.3 Radiographs	14
2.4 Optical Probe and Visual Inspection	15
3.0 Day 2: Pressure Test of Accident Valve	22
3.1 Day 2 Meeting	22
3.2 Test of As-received Relief Valve	23
3.2.1 Test Set-up	23
3.2.2 Test Results	25
4.0 Day 3: Pressure Tests of Valve and Dead Weight Tests	28
4.1 Day 3 Meeting	28
4.2 Day 3 Test Set-up	28
4.3 Day 3 Test of As-Received Valve	30
4.4 Dead Weight Tests	31
4.5 Dimensions of Pilot Valves	33
4.6 Disassembly of the Accident Pilot Valve	35
4.7 Day 3 Test of Relief Valve with HP Exemplar Pilot Valve Installed	40
5.0 Day 4: Pressure Tests of Relief Valve with HP Exemplar Valve Installed and Adjusted LP Exemplar Valve Installed	42
5.1 Day 4 Meeting	42
5.2 Test Set-up for Day 4	42
5.3 Test of Relief Valve with HP Pilot Valve Installed	43
5.4 Dead Weight Test to Adjust Set-point of LP Exemplar Valve	45
5.5 Disassembly of HP Exemplar Pilot Valve	46

5.6	Pressure Test of Relief Valve with Adjusted LP Exemplar Valve Installed	48
5.7	Comparison of the LP Exemplar, HP Exemplar, and Accident Pilot Valves	51
6.0	Day 5: Disassembly of Main Valve	56
6.1	Day 5 Meeting	56
6.2	Stereo Microscope Photographs	56
6.3	Reassembly of Pilot Valve	59
6.4	Disassembly of Relief Valve	59
6.5	Review of Notes From September 22, 2000	66
6.6	Reassembly and Transfer of Relief Valve to DOJ	66
7.0	Conclusions	68

APPENDICES

Appendix A: Handouts from September 18,2000

Appendix B: Radiographer Certification

Appendix **C**: Calibration Practices, Calibration Certificates, Hydraulic Oil Specifications, and ~~Test~~ Set-up Information

Appendix D: September 19, 2000 Test Results (Accident pilot Valve)

Appendix E: September **20,2000** Test Results (Accident Pilot Valve)

Appendix F AE Results

Appendix G September **20,2000** Test ~~Results~~ (**HP** Exemplar Pilot Valve)

Appendix **H**:September 21 ,**2000** Test Results (**HP** Exemplar Pilot Valve)

Appendix I September **21, 2000** Test Results (**LP** Exemplar Pilot Valve)

1.0 INTRODUCTION

Stress Engineering Services, Inc. (**SES**) was contracted by the National Transportation Safety Board (**NTSB**) to conduct a series of tests on an eight (**8**) inch **ANSI 300#** relief valve. The relief valve was designated as valve "RV1919". The tests were conducted as part of the **NTSB** investigation of the rupture of an Olympic Pipeline, **Co.** (Olympic) liquid pipeline. The pipeline was located in Bellingham, Washington and ruptured on June 10, 1999. Valve RV1919 was located at the inlet side of the Bayview station for the purpose of relieving pressure upstream of the valve. When opened, RV1919 would divert the flow of product from the liquid pipeline into surge tanks at the Bayview station.

During the **testing** process, there were some changes to the test protocol. **This report** details the tests as they were conducted as **SES**. The activities are listed in chronological order. The tests conducted at **SES** were intended to;

1. Determine the as-received condition of the valve through nondestructive testing
2. Determine if and/or at what inlet pressure the valve would operate in the as-received condition
3. Determine if and/or at what pressure the valve would operate with a new high pressure (HP) exemplar pilot valve installed
4. Determine if and/or at what pressure the valve would operate with a new low pressure (LP) exemplar pilot valve with the set point, as determined by testing on a dead weight tester, changed to match the accident pilot valve installed
5. Conduct dead weight tests of pilot valves to determine set points
6. Disassemble and compare the accident, LP exemplar, and HP exemplar pilot valves
7. Disassemble the main valve and note any abnormalities

28 DAY 1: NONDESTRUCTIVE EXAMINATION

Although the valve was received at **SES** on September 11, 2000 at 2:15 pm, testing did not start until September 18, 2000. When received, the valve was placed in a locked forensic storage unit. The crate was not removed from the storage unit or opened until the test witnesses were present on September 18, 2000.

Day 1 of testing began on September 18, 2000. The first activity was an introductory meeting. During this meeting, Robert Trainor of the **NTSB** gave an overview of the expected test plan. Key points included in his presentation were;

1. all photographs would be taken by **SES** and all parties will be provided copies of the photographs on a **CD**,
2. one set of field notes would be taken and distributed to all parties,
3. the **NTSB** took possession of the valve approximately ten (10) days after the accident,
4. the valve was shipped to **SES**, but has not been opened,
5. after the tests were completed, all parts of the valve would be turned over to the Department of Justice,
6. **NTSB** has purchased two exemplar pilot valves and will retain custody of the exemplar pilot valves,
7. any video tape taken during the test program would be taken without sound, and
8. **SES** is to prepare a report for the **NTSB** and the report will be distributed to all parties.

George Ross of **SES** gave a short presentation of a tentative test schedule and presented the lab safety rules for visitors to the group. The handouts provided by Dr. Ross are included in Appendix A of this report.

2.1 Uncrating the Valve

The first activity following the kick-off meeting **was** the removal of the crate containing the valve from the forensic storage unit and unpacking the valve. Figure 2.1 shows the valve being removed from the forensic storage unit. The sealed crate is shown in Figures 2.2 through 2.4.




Figure 2.1 Removing Crate From Storage




Figure 2.2 Sealed Crate



Figure 2.3 Signed Tags on Sealed Crate



Figure 2.4 Signed Tags on Sealed Crate

The steel bands on the crate were added by **SES** when **the** crate was received. Figures 2.3 and **2.4** show the tags that were signed by Allan Beshore, of the NTSB, when the valve was crated by the NTSB. The **tags** were secure and intact.

Representatives from Fischer-Rosemount noted that the crate was different from the one in which the valve **was** placed when in Bellingham, Washington. The NTSB representatives explained that the valve had to be repacked in order to comply with hazardous material shipping requirements and **was** repacked before shipment to NTSB in Washington, DC.

Once the crate was examined, it was opened and the valve removed. Figures **2.5** and 2.6 show the valve being unpacked and removed from the crate.




Figure 2.5 Unpacking Valve




Figure 2.6 Removal of Valve From Crate

Once the valve was removed from the crate, a visual examination of the valve was conducted to determine the overall condition of the valve. There was some absorbent material inside the outlet flange of the valve which **was** removed during this examination. There was nothing of note in the outlet flange of the valve.

A tag reading "RV-1919" was attached to the relief valve. The following data appeared on the name plate for the relief valve and the pilot valve:

Relief Valve Name Plate:	Size: 8" [inches] Flange (ANSI): 300
	Serial No.: 9801-27803-1-1
	Figure No.: M 760 AP
Pilot Valve Name Plate:	Model No.: 1760
	Part No.: 453200
	Spring Range: 70-180

Five manual valves were **installed** in the pilot sensing lines. The Fisher-Rosemount representatives stated that these manual valves were not standard equipment. Four of the valves appeared to be **ball** valves with handles. The **fifth** valve **was** located on a tee in one of the lines and had a knob that could be turned to open or close the valve. The four ball valves were tagged **and** numbered **1 through 4**. Valves 1, **2**, and 3 were **fully** closed. Valve **4** was located in the sensing line between the inlet side of the relief valve and the housing containing the needle valve and strainer assembly. Valve **4** was not fully closed. Photographs of the manual valves which show the orientations and locations of the manual valves **are** shown in Figures 2.7 through 2.10.



Figure 2.7 Orientation of Valves 1 and 2



Figure 2.8 Orientation of Valve 3




Figure 2.9 Orientation of Valve 4




Figure 2.10 Orientation of Valve in Sensing Line

The final item of note in relation to the visual examination of the valve is that two nuts were missing from the cylinder head. SES understands that these nuts were in place before the valve was removed from the line. Figure 2.11 shows the studs where the nuts were missing. In addition to the nuts being missing, one of the studs had significant thread damage. The damaged stud is the one with the pen pointing to it in Figure 2.11.




Figure 2.11 Missing Nuts and Damaged Stud

At this point, the valve was turned over to ~~Bart Gater~~ of CONAM for radiographic inspection. The radiographs were taken on the back lot at SES. While the radiographs were being taken, a meeting was held to discuss the test setup.

2.2 Discussion of Test Set-up

A meeting was held to discuss the test set-up. Each witness was provided with a schematic of the test set-up as shown in Figure 2.12. The intent of the schematic was to show the general arrangement of the plumbing for the test and the locations of the pressure transducers. The schematic does not show the location of the control valves for the test or the acoustic emission (AE) sensors.

In the meeting, it was explained that two AE sensors would be used, ~~one~~ on the pilot valve and one of the main valve body. In addition, the test set-up would contain a valve between the accumulator and the inlet of the relief valve and bleed valves to bleed pressure from the inlet flange and the dump vessel. SES also explained that the intent was to replace the ~~small~~ valves in the sensing ~~lines~~ with ~~tees~~ and attach pressure transducers to the tees. If it ~~was~~ found that the ~~small~~ valves were not free of debris, the instrumentation would need to be reexamined.

As a result of the discussion, ~~three~~ changes were made to the test set-up. The first change was that one of the pressure transducers was relocated ~~from~~ the line to the inlet flange to the inlet flange itself. This involved sending ~~the~~ inlet flange back to the machine shop and having a one quarter inch (1/4 inch) NPT port added to the flange. This flange was sent to the machine shop and returned to SES on the afternoon of September 18, 2000. The second change ~~was~~ to add an additional pressure transducer to the pilot valve sensing line (i.e., the line from the pilot valve to the inlet side of the ~~main~~ relief valve). The ~~thi~~ change was that a strainer was added between the outlet flange of the relief valve and the dump vessel. The strainer was ordered on September 18 and arrived on September 19. The ~~revised~~ test set-up is shown in Figure 2.13.

Data acquisition was discussed and it was explained that the AE data and the pressure transducer data would be taken on separate ~~systems~~. In order to correlate the data, the output from one pressure transducer would be read by both ~~systems'~~.

One comment made during the discussion concerned the fluid which would be used to apply pressure to the valve. SES intended to use hydraulic oil. The hydraulic oil to be used was an ISO Grade 46 hydraulic oil. The concern was with the difference in viscosities of the hydraulic oil and the product which the pipeline carried. Since the hydraulic ~~oil~~ is thicker than ~~gasoline~~, it was felt that the reaction times for the relief valve would be slower. SES pointed out that the valve ~~was~~ not being tested under full flow and that ~~this~~ would also affect the reaction time. It

was proposed that the test be conducted with mineral spirits. However, after some consideration by **SES**, it was decided that an internal review would be required before this could be done. The concern of **SES** was the danger due to the volatile nature of mineral spirits. It was felt that arrangements could be made to conduct the test with mineral spirits, but these arrangements would result in a delay in the test schedule. The group was presented with a sample of the hydraulic oil to be used in the test and it was agreed to proceed with the test using the hydraulic oil.




Figure 2.12 Original Schematic of Test Set-up




Figure 2.13 Revised Test Set-up

23 Radiographs

While the discussion of the test set-up **was** taking place, **CONAM was** taking radiographs of the relief valve. **This** included radiographs of the small valves which were tagged when the valve **was** unpacked (i.e., valves 1, 2, 3, 4, and the "knobbed" valve in the pressure sensing line), the pilot valve, and the main relief valve body. **Two** shots, approximately 90 degrees apart, were taken of valves 1, 2, 3, 4, and the "knobbed" valve in the pressure sensing line. One shot was taken of the pilot valve and one shot was taken of the main body of the relief valve. No broken parts, debris, or other abnormalities could be identified in the radiographs. The radiographer in charge was Bart Carter. The paperwork showing Bart Carter's certifications is presented in Appendix B.

24 Optical Probe and Visual Inspection

Once the radiographs were complete, the valve **was** moved from the back lot of the SES test facility into the main lab **area**. The valve was placed on a table and a visual and optical probe inspection conducted. The optical probe inspection was videotaped and photographs were taken during the inspection.

There was some light rust at the upstream side of the valve. The rust was cleaned out of the valve with **a** nylon bristle brush and placed in a labeled bag. The studs on the cylinder head which were missing nuts were labeled **1** and **2**. Thread damage was observed on both of these **studs**. [**Note:** The **NTSB** later confirmed that the two nuts were removed on June **29,1999**, to obtain the needed clearance for the removal of the relief valve **from** the pipeline system.]

The sensitivity screw was also examined. **This** sensitivity screw controls a needle valve. The position of the needle affects the closing speed of the relief valve. Measurements were taken to record the position of the sensitivity screw. The top of the screw was **0.345** inches below the top of the housing nut. The height of the housing nut was **9/16** inch. A sketch illustrating these dimensions is included in Figure **2.14**. The housing which contains the sensitivity screw is **rectangular** in shape and contains **a** strainer in addition to the needle valve. The pilot valve mounts to a port in **this** housing. In **Figure 2.9**, the housing **can** be seen adjacent to the pilot valve.




Figure 2.14 Measurements of Sensitivity Screw Location

An optical probe was then used to examine the valve. The probe was passed through all of the sensing lines. Due to the numerous turns in the lines, some of the connections in the sensing lines were opened to allow for insertion of the probe. Table 2.1 summarizes the optical probe examination.

Probe Number	Description	Observation
"	Through valve #4 into the strainer (straight ahead view)	No obstructions
2	Through valve #4 into the strainer (90 degree view)	No obstructions, strainer appears clean
3	Into needle valve/strainer housing	Probe view fuzzy due to gasoline in housing
4	Into needle valve/strainer housing after removing a few drops of gasoline with a cotton swab	Could see the shaft of needle valve, but could not see the end of the shaft
5	Through line from cylinder head to needle valve/strainer housing.	No obstructions
6	Through loop from pilot valve back to the sensing line on the inlet side of the main valve.	There was a small amount of gasoline in the line, but no obstructions.
7	Through loop from pilot valve to the outlet side of the main valve.	There was a small amount of gasoline in the line, but no obstructions.
8	Into the outlet side of the main valve (from the outside)	No obstructions
9	Into the pilot valve	No obstructions
10	From the inside of main valve outlet side to tee in the line	No obstructions, could see closed small valve
11	From the inside of main valve outlet side to tee in the line with small valve opened	No obstructions
12	Cylinder head	No obstructions
13	Cylinderhead	No obstructions
14	Inlet side of main valve	No obstructions

All of the lines and components were examined with the optical probe. There were no debris or blockages found. All of the lines and the strainer were clean. During the examination, a significant amount of gasoline, approximately 5 quarts, was drained from the cylinder head. Figure 2.15 shows the gasoline being drained ~~from~~ the cylinder head. Figure 2.16 shows the gasoline that was drained. The gasoline was discolored, but appeared ~~free~~ of debris. Figures 2.17 through 2.19 show the optical probe inspection.

There ~~was~~ nothing found during the radiographic, visual, or optical probe inspection that would indicate that the valve would not operate.



Figure 2.15 Draining Gasoline from Cylinder Head



Figure 2.16 Gasoline Drained from Cylinder Head




Figure 2.17 Optical Probe Inspection (View 1)



Figure 2.18 Optical Probe Inspection (View 2)




Figure 2.19 Optical Probe Inspection (View 3)

Once the inspection was complete, the valve was placed in the test pit. The test pit was sealed until representatives from NTSB arrived the following morning. The sealing of the test pit is shown in Figure 2.20.




Figure 2.20 Sealing of Test Pit

3.0 DAY 2: PRESSURE TEST OF ACCIDENT VALVE

The majority of the day on September 19, 2000 was spent setting up the test equipment. This included installing flanges on the relief valve and torquing the bolts to **188** ft-lbs, replacing the small valves with **tees**, mounting the pressure transducers and AE sensors, and assembling the plumbing for the test set-up. While the test equipment was being set-up, a meeting **was** held to review the proposed test protocol and the activities of the previous day. The **final** activity for the day was the pressure test of the as-received valve.

3.1 Day 2 Meeting

The group met at **10 am**. The first item of discussion was the set of field notes from the previous day. All of the parties were allowed to review the notes. The group was then asked to point out any areas in the **notes** that needed revision. Once the revisions were made, the participants signed the field **notes**.

During the meeting, the specifications for the hydraulic oil and the revised test set-up schematic as shown in **figure 2.13** were handed out.

One **area** of discussion concerned the calibration of the pressure transducers. Jim Liou, representing the City of Bellingham, suggested that the pressure transducers **be** checked on a dead weight tester prior to the test. George **Ross** of SES pointed out that the pressure transducers were all in calibration and that it is **standard SES** practice to **calibrate** transducers once a year. In addition, any time that a transducer is overloaded it is **red** tagged and recalibrated. **As** a result of the discussion, it was decided that the pressure transducers would not be checked on the dead weight tester prior to the test. However, the City of Bellingham **was** welcome to contract with **SES** to check the transducers immediately after the test. SES's standard calibration practices and the calibration certificates for the pressure transducers and the dead weight tester used in the **tests** are included in Appendix C.

3.2 Test of As-received Relief Valve

The pressure test of the as-received relief valve began on the afternoon of September 19, 2000 at approximately 3:45 pm. Although the test is referred to as testing the valve in the as-received condition, the valve had been disturbed to some extent. During the optical probe inspection, the sensing lines had to be removed to provide entrance points for the probe. In addition, in the pressure test, the small valves in the sensing lines were replaced with tees. It was necessary to replace the valves with tees so that the pressure transducers could be placed in the system. Since the small valves were found to be free of debris (i.e., clean and clear), it is felt that replacing the small valves with tees did not affect the operation of the valve.

3.2.1 Test Set-up

The test set-up used for this test is illustrated in Figure 3.1. The original test protocol had called for pressurizing the inlet and outlet of the relief valve to 20 psig. Unfortunately, during the initial test set-up, a bleed valve was not installed between the inlet flange and the isolation valve. The inlet pressure could be bled off, but would have to be bled through the pump. This would require bleeding the pressure from the accumulator. When this was discovered, the test protocol was changed so that the dump vessel would be vented to atmospheric pressure and the inlet pressure would be kept at the residual inlet pressure after each test run. This eliminated the need to bleed the inlet and accumulator pressure between runs and would result in less delay between test runs. The dump tank was then vented to atmosphere and the accumulator charged to 800 psig in preparation for the first test run. The bleed line on the dump tank was a small diameter (i.e., 1/4 inch) line. As a result it took some time to bleed the 20 psig pressure from the tank.

The principle behind the test set-up is that the accumulator is initially isolated from the relief valve. The pump is used to charge the accumulator to a preset pressure. The isolation valve between the pump and the accumulator is then shut. The data acquisition system is started. While taking data, the isolation valve between the accumulator and the relief valve is opened. Opening the isolation valve allows the fluid in the accumulator to flow, under pressure, to the relief valve.

There are two indicators from which it can be determined if the pilot valve activated. First there is an AE sensor on the pilot valve to pick up mechanical noise. Secondly, a change in pressure on the outlet side of the pilot would indicate that the pilot has activated. Similarly, if the relief valve activates, there will be a change in the outlet pressure and there is an AE sensor on the main valve body to check for mechanical noise.

A photograph of the test set-up is shown in Figure 3.2.




Figure 3.1 Test Set-up Prr As-received Valve




Figure 3.2 Photograph of Test Set-up

3.2.2 Test Results

The test was **started** with the accumulator charged to 800 psig. The isolation valve between the relief valve inlet flange and the accumulator was then opened. During this run, the inlet pressure reached a maximum of **52** psig. **A** second run **was** then made and the inlet pressure reached a maximum pressure **of** 99 psig. During the third run, the inlet pressure reached **a** maximum of 55 psig. On the fourth, **fifth**, and sixth runs, the inlet pressure reached **127** psig, **384** psig, and **762** psig. The inlet pressure was held for approximately 3 minutes and dropped **to** **706** psig during that time. The set point for the pilot valve was expected to be 440 psig. It **was** not until the sixth run, that a pressure on the inlet greater than **this** set point **was** achieved. There were no AE "hits" during the **test** that indicated that either the pilot or relief valve opened.

Table 3.1 summarizes the test results. Plots of the test data **are** included in Appendix D. The plots include traces of pressure **as** a function of time for all of the pressure transducers.

Table 3.1 Pressure Test of As-Received Valve

Run	Accumulator Pressure at Start of Run		Maximum Inlet Pressure Achieved		Maximum Outlet Pressure Achieved		Residual Inlet Pressure		Volume Outlet Flange (cups)	Volume of Fluid valve Outlet	Comments
	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)			
1	801	7.7	52	184.3	26	30.7	45	29.1	NA	NA	No AE hits indicating opening of the valves were detected
2	825	5	99	20.4	37	10.8	91.9	103.9	NA	NA	No AE hits indicating opening of the valves were detected
3	818	4.4	55	45.6	40	11.6	55	45.6	NA	NA	No AE hits indicating opening of the valves were detected
4	804	4	127	71.6	31	8.5	114	376	NA	NA	No AE hits indicating opening of the valves were detected
5	800	377	384	394	6	379	370	518	NA	NA	No AE hits indicating opening of the valves were detected
6	800	518.2	762	518.6	1	518.8	706	1354	NA	NA	No AE hits indicating opening of the valves were detected

*1 Pressure at Start of Run" is the time when the valve isolating the accumulator from the inlet of RV1919 was opened and marks the starting time of each test run.

It can be concluded **from** these test **runs** that the valve was leaking. **This** is evident because the valve was initially filled with hydraulic oil **and** the accumulator volume **is** on the same order **as** that of the valve. If the valve were not leaking, much higher inlet pressures would have been achieved on the first three test **runs**. In addition for run **1**, the peak outlet and inlet pressures were approximately equal. In runs **2** and **3**, outlet pressures comparable to those **at** the inlet were also **seen**. In run **4**, the valve began to seal better and the maximum inlet pressure was significantly higher than the outlet pressure. In runs **5** and **6**, the outlet pressure is negligible in comparison to the inlet pressure. **This** indicates that **as** the pressure on the inlet side increased, the valve began to **seal** better.

It can also be concluded that the pilot and relief valves did not open during the test. This is evident because the maximum inlet pressure of **762 psig** is much greater than the set point.

At the end of the day, some changes were made to the test set-up. These changes are discussed in Section 4 of the report, since they pertain to the day three tests. Once the set-up changes were made, the valve **was** left in the pit with the lids bolted down.

4.0 DAY 3: PRESSURE TESTS OF VALVE AND DEAD WEIGHT TESTS

Day 3 of testing began on September 20, 2000. The following activities took place;

1. Meeting to discuss the notes from the previous day
2. Retested relief valve with accident pilot (slight modifications to test set-up)
3. Dead weight tests
4. Disassembled accident pilot valve
5. Pressure test with high pressure (HP) exemplar valve

4.1 Day 3 Meeting

The day three meeting began at 8:30 am on September 20, 2000. The first item of discussion was the set of field notes from the previous day. All of the parties were allowed to review the notes. The group was then asked to point out any areas in the notes that needed revision. Once the revisions were made, the participants signed the field notes.

SES explained the changes made to the test set-up to the group. These changes consisted of increasing the size of the bleed line from the dump vessel, increasing the line size from the pump to the accumulator, and adding a bleed valve between the accumulator to inlet flange isolation valve and the inlet flange.

4.2 Day 3 Test Set-up

The revised test set-up used for the Day 3 tests is presented in Figure 4.1. The changes which were made to the set-up were;

1. the line size of the dump vessel bleed line was increased,
2. the size of the line between the pump and the accumulator was increased, and
3. a bleed valve was added between the accumulator to inlet flange isolation valve and the inlet flange.

These changes were made to improve the efficiency of the testing process.




Figure 4.1 Test Set-up Used for September 20,2000 Tests

The testing procedure used was the same as adopted the previous day. The dump vessel was open to atmospheric pressure and the accumulator charged to 800 psig. The intent was to test the valve with the residual pressure at the inlet. However, the relief valve did not operate during the test. Therefore, the bleed valve was used to bleed the inlet pressure to 300 psig between runs.

4.3 Day 3 Test of As-Received Valve

On September 20, 2000, the as-received valve was run through three pressure cycles. During the first pressure cycle, only 84 psig was achieved on the inlet side of the valve. The was accompanied with a pressure at the outlet of 22 psig. This pressure at the outlet is indicative of the valve leaking. On the second and third runs, the valve held pressures in excess of 690 psig on the inlet side of the valve. The maximum outlet pressures during the second and third runs were 6 psig and 1 psig respectively. The expected set point for the pilot valve was 440 psig. The data was consistent with the previous data in that both the pressure and AE data indicated that the relief valve and pilot valve did not operate during the test. The test runs are summarized in Table 4.1. Plots of the test data, which include traces of pressure as a function of time for each data channel, are included in Appendix E.

Table 4.1 Pressure Test of As-Received Valve (Day 3)

Run	Accumulator Pressure at Start of Run		Maximum Inlet Pressure Achieved		Maximum Outlet Pressure Achieved		Residual Inlet Pressure		Volume of Fluid from Outlet Flange (cups)	Volume of Fluid from Pilot Valve Outlet (cups)	Comments
	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)			
1	800	8.2	84	60.1	21.9	57.3	65.3	98.6	NA	NA	No AE hits indicating opening of the valves were detected
2	800	672.2	697	720	6.4	680.8	650	1349	NA	NA	No AE hits indicating opening of the valves were detected
3	800	153.5	792	155.9	0	NA	771	200	NA	NA	No AE hits indicating opening of the valves were detected

* Note: The time listed under "Accumulator Pressure at Start of Run" is the time when the valve isolating the accumulator from the inlet of RV1919 was opened and marks the starting time of each test run.

Once the test runs were complete, the accident pilot valve was removed from the relief valve for dead weight testing.

4.4 Dead Weight Tests

In order to establish the set-points of all of the pilot valves, the accident, HP exemplar, and LP exemplar pilot valves were tested on a dead weight tester. The set-up for the dead weight tests is shown in Figures 4.2 and 4.3.

The port from the dead weight tester was connected to the sensing port of the pilot valve. Shop air at 30 psig was connected to the inlet port of the pilot valve and a hose was connected from the outlet of the pilot valve to a graduated cylinder filled with water. When the dead weight tester supplies enough pressure to the sensing port, the pilot opens and the air is allowed to flow from the inlet to the outlet of the pilot valve. The air then travels from the outlet of the pilot valve through the tube and produces bubbles in the water filled graduated cylinder. Using this set-up, it was established that the HP exemplar pilot valve opened at 617 psig and the air flowed freely through the pilot valve at 650 psig. The LP exemplar pilot valve opened at 100 psig and allowed a free flow of air at 120 psig. The accident pilot valve first opened between 550 and 600 psig and reseated at 270 psig. In a subsequent run, the accident pilot valve first opened at 400 psig and reseated at 270 psig. In the final run, the accident pilot opened at 350 psig and exhibited full flow at 700 psig.

The results of the dead weight test on the accident pilot valve indicate that the accident pilot valve did not open consistently. The initial opening pressure ranged from 350 psig to 550 psig. This is an extremely large range. The HP and LP exemplar valves had much better defined opening pressures.




Figure 4.2 Dead Weight Test Set-up





Figure 4.3 Dead Weight Test Set-up (view 2)


4.5 Dimensions of Pilot Valves

Dimensions of the pilot valves were also taken. These dimensions were taken from the actual pilot valves and also from the radiograph taken on Monday, September 18, 2000. The dimensions taken from the actual valves are presented in Figures 4.4 through 4.6. The dimensions resulting from the examination of the radiograph are presented in Table 4.2.




Note: All dimensions are in inches

Figure 4.4 Outside Dimensions of Accident Pilot Valve



Note: All dimensions are in inches

Figure 4.5 Outside Dimensions of LP Exemplar Pilot Valve



Note: All dimensions are in inches

Figure 4.6 Outside Dimensions of HP Exemplar Pilot Valve

Description	Approximate Dimension (inches)
Diameter of Upper Cylinder	2 1/8
Diameter of Lower Cylinder (near bottom)	3 5/16 +
Diameter of Lower Cylinder (near top)	3 5/16 +
Apparent overall length of lower cylinder from bottom to top of lip	5 7/16
Apparent distance between the centerlines of 6 coils of the main spring	1 1/2

After the **dimensions** were taken, the accident pilot valve was disassembled, the HP exemplar pilot valve was installed on the relief valve, and the LP exemplar pilot valve set aside for subsequent **tests**.

The height of the adjustment screw on the top of the accident pilot valve was 0.906 inches. **On** the LP exemplar pilot valve, the adjustment screw height was **1.44** inches. **Since** the accident pilot was originally configured **as** a LP pilot valve, it **can** be concluded that the adjustment screw had been tightened down approximately 1/2 inch.

4.6 Disassembly of the Accident Pilot Valve

The accident pilot valve was disassembled to determine if there were **any** broken parts and to compare with the exemplar valves which were disassembled later in the test program.

The first item checked during the disassembly was the adjustment screw on top of the pilot valve. **This** adjustment screw is used to adjust the force of the **main spring** in the pilot valve. **As** the screw is tightened, the force required **to** activate the pilot valve increases. The **screw was** tightened **as far as** possible. It was found that the **screw** could be tightened less than one quarter **(1/4)** of a turn. **This** indicates that the spring in the pilot valve **was** compressed almost **as far as**

possible when it was in service. The adjustment screw was then loosened twenty-five **(25)** turns so that the pilot valve could be disassembled.

The next step in the disassembly process was to remove and inspect the spring cover. There **was** no apparent damage to the O-ring in the spring cover. The O-ring was brown in color and had no cuts or tears. The O-ring groove was clean. There **was** no visible damage to the inside of the cover. However, there was a sticky residue on the piston seating surface of the inside cover.

Once the cover was inspected, the spring **was** removed. The spring had a bronze colored stripe. According to the Hsher-Rosemount representatives, this bronze stripe is used by the relief valve manufacturer to indicate the pressure range of the spring. A measurement **was** taken between the centerlines of **six (6)** coils of the spring to compare to the compressed spring measurement taken from the radiograph. The measurement **was 1.73** inches for the uncompressed spring. The apparent length of the compressed spring **as** determined from the radiograph and presented in Table **4.2 was 1.5** inches. The spring **was** not damaged nor was any corrosion present.

The piston, inside the cylinder, **was** then examined. There was some black residue on the inner mating surface of the cover and the cylinder and some slight corrosion on the same surface. **This** region **was** wiped with a cotton swab and the swab retained in a plastic bag labeled "A". There **was** also some slight residue on the top of the piston (i.e., the spring side).

The piston was then removed **from** the cylinder. The bottom side of the piston **was** clean and **had a** light coating of **oil**. The **O-ring** on the piston **was** in good condition and brown in color. At **this** point in the disassembly procedure, some measurements were taken. The measurements **are** summarized in Table **4.3**.

Table 4.3 Measurements of Components in Accident Pilot Valve

Description	Measurement (inches)
Width of o-ring groove	0.1545
Diameter of o-ring groove	1.8775
Diameter of piston	2.1165
Diameter of piston without o-ring	2.1368 (average of 3 measurements)
Internal diameter of pilot cover	2.1245 (average of 2 measurements)

The damper spring was then removed. **This** was followed by the removal of the cage retainer ring, the cage assembly, and the poppet. In the opinion of the Fischer-Rosemount representatives, the poppet moved normally inside the cage assembly.

Finally, the poppet retaining ring and the poppet were removed. The inside of the cage was clean and the poppet o-ring in place. Figures 4.7 through 4.10 show some selected photographs taken during the disassembly of the accident pilot valve.




Figure 4.7 Accident Pilot Valve with Cover Removed




Figure 4.8 Inside Cover of Pilot Valve




Figure 4.9 Cover of Pilot Valve




Figure 4.10 Pilot Valve Poppet Assembly

4.7 Day 3 Test of Relief Valve with HP Exemplar Pilot Valve Installed

The relief valve was pressure tested with the HP exemplar pilot valve installed. The set point as determined by the dead weight tests was 617 psig. The first run resulted in an increase in the inlet pressure to approximately 43 psig. The second run resulted in an inlet pressure of 110 psig. This was accompanied by a slight momentary increase in the outlet pressure and it was noted at this point that there was a small steady stream of oil flowing from the overflow/bleed line coming from the dump tank. At this point the valve was removed from the end of the overflow/bleed line and the end of the line placed in a 55 gallon drum. On the third run, there was a large spike in the pressure at the outlet flange and oil could be heard flowing into the 55 gallon drum. On the subsequent runs, a noticeable spike in the outlet flange occurred each time pressure was applied to the valve. The residual inlet pressures were on the order of 400 psig, depending on the delay between successive pressure cycles. Between runs, the inlet pressures decreased. This decrease in inlet pressure is an indication the valve was leaking. The AE data for these runs was examined and indications were found that both the pilot and relief valves were opening and that the maximum time lapse between the opening of the pilot valve and the opening of the relief valve was 0.02 seconds. Appendix F contains a brief discussion of the AE data. The AE data taken during this series of test runs is in file 6947T32.DTA.

The test runs are summarized in Table 4.4. Plots of the test data are included in Appendix G. The plots include pressure as a function of time curves for each pressure transducer.

Run	Accumulator Pressure at Start of Run		Maximum Inlet Pressure Achieved		Maximum Outlet Pressure Achieved		Residual Inlet Pressure		Volume of Fluid from Outlet Flange (cups)	Volume of Fluid from Pilot Valve Outlet (cups)	Comments
	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)			
1	805	8	43	38.4	41	38.4	13	100	NA	NA	
2	800	644	110	672.3	37	668.8	34	2000	NA	NA	
3	801	175	498	203	471	192	418	628	NA	NA	
4	803	628	668	632	70	647	430	841	NA	NA	
5	802	841	662	841	135	849	298	1280	NA	NA	
6	802	1280	652	1281	51	1290	417	1490	NA	NA	
7	802	1490	645	1490	145	1500	445	1690	NA	NA	
8	800	1690	643	1700	229	1710	456	1950	NA	NA	
9	803	1950	645	1950	123	1960	556	2010	NA	NA	

From these test runs, it can be concluded that the relief valve itself operates properly and that any failure **to operate** is due to the pilot valve **not** functioning.

There **was** some discussion about measuring volumes output by **the pilot and main valve at this point**. **As** a result, some modifications were made to the **test set-up** to allow for **taking** some order of magnitude measurements on the following day.

5.0 DAY 4: PRESSURE TESTS OF RELIEF VALVE WITH HP EXEMPLAR VALVE INSTALLED AND ADJUSTED LP EXEMPLAR VALVE INSTALLED

Day 4 of testing began on September 21, 2000. The day's activities included;

1. Meeting to discuss the notes from the previous day and AE results
2. Retested relief valve **with** HP pilot (slight modifications to test set-up)
3. Dead weight test to adjust set-point of LP exemplar valve
4. Disassembled HP exemplar pilot valve
5. **Pressure** test of relief valve with adjusted LP exemplar valve installed
6. Disassembled LP exemplar valve

5.1 Day 4 Meeting

The meeting on day 4 was begun at 8:30am. **As** before, the field **notes** from the previous day were discussed, edited, and signed by the parties. Claudio Allevato, **ASNT** III of **SES** gave a brief **summary** of the AE results obtained during the test with the HP exemplar pilot valve installed. Mr. Allevato found evidence of mechanical noise from both the pilot and relief valves. The mechanical noise was of the **type** that would indicate that both valves opened.

Modifications which were made to the test set-up were also discussed.

5.2 ~~Test~~ Set-up for Day 4

Following the September 19, 2000 test of the relief valve, with the HP exemplar pilot valve installed, there was some discussion about measuring volumes output by the pilot and **main** valve. **As a** result, some modifications were made to the test set-up to allow for taking some order of magnitude measurements. The dump vessel was removed from the test set-up and a hose **from** the outlet flange of the relief valve was run **to** a bucket. In addition, the connection between the outlet port of the pilot valve and the relief valve was disconnected. **Pressure** transducer #4 **was** left on the relief valve and gave a reading of the pressure on the outlet side of

the relief valve. The line was capped off just past the pressure transducer. A hose was attached to the outlet port of the pilot valve and routed to a bucket. These modifications made it possible to take order of magnitude measurements of the volumes passing through the pilot and relief valves during the test. A schematic of this revised test set-up is shown in figure 5.1.




Figure 5.1 Test Set-up for September 21, 2000

Volumes of hydraulic fluid from each test run were measured from the catch buckets using a measuring cup. This resulted in order of magnitude measurements of the flow through the pilot and relief valves.

5.3 Test of Relief Valve with HP Pilot Valve Installed

The relief valve was tested with the modified set-up by charging the accumulator to 800 psig, isolating the pump from the accumulator, and then opening the isolation valve between the accumulator and the inlet flange. Pressure data and AE data were recorded during the test runs.

Between each run, the catch buckets for the relief valve outlet and pilot valve outlet were emptied and the volumes measured.

It should be noted there was a small steady stream of hydraulic fluid flowing from the line connected to the outlet flange of the relief valve throughout this test. This is indicative of a small leak in the relief valve. The slow reduction in the inlet pressure between the test runs is also an indication of the valve leaking. Another item of note is that for the first six (6) runs, no volumes were recorded from the pilot valve outlet catch bucket. This does not mean that there was not any fluid exiting the pilot valve. The hose connected to the pilot valve outlet was initially empty. Therefore, during the first six (6) runs, the fluid exiting the pilot valve was filling the hose.

As with the test conducted the day before, when the isolation valve between the accumulator and the inlet of the relief valve was opened, there was a spike in the outlet pressure. Residual inlet pressures on the order of 500 psig were seen. In addition, the AE sensors picked up mechanical noise from both the pilot and relief valves. The AE data is discussed in Appendix F. Finally, the hydraulic fluid entering the catch buckets indicated that the pilot and relief valves were opening.

A total of eleven runs were made. Run 8 was interrupted/stopped due to interference from one of the witnesses. The data plots for runs 4 through 7 and 9 through 11, included in Appendix I of this report, show that the reaction of the valve is repeatable.

These runs show that the relief valve operated properly when the HP exemplar pilot valve was installed. The maximum inlet pressures achieved are on the order of the pilot valve set point. In addition, significant volumes of hydraulic fluid were allowed to flow from the relief valve outlet and in the latter runs flow was measured from the pilot valve outlet. Finally, the AE data also indicate that both the pilot and relief valves were opening.

Table 5.1 Pressure Test of Relief Valve with HP Pilot Valve Installed (Day 4)

Run	Accumulator Pressure at Start of Run		Maximum Inlet Pressure Achieved		Maximum Outlet Pressure Achieved		Residual Inlet Pressure		Volume of Fluid from Outlet Flange (cups)	Volume of Fluid from Pilot Valve Outlet (cups)	Comments
	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)			
1	800	5.2	477	20	481	20	20	503	24	0	
2	799	503	541	509	544	509	48	872	32	0	
3	800	872	576	877	576	877	83	1235	30	0	
4	797	1235	632	1236	68	1237	351	1428	14	0	
5	804	1428	635	1429	181	1436	471	1619	13	0	
6	800	1619	648	1619	197	1626	558	1828	15	0	
7	794	1828	650	1828	146	1836	541	2033	12 ½	½	
8	798	2033	665	2033	13	2040	400	2162	8 1/2	1/3	Interrupted
9	804	2162	644	2164	131	2170	519	2358	15	½	
10	801	2358	655	2358	125	2365	503	2664	14	2/3	
11	800	2664	643	2665	76	2672	495	3000	17 1/3	1 1/3	

* Set point of HP pilot valve = 617 psig.

** Note: The time listed under "Accumulator Pressure at Start of Run" is the time when the valve isolating the accumulator from the inlet of RV1919 was opened and marks the starting time of each test run.

5.4 Dead Weight Test to Adjust Set-point of LP Exemplar Valve

The set point of the LP Exemplar pilot valve was changed using the dead weight tester. The same set-up was used for conducting the previous dead weight tests. The air pressure used was 15 psig air. The goal was to match the set point of the accident valve as closely as possible. This activity took several iterations which are summarized in Table 5.2. Once the set point was adjusted to the satisfaction of all parties, the HP exemplar pilot valve was removed from the relief valve and LP exemplar pilot valve was installed.

Height of Adjustment Screw (inches)	Pressure (psig)		
	Start of Release	Fully Open	
1.078	150	240	
1.048	145	244	Screw tightened ½ turn.
0.919	210	270-280	Screw adjusted to approx. height of accident pilot valve
0.853	-	-	Screw tightened 1 ¼ turns, nearly completely tightened. Valve did not open.
0.8595	700	-	Screw loosened 1/8 turn. Valve did not open fully
0.864	500	-	Screw loosened 1/8 turn. Valve did not open fully
0.8795	500	-	Screw loosened 1/8 turn. Valve did not open fully
0.870	500	600	Screw tightened 1/16 turn.
0.871	500	600-650	Screw tightened 1/16 turn. Valve left at this adjustment and installed on relief valve

The LP exemplar pilot valve **was** left at the last setting (i.e., fully **open** between 600-650 psig) and installed on the relief valve for pressure testing. Although the intent of this activity was to adjust to set point of the LP exemplar pilot valve, some conclusions can be made **from this information**. First the **set point** of the valve on the data plate is a maximum of 180 psig. In order to increase the **set point** to 600 psig, the adjustment screw had to be tightened down over ½ inch. This puts the spring in the valve in a nearly completely compressed state and the pilot valve becomes very sensitive to small changes in the adjustment screw setting. Even a change in the adjustment screw of 1/8 of a **turn** can mean the difference between the pilot valve opening or failing to **open**.

5.5 Disassembly of HP Exemplar Pilot Valve

While the LP exemplar pilot valve was being installed on the relief valve, the HP exemplar pilot valve **was** disassembled. Dimensions taken during the disassembly are presented in Table 5.3.

Table 5.3 Dimensions Taken During Disassembly of HP Exemplar Pilot Valve

Description	Dimension '(inches)
Adjustment Screw Height	0.886
Valve Cover External Diameter	2.126
Valve Base External Diameter	3.272
Height of Cover (to bottom of groove on base of cover)	3.468

In addition to the dimensions presented in Table 5.3, dimensions of the piston were also taken. The piston dimensions are presented in Figure 5.2.




Figure 5.2 Dimensions of Piston from HP Exemplar Pilot Valve

It was noted that the dimension taken at the top of the piston, 1.3665 inches, does not match the 1 13/64 inch dimension in the available literature (i.e., the pilot spring selection table).

In comparing the internal components of the HP exemplar pilot valve to the internal components from the accident pilot valve, the only difference of note was the piston. The two pistons are shown in Figure 5.3.



Figure 5.3 Pistons from HP Exemplar and Accident Pilot Valves

5.6 Pressure Test of Relief Valve with Adjusted LP Exemplar Valve Installed

The pressure test was run with the LP exemplar pilot valve installed on the relief valve. **This** test was done after the set point had been adjusted as discussed in Section 5.4. A total of fourteen (14) runs were made. **On** the first six (6) runs, the pressure on the outlet flange increased immediately when the pressure was applied to the relief valve. This was accompanied by a large flow into the outlet flange catch bucket. The AE indicated that the pilot valve was not activating. On each run, the pressure decreased rapidly to 50 psig on the inlet side. Therefore, it appeared that the fluid was leaking through the relief valve. This behavior is similar to what was experienced with the accident pilot valve installed and strengthens the conclusion that the valve was leaking.

For run 7, the pressure in the accumulator was increased to 1000 psig. This time, the inlet side of the valve retained approximately 25 psig. The accumulator was then pumped to a pressure of 1200 psig for run 8. At the end of run 8, the residual inlet pressure was approximately 367 psig. For all the subsequent runs, runs 9 through 14, the accumulator was charged to 800 psig and the inlet pressure held at approximately 800 psig. Between each run, the inlet pressure was bled to 350 to 400 psig before the next run. For run 9 there was still a small flow of hydraulic oil from the outlet flange, but the flow was only a very small stream. For runs 10, 11, and 12, this stream was reduced to a drip. This drip stopped (i.e., was not present) for runs 13 and 14.

The behavior of the relief valve with the adjusted LP exemplar pilot valve installed was essentially the same as that experienced when the relief valve was tested with the accident pilot valve installed. This leads one to the conclusion that the accident pilot valve was not modified adequately to perform reliably as a HP pilot valve. Information provided to SES indicated that some of the internal components in the accident pilot valve were changed before the set point was changed. However, it does not appear that these changes accomplished the intended objective.

The pressure test runs are summarized in Table 5.4. Plots of the test data, including pressure as a function of time plots for each data channel, are included in Appendix I.

Table 5.4 Pressure Test of Relief Valve with Adjusted LP Pilot Valve Installed (Day 4)

Run	Accumulator Pressure at Start of Run		Maximum Inlet Pressure Achieved		Maximum Outlet pressure Achieved		Residual Inlet Pressure		Volume of Fluid from Outlet Flange (cups)	Volume of Fluid from Pilot Valve Outlet (cups)	Comments
	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)	Press. (psig)	Time (sec)			
1	793	14	509	23.5	509	23.5	25	388	24 ½	0	
2	796	388	534	397.5	533	397.5	34	724	26	0	
3	799	724	553	731.9	552	731.9	46	1080	28	0	
4	798	1080	557	1087	555	1187	44	1503	30	0	
5	798	1503	574	1509	572	1509	56	1862	30	0	
6	800	1862	594	1865	594	1865	17	3000	28	0	
7	1000	3000	698	504.6	700	505	25	1390	68	0	
8	1210	1390	721	1391	723	1391	367	1879	68	0	
9	804	1879	857	1879	0	NA	782	2182	very small stream	0	
10	803	2182	798	2245	0	NA	788	2281	drip	0	Inlet pressure bled to 384 psig for start of this run
11	798	2281	793	2322	0	NA	786	2367	drip	0	Inlet pressure bled to 413 psig for start of this run
12	800	2367	795	2425	0	NA	782	2464	drip	0	Inlet pressure bled to 408 psig for start of this run
13	802	2464	798	2514	0	NA	780	2561	0	0	Inlet pressure bled to 347 psig for start of this run
14	798	2561	794	2601	0	NA	684	3263	0	0	Inlet pressure bled to 349 psig for start of this run. Inlet pressure dropped to 684 psig after a 10 minute hold

* Note: The time listed under "Accumulator Pressure at Start of Run" is the time when the valve isolating the accumulator from the inlet of RV1919 was opened and marks the starting time of each test run.

5.7 Comparison of the LP Exemplar Valve, HP Exemplar, and Accident Pilot Valves

The last activities to take place on September 21, 2000 were the disassembly of the LP exemplar pilot valve and the visual examination and comparison of the components from the LP, HP, and accident pilot valves.

The following observations were **made** during the visual examination and comparison of the components from the three pilot valves;

1. The piston and **main** spring cover from the LP exemplar pilot valve were different **than** the corresponding components from the HP exemplar pilot valve.
2. The components from the HP and LP pilot valves, excluding the piston and main spring cover, were the same. **This** includes the main spring and the lower cylindrical pilot valve body.
3. The piston and main spring cover from the accident pilot valve were the same **as** those from the LP exemplar pilot valve.
4. The components from the accident pilot valve (excluding the piston, main spring cover, and damping spring) were the same **as** those from the HP and LP pilot valves. The damping spring does not affect the **set** point of the pilot valve. Both the HP exemplar and LP exemplar pilot valves had damping springs 1 $\frac{3}{4}$ inches long. The damping spring in the accident pilot valve was **1 $\frac{9}{16}$** inches long.

The components from **all** three of the pilot **valves** were examined or damage and **wear**. The **only** notable observations were:

1. There was some possible scoring observed on the poppet valve stem of the LP exemplar pilot valve
2. There **was** some possible wear observed on the poppet valve stem of the accident pilot valve.
3. The poppet valves from **all** three pilot valves opened and closed freely.

Neither possible scoring on the poppet valve stem of the LP exemplar pilot valve nor the possible wear observed on the poppet valve stem of the accident pilot valve appeared to be severe enough to affect the operation of the pilot valve. The pilot valves were boxed-up for the night so that photographs of the poppet valve stems could be taken the next morning.

In summary, other than the difference in damping spring lengths, the components from the LP exemplar pilot valve appeared to be the same as those from the accident pilot valve. In addition, no wear or damage which would affect the operation of the pilot valves was observed.

Figure 5.4 shows the three pilot valves before disassembly. Figures 5.5 through 5.8 show side-by-side views of the disassembled pilot valves and selected components.




Figure 54 Pilot Valves Prior to Disassembly




Figure 5.5 Disassembled Pilot Valves




Figure 5.6 Inside of Top Covers from Pilot Valves




Figure 5.7 Main Springs from Pilot Valves




Figure 5.8 Pistons from Pilot Valves

Figure 5.8 is a key photograph in that it shows that the pistons in the LP and accident pilot valves were the same. However, the piston ~~from~~ the HP pilot valve is significantly different. Therefore, one **can** conclude that the accident pilot valve is essentially the same **as** the LP pilot valve and *can* be expected **to** behave in the same manner.

4.0 DAY 5: DISASSEMBLY OF MAIN VALVE

Day 5 of testing began on September 22, 2000. The activities for the day included;

1. Meeting to discuss the field notes from the previous day
2. Took photographs of pilot valve poppet assemblies under a stereo microscope
3. Reassembled pilot valves
4. Disassembled relief valve
5. Reassembled relief valve
6. Reviewed the notes from September 22, 2000
7. Transferred custody of relief valve and samples taken from the relief valve to DOJ

6.1 Day 5 Meeting

The meeting on day 5 was begun at 8am. As on the previous days, the field notes from the prior day were discussed, edited, and signed by the parties.

6.2 Stereo Microscope Photographs

Photographs were taken of the LP exemplar pilot valve, HP exemplar pilot valve, and accident pilot valve poppet shafts under a stereo microscope. Figures 6.1 through 6.5 show examples of the possible wear or scoring on the poppet valve stems from the LP exemplar and accident pilot valves. This possible wear or scoring was mentioned previously in Section 5.7 of this report.




Figure 6.1 LP Exemplar Pilot Valve Poppet Shaft




Figure 6.2 LP Exemplar Pilot Valve Poppet Shaft (view 2)



Figure 6.3 Accident Pilot Valve Poppet Shaft




Figure 6.4 Accident Pilot Valve Poppet Shaft (view 2)




Figure 6.5 Accident Pilot Valve Poppet Shaft Profile

6.3 Reassembly of Pilot Valves

Once the photographs were taken, the pilot valves were reassembled. The accident pilot valve was reassembled **as** closely **as** possible to the way it was received. It should be noted that the retaining ring for the cage and poppet did not reseal fully. The exemplar pilot valves were assembled hand tight, so that they could be **used** for demonstration purposes in the *future*.

6.4 Disassembly of Relief Valve

The final major activity **that** was part of this test program **was** the disassembly of the main relief valve. The first component which was examined **as** part of *this* activity was the needle valve/dstrainer assembly. When viewed through the fitting port, the shaft of the needle was smooth. The O-ring on the strainer was black in color **and** no particles were visible on the strainer. There was a small amount of residue on the base of the housing, but all the flow ports were open. At this point the strainer **was** removed **and** examined. The dimension **from** the top of

the adjustment screw to the top of the retaining nut was **0.346** inches. **This** agrees well with the dimension of **0.345** inches taken during the optical probe examination and presented in **Figure 2.14**. The needle was tightened and could be turned approximately **1 7/8** of a turn. The needle was then removed and examined.

The first step in disassembling the cylinder of the main valve was to number the studs on the cylinder head. The nuts removed **from** the cylinder head were placed **in** numbered bags so that the nuts could be placed in the **same** locations when the valve was reassembled. After removing the nuts from the cylinder head, the cylinder assembly was removed. The cylinder assembly **was** placed in **SES's** Baldwin test frame and the crosshead was lowered until it was just touching the top of the assembly. **This** was necessary to safely let the pressure off of the main valve spring.

The hex head set screws were removed from the cylinder head and then the crosshead of the Baldwin was slowly raised. The cylinder head was then removed. **This** was followed by the removal of the main valve spring and piston. Dimensions taken during this examination **are** summarized in Table **6.1**. Observations include:

1. The cylinder head gasket is a Garlock 3000
2. The O-ring on the cylinder head is black
3. Some **small** amounts of Teflon **tape** were found in the valve
4. **A** deposit and some **small** nicks were found on the sealing surface of the valve
5. Some signs of wear were noted on the piston
6. **A** black rubberlike material **was** found across the O-ring at the sealing surface. This material was wedged between the O-ring and the o-ring groove. The material **was** left in place.
7. The cylinder bore was found **to** be clean with no apparent damage.

Table 6.1 Dimensions Taken During Disassembly of Relief Valve

Description	Dimension (inches)
Diameter of Cylinder Head	7 13/16
Length of Main Relief Valve Spring	12 1/2
Diameter of Main Relief Valve Spring	4 13/16
Diameter of Spring Coil	7/16
Cylinder Length	11 1/4
Cylinder Outside Diameter	9 1/2
Cylinder Inside Diameter	8 3/4

Figures 6.6 through 6.14 show the disassembly process.



Figure 6.6 Strainer and Cap




Figure 6.7 Cap Removed From Strainer



Figure 6.8 Needle



Figure 6.9 Removing Cylinder Head Nuts




Figure 6.10 Cylinder Removed From Main Valve Body




Figure 6.11 Main Valve Body with Cylinder Removed




Figure 6.12 Removing Head From Cylinder




Figure 6.13 Cylinder with Head Removed




Figure 6.14 Examining Disassembled Relief Valve

At this point, the strainer which had been placed at the outlet of the relief valve in the test set-up was examined. No debris could be seen in the strainer. This is further evidence that there was no debris which would be detrimental to the functioning of the valve present when the valve was received by SES.

6.5 Review of Notes From September 22,2000

Once the examination of the disassembled relief valve was completed, the group reviewed the field notes taken on September 22,2000 and adjourned.

6.6 Reassembly and Transfer of Relief Valve to DOJ

As a final step in the testing process, the relief valve was reassembled. The valve was reassembled so that it was in as close to the same condition as possible as when it was received at SES. However, if additional testing is done, we would recommend that the cylinder head gasket be replaced and the retaining ring in the pilot valve replaced. Figures 6.15 and 6.16 show the reassembled valve. Once reassembled, custody of the valve was transferred from the NTSB to Louis Scharringhausen of the U.S. Environmental Protection Agency Criminal Investigation Division. Mr. Robert Trainor of the NTSB also turned over to Agent Scharringhausen all of the bagged residue samples and wipes taken during the examination of the three pilot valves and the main relief valve.



Figure 6.15 Reassembled Relief Valve




Figure 6.16 Reassembled Relief Valve (View 2)

7.0 CONCLUSIONS

From this test program it can be concluded that an attempt was made to modify a LP pilot valve to operate **as** a HP pilot valve and the steps taken for this modification were not adequate. Although the damping spring in the accident valve **was** shorter than the damping springs in the LP and HP exemplar, it is not clear whether the spring was original equipment or a replacement spring. The accident pilot valve behaves like a LP pilot valve **with** no modifications other **than** tightening the adjustment screw.

For the LP exemplar pilot valve to mimic the behavior of the accident pilot valve, the adjustment screw had to be tightened nearly all the way. **This** resulted in an unpredictable behavior of the pilot valve (i.e., the valve would open during a dead weight test, but not when pressure tested on the relief valve). **This** same behavior was observed with the accident pilot valve. **This** indicates that there **are** conditions where the relief valve could have operated in service and conditions where the valve could have failed to operate.

Pressures in the dead weight test were applied more slowly than in the test with the pilot valve on the relief valve. **This** means that there could be a rate dependence for the pilot valve when adjusted beyond the manufacture's specifications. In other words, the pilot valve may open if subjected to a slow increase in pressure but may fail to open when subjected to a rapid increase in pressure. **This** means that the relief valve could operate in **an** unpredictable manner, could open at pressures lower than intended set point, or fail to open at pressures much higher than the intended set point.

The components in the relief valve and accident pilot valve were in good condition. In addition, there were no debris or blockages in the valves, lines, or **small** valves in the lines which would prevent the valve **from** operating. Finally, when fitted with **an** exemplar HP pilot valve, the relief valve operated properly. **This** indicates that the failure of the relief valve to open and relieve pressure when the accident or **adjusted** LP exemplar pilot valves were installed is due to **the failure** of *the* pilot valves to open.