

Michael J. Hodges Investigator-In-Charge Office of Aviation Safety, Central Regional Office

**Date:** April 28, 2023

**Subject:** CEN22LA250

**Contact:** Aaron Farley,

The NTSB IIC spoke with Aaron Farley over the telephone. Aaron is an airframe and powerplant mechanic with inspection authorization. Aaron works for Wilco Aviation in Paragould, Arkansas.

Aaron performed a 100-hour inspection on the left propeller on N78K (Beech 58 airplane) on January 10, 2022.

Aaron was asked if he used any special equipment to aid in the inspection of the propeller blades and he reported that he performed a visual examination on the propeller blades just using his eyes. Aaron reported that the only damage he observed on the propeller blades was just normal damage you might see such as small nicks. Aaron dressed the small nicks on the propeller blades.

During the maintenance work, Aaron did not notice anything unusual with the propeller blades outside of the normal damage (the small nicks) that he dressed.

Aaron did not remember if he did any paint work on the propeller blades at the time of the maintenance work.

\*\*\*Nothing Follows\*\*\*

From: To:

Subject: Re: CEN22LA250 (N78KL, Beech 58) - Propeller Blade Maintenance Question (Late Aircraft Repair)

**Date:** Thursday, April 27, 2023 9:30:44 AM

Attachments:

image003 png image004 png image001 png image002 png

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Micheal,

Hello,

Sorry its taken so long to get back with you as i have been out of the office. We never did any repainting on that propeller during the time period that we maintained that aircraft. Only thing we did was maybe apply a little edge sealant to the deice strip. I can't remember if that was reapplied or not. Feel free to reach out to me if you have any further questions.

questions.	
Thanks Kevin Late	
On Tue, Apr 18, 2023 at 4:58 PM Hodges Michael	wrote:

I hope things are going well.

I am with the National Transportation Safety Board, and I have a question please about the incident with N78KL (Beech 58).

Here is the NTSB preliminary report:

https://data.ntsb.gov/carol-repgen/api/Aviation/ReportMain/GenerateNewestReport/105266/pdf

Our materials engineers examined the fracture surfaces on the blade that had the separation. The blade facture surfaces showed signatures consistent with high-cycle fatigue.





Our materials engineers also found that for the area of concern, it appeared to be covered with a thick black paint that had a composition that differed slightly from the thinner layer of black paint on the rest of the blade. It is possible that there might have been some underlying damage to the blade, and it might have been covered up with black spray paint.

I was going through the maintenance records for the left propeller, and I saw that Late Aircraft Repair did some previous work on the left propeller from September 2017 to December 2020.

Late Aircraft Repair	
9-18-2017 Hobbs 2652.1 TTP 2036.7 SOH N/A Hartzell HC-C4YF-2E SN GL195 N78KL Left prop —	
Remove propeller due to clogged grease fittings in hub. Propeller sent to Stallings propeller for repair- see 8130. Reinstall propeller IAW hartzell manual 115N Rev 5. Propeller cycled, regreased and dynamically balanced to .08 IPS @ 2400 RPM.	
I certify that this Propeller has been inspected in accordance with a 100hr/Annual inspection and is found to be in an Airworthy condition at this time.	
Kevin Late AP	
Late Aircraft Repair	
9-27-2018 Hobbs 2734.1 TTP 2118.7 SOH N/A Hartzell HC-C4YF-2E SN GL195 N78KL Left prop	
Lube hub IAW hartzell manual 115N Rev 5.	
I certify that this Propeller has been inspected in accordance with a 100hr/Annual inspection and is found to be in an Airworthy condition at this time.	
Kevin Late AP	
Late Aircraft Repair	
10-20-2019 Hobbs 2785 TTP 2169.6 SOH N/A Hartzell HC-C4YF-2E SN GL195 N78KL Left prop	
Lube hub IAW hartzell manual 115N Rev 5.	
I certify that this Propeller has been inspected in accordance with a 100hr/Annual inspection and is found to be in an Airworthy condition at this time.	
Kevin Late AP	
Late Aircraft Repair	
12-17-2020 Hobbs 2866.1 TTP 2250.7 SOH N/A Hartzell HC-C4YF-2E SN GL195 N78KL Left prop	
Lube hub IAW hartzell manual 115N Rev 5.	
I certify that this Propeller has been inspected in accordance with a 100hr/Annual inspection and is	
standard at this offic.	
Kevin Late AP	

 $I \ want \ to \ please \ ask-did \ your \ company \ do \ any \ repair/dressing \ work \ with \ spray \ paint \ on \ the \ left \ propeller \ blades?$ 

Thank you for the help. Have a good week.

Mike

Mike J. Hodges, MS

Aviation Accident Investigator, Central Region

National Transportation Safety Board

14291 East 4<sup>th</sup> Avenue, Suite 7-300

Aurora, Colorado 80011

Cellular:

Facsimile:

Response Operations Center (24/7): 1-844-373-9922

Work Hours: Monday-Friday, 0900-1730 Central Time

"Don't let yesterday use up too much of today." - Will Rogers

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.

From: To:

Subject:

Re: CEN22LA250 (N78KL, Beech 58) - Propeller Blade Maintenance Question (Stallings Aircraft Propeller LLC)

Date: Tuesday, April 18, 2023 5:41:22 PM

Attachments:

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the

The thicker paint/compound you are referring to is a Boot Dressing that is utilized to hold the edges of the Anti-Ice boot down. It's a conductive cement, like an epoxy.

It's a much thicker than the actual Sherwin Williams paint the blade is painted with.

These two propellers were in our shop for a reseal because they had been over serviced at the shop that was maintaining the

We do not have the records(work orders) dating back to 2017, but looking at the quickbooks we performed a basic Reseal, Complied with a Service Bulletin an Trued the ant-Ice Slip rings on both propellers.

If we would have done any blade work or installed new boots it would have been a full Overhaul or an IRAN(Inspect repair as Necessary), at a much higher price.

I will attach a copy of that.

If we can help in any way please don't hesitate to reach out.

5:27








Preview

Email





## INVOICE

**BILL TO** 

Late Aircraft

Pocahontas, AR 72455

INVOICE # **DATE** 08/29/2017 **DUE DATE** 09/28/2017 **TERMS** 

**ACTIVITY** QTY RATE **AMOUNT** 



Invoices not paid within terms are subject to a 2.5% monthly rebilling charge.

PAYMENT BALANCE DUE



Email:

Website: www.stallingsaircraftpropeller.com

## Customize how your invoices look

Thanks.

Cody Stallings Stallings Aircraft Propeller LLC RS# 5JRR748C Office# Hello,

I hope things are going well.

I am with the National Transportation Safety Board, and I have a question please about the incident with N78KL (Beech 58).

Here is the NTSB preliminary report:

https://data.ntsb.gov/carol-repgen/api/Aviation/ReportMain/GenerateNewestReport/105266/pdf

Our materials engineers examined the fracture surfaces on the blade that had the separation. The blade facture surfaces showed signatures consistent with high-cycle fatigue.

<image003.png>

<image004.png>

Our materials engineers also found that for the area of concern, it appeared to be covered with a thick black paint that had a composition that differed slightly from the thinner layer of black paint on the rest of the blade. It is possible that there might have been some underlying damage to the blade, and it might have been covered up with black spray paint.

I was going through the maintenance records for the left propeller, and I saw that Stallings Aircraft Propeller LLC did some previous work on the left propeller back in August 2017.

<image001.png>

<image002.png>

I want to please ask – did your company do any repair/dressing work with spray paint on the left propeller blades?

Thank you for the help. Have a good week.

Mike

Mike J. Hodges, MS Aviation Accident Investigator, Central Region National Transportation Safety Board

14291 East 4<sup>th</sup> Avenue, Suite 7-300 Aurora. Colorado 80011

Cellular: Facsimile:

Response Operations Center (24/7): 1-844-373-9922 Work Hours: Monday-Friday, 0900-1730 Central Time

"Don't let yesterday use up too much of today." – Will Rogers

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.

From: To:

Subject: Re: CEN22LA250 (N78KL, Beech 58) - Additional Question

**Date:** Tuesday, April 18, 2023 8:49:52 PM

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Hi Mike, wow! That's a heck of a picture! I know that I have never done anything to anything on the airplane and I have no knowledge of anyone else doing anything to the props. And I would be highly upset with someone if I new that they covered up something on a prop! I really don't see any of these guys doing anything like that. But I will send you Wilco Aviation and Aaron Farley's phone number. Andy

Sent from my iPhone

On Apr 18, 2023, at 4:23 PM, Hodges Michael wrote:

Hi Andy,

I hope you are doing well.

I have a follow-up question please about the incident with N78KL (Beech 58).

Our materials engineers examined the fracture surfaces on the blade. The blade facture surfaces showed signatures consistent with high-cycle fatigue.

<image003.png>

<image004.png>

Our materials engineers also found that for the area of concern, it appeared to be covered with a thick black paint that had a composition that differed slightly from the thinner layer of black paint on the rest of the blade. It is possible that there might have been some underlying damage to the blade, and it might have been covered up with black spray paint.

I wanted to ask – have you, the airplane owner, or anyone else to your knowledge ever use any spray paint on the left propeller blades?

Also, do you have contact information (telephone number and email) for Wilco Aviation (the mechanic listed in the maintenance records is Aaron L. Farley)? It appears they

were the last company to do maintenance work on the left propeller on 01/10/2022.

Thank you. Have a good week.

Mike

Mike J. Hodges, MS Aviation Accident Investigator, Central Region National Transportation Safety Board

14291 East 4<sup>th</sup> Avenue, Suite 7-300 Aurora, Colorado 80011

Cellular: Facsimile:

Response Operations Center (24/7): 1-844-373-9922 Work Hours: Monday-Friday, 0900-1730 Central Time

"Don't let yesterday use up too much of today." – Will Rogers

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.