

# **Analysis of Modules from Accident WPR19MA177**

S.R. Cain

Prepared for the National Transportation Safety  
Board

October 15, 2019


# Overview of the Analyses

- **Background of the samples**
  - NTBS designation: WPR19MA177
  - Two samples received for non-destructive analysis
    - “Early recovery”
    - “Later recovery”
- **Optical microscopy**
  - Leica Wild M420 zoom stereoscope
  - Bright field and dark field mode
- **X-ray**
  - GE Nanomex
  - 60-75 KV acceleration voltage (60 KV used for direct imaging, 75 KV used for tilted view)
  - 20 uA current
  - Direct and 70° tilted view
  - X-rays hardened with 4 sheets of aluminum foil as a filter
- **Acoustic microscopy**
  - Sonix HS550
  - 50 MHz transducer focused to 16 usec time of flight
  - Pulse echo mode
  - 4 active gates
- **Results for “early recovery” module**
  - SanDisk Extreme 32 GB
    - 3 chips in the module
    - 2 of the chips were stacked
    - Wire bond connections
  - No evidence of thermal damage
  - No evidence of mechanical damage, other than exposure of the package circuit plane from mechanical sanding
  - Wire bonds were intact
  - No evidence of chip cracking or delamination
  - **Evidence would suggest that this is a good candidate for data recovery**
- **Results for “later recovery” module**
  - SanDisk Ultra 32 GB
    - 2 chips in the module
    - Wire bond connections
  - No evidence of thermal damage
  - Two cracks were observed
  - Wire bonds to one of the chips were broken; the crack “missed” this chip
  - Wire bonds to the other chip were intact, but the crack was in the area of the chip
  - **Effective data recovery is doubtful**

Section 1


# EARLY RECOVERY MODULE

# Optical Image of the Top Side (Dark Field)




No evidence of thermal or mechanical damage

# Optical Image of the Bottom Side (Dark Field)



- No evidence of thermal or mechanical damage (other than the mechanical removal of the bottom dielectric)
- Grinding did not go through multiple planes

# X-ray: Global View the Module




# Top Row of Wire Bonds at Higher Magnification (1)



- No evidence of damage to the wire bonds
- Circuitry of the laminate appears to be intact


## Top Row of Wire Bonds at Higher Magnification (2)



- No evidence of damage to the wire bonds
- Circuitry of the laminate appears to be intact




# Top Row of Wire Bonds at Higher Magnification (3)




- No evidence of damage to the wire bonds
- Circuitry of the laminate appears to be intact

# Top Row of Wire Bonds at High Magnification




- No evidence of damage to the wire bonds
- Circuitry of the laminate appears to be intact

# Bottom Row and Left Column of Wire Bonds





- Stitched Images
- No evidence of damage to the wire bonds
- Circuitry of the laminate appears to be intact

# Left Side Wire Bonds at High Magnification




- No evidence of damage to the wire bonds
- Circuitry of the laminate appears to be intact

# Tilted View of the Corner Bonds (70° Tilt)




No evidence of out of plane string of bonds (lack of planar string can indicate that the wire bonds were pulled away from the chip)

# Tilted View of the Top Row of Wire Bonds



- No evidence of damage to the wire bonds
- Different row height confirms stacked configuration of the chips in this area

# Setup for the Sonic Imaging




Overmold

Top chip and SMT components


Bottom chip(s)



Laminate



# Image of the Top Chip



No evidence of damage to the chip



# Image of the Bottom Chip(s)



No evidence of damage to the either chip

# Image of the Top Layer of Circuitry in the Laminate



No evidence of suspicious delaminations in the package;

Section 2


# LATER RECOVERY MODULE

# Optical Image of the Top Side (Dark Field)





- No evidence of thermal
- Two cracks are visible from the surface

# Zoomed View of the Cracks from the Top Side



NOTE: zoomed images are rotated 90°

# Back Side View of the Area with the Fine Crack




- Crack has propagated through the module to the back side circuitry

# Permanent Deformation of the Package




# X-ray Global View of the Package






# Bottom Row of Wire Bonds at Higher Magnification (1)




- No evidence of damage to the wire bonds
- Circuitry of the laminate appears to be intact

## Bottom Row of Wire Bonds at Higher Magnification (2)




- No evidence of damage to the wire bonds
- Circuitry of the laminate appears to be intact

# Bottom Row of Wire Bonds at Higher Magnification (3)




- Stitched image
- No evidence of damage to the wire bonds
- Circuitry of the laminate may be damaged in the area of the crack (arrows)

# Crack in the Area of the 2<sup>nd</sup> Chip (Left side of the Package)





- Broken wire bonds (red arrows)
- Circuitry of the laminate may be damaged in the area of the crack (yellow arrows)
- Crack appears to miss the chip in this area (ball bonds are typically on the periphery of the chip)

# Cracked Area at High Magnification




# Tilted View of the Cracked Area (70° Tilt)



- No evidence of out of plane string of bonds (lack of planar string can indicate that the wire bonds were pulled away from the chip)
- Broken and bent wire bonds, nonetheless, are evident (arrows)




# Cracks Through the Overmold



- Yellow arrows highlight the cracks in the overmold
- The larger crack (left) is partly obscured by the difference in surface height




# Anomalies in the Chip



Shadow of wire bonds

- Yellow arrow highlight the crack (or shadow of the crack) in the chip area
- Suspicious delaminations (bright spots in the chip area, red arrows)
- 2<sup>nd</sup> chip is not visible (obscured by the surface feature)

# Cracks (or Shadows of Cracks) on the Laminate



- Yellow arrows highlight the cracks
- Based upon the optical images of the back side of the laminate, these cracks are not mere shadows, but indeed penetrate to the laminate