

# Hazardous Liquid Pipeline Strike and Subsequent Explosion and Fire Aboard Dredging Vessel Waymon Boyd

Corpus Christi, Texas August 21, 2020

1

### Virtual Board Meeting Staff Participants

Morgan Turrell Director, Office of Marine Safety (OMS) Luke Wisniewski Investigator-in-Charge (MS-10) Nautical Operation (MS-10) Drew Ehlers Mike Hoepf System Safety and Human Performance (RPH-40) Paul Stancil Pipeline Operations (RPH-20) Materials Engineering (RE-30) Frank Zakar Mary Pat McKay Medical Officer (RE-1) Safety Research (RE-10) Eric Emery Writer / Editor (MS-20) Becca Martini



#### Virtual Board Meeting Staff Participants

Kathleen Silbaugh Kathryn Catania Robert Hall Jim Ritter Eric Stolzenberg Liam Larue Rob Jones Mike Budinski Sean Lynum **Bob Beaton** Scott Rainey

General Counsel (GC-1) Deputy Director, Office of Safety Recommendations and Communications (SRC-1) Director, Office of Railroad, Pipeline, and Hazardous Materials Investigations (RPH-1) Director, Office of Research and Engineering (RE-1) Deputy Director, Office of Marine Safety (MS-1) Chief of Marine Investigations (MS-10) Deputy Chief of Marine Investigations (MS-10) Chief of Materials Laboratory (RE-30) Chief of Pipeline and Hazardous Materials (RPH-20) Chief of System Safety (RPH-40) Safety Recommendations (SRC-50)





Accident Overview: Hazardous Liquid Pipeline Strike and Subsequent Explosion and Fire Aboard Dredging Vessel Waymon Boyd

Luke Wisniewski Investigator-in-Charge

#### Staff Who Supported the Investigation

Roger Evans Benjamin Allen Bill English John O'Callaghan Edward Komarnicki Joseph Panagiotou Sean Payne Christy Spangler Katy Chisom Stephanie Matonek Rolando Garcia Jennifer Bishop Nicole Ashby Kristyn Jeschelnik

Pipeline & Hazardous Materials Division (RPH-20) Office of General Counsel (GC-1) Office of Aviation Safety (AS-10) Vehicle Performance Division (RE-60) Materials Laboratory Division (RE-30) Materials Laboratory Division (RE-30) Vehicle Recorder Division (RE-40) Digital Services Division (SRC-60) Transportation Disaster Assistance Division (MD-6) Transportation Disaster Assistance Division (MD-6) Special Operations MD-5 Investigative Products (MD-2I) Writer / Editor (MS-20) Writer / Editor (MS-20



#### Staff Who Produced Virtual Board Meeting

James AndersonAudio Visual Production (SRC-60)Deidre EstersManagement Support Specialist (AD-10)Kelley RomeoEnterprise Architect Coordinator (CIO-60)Rahiq SyedEnterprise Architect Chief (CIO-60)Carl PerkinsManagement Information Specialist (AD-10)Barton BarnumOffice of Marine Safety (MS-10)Brian YoungOffice of Marine Safety (MS-10)



#### Parties to the Investigation

- US Coast Guard
- Pipeline and Hazardous Materials Safety Administration (PHMSA)
- Railroad Commission of Texas
- Orion Group Holdings
- Enterprise Products
- HYPACK, a Xylem brand



#### Corpus Christi, Texas





#### **EPIC Marine Terminal**





Orion Group Holdings



Source: Orion



#### Cutter Suction Dredge Waymon Boyd





#### Enterprise Products Pipeline TX219





#### Waymon Boyd at the EPIC Marine Terminal East Dock

CONTRACTOR DESCRIPTION

Future Location of EPIC Marine Terminal East Dock

EPIC Marine Terminal West Dock

#### Waymon Boyd

A La march of the state of the second

Existing Mooring Dolphins (second dolphin obscured by moored tanker)

# **Corpus Christi Ship Channel**

Source: Orion Marine Group, annotated by NTSB

....



#### EPIC Marine Terminal Security Camera Video





# Initial Information

- August 21, 2020
- 8:02 a.m. Central daylight time
- Dredge Waymon Boyd
- Crew Injuries
  - Four fatal
  - Six serious





# Damages



- TX219 \$2.09 million
- Waymon Boyd \$9.48 million
- EPIC Facility -\$120,000





### Exclusions

- Personnel experience and qualifications of the equipment operators
- Fatigue
- Distraction from cell phone use
- Vessel mechanical and electrical systems failures
- Environmental conditions
- Leak detection systems on pipeline TX219
- Pipeline operating history and operating pressure
- Pipeline integrity
- Transport of non-odorized propane in the pipeline
- Pipeline depth of cover



### Safety Issues

#### • <u>Operations</u>

• Engineering plans, GPS Accuracy, DREDGEPACK, Training

#### • Project Planning & Risk Assessment

• Site Specific Safety Plan, Job Hazard Analysis, Safety Controls

#### • Pipeline Damage Prevention

• One-Call, Pipeline Marking, Tolerance Zones







ntsb.gov





# Nautical Operations

Andrew Ehlers Nautical Operations Group Chairman

#### Dredge Project Engineering Plans





#### Dredge Project Engineering Plans



Source: Orion Marine Group, annotated by NTSB



#### **Dredge Project Engineering Plans**





### What We Found: Dredge Project Engineering Plans

- Plans for the EPIC dock project did not clearly reflect the proximity of the pipeline to the full dredging area
- Schneider Engineering and Consulting did not have specifications, quality control measures, or best practices for including pipeline hazards and tolerance zones in engineering plans and drawings
- What we propose:
  - One recommendation to Orion Group Holdings



## DREDGEPACK Software

# Used aboard dredge to aid leverman

- Displays in real time position of cutterhead relative to dredge plan (template)
- Can display hazards, such as pipelines, and tolerance zones around those hazards





#### Hazard Awareness

- Incorporation of accurate pipeline location data into dredging software on board is a critical tool for avoiding pipeline strikes and other potential hazards
- Orion had no written procedures requiring pipelines or other utilities be entered into DREDGEPACK software
- Although location data was provided to the company, it was not included in the DREDGEPACK dredge template used by the Waymon Boyd
- Orion Marine Group did not have written policies or procedures for planning dredging operations near pipelines



#### What We Found: Hazard Awareness

- Orion Marine Group did not have adequate procedures to require that pipelines be identified and included in DREDGEPACK
- Waymon Boyd's leverman was unaware how close he was operating the cutterhead to the pipeline
- Written policies and procedures could have eliminated confusion about the pipeline location and minimum tolerance distances
- What we propose:
  - One recommendation to Orion Group Holdings



# Dredging Operation Accuracy

- Leverman stated that he did not operate the cutterhead outside the template
- Pipeline about 1' outside of dredge template
- Leverman reliant on DREDGEPACK for position of cutterhead relative to dredge template and any hazards
  - GPS accuracy: 1 meter (3.3 feet)
  - Accuracy of cutterhead position relative to GPS antenna and depth dependent on manual/auto inputs
  - Display resolution accuracy and symbology
- "It's not scalpel surgery"





Waymon Boyd cutterhead



### What We Found: Dredging Operation Accuracy

- GPS margin of error alone could have put the cutterhead within striking distance of the pipeline
- Probability of strike increased by other potential positional errors
- Dredging area specified in engineering plans was too close to pipeline TX219 for safe excavation using a cutterhead dredge.



# **Pipeline Hazard Training**

- Counsel for Dredging and Marine Construction Safety (CDMCS) guidelines recommended actions for a pipeline strike:
  - Immediately stop all operations
  - Shut down or minimize the use of all possible ignition sources
  - Account for crewmembers and communicate the hazards to them
  - Evacuate the vessel, if needed
- *Waymon Boyd* crew not trained in recommended actions for pipeline strike
- Orion had no emergency procedures for pipeline strike

STRIKE IS SOSPECTED			
SHUTDOWN • COMMUNICATE • EVACUATE			
If you recognize <u>ANY</u> signs of a pipeline leak, follow these steps:			
$\bigcirc$	۲	Immediately stop all operations and keep yourself safe.	
$\bigcirc$	0	Shut down or minimize use of all possible ignition sources: motors, generators, lights, etc.	
$\bigcirc$	(i)	Account for all crewmembers & communicate hazards to them.	
$\bigcirc$	•	Call 911 (required), Channel 16, or U.S. Coast Guard & describe your location.	
$\bigcirc$	<u>ů</u>	If possible, drift out of area before starting an ignition source.	
$\bigcirc$	<b>*</b>	Evacuate vessel if needed.	
$\bigcirc$	6	Contact pipeline company emergency number in your plan to shut down the line.	
$\bigcirc$	648	If you see a pipeline sign nearby, call emergency number listed.	
$\bigcirc$	•	Notify U.S. Coast Guard and National Response Center (800)-424-8802.	
$\bigcirc$	<b>&gt;</b>	Call 911 again to update emergency responders on situation.	
$\bigcirc$	Q	Check state laws for other entities you must notify.	
$\bigcirc$	A.	Notify USACE Quality Assurance POC, Safety POC, or Project Manager on the contract.	

=

CDMCS checklist of recommended procedures for pipeline strike



### What We Found: Pipeline Hazard Training

- Waymon Boyd crew lacked function-specific pipeline safety training and emergency procedures that could have prepared them to react quicker and more effectively to the pipeline strike.
- Postaccident, Orion Marine Group instituted utilities awareness training



#### What We Found: Pipeline Hazard Training

- Dredging industry would benefit from training on utilities awareness and emergency procedures in the event of a pipeline strike
- The circumstances of this accident also provide a number of lessons learned
- The Coastal and Marine Operators' (CAMO) Pipeline Industry Initiative online training course could be enhanced by lessons learned from this accident
- What we propose:
  - One recommendation to Coastal and Marine Operators (CAMO)







ntsb.gov



# System Safety: Project Planning & Risk Management

Mike Hoepf, Ph.D.

# **Project Planning**

EPIC

- Had Pipelines identified in a survey
- Requested pipelines included in project drawings

Orion & Schneider

• Specified a dredging area too close to pipeline TX219

#### Enterprise

- Not included in project planning
- May have discovered that dredging area was too close to pipeline TX219 and suggested safer alternatives



# Site-Specific Safety Plan (SSSP)

- Required by Orion's Health Safety and Environmental (HSE) policies manual
- Described as an emergency response plan
- Did not address pipelines, nor any site-specific risk
- Did not help manage risk



# Job Hazard Analysis (JHA)

- JHA required during "preplanning stage" not completed
- Did not complete a risk assessment
- Risk not documented or understood



Individual	Understanding of Distance Between Dredge Area and Pipelines
Schneider Design Engineer	8-10 feet
Orion Regional HSE Manager	Not aware of pipeline TX219
Orion Project Manager	30 feet
Orion Project Engineer	60 feet
Waymon Boyd Dredge Captain	Instructed to remain 20 feet from pipelines
Waymon Boyd Deck Captain	Instructed to remain 20 feet from pipelines
Waymon Boyd Accident Leverman	Not aware of pipeline TX219
Majority of <i>Waymon Boyd</i> Crew	Not aware of pipeline TX219
Enterprise One-Call Technicians	55 feet
	Actual distance about 1 fact

Actual distance about 1 foot



# Safety Controls

#### Effective controls

- Protect workers from workplace hazards
- Help avoid injuries, illnesses, and incidents

#### Hierarchy of controls to mitigate hazards

- Eliminate hazard > Engineering controls
- Engineering controls > Administrative controls

#### Engineering controls were available

• Establish tolerance zones around the pipelines



#### Proposed Bulkhead







### What We Found: Risk Management

- Project planning and risk management were inadequate
- Failure to identify and mitigate the risk of a cutterhead impact with pipeline TX219
- Critical that organizations have project planning steps that support accurate risk assessment and proportionate mitigation
- What we propose:
  - One recommendation to Orion







ntsb.gov



# Pipeline: Damage Prevention Safety Issues

Paul Stancil Pipeline Operations Group Chairman

# **One-Call Notification**

- Connect excavators with affected utility operators
- Orion Marine Group one-call notification
- Two pipelines identified near project area
- No on-site plan review
- Incomplete and misleading dredging plans



# **One-Call Communications**

- Orion Marine Group project engineer misinterpreted drawings
- Project engineer communicated incorrect dredging boundaries
  - Dredging would be 60 feet from pipelines
  - Dock platform (near shore) dredging already completed to grade
  - "Shouldn't be a need for concern"



#### Misleading Dredging Plans





# **One-Call Closeout**

- Believed pipeline TX219 would be clear of project
- Determined dredging boundary exceeded 50-foot limit for mandatory marking



#### Dredging Plan Analysis





### What We Found: One-Call for Dredging Projects

- Inaccurate communications and misinterpreted plans
- No pipeline markings or other protective measures
- Greater collaboration needed between pipeline and dredging companies
- What we propose:
  - One recommendation to Orion Marine Group
  - Recommendations to PHMSA, CAMO, and CDMCS



### Pipeline Locating and Marking

- Pipeline was not marked for excavation damage avoidance
- Follow up marking request for dredge anchor avoidance
- Courtesy marked with widely-spaced cane poles



#### **Pipeline Marking Options**





Source: Orion Marine Group

#### Courtesy marking (pre-accident)

#### Mandatory marking (post-accident)



# Dredge Area Pre-marking

- Pre-marking informs pipeline operator of proposed excavation areas
- 1997 NTSB safety study: pre-marking helps prevent excavation damage
- State regulations require pre-marking, but do not address marine construction
- Pre-marking could have prompted mandatory pipeline marking



### What We Found: Pipeline and Dredge Area Pre-marking

- Courtesy marking was not sufficient visual warning
- Project boundary pre-marking would provide visual confirmation of pipeline encroachment
- What we propose:
  - Recommendations to PHMSA, CAMO, and CDMCS



### Pipeline Tolerance Zones for Dredging

- Tolerance zones define areas where no mechanical excavation should occur
- Regulated tolerance zones intended for land-based excavation
- Best-practice tolerance zones developed by some companies
  - Some pipeline companies request up to 500 feet
  - Most dredging companies use 75 feet



#### What We Found: Tolerance Zones for Dredging

- Inherent cutterhead location inaccuracies make regulated tolerance zones inadequate for safe dredging
- Enterprise damage prevention program does not provide sufficiently large tolerance zone
- What we propose:
  - One recommendation to PHMSA
  - One Recommendation to Enterprise Products







ntsb.gov