

# **Service Report**

Make AA Work Order Status Invoiced Model 3516B Request ID 649524 Serial No. 09AN00260 Work Order No PW01349 **Delivered Date** Store No 00 **Contact Name** JACK CUTTITTE **Customer Name** OCEAN SERVICES LLC Employee ID Contact Phone **Customer Number Equipment Location** EMAILED PROFORMA 9/15 AO Date 07/15/2021 Service Meter Instructions OCEAN GUARDIAN--ALL 4 3516 GENS--SCHED THURS 7/22 Equipment No Purchase Order Job Control RR Vehicle No. Eng Serial No 09AN00260 P.O. Required NO Product ID No. Vehicle Make Eng Make AA Perf Spec 0K-2417 3516B Vehicle Model Eng Model Product Code 1743191 Vehicle Arr. No Eng Arr. No Warranty Standard Component Special Type Task MCustNo MCustCls LCustNo LCustNo PCustNo PCustCls Center Job Code Hours Seg Oper F/R Instructions Code Code Description 0.00 CUSTOMER ME 1901 598 01 0.0000 DOWNLOAD/UPLO QUESTIONS RECENT AD ENG INJECTOR FAILURES-**ELECTRONIC** ALL 43516 GENSETS CONT MOD 9AN00260-263 Warranty Standard Cost Component Special Type Task MCustNo MCustCls LCustNo LCustNo PCustNo PCustCls Center Job Code Hours Seg Oper F/R Instructions Code Description 0.00 TO/FROM STABBERT ME 1000 056 99 365.00 TRAVEL TO/FROM **ENGINE** 00 SERVICE COMMENTS Customer Signature Page 1 of 3 Technician Signature

Wednesday, June 08, 2022 01:06 PM

Report Generated by Wayne Valenta



# Service Report

Model 3516B Serial No. 09AN00260 Make AA

Request ID 649524 Work Order No PW01349 Work Order Status Invoiced

Delivered Date

\_\_\_\_

01

Repair Comment

Ocean Guardian:

Generator #1 9AN00263- Crew says #15 cylinder was running ~100f hotter than rest. Pull valve cover and inspect, setting looks OK, injector already an 0R number, but trim code was incorrect, input correct trim code into ECM, will need to run under load and verify. Engine hours also had reset themselves at 65,515, now reads 546. I reset the ECM but was only able to reset them to the old number of 65,515, this might be as high as the ECM can go, will need to run engine to confirm. Also, engine has code for erratic/abnormal turbine temps for LH + RH. The crew knows and is trying to replace both probes, needs correct adapter because they updated to a new style.

Generator #2 9AN00261- Crew claims engine will not reach 1800 RPM. Was not able to verify because they have coolant system taken apart right now, possible governor (Woodward) setting issue. They claim the fuel filters and fuel system has already been verified. Apparently generator went into reverse power alarm while transiting and hasn't worked since, might need EPG guy to take a look. Also, already had injectors 8+13 replaced, don't know cause or why, probably saw high or low EGTs.

Generator #3 9AN00260- Claims injectors 6+10 might need replacing, 3rd engineer did not know why or how they came to that conclusion, possibly been watching EGT temps. MAY have changed them in Hawaii, need to ask Jack.

Generator #4- 9AN00262- Engine has fault for injector #9 "OPEN". Remove valve cover and inspect, all OK inside. Remove harness and short pins, code does not change. Harness has open somewhere between ECM and injector. Either need to attempt to find the open, make an overlay harness or replace the entire engine harness.

### ALSO

Ocean Titan (LLB00137-140) is parked next to these guys, we topended all 4 engines back in Nov 2019. They are going on a long trip at the start of AUG and would like someone to come down and perform a full valve adjust and general inspection on all 4. TALK TO JACK, the crew is also putting a bug in his ear.

Customer Signature	Page 2 of 3	Technician Signature	



### Service Report

3516B Model

Make AA

Request ID 649524 Work Order No PW01349 Work Order Status Invoiced Delivered Date

Serial No. 09AN00260

99

Repair Comment

Ocean Guardian:

Generator #1 9AN00263- Crew says #15 cylinder was running ~100f hotter than rest. Pull valve cover and inspect, setting looks OK, injector already an 0R number, but trim code was incorrect, input correct trim code into ECM, will need to run under load and verify. Engine hours also had reset themselves at 65,515, now reads 546. I reset the ECM but was only able to reset them to the old number of 65,515, this might be as high as the ECM can go, will need to run engine to confirm . Also, engine has code for erratic/abnormal turbine temps for LH + RH. The crew knows and is trying to replace both probes, needs correct adapter because they updated to a new style.

Generator #2 9AN00261- Crew claims engine will not reach 1800 RPM. Was not able to verify because they have coolant system taken apart right now, possible governor (Woodward) setting issue. They claim the fuel filters and fuel system has already been verified. Apparently generator went into reverse power alarm while transiting and hasn't worked since, might need EPG guy to take a look. Also, already had injectors 8+13 replaced, don't know cause or why, probably saw high or low EGTs.

Generator #3 9AN00260- Claims injectors 6+10 might need replacing, 3rd engineer did not know why or how they came to that conclusion, possibly been watching EGT temps. MAY have changed them in Hawaii, need to ask Jack.

Generator #4- 9AN00262- Engine has fault for injector #9 "OPEN". Remove valve cover and inspect, all OK inside. Remove harness and short pins, code does not change. Harness has open somewhere between ECM and injector, Either need to attempt to find the open, make an overlay harness or replace the entire engine harness.

Ocean Titan (LLB00137-140) is parked next to these guys, we topended all 4 engines back in Nov 2019. They are going on a long trip at the start of AUG and would like someone to come down and perform a full valve adjust and general inspection on all 4, TALK TO JACK, the crew is also putting a bug in his ear.

Customer Signature	Page 3 of 3	Technician Signature	