



Aviation Investigation Factual Report

Location:	Carroll, Iowa	Accident Number:	CEN21LA319
Date & Time:	July 13, 2021, 16:54 Local	Registration:	N7315P
Aircraft:	AIR TRACTOR INC AT-401	Aircraft Damage:	Substantial
Defining Event:	Sys/Comp malf/fail (non-power)	Injuries:	1 None
Flight Conducted Under:	Part 137: Agricultural		

Factual Information

On July 13, 2021, at 1654 central daylight time, an Air Tractor Inc. AT-401, N7315P, sustained substantial damage when it was involved in an accident near Carroll, Iowa. The pilot was not injured. The airplane was operated under Title 14 *Code of Federal Regulations* Part 137 as an aerial application flight.

The pilot stated that he had completed half of the planned aerial application of a field when the engine lost power coming out of a turn. The pilot then performed a forced landing. The airplane impacted terrain and sustained substantial damage to its wings.

The airplane was modified by the installation of a Walter M601E-11 turbine engine through supplemental type certificate SA01281CH issued to Johnson Airspray Inc.

On-scene examination of the engine by a Federal Aviation Administration (FAA) principal maintenance inspector and representatives from GE Aviation revealed no mechanical anomalies that would have precluded normal operation. Subsequent removal and testing of the engine-driven fuel pump and fuel control revealed that both units met test specifications.

During the on-scene examination, a crane was used to level the aircraft, which ensured that the airplane header fuel tank was full. The main fuel line from the airplane fuel filters to the engine-driven fuel pump was disconnected at the fuel pump end and placed in a bucket to capture fuel. The electric-driven airframe inline boost pump was turned on, and there was no fuel flow from the main fuel line. The B-nut on the hose from the header tank to the selector valve was loosened at the selector valve end to confirm there was fuel in the header tank, and fuel was noted to be present. The B-nut was retightened, and the output fuel line from the airframe boost pump was loosened; a small amount of fuel dripped. The dripping could be stopped and started by opening and closing the airplane fuel selector valve. The airframe boost pump was again turned on; there was no steady flow output; and there was no bypass of fuel. The airframe boost pump was removed for further testing and examination at its manufacturer.

The airframe boost pump was a Weldon pump, part number 2003-B, serial number 130661, manufacturing date August 6, 2007. The pump was sent to the facilities of Weldon Pump for testing and examination under the supervision of an FAA aviation safety inspector. During testing, the pump was placed on a test stand and power was applied. The pump energized and turned; however, there was no fuel output, and fuel leaked from the shaft seal. The pump bypass was also checked on the test stand with no restrictions noted; fuel was able to flow through the pump. Disassembly of the pump from its electric motor revealed the motor's slotted shaft was worn to the point that it would not engage with the pump's rotor tang. Weldon Pump representatives stated that the company recommended a 10-year overhaul

requirement of the pump. There was no time-in-service requirement in Weldon Pump's recommendation.

An airplane logbook record, dated July 8, 2013, with an hour meter reading of 2,497.8 hours, stated, "R&R FUEL PUMP P/N 2003B WITH OH UNIT. OPS CHECK GOOD." At the time of the accident, the hour meter indicated 5,136.7 hours.

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	51, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	Helicopter	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	November 4, 2021
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	June 25, 2021
Flight Time:	5600 hours (Total, all aircraft), 600 hours (Total, this make and model), 5513 hours (Pilot In Command, all aircraft), 165 hours (Last 90 days, all aircraft), 85 hours (Last 30 days, all aircraft), 9 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	AIR TRACTOR INC	Registration:	N7315P
Model/Series:	AT-401	Aircraft Category:	Airplane
Year of Manufacture:	1987	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	401-0672
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	9100 lbs
Time Since Last Inspection:		Engines:	1 Turbo prop
Airframe Total Time:		Engine Manufacturer:	Walter
ELT:	Not installed	Engine Model/Series:	M601E-11
Registered Owner:	Central AG LLC	Rated Power:	750
Operator:	Central AG LLC	Operating Certificate(s) Held:	Agricultural aircraft (137)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	CIN,1204 ft msl	Distance from Accident Site:	4 Nautical Miles
Observation Time:	16:55 Local	Direction from Accident Site:	50°
Lowest Cloud Condition:	Clear	Visibility	8 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.01 inches Hg	Temperature/Dew Point:	24°C / 23°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Carroll, IA (CIN)	Type of Flight Plan Filed:	None
Destination:	Carroll, IA (CIN)	Type of Clearance:	None
Departure Time:	16:20 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.0656,-94.8673(est)

Administrative Information

Investigator In Charge (IIC):	Gallo, Mitchell
Additional Participating Persons:	Brian Lundquist; Federal Aviation Administration; Des Moines FSDO; Ankeny, IA David Osborne; Federal Aviation Administration, Cleveland FSDO; North Olmsted, OH Sam Farmiga; GE Aviation, US; Cincinnati, OH John McClure; Weldon Pump; Cleveland, OH
Report Date:	December 28, 2022
Last Revision Date:	
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=103480

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).