



Accident Number:

Aircraft Damage:

Registration:

FTW96LA057

N8603A

Destroyed

Aviation Investigation Factual Report

Location: LOVELAND, Colorado

Date & Time: November 30, 1995, 13:30 Local

Aircraft: BEECH D18S

Defining Event: 1 Serious, 2 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Factual Information

On November 30, 1995, approximately 1330 mountain standard time, a Beech D18S, N8603A, was substantially damaged when it collided with terrain during landing at Loveland, Colorado. The commercial pilot-in-command was seriously injured, and the commercial rated-second pilot and a pilot rated-passenger received minor injuries. Visual meteorological conditions prevailed, and no flight plan was filed for the personal flight conducted under Title 14 CFR Part 91 that originated at Fort Collins, Colorado, on November 30, 1995, approximately 1320.

The following is based on the Pilot/Operator Report submitted by the pilot-owner/operator, who was seated in the right seat. He said the pilot in the left seat flew the airplane from Fort Collins-Downtown Airpark to Fort Collins-Loveland Airport without incident. The wind was reported to be from the southwest at 20 knots with no reference to gusts. An approach to runway 15 was made in stable air with a right crosswind correction. The airplane was aligned approximately 40 feet left of runway centerline. The pilot failed to flare for landing, and the airplane contacted the runway and bounced back into the air with the right wing high. The airplane began to drift to the left. The pilot did not correct and the pilot-owner tried to lower the wing. A wind gust caused the airplane to drift further left of centerline. The pilot-owner then attempted to abort the landing and applied full power. The airplane collided with the ground and cartwheeled. Both engines were sheared off and the nose was crushed. The right propeller struck and penetrated the cabin roof above the right pilot's seat.

The following is based on the Pilot/Operator Aircraft Accident Report submitted by the second pilot. He said he was "receiving training" from the pilot-owner, and was "not at the controls" at the time of the accident. Of the number of hours he has logged in the Beech 18 or C-45, less than two hours were spent in landing practice.

Airport personnel said that when the pilot made his initial radio call, they told him the winds were from 270 degrees at 20 knots and gusting to 28 knots. A flight instructor who witnessed the accident said the landing on runway 15 appeared normal. The right wing suddenly came up and the left wing scraped the ground, spinning the airplane around in the median between the runway and the taxiway. The Colorado State Patrol reported that at the time of the accident, one of its officers was investigating an accident involving a "high profile" vehicle (tractor trailer) that had been blown over by the high winds. The accident was on Interstate Highway 25, just south of the airport.

Page 2 of 5 FTW96LA057

Pilot Information

| Certificate: | Commercial | Age: | 41,Male |
|---------------------------|--|------------------------|-------------------|
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Right |
| Other Aircraft Rating(s): | Helicopter | Restraint Used: | |
| Instrument Rating(s): | Airplane; Helicopter | Second Pilot Present: | Yes |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 2 Valid Medicalno waivers/lim. | Last FAA Medical Exam: | September 6, 1995 |
| Occupational Pilot: | No Last Flight Review or Equivalent: | | |
| Flight Time: | 7000 hours (Total, all aircraft), 800 hours (Total, this make and model), 6000 hours (Pilot In Command, all aircraft), 90 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | BEECH | Registration: | N8603A |
|----------------------------------|-------------------------|--|-------------------------------|
| Model/Series: | D18S D18S | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | A-557 |
| Landing Gear Type: | Retractable - Tailwheel | Seats: | 2 |
| Date/Type of Last Inspection: | January 10, 1995 Annual | Certified Max Gross Wt.: | 8750 lbs |
| Time Since Last Inspection: | | Engines: | 2 Reciprocating |
| Airframe Total Time: | 11281 Hrs | Engine Manufacturer: | P&W |
| ELT: | | Engine Model/Series: | R-985-AN14B |
| Registered Owner: | SKYDIVE ASSETS, INC. | Rated Power: | 450 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |
| ELT: Registered Owner: Operator: | | Engine Model/Series: Rated Power: Operating Certificate(s) Held: | R-985-AN14B 450 Horsepower |

Page 3 of 5 FTW96LA057

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|------------------------------|--------------------------------------|-------------|
| Observation Facility, Elevation: | FNL ,5016 ft msl | Distance from Accident Site: | |
| Observation Time: | 14:15 Local | Direction from Accident Site: | |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 24 knots / 30 knots | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 240° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 29 inches Hg | Temperature/Dew Point: | 18°C / -4°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ation | |
| Departure Point: | FORT COLLINS (3V5) | Type of Flight Plan Filed: | None |
| Destination: | (FNL) | Type of Clearance: | None |
| Departure Time: | 13:20 Local | Type of Airspace: | Class E |

Airport Information

| Airport: | FORT COLLINS-LOVELAND MUN FNL | Runway Surface Type: | Asphalt |
|----------------------|----------------------------------|---------------------------|--------------|
| Airport Elevation: | 5016 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 15 | IFR Approach: | None |
| Runway Length/Width: | 8500 ft / 100 ft | VFR Approach/Landing: | Touch and go |

Wreckage and Impact Information

| Crew Injuries: | 1 Serious, 1 Minor | Aircraft Damage: | Destroyed |
|------------------------|--------------------|-------------------------|----------------------------|
| Passenger Injuries: | 1 Minor | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 Serious, 2 Minor | Latitude, Longitude: | 40.409156,-105.069465(est) |

Page 4 of 5 FTW96LA057

Administrative Information

Investigator In Charge (IIC): Scott, Arnold

Additional Participating Persons:

Report Date: January 29, 1996

Last Revision Date:
Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=19719

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 FTW96LA057