



Aviation Investigation Factual Report

Location:	Ozona, Texas	Accident Number:	FTW02LA018
Date & Time:	October 19, 2001, 21:20 Local	Registration:	N8642Y
Aircraft:	Piper PA-30	Aircraft Damage:	Substantial
Defining Event:		Injuries:	4 Serious
Flight Conducted Under:	Part 91: General aviation - Personal		

Factual Information

On October 19, 2001, at 2120 central daylight time, a Piper PA-30, twin engine airplane, N8642Y, struck transmission lines and the terrain during a forced landing following a loss of engine power near Ozona, Texas. The airplane was owned and operated by a private individual under 14 Code of Federal Regulations Part 91. The airline transport pilot and the three passengers received serious injuries. The airplane sustained substantial damage. Dark night visual meteorological conditions prevailed for the cross-country flight with a planned refueling stop at San Angelo, Texas. The personal flight departed Lajitas, Texas, approximately 2020.

Witnesses located at the Lajitas Airport, reported that the airplane landed at Lajitas at 1930, on the unlighted 4,500-foot asphalt runway 04. One witness stated that sunset occurred at 1918, with dark night (1/4 moonlight) conditions. Skies were clear with a light breeze. Witnesses/local authorities reported that the airplane departed the airport to the east and climbed to the east/northeast.

The pilot reported that he flew the airplane from the Addison Airport, Dallas, Texas, to Lajitas, Texas, where the three passengers boarded the airplane for the return flight to Fort Worth. Fuel was not available at Lajitas. During the takeoff initial/climb, the pilot maintained full power on the engines until reaching cruise altitude. En route, at 9,500 feet msl, the pilot requested and received flight following from Albuquerque Air Route Traffic Control Center (ABQ ARTCC) and Houston ARTCC. When the flight was in the vicinity of the Ozona Municipal Airport, the pilot made a decision to land the airplane and refuel. The pilot reported that he tried to activate the pilot controlled runway lights on a frequency of 122.8 Megahertz (KHz) and "there were no lights or rotating beacon operating at the airport." After approximately 20 minutes of flying over Ozona and looking for the airport north of town, the left engine lost power due to fuel starvation. The pilot secured the left engine. Approximately 10 minutes later, the right engine lost power due to fuel starvation. Upon seeing a vacant lot, the pilot initiated the emergency landing procedures and extended the landing gear. During the approach, the upper portion of the vertical stabilizer struck power lines, the airplane nosed down, and subsequently, the airplane slid to a stop in the vacant lot.

Local authorities at Ozona reported that the night was "clear with light wind." The pilot reported dark night light conditions, clear skies, visibility 30 miles with no restrictions to visibility, and the wind calm. The utility company reported the power outage occurred about 2120.

A review of the Houston Air Route Traffic Control Center (ARTCC) data revealed that at 2049:55, when Houston ARTCC received a handoff from Albuquerque ARTCC, the airplane was approximately 47 nautical miles from Lajitas at latitude 29 degrees 04.06 minutes North, longitude 103 degrees 02.06 minutes West. The flight altitude readout was 9,500 feet with an

en route ground speed of 150 knots. At 2106, the aircraft was approximately 25 nautical miles from Ozona, Texas, when the pilot informed the controller that he would land the airplane at Ozona and refuel. At 2112, the airplane, at an altitude of 7,000 feet msl, was approximately 18 nautical miles from Ozona, when the Houston ARTCC controller tried to contact the pilot to terminate the flight following procedures and clear the pilot for a frequency change; however, the pilot did not respond. The controller continued to track the aircraft, and at 2017:21, the airplane, at an altitude of 4,000 feet msl (1,500 feet agl) was approximately 8 nautical miles from Ozona.

At the time of the accident, the airline transport rated pilot held airplane multiengine, single-engine, and instrument ratings. The pilot held a third class medical certificate, issued on August 24, 2000, with no limitations. On the Pilot/Operator Aircraft Accident Report (NTSB 6120.1/2) the pilot reported 2,879.4 hours of accumulated flight time, of which 1,510.1 hours was in multiengine airplanes. The pilot reported 607.8 hours of accumulated flight time in the make and model of the accident airplane, of which 11.4 was in the previous thirty days. The pilot's last biennial flight review was performed in September 2001 in a single-engine airplane.

A review of the maintenance records and FAA data by the FAA inspector revealed that the 1968 model Piper PA-30, serial number 30-1784, was purchased by the current owner on October 17, 2001. Both engines were Lycoming model IO-320-C1A, and each engine was equipped with the Hartzell propeller, model HC-E2YL-2BSF. The records indicated that the aircraft had accumulated 5,509.3 hours, the left engine 1,514.5 hours since major overhaul, and the right engine time 5,509.3 hours when the most recent annual inspection was performed on June 14, 2001.

The Ozona Municipal Airport (OZA), located approximately 1 mile north of Ozona, is owned and operated by the City of Ozona, Texas. Airport elevation is 2,381 feet. OZA is a non-towered airport with a single runway (runway 16/34). Runway 16/34 is an asphalt runway, 6,000 feet long, and 75 feet wide. A preset timer operates the runway lights at the low intensity and the taxiway lights; however, the intensity of the runway lights may be changed when the pilot keys the airplane microphone over the common traffic advisory frequency (CTAF) 122.8 KHz.

Witnesses, located at and in the vicinity of the Ozona Municipal Airport, reported the runway lights were on at the time they observed the airplane maneuvering near the airport. One witness stated to the best of her knowledge "all lights on [the] runway and [the rotating] beacon were working." On October 21, 2001, the FAA inspector observed the operation of the runway lights (frequency 122.8 KHz) and the rotating beacon. He reported the runway lights and beacon were operational.

Local authorities and the FAA inspector, responding to the site, found the airplane approximately 1 1/4 mile south and 1/4 mile west of the airport runway, resting upright in a parking lot approximately 100 feet beyond downed transmission lines. The upper 6 inches of the vertical stabilizer exhibited striations consistent with the size of the transmission cables. The right engine was separated from the firewall. The left propeller was feathered and the

right propeller exhibited "no evidence of power." One main landing gear was found approximately 6 feet prior to the resting position of the airplane. No evidence of fuel was found in either the area surrounding the accident site or in the aircraft's fuel tanks. No mechanical discrepancies were found that would have prevented operation of the airplane prior to the accident.

Pilot Information

Certificate:	Airline transport	Age:	52, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	August 24, 2000
Occupational Pilot:	No	Last Flight Review or Equivalent:	September 10, 2001
Flight Time:	2879 hours (Total, all aircraft), 608 hours (Total, this make and model), 2748 hours (Pilot In Command, all aircraft), 41 hours (Last 90 days, all aircraft), 37 hours (Last 30 days, all aircraft), 8 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N8642Y
Model/Series:	PA-30	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	30-1784
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	June 14, 2001 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	5509.3 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	IO-320-C1A
Registered Owner:	Sheila M. Arthur	Rated Power:	160 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night
Observation Facility, Elevation:	SJT, 1919 ft msl	Distance from Accident Site:	54 Nautical Miles
Observation Time:	20:53 Local	Direction from Accident Site:	35°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	30°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.95 inches Hg	Temperature/Dew Point:	20°C / 11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Lajitas, TX (17XS)	Type of Flight Plan Filed:	None
Destination:	San Angelo, TX (SJT)	Type of Clearance:	VFR flight following
Departure Time:	20:20 Local	Type of Airspace:	Class E

Airport Information

Airport:	Ozona Municipal OZA	Runway Surface Type:	Asphalt
Airport Elevation:	2381 ft msl	Runway Surface Condition:	Dry
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	6000 ft / 75 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	3 Serious	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 Serious	Latitude, Longitude:	30.735277,-101.203056

Administrative Information

Investigator In Charge (IIC):	Roach, Joyce
Additional Participating Persons:	Rick J Gorry; FAA FSDO; San Antonio, TX
Report Date:	December 19, 2002
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=53641

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).