



# Aviation Investigation Factual Report

<b>Location:</b>	Yuma, Arizona	<b>Accident Number:</b>	LAX02LA236
<b>Date &amp; Time:</b>	July 22, 2002, 21:00 Local	<b>Registration:</b>	N756EV
<b>Aircraft:</b>	Cessna TR182	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Factual Information

On July 22, 2002, about 2100 mountain standard time, a Cessna TR182, N756EV, landed with the gear partially extended at the Yuma International Airport, Yuma, Arizona. The pilot/owner was operating the airplane under the provisions of 14 CFR Part 91. The commercial pilot, the sole occupant, was not injured; the airplane sustained substantial damage. The cross-country personal flight departed the Fresno Yosemite International Airport, Fresno, California, about 1810 Pacific daylight time, with a planned destination of Yuma. Visual meteorological conditions prevailed, and a flight plan had not been filed.

During a telephone interview with a National Transportation Safety Board investigator, the pilot reported that he was attempting to land on runway 17 in night conditions. Upon touchdown, he did not recall feeling anything abnormal. As he started the landing roll, the airplane lifted up and then began to move back down, which he thought was a feeling consistent with the landing gear retracting. He explained that the Cessna 182's landing gear is designed in such a way that the gear retracts by extending down first, and will subsequently retract up, inside the fuselage. As the airplane began to sink, he inadvertently applied rudder inputs, resulting in the airplane veering off the runway. He noted that the nose gear remained in the down and locked position the entire duration of the accident sequence.

The pilot described his usual procedures of verifying that the landing gear was in a down and locked position. He stated that he visually looks at the gear handle, checking to make sure that it is in the corresponding down position. He checks to make sure that the gear indicator light is illuminated green. He looks out the window to get a visual confirmation that the landing gear is in the appropriate position. Finally, while landing, he listens for the gear warning horn, which is a horn that will sound if the gear is retracted and the manifold pressure is low.

The pilot further explained that the airplane has one sole gear-indicator light. When the landing gear is in the down and locked position, the gear indicator light can be dimmed by turning the knob that the indicator light is located in. When turned counterclockwise, the bulb is fully revealed, which illuminates the indicator light bright green. When turned clockwise, the bulb becomes covered and no illumination will be seen, making the knob dark. The knob also serves as a "press to test" button, which, once depressed, will illuminate bright green indicating that the light is functional. The gear indication light will not illuminate by turning the knob if the gear is not in the down and locked position; however, it will illuminate if the "press to test" button is depressed and the gear is not in the down and locked position.

Being a retired United States Air Force pilot, who was often flying night missions, the pilot stated that he likes the cockpit to be dark. He often dims all of the panel lights in an effort to help his eyes adjust, which facilitates his night vision. He stated that the night of the accident

he probably had the gear indicator light turned fully clockwise, in the full-dark position. While on final approach, he remembers specifically seeing the gear indicator light illuminated green. He said that is was a possibility that while attempting to illuminate the light by turning the knob counterclockwise, he had accidentally depressed the indicator knob. This would have given him a false indication that the gear was in the down and locked position.

The pilot stated that he did not hear the gear warning horn sound before touchdown. He does not remember if he looked out the window to confirm if the gear was down, but thought the night conditions might have made it difficult for him to determine their position.

A National Transportation Safety Board investigator interviewed an inspection authorization (IA) mechanic, who examined the damage to the airplane that incurred during the accident. He stated that the illumination setting for the gear indicator was in the dim position, which would make the green indicator light very difficult to see in dark conditions. He talked to other mechanics in Yuma that inspected the airplane immediately after the accident. Upon arriving at the wreckage, they noted that the circuit breaker for the landing gear had popped out. After resetting the circuit breaker, they put the airplane on jacks and cycled the landing gear. They found no mechanical deficiencies with the landing gear. The IA also cycled the land gear and inspected the system, finding no anomalies or mechanical defects. The IA further noted that the landing gear is designed in such a way that the nose wheel extends first, with the main gear simultaneously following.

### Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	70, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical--w/ waivers/lim	<b>Last FAA Medical Exam:</b>	July 17, 2001
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	July 1, 2002
<b>Flight Time:</b>	9150 hours (Total, all aircraft), 2970 hours (Total, this make and model), 60 hours (Last 90 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N756EV
<b>Model/Series:</b>	TR182	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	R18201056
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>		<b>Certified Max Gross Wt.:</b>	3100 lbs
<b>Time Since Last Inspection:</b>	60 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	2970 Hrs	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>		<b>Engine Model/Series:</b>	O-540-L3C5D
<b>Registered Owner:</b>	Ted Smith Equipment Company	<b>Rated Power:</b>	250 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Night
<b>Observation Facility, Elevation:</b>	NYL,213 ft msl	<b>Distance from Accident Site:</b>	1 Nautical Miles
<b>Observation Time:</b>	02:56 Local	<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Few / 20000 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	9 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	180°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.73 inches Hg	<b>Temperature/Dew Point:</b>	36°C / 10°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Fresno, CA (FAT )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Yuma, AZ (YUM )	<b>Type of Clearance:</b>	VFR
<b>Departure Time:</b>	18:10 Local	<b>Type of Airspace:</b>	Class D

## Airport Information

<b>Airport:</b>	Yuma International Airport YUM	<b>Runway Surface Type:</b>	Concrete
<b>Airport Elevation:</b>	216 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	17	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	5711 ft / 150 ft	<b>VFR Approach/Landing:</b>	Full stop

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	32.656387,-114.605834

## Administrative Information

Investigator In Charge (IIC):	Petterson, George
Additional Participating Persons:	Bruce Smith; Federal Aviation Administration; Scottsdale, AK
Report Date:	July 26, 2004
Last Revision Date:	
Investigation Class:	<a href="#">Class</a>
Note:	
Investigation Docket:	<a href="https://data.nts.gov/Docket?ProjectID=55314">https://data.nts.gov/Docket?ProjectID=55314</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).