



Aviation Investigation Factual Report

Location:	Plymouth, Michigan	Accident Number:	CHI03LA011
Date & Time:	October 20, 2002, 11:20 Local	Registration:	N56655
Aircraft:	Piper PA-32-300	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Factual Information

On October 20, 2002, about 1120 eastern daylight time, a Piper PA-32-300, N56655, piloted by a private pilot, sustained substantial damage when it went off the right side of the runway and struck a part of the visual approach slope indicator (VASI) system. The airplane was landing on runway 36 (2,556 feet by 75 feet, asphalt), at the Canton-Plymouth Mettetal Airport (1D2), Plymouth, Michigan. when the accident occurred. The 14 CFR Part 91 personal flight was operating in visual meteorological conditions. The pilot and passenger were not injured. The flight departed Paul C. Miller - Sparta Airport (8D4), Sparta, Michigan, at 1030.

The pilot reported that upon landing on runway 36, the winds were 270 at 8 knots. He stated that upon touching down he realized he was moving a little fast; the airplane didn't settle and seemed to float. He applied braking to slow down but the right brake was not working. The pilot attempted to slow the airplane by using left braking and right rudder. The pilot reported that the aircraft then veered to the right (east side) and went off the runway. The pilot noted that he attempted to bring the airplane back onto the runway. The aircraft subsequently struck the VASI system with the left wing and the airplane caught fire. The pilot and his passenger safely exited the aircraft and the fire was put out by the pilot and airport staff.

The pilot made a flight the day prior to the accident and reported that the brakes were working fine. The pilot stated "Had I known the brake fluid was low again, and that I did not have complete brake function, I wouldn't have made the flight." He reported that he had maintenance performed on the brakes on August 8th and September 25th of 2003, at which time the mechanic bled the lines and added fluid.

The pilot reported that, subsequent to the accident, a seal within the brake master cylinder was found to be defective. He reported that this allowed the fluid level to be low and air to enter the brake lines.

Pilot Information

Certificate:	Private	Age:	47,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	June 26, 2001
Occupational Pilot:		Last Flight Review or Equivalent:	April 13, 2002
Flight Time:	277 hours (Total, all aircraft), 156 hours (Total, this make and model), 211 hours (Pilot In Command, all aircraft), 40 hours (Last 90 days, all aircraft), 13 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N56655
Model/Series:	PA-32-300	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	32-7440012
Landing Gear Type:	Tricycle	Seats:	6
Date/Type of Last Inspection:	January 2, 2003 Annual	Certified Max Gross Wt.:	3400 lbs
Time Since Last Inspection:	137.32 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5049.12 Hrs	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	IO-540KIA5
Registered Owner:	David Dean Gear	Rated Power:	300 Horsepower
Operator:	David D. Gear	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DTW,646 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	10:54 Local	Direction from Accident Site:	150°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.01 inches Hg	Temperature/Dew Point:	3°C / 2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Sparta , MI (8D4)	Type of Flight Plan Filed:	Unknown
Destination:	Plymouth, MI (1D2)	Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Unknown

Airport Information

Airport:	Canton - Plymouth - Mettetal 1D2	Runway Surface Type:	Asphalt
Airport Elevation:	696 ft msl	Runway Surface Condition:	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	2556 ft / 75 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	On-ground
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	42.349998,-83.458335

Administrative Information

Investigator In Charge (IIC):	Brannen, John
Additional Participating Persons:	Richard Merrill; FAA-FSDO-Detroit, Michigan; Belleville, MI
Report Date:	August 1, 2003
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=55969

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).