



Aviation Investigation Factual Report

Location: Shoshone, California Accident Number: LAX04CA104

Date & Time: January 22, 2004, 12:30 Local Registration: N33HY

Aircraft: Beech F33A Aircraft Damage: Substantial

Defining Event: 1 Serious, 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

Factual Information

On January 22, 2004, about 1230 Pacific standard time, a Beech F33A, N33HY, collided with the ground during takeoff from the Shoshone Airport (L61), Shoshone, California, and came to rest inverted. The certified flight instructor (CFI) was operating the borrowed airplane under the provisions of 14 CFR Part 91. The CFI sustained serious injuries, and the private pilot/owner undergoing instruction (PUI) was not injured. The airplane sustained substantial damage. The instructional flight was en route to North Las Vegas Airport (VGT), Las Vegas, Nevada, and was originating at the time. Visual meteorological conditions prevailed and no flight plan had been filed.

In a written statement, the CFI reported that the airplane landed uneventfully at the Shoshone airport earlier that day. Based on the windsock, the winds were from 290 degrees at 15 to 24 knots, variable and gusty. The CFI and PUI went to lunch. After lunch, the windsock was indicating variable winds from 290 degrees. The CFI had a brief discussion with the student about downhill and downwind takeoffs. After a preflight, they taxied to runway 15. The airplane did not accelerate as expected, and the remaining runway was insufficient to abort. The CFI continued the takeoff, and "forced the aircraft to fly at a very, low airspeed." The CFI then extended the flaps 15 degrees to lower the stall speed.

As the airplane touched down, the CFI was unsure if the tail touched down first. He reduced the power, and the nose gear collapsed. The tail of the airplane then came over the top, and the airplane came to rest inverted. Local residents near and at the airport indicated that the wind had been "on and off" all morning, and as high as 15 to 20 knots. The pilot believed that the wind picked up during the time of the preflight, to the takeoff roll. He did not recheck the windsock. The CFI noted no mechanical malfunctions with the airplane prior to the accident. To prevent future accidents the CFI recommended completing a final check on the wind direction, prior to starting the takeoff roll.

In a telephone conversation, the PUI reported that he had recently purchased the airplane. He was becoming familiar with the airplane, and the CFI operated the airplane controls during the takeoff. The airplane was equipped with a "throw-over" yoke. The yoke was positioned to the left front. The PUI was seated in the right front.

The Airport/Facility Directory indicated that runway 15/33 was 2,380 feet long and 30 feet wide.

Page 2 of 6 LAX04CA104

Flight instructor Information

Certificate:	Airline transport; Commercial; Flight instructor	Age:	60,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 1	Last FAA Medical Exam:	June 16, 2003
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	19573 hours (Total, all aircraft), 100 hours (Total, this make and model), 121 hours (Last 90 days, all aircraft), 59 hours (Last 30 days, all aircraft)		

Student pilot Information

Certificate:	Private	Age:	51,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3	Last FAA Medical Exam:	June 1, 2003
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:			

Page 3 of 6 LAX04CA104

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N33HY
Model/Series:	F33A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	CE-1260
Landing Gear Type:	Retractable - Tricycle	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:		Engine Model/Series:	10-520
Registered Owner:	Pioneer Plumbing, Inc.	Rated Power:	
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

The state of the ground in the state of the			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	Shoshone, CA (L61)	Type of Flight Plan Filed:	None
Destination:	Las Vegas, NV (VGT)	Type of Clearance:	None
Departure Time:	12:00 Local	Type of Airspace:	Class G

Page 4 of 6 LAX04CA104

Airport Information

Airport:	Shoshone Airport L61	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	15	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 Serious, 1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	
Total Injuries:	1 Serious, 1 None	Latitude, Longitude:	35.968612,-116.269447

Page 5 of 6 LAX04CA104

Administrative Information

Investigator In Charge (IIC):	Charnon, Nicole
Additional Participating Persons:	Dick Wright; Federal Aviation Administration; Las Vegas, NV
Report Date:	March 6, 2004
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=58663

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX04CA104