



Aviation Investigation Factual Report

Location:	Havre, Montana	Accident Number:	SEA04LA094
Date & Time:	May 29, 2004, 11:35 Local	Registration:	N7DR
Aircraft:	Beech P-35	Aircraft Damage:	Substantial
Defining Event:		Injuries:	4 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Factual Information

On May 29, 2004, approximately 1310 mountain daylight time, a Beech P-35, N7DR, registered to and operated by the pilot as a 14 CFR Part 91 local flight, experienced a loss of engine power shortly after takeoff from Havre, Montana. During the emergency landing, the aircraft was substantially damaged. Visual meteorological conditions prevailed at the time and no flight plan was filed. The commercial pilot and his three passengers were not injured.

During a telephone interview and subsequent written statement, the pilot reported that just after lift-off from runway 25, he verified a positive rate of climb and retracted the landing gear. Shortly thereafter, the pilot felt a slight hesitation in the engine. The pilot switched the fuel selector when the engine suddenly lost power. The pilot noted that at this time the aircraft had drifted about 200 feet off of runway centerline. He immediately lowered the nose to maintain airspeed and extended the landing gear to re-land on the remaining runway. The aircraft touched down and the right main gear collapsed. The right wing contacted the runway surface and the aircraft spun around coming to rest near the end of the runway.

After the aircraft was removed from the runway and placed in a secured location, a Federal Aviation Administration Inspector from the Helena, Montana, Flight Standards District Office, and a certified Airframe & Powerplant, Inspection Authorization mechanic inspected the aircraft. The mechanic reported that during the engine inspection, no evidence of a mechanical malfunction was noted. No fuel leaks were detected. The fuel selector was checked and found functional.

Both fuel tanks were inspected for fuel and a trace amount of fuel was found in each fuel bladder. Inspection of the right wing inboard fuel sender found that the unit was unsecured. The left wings sender unit was secured. Both sender units were checked for cockpit indications. Both indicated empty when the float was extended to the bottom of the tanks and indicated fuel levels throughout the movement of the float from top to bottom. Approximately three gallons of fuel was put in the right side fuel tank to inspect for leaks. None were detected. The left wings piping structure had pulled out of the bladder connector during the accident sequence which allowed fuel to drain from the left fuel tank therefore fuel quantity could not be determined. The left and right side fuel tanks are not interconnected.

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	61,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	April 28, 2004
Occupational Pilot:	No	Last Flight Review or Equivalent:	April 28, 2004
Flight Time:	996 hours (Total, all aircraft), 220 hours (Total, this make and model), 920 hours (Pilot In Command, all aircraft), 31 hours (Last 90 days, all aircraft), 17 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N7DR
Model/Series:	P-35	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	D-6995
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	June 1, 2003 Annual	Certified Max Gross Wt.:	3125 lbs
Time Since Last Inspection:	75 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4720 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO-470-N
Registered Owner:	Walter E. Herman	Rated Power:	260 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	HVR,2590 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	11:55 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Few / 3000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 4900 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	16 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.62 inches Hg	Temperature/Dew Point:	13°C / 7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Havre, MT (HVR)	Type of Flight Plan Filed:	None
Destination:	Big Sandy, MT (3U8)	Type of Clearance:	None
Departure Time:	11:35 Local	Type of Airspace:	Class E

Airport Information

Airport:	Havre City - County HVR	Runway Surface Type:	Asphalt
Airport Elevation:	2590 ft msl	Runway Surface Condition:	Dry
Runway Used:	25	IFR Approach:	None
Runway Length/Width:	5205 ft / 100 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	48.549446,-109.75

Administrative Information

Investigator In Charge (IIC):	Eckrote, Debra
Additional Participating Persons:	Leonard R Wheeler; FAA-FSDO; Helena, MT
Report Date:	August 27, 2004
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=59365

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).