



WPR10LA021

Aviation Investigation Factual Report

Location: Virgin, Utah **Accident Number:**

Date & Time: October 17, 2009, 17:00 Local Registration: N10LK

Aircraft: Aerotrike Naked Cobra Aircraft Damage: Substantial

Defining Event: Loss of engine power (total) **Injuries:** 1 Serious, 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Factual Information

HISTORY OF FLIGHT

On October 17, 2009, about 1700 mountain daylight time, an Aerotrike Naked Cobra, N10LK, collided with wooded terrain during cruise flight in Zion National Park near Virgin, Utah. The student pilot was operating the weight-shift-control experimental airplane under the provisions of 14 Code of Federal Regulations Part 91. The pilot was not injured; the passenger sustained serious injuries. The airplane sustained substantial damage to the fuselage and wing spar. The personal flight departed from a private airstrip in St. George, Utah, about 1600, with a planned destination of General Dick Stout Field Airport, Hurricane, Utah. Visual meteorological conditions prevailed, and no flight plan had been filed.

The pilot reported to the National Park Service (NPS) Ranger who responded to the scene that he was flying at an altitude of 500 feet above ground level (agl), when the engine experienced a loss of power. He attempted to restart the engine, but was unsuccessful. Unable to locate a suitable landing area he performed a forced landing into trees. The pilot stated that he held a "Sportsman's License."

During a subsequent interview with a Federal Aviation Administration (FAA) inspector, the pilot revealed that he held a student pilot certificate, and that he had been flying at 2,000 feet agl when the engine lost power.

The airplane was equipped with an experimental two-stroke Rotax 582 series engine, serial number 4016143.

The accident occurred in a remote area of Zion National Park, and as such an on-scene examination could not be performed. According to the NPS Ranger, the pilot removed the engine from the accident site on November 25, 2009, without prior approval or permission of the NPS. The remaining fuselage was recovered by the pilot and NPS personnel on December 5, 2009, and January 7, 2010.

Despite numerous attempts, the pilot did not provide either a written statement, or a copy of the NTSB Pilot/Operator Aircraft Accident Report, Form 6120.1/2. Additionally, the pilot did not respond to multiple requests to make the airplane or engine available for examination.

Page 2 of 5 WPR10LA021

Student pilot Information

| Certificate: | Student | Age: | 28,Male |
|---------------------------|---------|-----------------------------------|---------|
| Airplane Rating(s): | None | Seat Occupied: | Front |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Unknown | Last FAA Medical Exam: | |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | |
| Flight Time: | | | |

Aircraft and Owner/Operator Information

| Aireneft Maker | Agnotuiko | Domintuntions | NIOLK |
|-------------------------------|------------------------|-----------------------------------|-----------------|
| Aircraft Make: | Aerotrike | Registration: | N10LK |
| Model/Series: | Naked Cobra | Aircraft Category: | Weight-shift |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Experimental (Special) | Serial Number: | 0001 |
| Landing Gear Type: | Tricycle | Seats: | 2 |
| Date/Type of Last Inspection: | Unknown | Certified Max Gross Wt.: | 543 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | Rotax |
| ELT: | Not installed | Engine Model/Series: | 582 |
| Registered Owner: | On file | Rated Power: | 65 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |

Page 3 of 5 WPR10LA021

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|-------------------|
| Observation Facility, Elevation: | SGU,2938 ft msl | Distance from Accident Site: | 28 Nautical Miles |
| Observation Time: | 17:55 Local | Direction from Accident Site: | 60° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 4 knots / None | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 260° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30.02 inches Hg | Temperature/Dew Point: | 32°C / -1°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Saint George, UT (PVT) | Type of Flight Plan Filed: | None |
| Destination: | Hurricane, UT (1L8) | Type of Clearance: | None |
| Departure Time: | 16:00 Local | Type of Airspace: | |

Airport Information

| Airport: | Saint George PVT | Runway Surface Type: | |
|----------------------|------------------|---------------------------|---------|
| Airport Elevation: | 2500 ft msl | Runway Surface Condition: | |
| Runway Used: | | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | Unknown |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|-------------------|-------------------------|----------------------|
| Passenger Injuries: | 1 Serious | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 Serious, 1 None | Latitude, Longitude: | 37.26472,-113.098335 |

Page 4 of 5 WPR10LA021

Administrative Information

Investigator In Charge (IIC): Simpson, Eliott

Additional Participating Persons:

Report Date: April 2, 2010

Last Revision Date:
Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=74916

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 WPR10LA021