



# Aviation Investigation Final Report

---

<b>Location:</b>	Panama City, Florida	<b>Accident Number:</b>	ERA19TA276
<b>Date &amp; Time:</b>	September 10, 2019, 12:20 Local	<b>Registration:</b>	N3555R
<b>Aircraft:</b>	Beech 23	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Fuel starvation	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Instructional		

---

## Analysis

After returning from a roundtrip, cross-country flight, the student pilot and flight instructor were conducting airport pattern work, go-arounds, and touch-and-go landings. After a normal go-around due to excessive crosswinds, they initiated a no-flap landing for the next attempt. As the student pilot established the airplane on short final, he attempted to arrest the airplane's descent by increasing engine power, but the engine did not respond. The instructor told the student pilot to "push it back in to add power," and the student pilot pulled and pushed the throttle several times to try to increase engine power. After several unsuccessful attempts to increase engine power, the instructor took control of the airplane and attempted a forced landing. The airplane touched down short of the runway, bounced hard, and struck the landing lights before landing back on the runway. The airplane's airframe sustained substantial damage.

Postaccident examination of the airplane revealed an obstructed right trailing edge fuel vent line that likely blocked venting of the fuel tank and resulted a negative pressure within the tank, which subsequently starved the engine of fuel and resulted a total loss of engine power. The airplane's flight manual specified that during a preflight inspection, the fuel vent line should be checked for any obstructions, but the flight instructor did not witness the student pilot conduct the preflight inspection of the airplane. It is likely that the student pilot did not detect the blocked vent line during the preflight inspection; had more direct supervision been provided by the flight instructor during the preflight inspection, the blockage would have been discovered.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power due to an obstructed fuel vent, and the flight instructor's failure to ensure that the student did an adequate preflight inspection, which resulted in a forced landing.

## Findings

<b>Personnel issues</b>	Preflight inspection - Student/instructed pilot
<b>Personnel issues</b>	Preflight inspection - Instructor/check pilot
<b>Environmental issues</b>	Debris/dirt/foreign object - Awareness of condition
<b>Aircraft</b>	Fuel distribution - Damaged/degraded
<b>Aircraft</b>	Fuel distribution - Inadequate inspection

## Factual Information

### History of Flight

<b>Approach-VFR pattern final</b>	Fuel starvation (Defining event)
<b>Landing-flare/touchdown</b>	Hard landing
<b>Landing-flare/touchdown</b>	Collision with terr/obj (non-CFIT)

On September 10, 2019, about 1220 central daylight time, a Beech A-23, N3555R, was substantially damaged during a forced landing at Northwest Florida Beaches International Airport (ECP) Panama City, Florida. The student pilot/owner and flight instructor were not injured. The airplane was registered to and operated by the student pilot under the provisions of Title 14 *Code of Federal Regulations* as a part 91 instructional flight. Visual meteorological conditions prevailed, and no flight plan was filed for the flight that departed South Alabama Regional Airport at Bill Benton Field (79J) Andalusia, Alabama about 1130.

The student pilot and his flight instructor had just completed a cross country flight from ECP to 79J, then back to ECP and were conducting airport traffic pattern work, go-arounds and touch and go landings to runway 16. After a normal go-around due to excessive crosswinds, they initiated a no-flap landing for the next attempt. As the student pilot became established on short final, he reported that the approach was normal, but when he attempted to arrest his descent by increasing engine power, the engine did not respond. The student pulled and pushed the throttle several times and the instructor told him to immediately "push it back in to add power." The instructor's first thought was that the throttle cable had broken. After several unsuccessful attempts to regain engine power, the instructor took control of the airplane and attempted a landing, but touched down short of the runway; the airplane bounced hard, struck the approach lights, then settled back onto the runway before rolling to a stop.

According to Federal Aviation Administration (FAA) airmen records, the flight instructor held a commercial pilot certificate with ratings for airplane single engine land, multiengine land, instrument airplane. She also held a flight instructor certificate with ratings for airplane single engine land instrument airplane. She reported 3,150 hours total time and was issued an FAA second-class medical certificate in May 1, 2019.

The student pilot/owner reported 36.1 hours total time with 6.1 hours in the accident airplane make and model and was issued an FAA third-class medical certificate on August 30, 2017.

According to FAA airworthiness and maintenance records, the airplane was issued a standard airworthiness certificate on April 12, 1965. It was a four-place, internally braced low-wing airplane, that was equipped with fixed tricycle landing gear, and a Continental IO-346A, 165-horsepower engine driving a two-blade metal fixed pitch propeller. The airframe and engine had accumulated 3,023 hours total time; the engine accumulated 669 hours total time since overhaul as of the last annual inspection on April 2, 2019. The student pilot purchased the airplane on May 10, 2017.

The weather conditions reported at ECP at 1153 included winds 080° at 7 knots, visibility 10 statute miles, scattered clouds at 4,500 ft, temperature 34° C, dew point 22° C, and an altimeter setting of 30.18 inches of mercury.

Postaccident examination of the airplane revealed that the right wing spar was damaged, and the upper and lower areas on the right wing were buckled. The right gear fairing was buckled, and the left wing was wrinkled where the gear assembly was attached and resulted in damage to the left wing spar. Examination of the airplane's fuel venting system by a mechanic revealed foreign object debris with the consistency of dirt obstructing the right trailing edge fuel vent line. Upon closer examination, it was revealed that the fuel tank vent tube was clogged with mud from an insect, commonly referred to as a "Mud Dauber" wasp.

According to the manufacturer's Airplane Flight Manual (AFM), under Section IV Normal procedures, the preflight inspection includes a specific line item to ensure that the right wing trailing edge, fuel tank vent line, is unobstructed. The flight instructor stated that she did not witness the student pilot conduct the preflight inspection of his airplane.

### Pilot Information

<b>Certificate:</b>	Student	<b>Age:</b>	54, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Lap only
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	August 30, 2017
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	36 hours (Total, all aircraft), 6 hours (Total, this make and model)		

## Flight instructor Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	59,Female
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>		<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 With waivers/limitations	<b>Last FAA Medical Exam:</b>	May 1, 2019
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	June 1, 2018
<b>Flight Time:</b>	(Estimated) 3150 hours (Total, all aircraft), 15 hours (Total, this make and model), 80 hours (Last 90 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Beech	<b>Registration:</b>	N3555R
<b>Model/Series:</b>	23 A23	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1965	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal; Utility	<b>Serial Number:</b>	M-729
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	April 2, 2019 Annual	<b>Certified Max Gross Wt.:</b>	2400 lbs
<b>Time Since Last Inspection:</b>	3 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	3023.1 Hrs as of last inspection	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	IO-346A
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	165 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	ECP,68 ft msl	<b>Distance from Accident Site:</b>	1 Nautical Miles
<b>Observation Time:</b>	16:53 Local	<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Scattered / 4500 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>		<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	7 knots /	<b>Turbulence Type Forecast/Actual:</b>	None / None
<b>Wind Direction:</b>	80°	<b>Turbulence Severity Forecast/Actual:</b>	N/A / N/A
<b>Altimeter Setting:</b>	30.18 inches Hg	<b>Temperature/Dew Point:</b>	34°C / 22°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Panama City, FL (ECP )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Panama City, FL (ECP )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	12:10 Local	<b>Type of Airspace:</b>	Class D

## Airport Information

<b>Airport:</b>	Northwest Florida Beaches Intl ECP	<b>Runway Surface Type:</b>	Concrete
<b>Airport Elevation:</b>	68 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	16	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	10000 ft / 150 ft	<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	30.358333,-85.795555(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Mccarter, Lawrence
<b>Additional Participating Persons:</b>	Clayton Caessens; FAA ; Birmingham, AL
<b>Original Publish Date:</b>	January 28, 2021
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class 3</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=100294">https://data.ntsb.gov/Docket?ProjectID=100294</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).