



Aviation Investigation Final Report

Location: Laytonsville, Maryland Accident Number: ERA20CA091

Date & Time: January 17, 2020, 17:05 Local Registration: N1557F

Aircraft: Cessna 185 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

After two uneventful circuits in the traffic pattern, the pilot aligned the airplane to the runway for another a touch-and-go landing. As he applied engine power, he used the right rudder to center the airplane on the runway. About 50 ft into the takeoff roll, the airplane veered left. The pilot applied right brake and right rudder to correct; however, the airplane became "momentarily airborne." He reduced the engine power, and as the airplane settled back onto the runway, it veered right. The pilot attempted to stop the airplane by applying the brakes; however, it continued off the right side of the runway and traveled through mud, and subsequently, the left main landing gear collapsed. The left wing, left elevator, and left horizontal stabilizer sustained substantial damage. An examination of the wreckage by a Federal Aviation Administration inspector revealed that the airplane came to rest on the left side of the fuselage. The tailwheel attachment tube was separated from the empennage, but the tailwheel control cables remained attached.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The failure of the tailwheel attachment tube during the takeoff roll, which resulted in a loss of directional control, a runway excursion, and the left main landing gear collapsing.

Findings

Aircraft	Nose/tail landing gear - Failure
Aircraft	Directional control - Attain/maintain not possible

Page 2 of 6 ERA20CA091

Factual Information

History of Flight

Takeoff	Part(s) separation from AC	
Takeoff	Loss of control on ground (Defining event)	
Takeoff	Attempted remediation/recovery	
Takeoff	Runway excursion	
Takeoff	Landing gear collapse	

Pilot Information

Certificate:	Private	Age:	71,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	October 1, 2019
Occupational Pilot:	No	Last Flight Review or Equivalent:	January 4, 2019
Flight Time:	1800 hours (Total, all aircraft), 900 hours (Total, this make and model)		

Page 3 of 6 ERA20CA091

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N1557F
Model/Series:	185 D	Aircraft Category:	Airplane
Year of Manufacture:	1965	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	185-0928
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	August 19, 2019 Annual	Certified Max Gross Wt.:	3197 lbs
Time Since Last Inspection:	14 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3697.3 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	IO-470 SERIES
Registered Owner:	On file	Rated Power:	265 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	GAI,539 ft msl	Distance from Accident Site:	5 Nautical Miles
Observation Time:	16:56 Local	Direction from Accident Site:	190°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.69 inches Hg	Temperature/Dew Point:	-1°C / -11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Laytonsville, MD (W50)	Type of Flight Plan Filed:	VFR
Destination:	Laytonsville, MD (W50)	Type of Clearance:	Special VFR
Departure Time:	17:05 Local	Type of Airspace:	Class B

Page 4 of 6 ERA20CA091

Airport Information

Airport:	Davis W50	Runway Surface Type:	Asphalt
Airport Elevation:	609 ft msl	Runway Surface Condition:	Dry
Runway Used:	08	IFR Approach:	None
Runway Length/Width:	2000 ft / 50 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.243331,-77.150001(est)

Page 5 of 6 ERA20CA091

Administrative Information

Investigator In Charge (IIC):	Kemner, Heidi
Additional Participating Persons:	Philippe Derosier; FAA/FSDO ; Baltimore , MD
Original Publish Date:	June 16, 2020
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=100889

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA20CA091