



# Aviation Investigation Final Report

<b>Location:</b>	Waynesville, North Carolina	<b>Accident Number:</b>	DCA20CA071
<b>Date &amp; Time:</b>	February 7, 2020, 01:05 Local	<b>Registration:</b>	N610NN
<b>Aircraft:</b>	Bombardier CL-600-2D24	<b>Aircraft Damage:</b>	Minor
<b>Defining Event:</b>	Turbulence encounter	<b>Injuries:</b>	1 Serious, 22 Minor, 50 None
<b>Flight Conducted Under:</b>	Part 121: Air carrier - Scheduled		

## Analysis

On February 7, 2020, about 0105 eastern standard time, PSA Airlines flight 5634, a Canadair CRJ-900, N610NN, encountered turbulence during enroute descent to McGhee Tyson Airport (KTYN), Knoxville, Tennessee. Of the 73 passengers and crew onboard, one flight attendant received serious injuries and there were 21 minor injuries. The airplane sustained minor damage. The regularly scheduled domestic passenger flight was operating under the provisions of 14 Code of Federal Regulations Part 121 from Charlotte Douglas International Airport (KCLT), Charlotte, North Carolina, to KTYN.

The accident flight departed 4 hours late due to the late arrival of the inbound airplane in KCLT because of persistent severe weather that had been in the area. According to the flight crew, they kept the seatbelt sign illuminated for the entire flight because of the late night and weather in the area. They indicated that the takeoff, climb, and cruise were uneventful. Most of the flight was conducted at flight level (FL) 220 in clear air, with clouds beneath.

As they approached KTYN, the flight was cleared to descend at pilot's discretion to 13,000 feet. During the descent, the onboard radar was on but did not depict any precipitation in the cloud layer below them. In the early stages of the descent, the flight began entering and exiting various cloud layers and experienced very light/intermittent chop. At about FL 185, the flight went into a cloud and encountered severe turbulence, causing the autopilot to disengage and the airplane pitched nose down rapidly. The pilot flying reduced power, leveled the wings, and the airplane quickly exited the clouds into visual meteorological (VMC) conditions again. The flight continued to experience moderate turbulence during the descent.

The captain called back to check on the flight attendants (FA) and passengers but initially received no reply. A short time later, the captain called back again and was informed by a dead-heading flight attendant (FA) that both FAs had been injured.

At the time of the turbulence encounter, the forward FA was preparing the galley for landing and was thrown to the ceiling and back to the floor, injuring both ankles. The FA could not stand, and a dead-heading pilot helped her to a passenger seat. The aft FA was conducting final compliance checks in the cabin and was also thrown to the ceiling and back to the floor, causing her to black out for a short time. Multiple passengers received various injuries, that included head bumps/bruises, scrapes, and anxiety issues. Two dead-heading FAs assumed the duties of the two injured FAs for the remainder of the flight. After landing, paramedics met the airplane at the gate and the two FAs and several passengers were transported to the hospital. The forward FA was diagnosed with fractures in both ankles.

Post accident examination of the weather data determined that the turbulence encounter occurred in a strong sheared environment with a 155-knot jet stream. There were several pilot reports (PIREPs) of moderate to severe turbulence in the area, and there was a National Weather Service SIGMET current for severe turbulence in the area.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

An encounter with severe convective turbulence associated with a strong sheared environment associated with the jet stream.

Findings	
Environmental issues	Convective turbulence - Effect on personnel

## Factual Information

### History of Flight

Enroute-descent	Turbulence encounter (Defining event)
-----------------	---------------------------------------

### Pilot Information

Certificate:	Airline transport	Age:	53,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	5-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	November 4, 2019
Flight Time:	8700 hours (Total, all aircraft), 2800 hours (Total, this make and model), 7700 hours (Pilot In Command, all aircraft), 235 hours (Last 90 days, all aircraft), 70 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

### Co-pilot Information

Certificate:	Airline transport	Age:	30,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	5-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	April 12, 2019
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 18, 2020
Flight Time:	3106 hours (Total, all aircraft), 1300 hours (Total, this make and model), 1602 hours (Pilot In Command, all aircraft), 9 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Bombardier	<b>Registration:</b>	N610NN
<b>Model/Series:</b>	CL-600-2D24	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	2019	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Transport	<b>Serial Number:</b>	15476
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	
<b>Date/Type of Last Inspection:</b>		<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	Turbo fan
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	General Electric
<b>ELT:</b>		<b>Engine Model/Series:</b>	CF34-8C5
<b>Registered Owner:</b>	American Airlines Inc.	<b>Rated Power:</b>	
<b>Operator:</b>	PSA Airlines	<b>Operating Certificate(s) Held:</b>	Flag carrier (121)

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Night
<b>Observation Facility, Elevation:</b>	TYS	<b>Distance from Accident Site:</b>	55 Nautical Miles
<b>Observation Time:</b>	05:53 Local	<b>Direction from Accident Site:</b>	119°
<b>Lowest Cloud Condition:</b>		<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Overcast / 2800 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	9 knots / None	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	280°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.35 inches Hg	<b>Temperature/Dew Point:</b>	6°C / 3°C
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	Charlotte, NC (CLT )	<b>Type of Flight Plan Filed:</b>	IFR
<b>Destination:</b>	Knoxville, TN (TYS )	<b>Type of Clearance:</b>	IFR
<b>Departure Time:</b>	05:35 UTC	<b>Type of Airspace:</b>	

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Serious, 1 Minor, 2 None	<b>Aircraft Damage:</b>	Minor
<b>Passenger Injuries:</b>	21 Minor, 48 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Serious, 22 Minor, 50 None	<b>Latitude, Longitude:</b>	35.488609,-82.988609

## Administrative Information

**Investigator In Charge (IIC):** Lovell, John

**Additional Participating Persons:**

**Original Publish Date:** January 26, 2021

**Last Revision Date:** December 19, 2024

**Investigation Class:** [Class 4](#)

**Note:** This accident report documents the factual circumstances of this accident as described to the NTSB.

**Investigation Docket:** <https://data.nts.gov/Docket?ProjectID=100913>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).