

# **Aviation Investigation Final Report**

Location: Red Wing, Minnesota Accident Number: CEN20CA250

Date & Time: June 25, 2020, 15:00 Local Registration: N35JA

Aircraft: Hatz HATZ CB 1 Aircraft Damage: Substantial

**Defining Event:** Abnormal runway contact **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The commercial pilot was practicing landings with light wind present in his tailwheel airplane on an occasionally used grass area south of the paved runway. The pilot made one successful landing on the grass. During the next landing, the airplane bounced, which resulted in a nose up attitude. The pilot does not recall if he added engine power to remedy the bounced landing. However, the pilot did not perform a go-around as recommended by the Federal Aviation Administration Airplane Flying Handbook. The airplane stalled and impacted terrain in a nose low attitude. The propeller "dug in" the terrain and the airplane nosed over. The airplane subsequently sustained substantial empennage damage. The pilot indicated that there were no mechanical malfunctions with the airplane.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to perform a go around following a bounced landing that resulted in an aerodynamic stall.

## **Findings**

Personnel issues

Aircraft control - Pilot

Page 2 of 5 CEN20CA250

## **Factual Information**

## History of Flight

Landing	Abnormal runway contact (Defining event)
Landing	Aerodynamic stall/spin

#### **Pilot Information**

Certificate:	Commercial	Age:	71,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	BasicMed	Last FAA Medical Exam:	October 3, 2019
Occupational Pilot:	No	Last Flight Review or Equivalent:	July 26, 2018
Flight Time:	1804 hours (Total, all aircraft), 12.5 hours (Total, this make and model), 1602 hours (Pilot In Command, all aircraft), 5.3 hours (Last 90 days, all aircraft), 2.5 hours (Last 30 days, all aircraft), 0.5 hours (Last 24 hours, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Hatz	Registration:	N35JA
Model/Series:	HATZ CB 1 No Series	Aircraft Category:	Airplane
Year of Manufacture:	1979	Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	20
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	March 20, 2020 Condition	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	485 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	0-320-A3B
Registered Owner:	On file	Rated Power:	150 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 CEN20CA250

**Meteorological Information and Flight Plan** 

			_
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KRGK,780 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	15:35 Local	Direction from Accident Site:	180°
<b>Lowest Cloud Condition:</b>	Scattered / 7000 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	250°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.88 inches Hg	Temperature/Dew Point:	29°C / 10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Red Wing, MN (RGK)	Type of Flight Plan Filed:	None
Destination:	Red Wing, MN (RGK)	Type of Clearance:	None
Departure Time:	14:30 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	RED WING RGNL RGK	Runway Surface Type:	Grass/turf
Airport Elevation:	777 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	5010 ft / 100 ft	VFR Approach/Landing:	Full stop

## **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.589443,-92.485(est)

Page 4 of 5 CEN20CA250

#### **Administrative Information**

Investigator In Charge (IIC):	Malinowski, Edward
Additional Participating Persons:	Edward Martin; Federal Aviation Administration; Minneapolis, MN
Original Publish Date:	May 6, 2021
Last Revision Date:	
Investigation Class:	Class 4
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=101504

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN20CA250