



Aviation Investigation Final Report

Location: Cambridge, Minnesota Accident Number: CEN20CA298

Date & Time: July 21, 2020, 16:20 Local Registration: N2943C

Aircraft: Cessna 180 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The pilot and flight instructor conducted an instructional flight in a single-engine tailwheel airplane. The pilot had recently purchased the airplane and needed a tailwheel endorsement. After some ground instruction, they performed taxi and high-speed taxi operations in the airplane. They then flew to another airport, where they performed six take-off and landings to a full stop on a grass runway. En route back to their original airport, they stopped at another airport which had a grass runway and performed another seven takeoffs and landings. They then returned to the original airport, where the pilot completed a landing and takeoff from an asphalt runway. During the final landing to runway 34, the airplane bounced, and bounced a second time, before the airplane ground looped. The airplane came to rest inverted beside the runway, and substantial damage was noted to the airplane's empennage and wing. A review of the weather conditions about the time of the accident noted wind at 220 deg; at 5 kts. Using runway 34, the airplane would have experienced a slight quartering tailwind condition during landing.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of directional control while landing a tailwheel airplane with a slight left quartering a tailwind. Contributing to the accident was the flight instructor's delayed remedial action.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Personnel issues Aircraft control - Instructor/check pilot

Personnel issues Delayed action - Instructor/check pilot

Page 2 of 6 CEN20CA298

Factual Information

History of Flight

Loss of control on ground (Defining event)	Landing-flare/touchdown	Loss of control on ground (Defining event)
--	-------------------------	--

Pilot Information

Certificate:	Private	Age:	48
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	May 14, 2019
Occupational Pilot:	No	Last Flight Review or Equivalent:	June 24, 2020
Flight Time:	529 hours (Total, all aircraft), 17.2 hours (Total, this make and model), 480 hours (Pilot In Command, all aircraft), 72 hours (Last 90 days, all aircraft), 13 hours (Last 30 days, all aircraft), 2.2 hours (Last 24 hours, all aircraft)		

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	70
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	July 31, 2019
Occupational Pilot:	No	Last Flight Review or Equivalent:	July 7, 2020
Flight Time:	6200 hours (Total, all aircraft), 45 hours (Total, this make and model), 5933 hours (Pilot In Command, all aircraft), 70 hours (Last 90 days, all aircraft), 46 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CEN20CA298

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N2943C
Model/Series:	180 Undesignat	Aircraft Category:	Airplane
Year of Manufacture:	1954	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	30843
Landing Gear Type:	Tailwheel	Seats:	
Date/Type of Last Inspection:	October 1, 2019 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3800 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	0-470 SERIES
Registered Owner:	On file	Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

<u> </u>	<u> </u>		
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCBG	Distance from Accident Site:	
Observation Time:	15:55 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 3300 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.86 inches Hg	Temperature/Dew Point:	26°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Cambridge, MN (CBG)	Type of Flight Plan Filed:	None
Destination:	Cambridge, MN (CBG)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Page 4 of 6 CEN20CA298

Airport Information

Airport:	Cambridge Muncipal CBG	Runway Surface Type:	Asphalt
Airport Elevation:	945 ft msl	Runway Surface Condition:	Dry
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	4001 ft / 75 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	45.558055,-93.264442(est)

Page 5 of 6 CEN20CA298

Administrative Information

Investigator In Charge (IIC):	Hatch, Craig
Additional Participating Persons:	Nick Halatsis; FAA FSDO; Minneapolis, MN
Original Publish Date:	May 6, 2021
Last Revision Date:	
Investigation Class:	Class 4
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=101650

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN20CA298