



# Aviation Investigation Final Report

<b>Location:</b>	Cedar City, Utah	<b>Accident Number:</b>	WPR20LA249
<b>Date &amp; Time:</b>	August 2, 2020, 08:41 Local	<b>Registration:</b>	N225HJ
<b>Aircraft:</b>	North American Navion	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Fuel exhaustion	<b>Injuries:</b>	2 Fatal
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The pilot and pilot-rated passenger departed from Strawberry Valley Estates Airport (UT24), Alton, Utah, on a cross-country flight. The airplane flew in a direction that was consistent with a heading toward their planned destination, Cedar City Regional Airport (CDC), Cedar City, Utah. As the airplane neared its destination, witnesses heard the pilot make a distress call indicating that the airplane was out of gas and that he was trying to make a forced landing in a field. Other witnesses observed the airplane descending and then impacting terrain. Shortly thereafter, a nearby communications tower collapsed.

Postaccident examination of the airframe and engine revealed no preimpact malfunctions or failures that would have precluded normal operation. The airplane's main fuel tanks held 20 gallons each with a total of 39.5 gallons of usable fuel. According to a friend of the pilot, the airplane was fueled at North Las Vegas Airport (VGT), Las Vegas, Nevada, on the day before the accident. The airplane then departed VGT and flew two flights with a total time of about 1 hour 55 minutes. On the day of the accident, the airplane departed UT24, which was about 30 miles (and about 20 minutes of flying time) from the last known point of contact from the previous day. The accident flight's duration was about 31 minutes. The airplane's distance traveled since fueling was consistent with consuming the usable fuel in the main fuel tanks. Thus, the airplane's fuel load at the time of departure from UT24 was insufficient to complete the planned flight to CDC, and a total loss of engine power ensued.

Additionally, examination of the airplane wreckage at the accident site revealed a support guy wire from the communications tower wrapped around the front of the airplane. Thus, while attempting the forced landing, the pilot failed to see and avoid the communications tower and subsequently struck the guy wire.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power due to fuel exhaustion. Contributing to the accident was the pilot's improper fuel planning and failure to see and avoid the communications tower support guy wire.

### Findings

<b>Aircraft</b>	Fuel - Fluid management
<b>Personnel issues</b>	Fuel planning - Pilot
<b>Personnel issues</b>	Monitoring environment - Pilot
<b>Environmental issues</b>	Tower/antenna (incl guy wires) - Effect on equipment

## Factual Information

### History of Flight

Enroute	Fuel exhaustion (Defining event)
---------	----------------------------------

#### HISTORY OF FLIGHT

On August 2, 2020, about 0841 mountain daylight time, a North American Navion airplane, N225HJ, was substantially damaged when it was involved in an accident near Cedar City Regional Airport (CDC), Cedar City, Utah. The pilot and pilot-rated passenger were fatally injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

According to a friend of the pilot, the airplane was topped off with fuel at North Las Vegas Airport (VGT), Las Vegas, Nevada, on the day before the accident. The airplane's main fuel tanks held 20 gallons each with a total of 39.5 gallons of usable fuel. Publicly available radar information indicated that the airplane departed VGT that day and flew two flights with a total time of about 1 hour 55 minutes. Radar data showed that, on the day of the accident, the airplane departed Strawberry Valley Estates Airport (UT24), Alton, Utah, about 0815; UT24 was about 30 miles (and about 20 minutes of flying time) from the last known point of contact from the previous day. After departure, the airplane flew southwest before turning north where it continued to track for the remaining portion of the flight captured by radar data. The airplane's direction was consistent with a heading toward CDC.

As the airplane approached its destination, witnesses heard the pilot make a distress call. The pilot stated that the airplane was out of gas and that he was going to try to land in a field. Other witnesses observed the airplane descending and then impacting terrain. Shortly thereafter, a nearby communications tower collapsed.

#### WRECKAGE AND IMPACT INFORMATION

Local law enforcement and the Federal Aviation Administration responded to the accident site. Examination of the accident site revealed that all major components of the airplane were located at the site. A support guy wire from the tower was observed wrapped around the front of the airplane. There was no post impact fire.

The airplane came to rest inverted about 7 miles southwest from CDC and a few hundred feet from the collapsed tower. The wreckage site was on flat terrain at an elevation of about 5,475 ft. The outboard portion of the right wing separated and was found a few feet from the main wreckage. The right horizontal stabilizer and elevator remained attached but sustained impact damage. The front of the fuselage was also damaged. The main landing gear was extended, and the nose wheel had separated.

A review of information on the communication tower revealed that it was about 400 ft in height and constructed of steel. The tower had 5 sets of guy wires that were connected to it at different elevations. The first wire was at 80 ft, the second wire at 160 ft, the third wire at 240 ft, the fourth wire at 320 ft, and the highest wire at 380 ft. Each wire had a varying width between 5/16 to 9/16 of an inch, which increased in width the higher the elevation. There were 3 guy wires at each elevation.

Postaccident examination of the airframe and engine revealed no preimpact anomalies that would have precluded normal operation.

## MEDICAL AND PATHOLOGICAL INFORMATION

The Office of the Medical Examiner, Utah Department of Health, Taylorville, Utah, conducted an autopsy on the pilot. His cause of death was blunt trauma. Toxicology testing performed by the Federal Aviation Administration Forensic Sciences Laboratory on the pilot's liver specimen detected dextrophan, which is a cough suppressant used in many cold medications and is generally considered not impairing.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	52, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Unknown
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Unknown
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	November 19, 2019
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	(Estimated) 100 hours (Total, all aircraft)		

## Pilot-rated passenger Information

<b>Certificate:</b>	Private	<b>Age:</b>	63, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Unknown
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Unknown
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 None	<b>Last FAA Medical Exam:</b>	October 20, 1995
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	(Estimated) 280 hours (Total, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	North American	<b>Registration:</b>	N225HJ
<b>Model/Series:</b>	Navion No Series	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1947	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	NAV-4-188
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	April 14, 2020 Annual	<b>Certified Max Gross Wt.:</b>	2750 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	2308.3 Hrs as of last inspection	<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>	C91 installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	E-225-9
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	225 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KCDC,5618 ft msl	<b>Distance from Accident Site:</b>	8 Nautical Miles
<b>Observation Time:</b>	08:53 Local	<b>Direction from Accident Site:</b>	35°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	None / None
<b>Wind Direction:</b>		<b>Turbulence Severity Forecast/Actual:</b>	N/A / N/A
<b>Altimeter Setting:</b>	30.21 inches Hg	<b>Temperature/Dew Point:</b>	25°C / 0°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Alton, UT (UT24)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Cedar City, UT (CDC)	<b>Type of Clearance:</b>	Unknown
<b>Departure Time:</b>	08:14 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	Cedar City Rgnl CDC	<b>Runway Surface Type:</b>	Dirt
<b>Airport Elevation:</b>	5621 ft msl	<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Fatal	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 Fatal	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 Fatal	<b>Latitude, Longitude:</b>	37.603332,-113.18888(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Nixon, Albert
<b>Additional Participating Persons:</b>	Kenneth Joyce; Federal Aviation Administration; Salt Lake City, UT
<b>Original Publish Date:</b>	September 14, 2022
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class 3</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=101721">https://data.nts.gov/Docket?ProjectID=101721</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).