



# **Aviation Investigation Final Report**

| Location:               | Inverness, Mississippi         | Accident Number: | CEN20LA353  |
|-------------------------|--------------------------------|------------------|-------------|
| Date & Time:            | August 20, 2020, 09:00 Local   | Registration:    | N604MG      |
| Aircraft:               | Air Tractor AT602              | Aircraft Damage: | Substantial |
| Defining Event:         | Sys/Comp malf/fail (non-power) | Injuries:        | 1 None      |
| Flight Conducted Under: | Part 137: Agricultural         |                  |             |

#### Analysis

The turbine-powered agricultural airplane was on short final to land at the private airstrip. In attempt to slow down the airplane, the pilot actuated the power control lever (PCL) into beta, which caused the PCL, cam box, and associated linkage to get stuck in place. The airplane required more engine power to make the runway so he attempted to advance the PCL, but it would not move. The pilot made a forced landing in a field short of the runway, the airplane came to rest upright, and sustained substantial damage to both wings.

The engine data revealed that the PCL was moved to beta while the airplane was on short final. The beta signal was still on after engine shutdown, which indicates that the cam box was likely stuck in beta.

A service letter issued by the airplane manufacturer states that the use of beta mode in flight is not authorized and can result in a dangerous situation, leading to a loss of control.

In this event, when the PCL was actuated into beta in flight and the propeller servo pressure dropped to maintain control of the propeller, the servo pressure went into a negative range, and the propeller blade angle was quickly forced to the max reverse stop, which allowed the beta ring to move to the most forward position. Since the beta valve does not allow this amount of movement, the additional movement of the beta ring was transferred to the cam box and the cam box jammed in place.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's decision to move the power control lever into beta during flight, which resulted in the power control lever and associated linkage becoming stuck in the beta position.

| Findings         |                                       |
|------------------|---------------------------------------|
| Personnel issues | Incorrect action selection - Pilot    |
| Personnel issues | Use of equip/system - Pilot           |
| Aircraft         | Power lever - Incorrect use/operation |

### **Factual Information**

| History of Flight           |   |  |
|-----------------------------|---|--|
| Approach                    | Off-field or emergency landing                  |  |
| Approach-IFR final approach | Sys/Comp malf/fail (non-power) (Defining event) |  |

On August 20, 2020, about 0900 central daylight time, an Air Tractor AT602 airplane, N604MG, was substantially damaged when it was involved in an accident near Inverness, Mississippi. The pilot was not injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 137 aerial application flight.

The pilot stated that when he was on short final, the airplane required more engine power to reach the runway. He attempted to advance the power control lever (PCL), but it would not move. He subsequently made a forced landing in a field and the airplane sustained substantial damage to both wings. An initial examination of the PCL revealed that it was stuck near the idle position and could not be moved.

The pilot reported that during the accident flight, he positioned the PCL friction lock such that the lever would move smoothly and characterized its friction as a "medium range." He said that during some previous flights, he had used beta in flight to quickly slow the airplane. He could not recall if he had put the PCL into beta range before it became stuck but said it was possible.

The actual commanded position of the PCL provides an indication to the airplane's MVP-50T engine monitor. The recorded data revealed that the PCL was moved into beta during the accident flight. Also, the beta signal was still on after engine shutdown.

According to the Airplane Flying Handbook (FAA-H-8083-3B), the beta range of operation consists of power lever positions from flight idle to maximum reverse. Beginning at power lever positions just aft of flight idle, propeller blade pitch angles become progressively flatter with aft movement of the power lever until they go beyond maximum flat pitch and into negative pitch, resulting in reverse thrust.

To move the PCL into beta, a pilot moves the thumb latch on the top of the PCL forward, which raises the idle stop and allows the PCL to move aft of the anti-reversing plate. A fence on the power quadrant keeps the idle stop in line with the anti-reversing lock plate to prevent the PCL from inadvertently moving into beta.

When the PCL is actuated aft of the idle stop position and into the beta range it reduces the propeller blade angle below the flight idle position. Under some flight conditions blade angles below flight idle result in blade aerodynamic forces that cause the propeller servo pressure to decrease and the propeller to become uncontrolled by the propeller governor. In this condition

the propeller blade angle would be aerodynamically forced – without pilot action – to the max reverse stop.

When the propeller blade angle moves to the reverse stop, the beta ring moves to the mostforward position. If the propeller is not controlled by the governor/beta valve at this point, movement of the PCL out of beta range moves the beta valve to its max forward stop without corresponding aft movement of the propeller beta ring. With the beta ring and beta valve in those positions, no further movement of the reversing cable/reversing cam would be possible, and the cam box could get jammed. The cam box is the intermediate linkage between the cockpit levers, the propeller governor, and the fuel control unit. If the cam follower pin is in the reversing range of the cam when this occurs, it will prevent forward movement of the PCL.

Air Tractor Service Letter 364 states in part:

The use of beta mode in flight is not authorized on Air Tractor aircraft and can result in a dangerous situation, leading to aircraft loss of control...beta mode and reverse thrust settings are only authorized for ground operations. These settings may be used during taxi operations to reduce brake system wear and to reduce taxi speeds. Beta mode and reverse thrust may be used during the landing rollout, but only after all three wheels are on the ground.

| Certificate:              | Commercial; Flight instructor   | Age:                              | 38,Male          |
|---------------------------|---|-----------------------------------|------------------|
| Airplane Rating(s):       | Single-engine land; Multi-engine<br>land  | Seat Occupied:                    | Single           |
| Other Aircraft Rating(s): | None  | Restraint Used:                   | 5-point          |
| Instrument Rating(s):     | Airplane  | Second Pilot Present:             | No               |
| Instructor Rating(s):     | Airplane multi-engine; Airplane<br>single-engine; Instrument airplane   | Toxicology Performed:             | No               |
| Medical Certification:    | Class 2 Without<br>waivers/limitations  | Last FAA Medical Exam:            | January 3, 2020  |
| Occupational Pilot:       | Yes   | Last Flight Review or Equivalent: | February 9, 2019 |
| Flight Time:              | 7067 hours (Total, all aircraft), 445 hours (Total, this make and model), 6945 hours (Pilot In<br>Command, all aircraft), 211 hours (Last 90 days, all aircraft), 63 hours (Last 30 days, all aircraft),<br>3 hours (Last 24 hours, all aircraft) |                                   |                  |

#### **Pilot Information**

#### Aircraft and Owner/Operator Information

| Aircraft Make:                   | Air Tractor                 | Registration:                     | N604MG                      |
|----------------------------------|-----------------------------|-----------------------------------|-----------------------------|
| Model/Series:                    | AT602                       | Aircraft Category:                | Airplane                    |
| Year of Manufacture:             | 2019                        | Amateur Built:                    |                             |
| Airworthiness Certificate:       | Restricted (Special)        | Serial Number:                    | 602-1306                    |
| Landing Gear Type:               | Tailwheel                   | Seats:                            | 1                           |
| Date/Type of Last<br>Inspection: | December 19, 2019 Annual    | Certified Max Gross Wt.:          | 12500 lbs                   |
| Time Since Last Inspection:      |                             | Engines:                          | 1 Turbo prop                |
| Airframe Total Time:             | 375 Hrs at time of accident | Engine Manufacturer:              | Pratt & Whitney Canada      |
| ELT:                             | Not installed               | Engine Model/Series:              | PT6A-60AG                   |
| Registered Owner:                | Gary Flying Service         | Rated Power:                      | 1173 Horsepower             |
| Operator:                        | Gary Flying Service         | Operating Certificate(s)<br>Held: | Agricultural aircraft (137) |

## Meteorological Information and Flight Plan

| Conditions at Accident Site:            | Visual (VMC)                     | Condition of Light:                     | Day               |
|---|----------------------------------|---|-------------------|
| <b>Observation Facility, Elevation:</b> | KGLH,128 ft msl                  | Distance from Accident Site:            | 22 Nautical Miles |
| Observation Time:                       | 08:53 Local                      | Direction from Accident Site:           | 294°              |
| Lowest Cloud Condition:                 | Clear                            | Visibility                              | 10 miles          |
| Lowest Ceiling:                         | None                             | Visibility (RVR):                       |                   |
| Wind Speed/Gusts:                       | 6 knots / None                   | Turbulence Type<br>Forecast/Actual:     | /                 |
| Wind Direction:                         | 40°                              | Turbulence Severity<br>Forecast/Actual: | /                 |
| Altimeter Setting:                      | 29.93 inches Hg                  | Temperature/Dew Point:                  | 23°C / 21°C       |
| Precipitation and Obscuration:          | No Obscuration; No Precipitation |   |                   |
| Departure Point:                        | Inverness, MS (MS21)             | Type of Flight Plan Filed:              | None              |
| Destination:                            | Inverness, MS (MS21)             | Type of Clearance:                      | None              |
| Departure Time:                         | 08:15 Local                      | Type of Airspace:                       | Class G           |

#### **Airport Information**

| Airport:             | LESTER FIELD MS21 | Runway Surface Type:             | Concrete;Grass/turf                     |
|----------------------|-------------------|----------------------------------|---|
| Airport Elevation:   | 115 ft msl        | <b>Runway Surface Condition:</b> | Dry                                     |
| Runway Used:         | 18                | IFR Approach:                    | None                                    |
| Runway Length/Width: | 3000 ft / 65 ft   | VFR Approach/Landing:            | Forced landing;Full<br>stop;Straight-in |

## Wreckage and Impact Information

| Crew Injuries:         | 1 None | Aircraft Damage:        | Substantial              |
|------------------------|--------|-------------------------|--------------------------|
| Passenger<br>Injuries: |        | Aircraft Fire:          | None                     |
| Ground Injuries:       | N/A    | Aircraft Explosion:     | None                     |
| Total Injuries:        | 1 None | Latitude,<br>Longitude: | 33.336944,-90.58139(est) |

#### **Administrative Information**

| Investigator In Charge (IIC):        | Lindberg, Joshua   |
|--------------------------------------|--|
| Additional Participating<br>Persons: | Michael Jones; Federal Aviation Adminstration; Jackson, MS<br>Dakota Lowe; Air Tractor; Olney, TX<br>Jeremy Ganivet; PWC<br>Beverly Harvey; TSB Canada<br>Les Doud; Hartzell; Piqua, OH<br>Jim Rosplock; Woodward Inc.; Loves Park, IL |
| Original Publish Date:               | June 14, 2022  |
| Last Revision Date:                  |  |
| Investigation Class:                 | Class 3  |
| Note:                                | The NTSB did not travel to the scene of this accident.   |
| Investigation Docket:                | https://data.ntsb.gov/Docket?ProjectID=101837  |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.