



Aviation Investigation Final Report

Location:	Stockton, California	Accident Number:	WPR20LA311
Date & Time:	September 19, 2020, 19:25 Local	Registration:	N7946C
Aircraft:	North American B25N	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (total)	Injuries:	2 Serious, 1 Minor
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

While the airplane was in cruise flight and being flown by the copilot, the left engine fuel pressure fluctuated, which was followed by a brief loss of engine power. Concerned that the airplane might have a failed engine-driven fuel pump, the pilot turned the boost pumps to high and asked the passenger (the airplane's mechanic) to open the fuel cross-feed valve. As the airplane approached its intended destination, both fuel pressure needles began to fluctuate. The pilot assumed that fuel starvation to the engines was occurring and decided to make an off-airport landing to a field behind their airplane's position due to residential areas located between the airplane's location and the airport. The pilot stated that he took control of the airplane from the copilot and initiated a right turn toward the field, and that, shortly afterward, both engines lost total power. During the landing roll, the pilot observed a ditch in front of the airplane and was able to get the airplane airborne briefly to avoid the first ditch; however, he was not able to avoid a second, larger ditch. Subsequently, the airplane struck the second ditch, became airborne, and impacted the ground, which resulted in substantial damage to the fuselage.

Recovery company personnel reported that, during recovery of the wreckage, about 1 gallon of fuel was removed from the two forward and the two aft wing fuel tanks. Postaccident examination of the airplane revealed no evidence of any pre-existing anomalies that would have precluded normal operation of either engine except that all four main fuel tank fuel gauges displayed erroneous indications after each tank was filled with water. No leaks were observed throughout the fuel system. The airplane was last refueled on the day before the accident with 497.7 gallons. When the airplane was last refueled, the fuel tanks were reportedly filled to about 3 inches below the fuel filler neck. The investigation could not determine, based on the available evidence for this accident, how much of the airplane's fuel load (maximum capacity was 670 gallons) the airplane had onboard after it was refueled.

Additionally, the pilot reported that he commonly used a fuel burn rate of 150 gallons per hour for flight planning purposes; that figure included takeoff fuel burn. Recorded automatic dependent surveillance-broadcast data showed that the airplane had flown for 4 hours 1 minute since refueling and included six takeoffs and five landings (but did not include taxi times). As part of the investigation, the pilot

estimated that 485.9 gallons of fuel had been used since the last refueling. However, on the basis of the pilot's initial planned fuel load and recorded flight times, the airplane would have used about 600 gallons of fuel. The pilot later submitted an estimated fuel burn for the flights since refueling of 485.9 gallons. The flight manual did not have fuel burn references for the exact power settings and altitudes flown; thus, the hourly fuel burn could not be determined.

The pilot, copilot, and passenger did not visually verify the fuel levels in all four main fuel tanks before the accident flight. The pilot also underestimated the amount of fuel that would be used for the planned flights. As a result, fuel exhaustion occurred, which led to a total loss of engine power.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power due to fuel exhaustion. Contributing to the accident was the erroneous fuel gauge indications and inadequate preflight planning and inspection

Findings

Personnel issues	Preflight inspection - Flight crew
Personnel issues	Fuel planning - Pilot
Personnel issues	Decision making/judgment - Pilot
Aircraft	Fuel - Fluid level
Environmental issues	Rough terrain - Effect on operation

Factual Information

History of Flight

Enroute

Loss of engine power (total) (Defining event)

On September 19, 2020, about 1925 Pacific daylight time, a North American B-25N, N7946C, was substantially damaged when it was involved in an accident near Stockton, California. The copilot and the passenger sustained serious injuries, and the pilot sustained minor injuries. The airplane was operated as a Title 14 *Code of Federal Regulations* 91 personal flight.

The airplane had made two previous flights on the day of the accident (as discussed later in this section.) For the accident flight, the pilot (who was in the right seat and not flying at the time) reported that, while the airplane was in cruise flight at 1,500 ft mean sea level (msl) and about 7 miles from its intended destination, the left engine fuel pressure fluctuated, and the left engine lost power momentarily but resumed operation. The pilot saw that the fuel pressure needle returned to normal, but he was concerned that an engine-driven fuel pump might have failed. The pilot subsequently turned the boost pumps to high and asked the passenger to open the fuel cross-feed valve. When the airplane was about 6 miles from its intended destination, both fuel pressure needles began to fluctuate. The pilot assumed that fuel starvation to the engines had occurred and decided to make an off-airport landing to a field behind the airplane's position due to residential areas between the location and the airport. The pilot stated that he took control of the airplane from the copilot (who was in the left seat) and initiated a right turn toward the field. Shortly afterward, the fuel pressure dropped below 10 pounds per square inch, and both engines lost power.

The right-seat pilot stated that, during the rollout after landing in the field, he observed ditches in front of the airplane. He was able to get the airplane airborne briefly to avoid one ditch but was not able to avoid a second large ditch. Subsequently, the airplane struck the second ditch, became airborne, and impacted the ground in a nose-low attitude. All three landing gear collapsed.

In postaccident statements, the pilot reported that he used a 150-gallons-per-hour fuel burn for flight planning purposes, which included the takeoff fuel burn. The pilot also stated that, before the accident flight, neither he nor the other airplane occupants had visually verified the fuel levels in the fuel tanks.

The copilot reported that, when he boarded the airplane before the flight, he questioned the pilot about the fuel level and was told that it was calculated to be more than 200 gallons of fuel, which was more than enough for the 20-minute flight. The copilot provided a photograph from inside the airplane before the loss of power, which showed a power setting of about 1,700 rpm and 27 inches of manifold pressure. The photograph also captured the front and aft fuel tank gauges. The front tank fuel gauges showed about 70 gallons on the left side and about 55 gallons on the right side. The aft gauges displayed 0 and were fully deflected to the bottom for both the left and right sides.

The passenger, who was also the airplane's mechanic, reported that, when the airplane was topped off with fuel at Brown Field (SDM), San Diego, California, the fuel level was about 3 inches below the bottom of the fuel filler neck. He further reported that, when he had arrived at Vacaville Airport (VCB),

Vacaville, California, he was told to board the accident airplane and prepare for departure. The passenger stated that, because he had rushed into the airplane, he did not accomplish his normal routine, which included checking fuel and oil levels. The passenger stated that he "always tops the tanks off, either to the top or maybe 2.5 inches from the top of the filler neck."

Refueling records showed that the airplane had been last refueled on September 18, 2020, with 497.7 gallons of fuel. No evidence showed the fuel level after refueling.

Automatic dependent surveillance-broadcast (ADS-B) data showed six flights since the airplane was refueled, as shown in table 1. The ADS-B times listed do not account for operational time before takeoff and after landing.

Date	Departure	Destination	Flight Time (minutes)
September 18, 2020	SDM	North Island Naval Air Station (NZY), San Diego, California	8
September 18, 2020	NZY	Local	33
September 19, 2020	NZY	Local	19
September 19, 2020	NZY	Chino Airport (CNO), Chino, California	38
September 19, 2020	CNO	VCB	127
September 19, 2020	VCB	Stockton, California	16
Total Flight Time:			241 Minutes

Table 1. Accident airplane flights after refueling.

The airplane was equipped with two interconnected forward and aft main fuel tanks in each wing, which could hold a total of 670 gallons of fuel. The flight handbook for the accident airplane stated, in part, "useable fuel is slightly less than quantity listed." Recovery company personnel reported that, during the recovery of the wreckage, about 1 gallon of fuel was removed from each forward and aft wing fuel tank.

The pilot provided more detailed postaccident calculations of the accident airplane's fuel burn, which indicated that the airplane would have used 485.9 gallons of fuel after the airplane had been last refueled (not including fuel usage for taxi and runup). The pilot reported that he used power settings of 30 inches of manifold pressure and 2,000 rpm for takeoff and 20 inches manifold pressure and 1,800 rpm for cruise flight. The flight handbook for the accident airplane model contained no specific data for performance charts and fuel burn data for the pilot's power settings in cruise flight at the altitudes flown (as shown in the ADS-B data for the accident flight).

Postaccident examination of the recovered wreckage revealed that the fuselage was substantially damaged. The left and right forward and aft main fuel tanks were undamaged. Both main forward and main aft fuel gauges were removed from the instrument panel and connected to their respective center section wiring with external power applied. Each fuel tank was subsequently filled with water, and fuel gauge indications were captured at various water levels. All four fuel gauges displayed erroneous indications at almost all levels measured. No leaks were observed throughout the fuel system. Table 2 shows the fluid levels that were captured at the top and bottom of each fuel pickup port for all four fuel tanks.

Fuel tank	Bottom of pickup port (gallons)	Top of pickup port (gallons)
Left forward	1.1	14.3
Left aft	1.5	7.0
Right forward	1.5	14.3
Right aft	1.2	7.0

Table 2. Fuel tank fluid levels during postaccident examination.

Impact damage to both carburetors precluded a functional check and a determination of the fuel flow setting.

Pilot Information

Certificate:	Commercial	Age:	57, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	January 6, 2020
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 16, 2020
Flight Time:	5100 hours (Total, all aircraft), 296 hours (Total, this make and model), 4800 hours (Pilot In Command, all aircraft), 18 hours (Last 90 days, all aircraft), 12 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Co-pilot Information

Certificate:	Airline transport	Age:	25, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:	Class 1	Last FAA Medical Exam:	
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	North American	Registration:	N7946C
Model/Series:	B25N	Aircraft Category:	Airplane
Year of Manufacture:	1944	Amateur Built:	
Airworthiness Certificate:	Limited (Special)	Serial Number:	44-28938
Landing Gear Type:	Retractable - Tricycle	Seats:	
Date/Type of Last Inspection:	July 23, 2020 Continuous airworthiness	Certified Max Gross Wt.:	35000 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	8099.1 Hrs as of last inspection	Engine Manufacturer:	Wright
ELT:		Engine Model/Series:	R2600
Registered Owner:	PROAIR Holding Company	Rated Power:	1700
Operator:	PROAIR Holding Company	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSCK,33 ft msl	Distance from Accident Site:	4.4 Nautical Miles
Observation Time:	18:55 Local	Direction from Accident Site:	104°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.85 inches Hg	Temperature/Dew Point:	28°C / 10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Vacaville, CA (VCB)	Type of Flight Plan Filed:	None
Destination:	Stockton, CA	Type of Clearance:	None
Departure Time:	19:06 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 Serious, 1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Serious	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 Serious, 1 Minor	Latitude, Longitude:	37.909216,-121.34045(est)

Administrative Information

Investigator In Charge (IIC):	Cawthra, Joshua
Additional Participating Persons:	Matthew DeSeelhorst; Federal Aviation Administration; Oakland, CA
Original Publish Date:	February 3, 2023
Last Revision Date:	
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=101996

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).