



Aviation Investigation Final Report

Location: INVER GROVE, Minnesota Accident Number: CHI96LA177

Date & Time: May 28, 1996, 14:00 Local Registration: N5192U

Aircraft: Cessna U206 Aircraft Damage: Destroyed

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that over the water during landing the winds were gusty. The pilot reported the airplane hit the water, skipped once, caught a float, and flipped over. The winds at an airport approximately three nautical miles from the accident location were 15 knots, gusting to 21 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's improper recovery from the bounced landing. The gusty wind condition was a factor.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) WEATHER CONDITION - GUSTS

2. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND

Occurrence #2: NOSE OVER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Page 2 of 6 CHI96LA177

Factual Information

On May 28, 1996, at 1400 central daylight time (cdt), a Cessna U206, N5192U, was substantially damaged, when the aircraft flipped over during a water landing, at the Wipline Sea Plane Base, Inver Grove, Minnesota. After the aircraft flipped over, the private pilot and passenger exited the aircraft through the cabin doors. The pilot and the passenger were uninjured in the accident. Visual meteorological conditions existed at the time of the 14 CFR Part 91 fight, and no flight plan was filed.

The pilot reported on the NTSB form 6120.1/2 that he had departed from Baudette, Minnesota en route to the Wipline Airport, Inver Grove Heights, Minnesota. The pilot wrote that before landing he checked the weather conditions on the radio. The pilot wrote that once over the river there were "... a couple of bad gusts." The pilot then reported that "... I hit the water and skipped once, caught a float, and flipped over." The winds at the South St. Paul, Fleming Airport, which is approximately three nautical miles from the accident location at 1416 cdt were 15 knots, gusting to 21 knots. The pilot did not list any aircraft component failures on the accident form.

Aircraft damage consisted of a fractured right pontoon, a twisted fuselage between the cabin and the empennage, and buckling of the wing skins.

Pilot Information

T HOC HITOTHIACION			
Certificate:	Private	Age:	51,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 1, 1995
Occupational Pilot:	UNK	NK Last Flight Review or Equivalent:	
Flight Time:	300 hours (Total, all aircraft), 80 hours (Total, this make and model), 300 hours (Pilot In Command, all aircraft), 40 hours (Last 90 days, all aircraft), 11 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CHI96LA177

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N5192U
Model/Series:	U206 U206	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	206-0192
Landing Gear Type:	Float	Seats:	4
Date/Type of Last Inspection:	January 10, 1996 Annual	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:	40 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3191 Hrs	Engine Manufacturer:	Continental
ELT:	Installed	Engine Model/Series:	IO-520-A
Registered Owner:	ROBERT L. SWANSON	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

motor or grown miles			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	D97 ,820 ft msl	Distance from Accident Site:	3 Nautical Miles
Observation Time:	14:16 Local	Direction from Accident Site:	340°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	15 knots / 21 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	70°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	23°C / 1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	BAUDETTE , MN (BDE)	Type of Flight Plan Filed:	None
Destination:	(097)	Type of Clearance:	None
Departure Time:	12:00 Local	Type of Airspace:	Class E

Page 4 of 6 CHI96LA177

Airport Information

Airport:	WIPLINE SEAPLANE BASE 094	Runway Surface Type:	Water
Airport Elevation:	687 ft msl	Runway Surface Condition:	Water-choppy
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Destroyed
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	44.88002,-93.040649(est)

Page 5 of 6 CHI96LA177

Administrative Information

Investigator In Charge (IIC):	Boldenow, David	
Additional Participating Persons:	RUDI HARTLEBEN; MINNEAPOLIS , MN	
Original Publish Date:	July 25, 1996	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=10259	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CHI96LA177