



Aviation Investigation Final Report

Location: Chignik Lagoon, Alaska Accident Number: ANC21LA030

Date & Time: April 16, 2021, 10:10 Local Registration: N991AK

Aircraft: Beech C-99 Aircraft Damage: Substantial

Defining Event: Collision with terr/obj (non-CFIT) **Injuries:** 9 None

Flight Conducted Under: Part 135: Air taxi & commuter - Scheduled

Analysis

The pilot reported that, during final approach to land, he noticed a road grader operating on the far end of the runway. He made a radio transmission stating that the flight was 4 miles out on final approach and observed the road grader pull over at the opposite end of the airport and park. Believing that the operator of the road grader heard his call and parked, he proceeded with a normal approach and landing. After touchdown, he applied reverse with moderate braking. When the airplane was fully out of reverse and had slowed to about 35 mph, he noticed a large piece of foreign object debris (FOD) on the runway centerline. The FOD appeared to be about 18 inches wide and about 12 inches tall. He veered to the left in an effort to straddle the FOD with main landing gear. Subsequently, the right main landing gear struck the FOD, the right main landing gear collapsed, and the airplane slid about 75 ft down the runway centerline before coming to a stop. The airplane sustained substantial damage to the right wing.

A postaccident inspection revealed that the FOD was a chunk of ice. The pilot also learned that the road grader was not equipped with an aircraft radio.

The pilot reported no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The Federal Aviation Administration Supplement Alaska for the applicable airport under AIRPORT REMARKS states in part:

Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Seabirds on and invof arpt. Vehicle and pedestrians frequently use numerous roads and trails that cross rwy. Loose rocks on rwy sfc up to 6". Rwy 04–22 sfc contains numerous rocks and puddles. Several roads and trails cross Rwy 04–22. Rwy 04 thlds marked with orange reflective cones.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to visually inspect the runway condition before landing, which resulted in a collision with an ice chunk and main landing gear separation during landing.

Findings

Personnel issues	(general) - Pilot
Personnel issues	Decision making/judgment - Pilot
Personnel issues	Expectation/assumption - Pilot
Environmental issues	Snow/ice - Effect on equipment

Page 2 of 6 ANC21LA030

Factual Information

History of Flight

Landing-landing roll	Collision with terr/obj (non-CFIT) (Defining event)
Landing-landing roll	Part(s) separation from AC
Landing-landing roll	Nose over/nose down

Pilot Information

Certificate:	Commercial	Age:	54,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	April 1, 2020
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 9, 2021
Flight Time:	(Estimated) 13724 hours (Total, all aircraft), 3020 hours (Total, this make and model), 13624 hours (Pilot In Command, all aircraft), 341 hours (Last 90 days, all aircraft), 139 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC21LA030

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N991AK
Model/Series:	C-99	Aircraft Category:	Airplane
Year of Manufacture:	1982	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	U-189
Landing Gear Type:	Retractable - Tricycle	Seats:	9
Date/Type of Last Inspection:	April 8, 2021 100 hour	Certified Max Gross Wt.:	11380 lbs
Time Since Last Inspection:		Engines:	2 Turbo prop
Airframe Total Time:	27917.9 Hrs at time of accident	Engine Manufacturer:	P&W CANADA
ELT:	C126 installed, not activated	Engine Model/Series:	PT6A-36
Registered Owner:	LAKE CLARK AIR INC	Rated Power:	783 Horsepower
Operator:	LAKE CLARK AIR INC	Operating Certificate(s) Held:	On-demand air taxi (135)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAJC,18 ft msl	Distance from Accident Site:	5 Nautical Miles
Observation Time:	09:57 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.49 inches Hg	Temperature/Dew Point:	3°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Anchorage, AK (MRI)	Type of Flight Plan Filed:	Company VFR
Destination:	Chignik Lagoon, AK	Type of Clearance:	None
Departure Time:	08:20 Local	Type of Airspace:	Class G

Page 4 of 6 ANC21LA030

Airport Information

Airport:	CHIGNIK LAGOON KCL	Runway Surface Type:	Dirt;Gravel
Airport Elevation:	27 ft msl	Runway Surface Condition:	Dry;lce;Rough
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	2200 ft / 90 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	8 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	9 None	Latitude, Longitude:	56.31084,-158.5348(est)

Page 5 of 6 ANC21LA030

Administrative Information

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	Douglas Epps; FAA; Anchorage, AK
Original Publish Date:	October 19, 2021
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=102941

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC21LA030