



Aviation Investigation Final Report

Location: SAINT CHARLES, Missouri Accident Number: CHI96LA239

Date & Time: July 15, 1996, 10:15 Local Registration: N9703J

Aircraft: Cessna A188B Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

While conducting aerial application maneuvers, the pilot noticed a partial loss of engine power. The pilot tried to climb over the trees but was unable to due to the loss of airspeed. He was unable to dump his chemical load and impacted terrain hard. No discrepancies were found with the engine or dump valve.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: a partial loss of engine power due to undetermined reasons and the pilot's failure to maintain aircraft control. The factors involved were the pilot did not perform load jettison and low airspeed.

Findings

Occurrence #1: LOSS OF ENGINE POWER(PARTIAL) - NONMECHANICAL

Phase of Operation: MANEUVERING - AERIAL APPLICATION

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

2. (F) LOAD JETTISON - NOT PERFORMED - PILOT IN COMMAND

Occurrence #3: LOSS OF CONTROL - IN FLIGHT Phase of Operation: EMERGENCY LANDING

Findings

3. (F) AIRSPEED - LOW - PILOT IN COMMAND

4. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: EMERGENCY LANDING

Page 2 of 6 CHI96LA239

Factual Information

On July 15, 1996, at 1015 central daylight time (cdt), a Cessna A188B, N9703J, registered to W. L. S. Flying Service, of Litchfield, Illinois, was substantially damaged following a partial loss of engine power and subsequent forced landing in a farmer's field approximately 1/4 mile north of the Saint Charles County Airport, Saint Charles, Missouri. The commercial pilot reported no injuries. The 14 CFR Part 137 aerial application flight was not operating on a flight plan. Visual meteorological conditions prevailed at the time of the accident. The flight departed from the Saint Charles County Airport, Saint Charles, Missouri, at 1005 cdt.

According to the pilot's written statement, he loaded the airplane with 1,000 pounds of millet seed and 3/4 of a tank of 100 low lead fuel (40 gallons). The takeoff and climb out were normal. The pilot conducted three to four aerial application passes when he noticed that the airplane's engine "...was running smooth but with a definite loss of power." The pilot tried to climb over the tall trees but lost a lot of airspeed. The pilot stated, "At this point, the airplane was very difficult to control. I had to push full forward just to keep from stalling. The airplane never did stall, but because the plane was loaded, the landing was very hard." Before impact with the terrain, the pilot attempted to dump the load with out success. The pilot stated, "Everything seemed to happen in just a few seconds, and my main concern was to try to keep the plane flying."

A Federal Aviation Administration (FAA) Principal Maintenance Inspector (PMI), represented the NTSB on-scene. The PMI inspected the engine and accessories. No discrepancies were found.

Pilot Information

Certificate:	Commercial	Age:	37,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	April 30, 1996
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	2410 hours (Total, all aircraft), 1590 hours (Total, this make and model), 2300 hours (Pilot In Command, all aircraft), 22 hours (Last 90 days, all aircraft)		

Page 3 of 6 CHI96LA239

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N9703J
Model/Series:	A188B A188B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	18803841T
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	March 20, 1996 Annual	Certified Max Gross Wt.:	4200 lbs
Time Since Last Inspection:	74 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3086 Hrs	Engine Manufacturer:	Continental
ELT:	Not installed	Engine Model/Series:	IO-520-D
Registered Owner:	W. L. S. FLYING SERVICE	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	STL ,605 ft msl	Distance from Accident Site:	11 Nautical Miles
Observation Time:	09:55 Local	Direction from Accident Site:	340°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots / 17 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	24°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	(3SZ)	Type of Flight Plan Filed:	None
Destination:	(3SZ)	Type of Clearance:	None
Departure Time:	10:05 Local	Type of Airspace:	Class G

Page 4 of 6 CHI96LA239

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	Dry;Vegetation
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.789371,-90.509506(est)

Page 5 of 6 CHI96LA239

Administrative Information

Investigator In Charge (IIC): Carlson, Todd JUNE L TONSING; ST. ANN Additional Participating , MO ROGER L HELMS; ST. ANN Persons: . MO **Original Publish Date:** December 23, 1996 **Last Revision Date: Investigation Class:** Class Note: **Investigation Docket:** https://data.ntsb.gov/Docket?ProjectID=10309

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CHI96LA239