



# **Aviation Investigation Final Report**

Location: Ray, Michigan Accident Number: CEN21LA295

Date & Time: June 28, 2021, 19:30 Local Registration: N920SS

Aircraft: FLIGHT DESIGN GMBH CTLS Aircraft Damage: Minor

**Defining Event:** AC/prop/rotor contact w person **Injuries:** 1 Serious, 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

The flight instructor was conducting the 16-year-old student pilot's first instructional flight. After completing several takeoffs and landings, they "taxied around the airport multiple times," during which they experienced "light to sometimes moderate" rain. At the conclusion of the lesson, the rain became heavy enough that visibility was reduced, and the instructor decided to taxi the airplane into its open hangar to avoid getting wet. As they approached the hangar, the instructor noted a set of wheel chocks on the ground, and with the engine still running, he instructed the student to exit the airplane, walk around the propeller arc, and move the chocks so that he, "could taxi the airplane nose-first into the hangar...then turn it around once inside and shut down." He stated that he repeated the instructions to ensure that the student understood. The student subsequently exited the airplane and walked forward into the spinning propeller, resulting in serious injury. The instructor reported that there were no preaccident mechanical malfunctions or failures of the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The flight instructor's improper decision to direct the student pilot to exit the airplane with the engine running, which resulted in serious injury when the student walked into the propeller arc.

### **Findings**

Personnel issues

Decision making/judgment - Instructor/check pilot

Page 2 of 5 CEN21LA295

## **Factual Information**

## **History of Flight**

Other AC/prop/rotor contact w person (Defining event)	
---	--

#### **Pilot Information**

Certificate:	Commercial; Flight instructor	Age:	37
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 2 Unknown	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	April 14, 2021
Flight Time:	(Estimated) 571 hours (Total, all aircraft), 4.2 hours (Total, this make and model), 46.6 hours (Pilot In Command, all aircraft), 1080.9 hours (Last 90 days, all aircraft), 27 hours (Last 30 days, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	FLIGHT DESIGN GMBH	Registration:	N920SS
Model/Series:	CTLS	Aircraft Category:	Airplane
Year of Manufacture:	2010	Amateur Built:	
Airworthiness Certificate:	Special light-sport (Special)	Serial Number:	F-10-02-05
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	March 2, 2021 Condition	Certified Max Gross Wt.:	1320 lbs
Time Since Last Inspection:	45.5 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2315 Hrs as of last inspection	Engine Manufacturer:	Rotax
ELT:	C126 installed, not activated	Engine Model/Series:	912ULS
Registered Owner:	DODGER AIRCRAFT LLC	Rated Power:	100 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 CEN21LA295

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMTC,580 ft msl	Distance from Accident Site:	8 Nautical Miles
Observation Time:	18:56 Local	Direction from Accident Site:	158°
<b>Lowest Cloud Condition:</b>	Scattered / 4000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 5000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.11 inches Hg	Temperature/Dew Point:	26°C / 26°C
Precipitation and Obscuration:	Light - Showers - Rain		
Departure Point:	Ray, MI	Type of Flight Plan Filed:	
Destination:	Ray, MI	Type of Clearance:	None
Departure Time:		Type of Airspace:	

## **Airport Information**

Airport:	RAY COMMUNITY 57D	Runway Surface Type:	
Airport Elevation:	632 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 Serious, 1 None	Aircraft Damage:	Minor
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 None	Latitude, Longitude:	42.738367,-82.889726(est)

Page 4 of 5 CEN21LA295

#### **Administrative Information**

Investigator In Charge (IIC):	Aguilera, Jason
Additional Participating Persons:	David Schrader; FAA FSDO; Belleville, MI
Original Publish Date:	February 18, 2022
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=103380

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN21LA295