



# **Aviation Investigation Final Report**

Location:	Hastings, Michigan	Accident Number:	CEN21LA303
Date & Time:	June 30, 2021, 18:00 Local	Registration:	N1175H
Aircraft:	Aeronca 15AC	Aircraft Damage:	Substantial
Defining Event:	Unknown or undetermined	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Instructional		

# Analysis

The pilot receiving instruction and flight instructor were conducting a flight review. About 45 minutes into the flight, the engine "sputtered" and lost power following a practice goaround. The flight instructor took control of the airplane and performed a forced landing, during which the airplane sustained substantial damage. The pilot reported that they departed on the flight with 8 gallons of fuel in the left-wing tank and 7 gallons of fuel in the right-wing tank. The flight instructor recalled that, shortly before the loss of engine power, the left and right tanks contained about 8 gallons and 2 gallons, respectively. The mechanic who recovered the airplane reported that about 6 gallons remained in the left fuel tank and 2 gallons in the right fuel tank. The fuel caps were secure, and the accident site did not exhibit any evidence of a fuel spill.

A postaccident examination and engine test run did not reveal any anomalies consistent with a preimpact failure or malfunction. Continuity of the airframe fuel system was confirmed. The reason that fuel was being drawn predominantly from the right fuel tank could not be determined. The reason for the loss of engine power could not be determined based on the available information.

# **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power for reasons that could not be determined based on the available

#### information.

#### **Findings**

Not determined

(general) - Unknown/Not determined

# **Factual Information**

History of Flight	
Approach-VFR go-around	Loss of engine power (total)
Approach-VFR go-around	Unknown or undetermined (Defining event)
Emergency descent	Off-field or emergency landing

On June 30, 2021, about 1800 eastern daylight time, an Aeronca 15AC airplane, N1175H, was substantially damaged when it was involved in an accident near Hastings, Michigan. The pilot receiving instruction and flight instructor were not injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 instructional flight.

The flight instructor reported that, about 45 minutes into a flight review, the engine lost power following a practice go-around. The pilot noted that the engine was "good and strong" during the initial portion of the go-around. About 400 ft above ground level, the engine "sputtered" and lost power. When the pilot leveled the wings, engine power was restored. The flight instructor took control of the airplane, and the engine subsequently lost power again, after which the flight instructor performed a forced landing to a grass area on airport property. During the landing, the airplane nosed over and came to rest inverted near the perimeter fence, resulting in substantial damage to the left-wing strut and rudder.

The pilot reported that they departed on the flight with about 15 total gallons of fuel; 8 gallons in the left wing fuel tank and 7 gallons in the right wing fuel tank. The airplane was equipped with sight gauges at each wing root to indicate fuel quantity. The flight instructor recalled that, shortly before the loss of engine power, about 8 gallons and 2 gallons of fuel remained in the left and right fuel tanks, respectively. The mechanic who recovered the airplane reported that about 6 gallons remained in the left fuel tank and 2 gallons remained in the right fuel tank. The fuel caps were secure, and the accident site did not exhibit any evidence of a fuel spill.

A postaccident examination and engine test run did not reveal any anomalies consistent with a preimpact failure or malfunction. Continuity of the airframe fuel system was confirmed.

#### **Pilot Information**

Certificate:	Private	Age:	69,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	March 15, 2018
Flight Time:	525 hours (Total, all aircraft), 241 ho aircraft)	urs (Total, this make and model), 2 ho	urs (Last 30 days, all

### Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	61,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	November 3, 2020
Occupational Pilot:	No	Last Flight Review or Equivalent:	December 7, 2019
Flight Time:	2454 hours (Total, all aircraft), 10 hours (Total, this make and model), 2363 hours (Pilot In Command, all aircraft), 20 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

### Aircraft and Owner/Operator Information

Aircraft Make:	Aeronca	Registration:	N1175H
Model/Series:	15AC	Aircraft Category:	Airplane
Year of Manufacture:	1948	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	15AC-188
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	May 8, 2021 Annual	Certified Max Gross Wt.:	2050 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2875 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	O-300
Registered Owner:	On file	Rated Power:	145 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
<b>Observation Facility, Elevation:</b>	GRR,794 ft msl	Distance from Accident Site:	15 Nautical Miles
Observation Time:	17:53 Local	Direction from Accident Site:	330°
Lowest Cloud Condition:	Scattered / 4400 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	13 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.03 inches Hg	Temperature/Dew Point:	27°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipitat	tion	
Departure Point:	Hastings, MI (9D9)	Type of Flight Plan Filed:	None
Destination:	Hastings, MI (9D9)	Type of Clearance:	None
Departure Time:	17:16 Local	Type of Airspace:	Class G

### **Airport Information**

Airport:	Hastings 9D9	Runway Surface Type:	
Airport Elevation:	800 ft msl	Runway Surface Condition:	Dry;Vegetation
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

# Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	42.66739,-85.35251

#### **Administrative Information**

Investigator In Charge (IIC):	Sorensen, Timothy
Additional Participating Persons:	Michael W. Matthews; FAA Flight Standards; Grand Rapids, MI
Original Publish Date:	January 19, 2023
Last Revision Date:	
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=103405

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.