



Aviation Investigation Final Report

Location:	Comstock, Texas	Accident Number:	CEN21FA327
Date & Time:	July 17, 2021, 20:40 Local	Registration:	N2054B
Aircraft:	Luscombe 8F	Aircraft Damage:	Destroyed
Defining Event:	Unknown or undetermined	Injuries:	1 Fatal
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot departed on a personal flight, and the wreckage was located about 20 nautical miles from the departure airport by the property owner. There were no witnesses to the accident. Recorded data showed that, after maneuvering over the area of the accident site for about 6 minutes, the airplane entered a near-vertical descent. The airplane impacted terrain and was destroyed. The wreckage was consistent with a wings-level, near-vertical impact. Postaccident examination revealed no mechanical anomalies that would have precluded normal operation.

Toxicology testing of the pilot identified ethanol. The large discrepancy among the ethanol levels in muscle, heart, and liver indicates that at least some of the detected ethanol was likely from sources other than consumption. Notably, the severity of injury made postmortem microbial ethanol production more likely, and the detectable n-propanol and n-butanol in muscle and heart indicate likely postmortem microbial activity in these tissues (although such activity does not always produce ethanol).

Although at least some of the detected ethanol was likely from sources other than consumption, the available ethanol results are insufficient to exclude the possibility that consumed ethanol may have exerted impairing effects on the pilot, particularly given that diphenhydramine was also detected. Like ethanol, diphenhydramine may exert impairing sedative effects, and such effects may combine with those of ethanol. There is insufficient medical and operational evidence to determine whether ethanol or diphenhydramine caused impairment that contributed to the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Impact with terrain for reasons that could not be determined based on the available information.

Findings

Personnel issues	(general) - Flight crew
------------------	-------------------------

Factual Information

History of Flight

Maneuvering	Unknown or undetermined (Defining event)
-------------	--

On July 18, 2021, about 2040 central daylight time, a Luscombe 8F, N2054B, was destroyed when it was involved in an accident near Comstock, Texas. The commercial pilot sustained fatal injuries. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The airplane departed from Del Rio International Airport (DRT), Del Rio, Texas, about 2015. The wreckage was found by a landowner while he was checking the field's fence; he did not hear or see the accident. There were no known witnesses to the accident.

Pilot Information

Certificate:	Commercial	Age:	34, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	December 27, 2006
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 717 hours (Total, all aircraft)		

The pilot was a United States Air Force pilot. He accumulated a total military flight experience of 2,084 hours, and his total civilian flight time was 717 hours as of his most recent logbook entry, dated September 2, 2018.

Aircraft and Owner/Operator Information

Aircraft Make:	Luscombe	Registration:	N2054B
Model/Series:	8F	Aircraft Category:	Airplane
Year of Manufacture:	1949	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	6481
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	December 7, 2020 Annual	Certified Max Gross Wt.:	1400 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3953 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	C91 installed, activated, did not aid in locating accident	Engine Model/Series:	C90-8F
Registered Owner:	On file	Rated Power:	90 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dusk
Observation Facility, Elevation:	DRT, 1002 ft msl	Distance from Accident Site:	20 Nautical Miles
Observation Time:	20:53 Local	Direction from Accident Site:	315°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	7 knots / None	Turbulence Type Forecast/Actual:	None /
Wind Direction:	110°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.97 inches Hg	Temperature/Dew Point:	33°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Del Rio, TX (DRT)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	20:11 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Fatal	Latitude, Longitude:	29.640618,-101.06117

The wreckage was located about 20 miles north-northwest of DRT. The airplane came to rest inverted on a magnetic heading of 202°. The propeller, located several feet forward of the nose, exhibited chordwise scratching consistent with rotation. The propeller hub was split in half, consistent with impact damage. Ground scarring was limited to the areas under the propeller and the airframe. There was no ground scarring across the field. The airplane exhibited substantial damage to the fuselage, wings, and empennage.

The crush damage to the nose and both wings was consistent with a wings-level, nearly vertical impact angle. All control surfaces were located with the fuselage at the accident site. Both wing flaps were retracted.

Postaccident examination of the airplane confirmed continuity each of the flight control surfaces to the cockpit controls. All separations in the control system were consistent with overstress due to impact forces.

The engine crankcase was broken open. The internal engine components did not exhibit failure.

The tachometer gauge needle was deformed along the tachometer face. The tachometer indicated about 2,600 rpm.

Medical and Pathological Information

The pilot's most recent third-class Federal Aviation Administration medical certificate was issued on December 27, 2006. At that time, he reported no medication use and no active medical conditions.

The Webb County Medical Examiner's Office, Laredo, Texas, performed the pilot's autopsy. According to the autopsy report, the cause of death was multiple traumatic injuries, and the manner of death was accident. The autopsy was limited by the severity of injuries, with no

major heart or brain structures described. Within this limitation, the autopsy did not identify significant natural disease.

Toxicological testing at the FAA Forensic Sciences Laboratory detected ethanol in muscle at 0.182 g/dL, in heart at 0.065 g/dL, and in liver at 0.034 g/dL. Ethanol testing in brain was inconclusive. N-propanol and n-butanol were detected in muscle and heart. Diphenhydramine was detected in muscle and liver.

Ethanol is the intoxicating alcohol in beer, wine, and liquor. It can impair judgment, psychomotor performance, cognition, and vigilance. FAA regulation imposes strict limits on flying after consuming ethanol. This includes a prohibition on acting as a crewmember of a civil aircraft while having a blood ethanol level of 0.04 g/dL or greater. Ethanol can also be produced by microbes in a person's body tissues after death. N-propanol and n-butanol are other alcohols that can be produced by microbes in a person's body tissues after death.

Diphenhydramine is a sedating antihistamine available over the counter in multiple cold and allergy products as well as sleep aids. Diphenhydramine can cause drowsiness and cognitive and psychomotor impairment. It typically carries a warning to be cautious with tasks like driving and operating machinery, and to avoid use with alcohol, which can increase its sedative effects. The FAA states that pilots should not fly within 60 hours of using diphenhydramine, to allow time for it to be eliminated from circulation.

Additional Information

Download of data from the pilot's watch indicated that he was maneuvering the airplane near the accident site for about 6 minutes before the airplane entered a steep descent over the accident site.

Administrative Information

Investigator In Charge (IIC):	Gallo, Mitchell
Additional Participating Persons:	Jeffrey Johnson; Federal Aviation Administration; San Antonio FSDO; San Antonio, TX Jose Ojeda; Federal Aviation Administration; San Antonio FSDO; San Antonio, TX Gary Watson; Federal Aviation Administration; North Texas FSDO; Irving, TX
Original Publish Date:	August 12, 2022
Last Revision Date:	
Investigation Class:	Class 3
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=103501

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).