



Aviation Investigation Final Report

| | | | |
|--------------------------------|--------------------------------------|-------------------------|------------|
| Location: | Wadsworth, Ohio | Accident Number: | CEN21FA426 |
| Date & Time: | September 18, 2021, 18:45 Local | Registration: | N6915G |
| Aircraft: | RANS S20 | Aircraft Damage: | Destroyed |
| Defining Event: | Aircraft wake turb encounter | Injuries: | 1 Fatal |
| Flight Conducted Under: | Part 91: General aviation - Personal | | |

Analysis

The pilot of the airplane was holding short of the runway for takeoff when he asked the pilot of an inbound helicopter to side-step to the taxiway so that the airplane could depart. The helicopter pilot reported that a side-step would have resulted in the helicopter flying directly over the airplane and that he side-stepped the helicopter toward the taxiway after clearing the airplane. An airport surveillance camera captured the airplane start the takeoff roll after the helicopter passed. Shortly after takeoff, the airplane entered a steep roll and impacted the runway. A postimpact fire ensued.

Toxicology testing of the pilot was positive for ethanol in blood, vitreous fluid, urine, gastric contents, and liver tissue. The ethanol in blood concentration (0.108 gm/dL) was associated with impairment, and alcohol consumption was fairly recent to the accident based on the concentration levels in the pilot's body.

The pilot completed building the airplane about 5 months before the accident. The engine had a history of high oil and cylinder head temperatures, which may have been a factor in the pilot's decision to depart so soon after the helicopter to reduce idling time on the ground.

Based on the available information, it is likely that the airplane encountered wake turbulence from the landing helicopter during takeoff, which resulted in the pilot's loss of control. It is likely that the pilot's impairment from ethanol contributed to the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's decision to depart shortly after a landing helicopter, which resulted in an encounter with the helicopter's wake turbulence and a loss of airplane control. Contributing to the accident was the pilot's impairment by his recent use of ethanol.

Findings

| | |
|-----------------------------|---|
| Aircraft | Lateral/bank control - Attain/maintain not possible |
| Personnel issues | Alcohol - Pilot |
| Environmental issues | Wake turbulence - Awareness of condition |

Factual Information

History of Flight

| | |
|---------|---|
| Takeoff | Aircraft wake turb encounter (Defining event) |
| Takeoff | Loss of control in flight |

On September 18, 2021, about 1845 eastern daylight time, a Rans S-20 airplane, N6915G, was destroyed when it was involved in an accident at Wadsworth Municipal Airport (3G3), Wadsworth, Ohio. The pilot was fatally injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

A review of airport surveillance video revealed that a Sikorsky S-76 helicopter was on approach to Runway 2 as the accident airplane taxied to the runway. According to the helicopter pilot, the accident pilot requested that the helicopter side-step to the west of the runway to facilitate the airplane’s departure.

A few seconds after the helicopter flew over the approach end of runway 2, the accident pilot taxied onto the runway and started the takeoff roll. Soon after liftoff, the airplane entered a steep roll, descended, and impacted the runway (see figure 1). A postimpact fire ensued.



Figure 1. Screenshot of airport surveillance video. Red arrow points to accident airplane.

Pilot Information

| | | | |
|----------------------------------|---|--|---------|
| Certificate: | Private | Age: | 64, |
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | Unknown |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | Yes |
| Medical Certification: | BasicMed Without waivers/limitations | Last FAA Medical Exam: | |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | |
| Flight Time: | 517 hours (Total, all aircraft), 16 hours (Total, this make and model), 6 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| | | | |
|--------------------------------------|------------------------------|---------------------------------------|-----------------|
| Aircraft Make: | RANS | Registration: | N6915G |
| Model/Series: | S20 | Aircraft Category: | Airplane |
| Year of Manufacture: | 2021 | Amateur Built: | Yes |
| Airworthiness Certificate: | Experimental (Special) | Serial Number: | 05170072 |
| Landing Gear Type: | Tailwheel | Seats: | 2 |
| Date/Type of Last Inspection: | April 20, 2021 Condition | Certified Max Gross Wt.: | |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 22.1 Hrs at time of accident | Engine Manufacturer: | Covair |
| ELT: | Installed | Engine Model/Series: | |
| Registered Owner: | On file | Rated Power: | |
| Operator: | On file | Operating Certificate(s) Held: | None |

The kit airplane was built by the pilot and the FAA granted a special airworthiness certificate in April 2021. According to maintenance records and a newsletter article written by the pilot, the airplane had a history of high engine oil and cylinder head temperatures.

Meteorological Information and Flight Plan

| | | | |
|---|----------------------------------|---|-------------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | KBJJ, 1137 ft msl | Distance from Accident Site: | 10 Nautical Miles |
| Observation Time: | 18:56 Local | Direction from Accident Site: | 217° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 6 knots / None | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 20° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30.14 inches Hg | Temperature/Dew Point: | 24°C / 17°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Wadsworth, OH (3G3) | Type of Flight Plan Filed: | None |
| Destination: | Wadsworth, OH (3G3) | Type of Clearance: | None |
| Departure Time: | 18:45 Local | Type of Airspace: | Class E |

Airport Information

| | | | |
|-----------------------------|-------------------------|----------------------------------|---------|
| Airport: | Wadsworth Municipal 3G3 | Runway Surface Type: | Asphalt |
| Airport Elevation: | 973 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 2 | IFR Approach: | None |
| Runway Length/Width: | 3530 ft / 75 ft | VFR Approach/Landing: | None |

Wreckage and Impact Information

| | | | |
|----------------------------|---------|-----------------------------|---------------------------|
| Crew Injuries: | 1 Fatal | Aircraft Damage: | Destroyed |
| Passenger Injuries: | | Aircraft Fire: | On-ground |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 1 Fatal | Latitude, Longitude: | 41.004559,-81.755136(est) |

Most of the airplane was destroyed by the postcrash fire (see Figure 2).



Figure 2 – Airplane at Accident Site

Examination of the wreckage did not identify any pre-impact anomalies that would have precluded normal operation.

Medical and Pathological Information

Toxicology testing performed by the FAA Forensic Sciences Laboratory detected ethanol at 0.108 grams per deciliter (gm/dL) in the pilot's blood. Ethanol was detected in his vitreous fluid at 0.119 gm/dL, urine at 0.075 gm/dL, gastric contents at 0.484 gm/dL, and liver tissue at 0.072 grams per hectogram.

Additional Information

According to the Pilot's Handbook of Aeronautical Knowledge (FAA-H-8083-25B), Chapter 5, Avoiding Wake Turbulence:

A helicopter generates a down wash from its main rotor(s) similar to the vortices of an airplane...In forward flight, this energy is transformed into a pair of strong, high-speed trailing vortices similar to wing-tip vortices of larger fixed-wing aircraft. Helicopter vortices should be avoided because helicopter forward flight airspeeds are often very slow and can generate exceptionally strong wake turbulence.

Administrative Information

| | |
|-----------------------------------|---|
| Investigator In Charge (IIC): | Hatch, Craig |
| Additional Participating Persons: | Alexander McAninch; FAA FSDO; Cleveland, OH |
| Original Publish Date: | August 31, 2022 |
| Last Revision Date: | |
| Investigation Class: | Class 3 |
| Note: | |
| Investigation Docket: | https://data.nts.gov/Docket?ProjectID=103903 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).