



# Aviation Investigation Final Report

---

<b>Location:</b>	Bulverde, Texas	<b>Accident Number:</b>	CEN22LA283
<b>Date &amp; Time:</b>	June 24, 2022, 08:48 Local	<b>Registration:</b>	N10236
<b>Aircraft:</b>	Osprey II	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Fuel starvation	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

---

## Analysis

The pilot reported that the amphibious airplane’s engine gradually lost partial power shortly after takeoff and he was unable to maintain altitude. He performed a forced landing in a field with the retractable landing gear in the retracted position. After touchdown on the hull, as the airplane slowed, the right wing settled to the ground and the right-wing sponson struck the ground. The airplane incurred substantial damage to the right wing and fuselage during the forced landing.

Postaccident examination of the airplane revealed that the fiberglass fuel tanks of the airplane had debris and deterioration. The resin used in construction of the fuel tanks was not compatible with automotive gasoline. The pilot/owner had never used automotive gasoline but could not attest to what previous owners had used. Further examination did not reveal any other preimpact anomalies with the engine that would have precluded normal operations.

Although there was a potential for carburetor icing at glide power, based on the available evidence and that the airplane was taking off at the time of the accident, the engine likely lost power due to fuel starvation caused by debris obstructing the fuel outlet port of the fuel tank.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A loss of engine power due to fuel starvation due to a blockage of the fuel tank outlet port.

## Findings

**Aircraft**

Fuel storage - Damaged/degraded

## Factual Information

### History of Flight

<b>Initial climb</b>	Fuel starvation (Defining event)
<b>Initial climb</b>	Loss of engine power (partial)
<b>Emergency descent</b>	Off-field or emergency landing

On June 24, 2022, about 0848 central daylight time, an Osprey II airplane, N10236, was substantially damaged when it was involved in an accident near Bulverde, Texas. There were no injuries. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The pilot reported that the airplane was not fueled on the day of the accident and had last been fueled a week before. The fuel tanks were about ½ full with about 6 gallons in each of the 2 tanks. He sampled the fuel tanks and observed no contaminants. The engine start and run-up were normal, and he proceeded to runway 16 at the Bulverde Airpark (1TT8) for takeoff.

The engine operated normally during the takeoff roll. Shortly after rotation, the engine sounded quieter, and the rpms fluctuated between 2,300 - 2,500 rpm. An engine speed of 2,600 rpm was normal for takeoff. He retracted the landing gear, which helped the climb a little, but the engine power continued to deteriorate. No engine roughness was felt at this time. The airplane was placed at the best angle for climb, about 70 mph. As the airplane cleared the 35-ft-tall trees at the end of the runway, the engine rpm was about 2,100 - 2,300 rpm and some roughness was now felt. The airplane would not climb, and the pilot selected a field and landed the airplane with the retractable landing gear in the retracted position. Before touchdown, the mixture was leaned to shutoff and the throttle was closed. After touchdown on the hull, as the airplane slowed, the right wing settled to the ground and the right-wing sponson struck the ground. The airplane incurred substantial damage to the right wing and fuselage during the forced landing.

Postaccident examination of the airplane revealed that the fiberglass fuel tanks contained a considerable amount of contamination and the resin system appeared to be deteriorating. The resin system used in construction was believed to be polyester resin, which was not compatible with automotive fuel. The pilot/owner was not the original builder and had only used 100 low lead aviation gasoline since purchasing the airplane, but he could not say if previous owners had used automotive gasoline. The baffling in the tanks prevented visual inspection with the tanks mounted in the airplane and removal was not possible, requiring disassembly of the wings. The pilot noted that when he first purchased the airplane the gascolator had debris and after the accident it had some debris in it as well. Examination of the engine confirmed compression on all cylinders. Although ignition was not verified during

the examination, the pilot reported that during the accident flight the engine never stopped running, indicating that the ignition system was operating during the event.

The air temperature about the time of the accident was 80° F and the dew point was 70° F. The Federal Aviation Administration’s Carburetor Icing Probability Graph indicates that, under those conditions, the airplane encountered a serious risk of carburetor icing at glide power.

### Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	31, Male
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Unmanned (sUAS)	<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 2 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	January 1, 2022
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	2800 hours (Total, all aircraft), 89 hours (Total, this make and model), 2600 hours (Pilot In Command, all aircraft), 25 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft)		

### Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Osprey	<b>Registration:</b>	N10236
<b>Model/Series:</b>	II	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	2006	<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental (Special)	<b>Serial Number:</b>	289
<b>Landing Gear Type:</b>	Retractable - Tricycle; Amphibian	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	January 11, 2022 Condition	<b>Certified Max Gross Wt.:</b>	1560 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	140 Hrs as of last inspection	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	C91A installed, not activated	<b>Engine Model/Series:</b>	O-320-E2D
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	150 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KSAT,799 ft msl	<b>Distance from Accident Site:</b>	16 Nautical Miles
<b>Observation Time:</b>	08:51 Local	<b>Direction from Accident Site:</b>	192°
<b>Lowest Cloud Condition:</b>	Few / 10000 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	7 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	220°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.99 inches Hg	<b>Temperature/Dew Point:</b>	27°C / 21°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Bulverde, TX	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Bulverde, TX	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>		<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	BULVERDE AIRPARK 1T8	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	1080 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	16	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	2890 ft / 40 ft	<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	29.7979,-98.4229

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Brannen, John
<b>Additional Participating Persons:</b>	Robert McGee; Houston FAA FSDO; Houston, TX
<b>Original Publish Date:</b>	November 15, 2023
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class 3</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=105347">https://data.ntsb.gov/Docket?ProjectID=105347</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).